

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Tax invoice

Preview

Page 1/4

Document no.
Document date 07-06-2019
Customer no. 5211024655
Customer GST-ID
Dealer 39999
Job order number 2019000868/ 1
Job order date 06-06-2019
Service Advisor YEN MEI WONG

Ms.
SEAH
IRENE MESTON NEE TELFER
259 ARCADIA ROAD
#02-07
Singapore 289852

*14 Days.
before paint photos.
Eno Qiang - 82880282
07/6/19.*

License plate	Model code	First registration	VIN	Model	Mileage
SMD3747J	BQ13HZ	16-08-2018	WVWZZZAUZJW286151	Golf Comfortline 1.4 TSI 92kW DSG	18

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Leaked Check, Vacuum & Regas	1	pcs.	420.00	#1	420.00	449.40
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	R&R RHS U/CARRIAGE	1.5	pcs.	840.00	#1	1260.00	2,696.40
	R&R LHS U/CARRIAGE	1.5	pcs.	840.00	#1	1260.00	2,696.40
	R&R SUB FRAME	1	pcs.	840.00	#1	840.00	1,797.60
	R&R RIM & BALANCE	3	pcs.	50.00	#1	150.00	160.50
5G2823531D	Cable Hood Latch	1	pcs.	31.27	#1	31.27	33.46
	LOCK CABLE ?						
5G0807217FNGRU	Cover For Bumper Primed	1	pcs.	1,083.64	#1	1,083.64	1,159.49
5G0805915J 9B9	Retainer For Spoiler Sati	1	pcs.	174.53	#1	174.53	186.75
5G0807723F	Support Part	1	pcs.	50.49	#1	50.49	54.02
	BUMPER INNER BRACKET LH						
5G0807724F	Support Part	1	pcs.	50.49	#1	50.49	54.02
	BUMPER INNER BRACKET RH						
5G0807049B	Guide Piece		pcs.	19.18	#1	19.18	20.52
	BUMPER SIDE BRACKET LH						
5G0807050B	Guide Piece	1	pcs.	19.18	#1	19.18	20.52
	BUMPER INNER BRACKET RH						
5G0807109AL	Impact Beam	1	pcs.	587.84	#1	587.84	628.99
	REINFORCEMENT						
5G0919493L	Sensor Bracket	1	pcs.	11.67	#1	11.67	12.49
5G0919493J	Sensor Bracket	2	pcs.	10.98	#1	21.96	23.50
5G0919494G	Sensor Bracket	1	pcs.	11.67	#1	11.67	12.49
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	74.29	#1	74.29	79.49
D 822150A1	Bonding Agent For Plastic	1	pcs.	56.90	#1	56.90	60.88
5Q0825236Q	Sound Baffle	1	pcs.	137.36	#1	137.36	146.98
	ENGINE LOWER COVER						
5G0853671G RYP	Cooling Air Grill Satin B	1	pcs.	229.28	#1	229.28	245.33
	CENTRE LOWER GRILLE						
5G0853665L 9B9	Cooling Air Grill Satin B	1	pcs.	70.75	#1	70.75	75.70
	LHS FOG LAMP GRILLE LOWER						
5G0853666L 9B9	Cooling Air Grill Satin B	1	pcs.	70.75	#1	70.75	75.70
	RHS FOG LAMP GRILLE LOWER						
5G0853212H 9B9	Cover Part For Bumper Sat	1	pcs.	31.13	#1	31.13	33.31
	RHS FOG LAMP GRILLE CENTRE						
5G0854662F RYP	Cooling Air Grill Satin B	1	pcs.	91.02	#1	91.02	97.39
	RHS FOG LAMP GRILLE UPPER						
5G2941774	Led Headlight	1	pcs.	2,708.49	#1	2,708.49	2,898.08
	H/LAMP RH						
5G0805588AC	Lock Carrier With Mountin	1	pcs.	1,097.98	#1	1,097.98	1,174.84
5G0805705R	Guide	1	pcs.	36.62	#1	36.62	39.18
	BUMPER CENTRE BRACKET						
5G0121283BB	Air Duct	1	pcs.	21.28	#1	21.28	22.77
	AIR GUIDE LH						
5G0121284AD	Air Duct	1	pcs.	21.28	#1	21.28	22.77
	AIR GUIDE RH						

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Volkswagen



SKODA



Commercial Vehicles

Tax invoice

Preview

Page 2/4

Ms.
SEAH
IRENE MESTON NEE TELFER
259 ARCADIA ROAD
#02-07
Singapore 289852

Document no.
Document date 07-06-2019
Customer no. 5211024655
Customer GST-ID
Dealer 39999
Job order number 2019000868/ 1
Job order date 06-06-2019
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMD3747J	BQ13HZ	16-08-2018	WVWZZZAUZJW286151	Golf Comfortline 1.4 I TSI 92kW DSG	18

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5G0805911AJ	Wheelhouse Liner	1	pcs.	86.69	#1	86.69	92.76
	FENDER LINER LOWER LH	1	pcs.		#1		
5G0821106B	Fender RH	1	pcs.	569.67	#1	569.67	609.55
N 90817302	Rivetted Cap Nut	4	pcs.	1.14	#1	4.56	4.88
5G0805912S	Wheelhouse Liner	1	pcs.	86.69	#1	86.69	92.76
	FENDER LINER LOWER RH	1	pcs.		#1		
5G0805970N	Wheelhouse Liner	1	pcs.	152.98	#1	152.98	163.69
	FENDER LINER UPPER RH	1	pcs.		#1		
5G0864237H	Sound Absorber For Fender	1	pcs.	13.41	#1	13.41	14.35
	FENDER INNER TOP SPONGE	1	pcs.		#1		
5G0821112C	Sound Absorber For Fender	1	pcs.	43.71	#1	43.71	46.77
	FENDER ELEMENT	1	pcs.		#1		
5G4831056AS	Door	1	pcs.	2,005.29	#1	2,005.29	2,145.66
	RHS FRT DOOR	1	pcs.		#1		
5G4837652B	Door Seal	1	pcs.	94.20	#1	94.20	100.79
D 378500A2	Sound Absorber Laminated	1	pcs.	38.79	#1	38.79	41.51
5G2857508BG9B9	Rear View Mirror Housing	1	pcs.	568.11	#1	568.11	607.88
5G0857522A	Mirror Glass	1	pcs.	185.77	#1	185.77	198.77
5G0857538E GRU	Mirror Cap Primed	1	pcs.	150.42	#1	150.42	160.95
	MIRROR COVER RH	1	pcs.		#1		
5G0845412E NVB	Side Window	1	pcs.	110.54	#1	110.54	118.28
	1/4 A-PILLAR GLASS RH	1	pcs.		#1		
D 004660M2	2k-Glass Glue Application	1	pcs.	123.02	#1	123.02	131.63
D 00940104	All Purpose Cleaner	1	pcs.	89.95	#1	89.95	96.25
D 00920002	Primer	1	pcs.	25.92	#1	25.92	27.73
D 00950025	Applicator	2	pcs.	9.48	#1	18.96	20.29
D 181802M1	Activator For Precoated W	1	pcs.	23.63	#1	23.63	25.28
5G0073147E FZZ	Wheel Disc 'Alum.' With RIM	3	pcs.	1,768.00	#1	5,304.00	5,675.28
839601361	Rubber Valve	3	pcs.	2.32	#1	6.96	7.45
8V0498625	Wheel Bearing With Mounti	1	pcs.	562.42	#1	562.42	601.79
	WHEEL BEARING LH	1	pcs.		#1		
5Q0407255Q	Wheel Bearing Housing LH	1	pcs.	560.35	#1	560.35	599.57
3Q0199315D	Sub-Frame	1	pcs.	576.97	#1	576.97	617.36
5Q0198037A	1 Set Bonded Rubber Bushe	1	pcs.	167.02	#1	167.02	178.71
8V0498625	Wheel Bearing With Mounti	1	pcs.	562.42	#1	562.42	601.79
	WHEEL BEARING RH	1	pcs.		#1		
5Q0407256Q	Wheel Bearing Housing RH	1	pcs.	560.35	#1	560.35	599.57
5Q0407366A	Guide Joint	1	pcs.	122.52	#1	122.52	131.10
5Q0407152R	Track Control Arm Complet	1	pcs.	328.80	#1	328.80	351.82
	FRT LOWER ARM RH	1	pcs.		#1		
5Q0413023FH	Gas-Filled Shock Absorber	1	pcs.	316.32	#1	316.32	338.46

VOLKSWAGEN CENTRE SINGAPORE

9 Tuas Avenue
Singapore 639176
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Tax invoice

Preview

Page 3/4

Ms.
SEAH
IRENE MESTON NEE TELFER
259 ARCADIA ROAD
#02-07
Singapore 289852

Document no.
Document date 07-06-2019
Customer no. 5211024655
Customer GST-ID
Dealer 39999
Job order number 2019000868/ 1
Job order date 06-06-2019
Service Advisor YEN MEI WONG

License plate	Model code	First registration	VIN	Model	Mileage
SMD3747J	BQ13HZ	16-08-2018	WVWZZZAUZJW286151	Golf Comfortline 1.4 TSI 92kW DSG	18

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5Q0412249F	Ball Bearing	1	pcs.	44.70	#1	44.70	47.83
5Q0412331E	TOP BEARING	1	pcs.	91.61	#1	91.61	98.02
5Q0407762 X	Suspension Strut Mounting	1	pcs.	977.71	#1	977.71	1,046.15
1K0423810A	TOP MTG	1	pcs.	100.29	#1	100.29	107.31
1K0423812J	Drive Shaft With Constant RH	1	pcs.	138.02	#1	138.02	147.68
N 90834901	Tie Rod	2	pcs.	4.64	#1	9.28	9.93
LIQUIMOLY3318	Tie Rod End	1	pcs.	38.22	#1	38.22	40.90
G 013040M2	Retaining Clip	2	pcs.	21.44	#1	42.88	45.88
	DEGREASER CLEANER 500ml	1	pcs.	60.00	#1	60.00	64.20
	Ready-Mix Coolant Frost P	1	pcs.	840.00	#1	840.00	898.80
	A/C GAS	1	pcs.	800.00	#1	800.00	840.00
	LABOUR	6	hrs	800.00	#1	4,800.00	5,136.00
	Spray Painting	4	hrs	800.00	#1	3,200.00	3,360.00
	TRANSFER DOOR MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	TYRE PIRELLI CINTURATO P7 225/45/17	2	pcs.	720.00	#1	1,440.00	1,540.80
	R&R A-PILLAR GLASS	1	pcs.	840.00	#1	840.00	898.80
	MSIG WINNER VS AIG: D.O.A: 04-06-19						

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	8,050.00	36,312.20	7%	3,105.35	44,362.20	47,467.55
Total	8,050.00	36,312.20		3,105.35	44,362.20	47,467.55

Customer

Service Advisor

Please inspect your vehicle prior to leaving our premises. We seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.

---VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and www.skoda.com.sg (for additional services, products and promotions).---

LKK Auto Consultants hence notify the Repairer of the following:

- To seek your understanding that we are not able to honour claims on scratches, dents etc. after your car has left our premises.
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Subsequent appointments must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: