

CC31 MSC919010052 / Uqd3n2

(08/17/13) wef

REF:

ASS. REC. BY: Marcus

MS16

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLS 32R

at Workshop m/s

AP.

of

Insured:

SAN 12/3P

Policy No.

802506815MP

Claims No.

595781

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

60k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res: Yes or No

Lum Sum:

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

LIA 45660

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLS 32R

Yr Regn:

1/1/2

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CIA

Make:

Mer Benz C160 c.c 1595

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

110004

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2040312A78159

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

6/6/19

D.O.I.

7/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

3y18 Subh Rep 13k.

07/6/19 @ 4.47pm Email GIA, police report to mer.

24/7/19 4/5 4400 confirmed with Alex. (Red & 77007.42, 87%) 25/7/2019

RECEIVED 26 JUL 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 25/7/19 Final

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

250

11

) S + RS SI

) Photos

) Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

4000

TOTAL

261

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 25 Jul 2019

Preliminary Advice

Insured Vehicle No	: SGN1213P	Accident Date	: 06/06/2019
TP Vehicle No	: SLS32R	Assignment Date	: 10/06/2019
Make	: MERCEDES-BENZ C180	Est. Duration of Repair	: 4.00
Date of Inspection	: 07/06/2019		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,007.42
Revised Amount	:S\$	5,009.77
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,009.77
Lump Sum Repair	:S\$	4,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY ASSIST TO AMEND THE MAKE & MODEL OF SLS 32R TO MERCEDES BENZ C180 BLUEEFFICIENCY (1595cc) INSTEAD OF MERCEDES BENZ C180 1.8 IN MERIMEN SYSTEM.

Shiau Chan (LKKAUTO)

From: Eileen Ang <eileen_ang@sg.msig-asia.com>
Sent: Monday, 10 June 2019 1:25 PM
To: Shiau Chan (LKKAUTO)
Cc: Katherine Wong
Subject: FW: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 06/06/2019, SLS 32R (TP VEHICLE), SGN 1213P (OI VEHICLE)
Attachments: SLS32 PR.pdf; SLS32 GIA.pdf

Dear Shiau,

TP folder created, claim ref is 595781.

Eileen Ang
Senior Admin Officer, Claims Services
D: +65 6594 2561 | F: +65 6827 2702 | eileen_ang@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Shiau Chan (LKKAUTO) [<mailto:siewsc@lkkauto.com>]
Sent: Friday, 7 June 2019 4:47 PM
To: Motor Survey <motorsurvey@sg.msig-asia.com>
Cc: SUR <sur@lkkauto.com>; Accounts (LKKAUTO) <account@lkkauto.com>; KKLau <kklau@lkkauto.com>
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 06/06/2019, SLS 32R (TP VEHICLE), SGN 1213P (OI VEHICLE)

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLS 32R at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 07/06/2019.

Enclosed herewith a copy of TP's GIA report & Police Report Statement. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

MANAGEMENT CAR DEALS. 7 – 9 JUNE 2019.

Find out more

Performance Premium Selection Limited. 280 Kampong Arang Road, S438180.



Advanced Search

Home » Used Cars » MS Carz » Mercedes-Benz C-Class C180 CGI Avantgarde

Mercedes-Benz C-Class C180 CGI Avantgarde

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$60,800		
Depreciation	\$13,580 /yr <small>View models with similar depre:</small>	Reg Date	19-Oct-2012 (3yrs 4mths 11days COE left)
Mileage	99,000 km (14.9k /yr)	Manufactured	2012
Road Tax	\$740 /yr	Transmission	Auto
Dereg Value	\$44,337 as of today (change)	OMV	\$30,136
COE	\$73,501	ARF	\$30,136
Engine Cap	1,595 cc	Power	115.0 kW (154 bhp)
Curb Weight	1,485 kg	No. of Owners	2
Type of Vehicle	Luxury Sedan		

Features

Smooth 1.6L Inline 4 Turbocharged Engine, 7G CGI, Eco-mode, Cruise Control, Daytime Running Lights, Auto Headlights, Rain Sensors, Rear Aircon. View specs of the Mercedes-Benz C-Class Saloon (2011-2014)

Accessories

Bluetooth, Cruise Control, Daytime LED Lights, 6 CDs Changer, Auto Wipers And Headlamps, Dual Climate Control, Sports Rims, Solar Film. Non-Smoker.

Description

Pristine Condition Coupled With Luxurious Interior. One Of The Best Selling Luxury Sedan. Well Maintained With No Flaws. View To Be Impressed With Its Sleek Look. 100% Loan Or Low Down Payment Available Coupled With Competitive Interest Rates. Do Call Our Professional Sales Consultant For More Details.

Category

PARF Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Location Map

Price Chart

Summary

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

Seller Information

Company

MS Carz

• dealer's pricelist

• 16 vehs sold | 13 vehs available

Address

210 Turf Club Road Lot B31

Search cars nearby this location

Posted on: 01-Jun-2019 | Last Updated on: 01-Jun-2019

Compare

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 7 June 2019 4:47 PM
To: motorsurvey@sg.msig-asia.com
Cc: SUR; Accounts (LKKAuto); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 06/06/2019, SLS 32R (TP VEHICLE), SGN 1213P (OI VEHICLE)
Attachments: SLS32 PR.pdf; SLS32 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLS 32R at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 07/06/2019.

Enclosed herewith a copy of TP's GIA report & Police Report Statement. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	3722H

Vehicle Details

Vehicle No.:	SLS32R
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 BLUEEFFICIENCY
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	27491030020584
Chassis No.:	WDD2040312A781159
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$32,381.00
Original Registration Date:	26 Nov 2012
First Registration Date:	26 Nov 2012
Transfer Count:	2
Actual ARF Paid:	\$32,381.00 16190.5'

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Nov 2022
PARF Rebate Amount:	\$21,047.00

Intended COE Rebate Details

COE Expiry Date:	25 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$71,001.00
COE Rebate Amount:	\$24,613.00
Total Rebate Amount:	\$45,660.00

The information contained herein is correct as at 07 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/06/2019 22:05
Date Of Accident	06/06/2019 14:30
Exact Location Of Accident	SLIP ROAD TWRDS UPPER THOMSON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS32R
Insured/Policyholder	
Name Of Registered Owner	TAN BAK KOON EDMUND
NRIC No	S7823722H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88553232
Alternative Phone No	OTHERS-88553232

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C 180 BLUEEFFICIENCY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5109301247
Cover Note Number	

Driver

Name of Driver	TAN BAK KOON EDMUND
NRIC No	S7823722H
Date Of Birth	12/08/1978
Occupation	INDOOR
Date Of Driving Pass	14/06/1996
Driving Experience	22 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88553232
Fax Number	
Contact Number	OTHERS-88553232
Email Address	NOEMAIL

Address	BLK 98 #18-1902 BEDOK NORTH AVENUE 4 PEARL GARDEN
Postcode	460098
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ZHUANG JINGWEI PRICILLA
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN1213P
Vehicle Make/Model/Colour	BMW 523I 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN BAK KOON EDMUND
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLS32R
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 98 #18-1902 BEDOK NORTH AVENUE 4 PEARL GARDEN
Postcode	460098

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: 
 NRIC/FIN Number: 

Date of Accident : 6/6/19 Accident Time: 2.30pm (24-HR-Format)
Accident Place : Slip road towards upper Thomson
Vehicle. No. (Car Plate No.) : SLS 32R Make/Model: Mercedes Benz
Insurance Company : NTUC Policy No: 510
Owner or Company Name /IC No. : Tim Bak Koon Edmund /578237224
Owner or Company Contact No. : _____ Owner's Hp 88553232 Company Tel _____
DRIVER'S Name / IC No. : as above
DRIVER'S Date Of Birth : 12/8/1978 DRIVER'S License Pass Date 14/6/1996
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner
DRIVER'S Address : as above
DRIVER'S Contact No / Alt No. : 1) _____ 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : _____
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim \ Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 2 person

Was there any video Captured by car camera: YES \ NO
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): yes

Other Party Driver's Particular (if any)

Vehicle. No: <u>SGN1213F</u>	Vehicle. No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

Zhuang Jingwei Priscilla (F)


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



A - SL532R

B - SG1N1213P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time, I was travelling along slip road towards upper Thomson road. I stop and wait for on coming vehicle to be clear. Suddenly vehicle B hit on my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

[Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20190606/7020

1 of 3

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20190606/7020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/06/2019 23:16		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TAN BAK KOON, EDMUND			Address: APT BLK 98 BEDOK NORTH AVENUE 4 #18-1902 SINGAPORE 460098		
ID Type / ID No.: NRIC NO / S7823722H			Contact No.: Home/Office: Mobile: 88553232		
Nationality: SINGAPORE CITIZEN			Email: edtan66@hotmail.com		
Sex: Male	Age: 40	Date of Birth: 12/08/1978	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Unemployed			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/06/2019 14:30	Type of Location: Slip Road
Location: ANG MO KIO AVENUE 6				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGN1213P	Car	BMW	523i	Blue	Slightly Damaged	2
SLS32R	Car	MERCEDES BENZ	C 180 BLUEEFFICI ENCY	White	Slightly Damaged	2

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS32R	NTUC Income Insurance Co-Operative Limited	5109301247	09/05/2019	25/05/2020



**SINGAPORE
POLICE FORCE**



T/20190606/7020

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20190606/7020

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Passenger			
Name	ZHUANG JINGWEI PRISCILLA	ID No.	S8219476B
Related Vehicle	SLS32R (Car)	Contact No.	82826115
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	06/06/2019	Date Discharge	06/06/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	TAN BAK KOON, EDMUND	ID No.	S7823722H
Related Vehicle	SLS32R (Car)	Contact No.	88553232
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	06/06/2019	Date Discharge	06/06/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

I am travelling along Ang Mo Kio Avenue 6 in my car VRN: SLS32R with my wife who is expecting. I entered a slip road which leads to Yio Chu Kang Road (towards Upper Thomson Road). There was a road work conducted at Yio Chu Kang Road, right before and also after the slip road to Yio Chu Kang Road, leaving only one lane at Yio Chu Kang road for traffic. I stopped to give way to the traffic along Yio Chu Kang Road, and a BMW VRN: SGN1213P knocked my car from behind thereafter



**SINGAPORE
POLICE FORCE**



T/20190606/7020

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20190606/7020

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
MOHAMAD ZULFAZDLI BIN ABDULLAH
Contact No.: 65476204

Authentication Stamp

NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
06/06/2019 23:16

Classification Of Case:

FASTECT AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
N/A
7/6/19
L/S \$ 4000
Hdy.

VEHICLE NO: SLS 32R

QTY	PARTICULAR			
1 PCS	BOOTLID	12	\$2,481.10	X
1 PCS	BOOTLID REAR LOGO	rec	\$60.00	—
1 PCS	BOOTLID 'G-TRONIC' EMBLEM	rec	\$82.00	—
1 PCS	BOOTLID 'C180' EMBLEM	rec	\$85.00	—
1 PCS	BOOTLID 'C & C' EMBLEM	rec	\$45.00	—
1 PCS	BOOTLID CHROME MOULDING	11	\$361.10	X
1 PCS	BOOTLID WEATHERSTRIP 299	7w1	\$366.20	—
1 PCS	BOOTLID INNER LOCK	11	\$491.10	X
1 PCS	BOOTLID INNER TRIM	11	\$650.20	X
1 SET	BOOTLID INNER TRIM CLIPS	11	\$60.00	X
2 PCS	BOOTLID HINGES @\$185.00	11	\$370.00	X
2 PCS	TAILLAMPS @\$850.00 825.00	o/sene	\$1,700.00	1PC
2 PCS	TAILLAMP SIDE GARNISHS @\$30.00	71	\$60.00	X
1 PCS	REAR BUMPER 1315.30	DD/OE	\$1,906.10	—
1 PCS ref	REAR BUMPER CENTRE CHROME MOULDING 425.00	rec	\$488.20	—
1 PCS	REAR BUMPER TOW COVER	11	\$60.00	X
2 PCS	REAR BUMPER SIDE HOLDERS @\$250.00	11	\$500.00	X
1 SET	REAR BUMPER CLIPS	rec	\$60.00	—
1 PCS	REAR BUMPER LOWER GARNISH	11	\$620.00	X
1 PCS	REAR BUMPER REINFORCEMENT 605	o/sene	\$815.00	—
1 PCS	REAR BUMPER TOP RETAINER 184	7w1	\$216.90	—
2 PCS	REAR BUMPER LOWER BRACKETS @\$105.00	11	\$210.00	X
8 PCS ref	REAR BUMPER PDC SENSORS @\$250.00	shohd	\$1,500.00	2 (O.S. N)
1 PCS	REAR BUMPER PDC SENSOR WIRE	11	\$388.00	X
1 PCS	REAR BUMPER INNER CENTRE GUIDE	11	\$266.20	X
1 PCS	REAR END PANEL	12	\$1,506.00	X
1 PCS	REAR END PANEL TOP GARNISH	11	\$485.12	X
1 PCS	REAR FLOOR PANEL	11	\$1,140.60	X
1 PCS	REAR FLOOR PANEL TOP BOARD	11	\$820.60	X
1 PCS	REAR FLOOR PANEL FIBRE WELL	11	\$1,020.00	X
1 PCS	REAR EXHAUST	11	\$2,115.00	X
1 PCS	REAR EXHAUST HEAT SHIELD N/S	11	\$388.00	X
2 PCS	REAR FENDERS @\$1800.00	11	\$3,600.00	X
2 PCS	REAR FENDER INNER TRIMS @\$620.00	11	\$1,240.00	X
			\$26,157.42	
	S.NETT			
1 PCS	REAR LICENCE PLATE W/HOLDER	11	\$50.00	X
1 PCS	REAR END PANEL SEALANT	11	\$80.00	X
1 PCS	REAR WINDSCREEN SEALANT	11	\$80.00	X
	LABOUR CHARGES:			
	TOWING CHARGE	11	\$120.00	X
	TO CHECK WIRING		\$80.00	30
	TO DISMANTLE & REPLACING PDC SENSOR		\$100.00	50
	TO DISMANTLE & REFIX REAR EXHAUST	11	\$150.00	X
	TO DISMANTLE & REFIX PETROL TANK	11	\$100.00	X


3755.3

1070
3379.77

102

TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	\$120.00	100
TO DISMANTLE & REFIX BOOTLID MECHANISM	11 \$100.00	X
TO DISMANTLE & REFIX REAR WINDSCREEN	11 \$150.00	X
TO SPRAY RUST PROOFING	11 \$120.00	X
LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED	\$1,800.00	600
& REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	\$1,800.00	600
TOTAL	\$31,007.42	

5009.77



LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19010052/UQD3N2

Date: 30/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80250681SMP
Claimant Vehicle No :	SLS32R	Insured Vehicle No :	SGN1213P
Date of Loss:	06/06/2019	Nature of Claim:	TP
		Claim No:	595781

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS32R	Engine No:	27491030020584
Make & Model:	MERCEDES-BENZ C180 BLUE EFFICIENCY, 1.6 (A)	Chassis No:	WDD2040312A781159
Reg. Date:	26/11/2012 (Man. Year: 2012)	Odometer:	110004 km
Colour:	White		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	26,367.42	3,629.77	22,737.65	86.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	1,380.00	3,260.00	70.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	31,007.42	5,009.77	25,997.65	83.84
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	31,007.42	4,000.00	27,007.42	87.10
+ GST 7.00/7.00% (\$\$)	2,170.52	280.00	1,890.52	87.10
Nett Amount (\$\$)	33,177.94	4,280.00	28,897.94	87.10

INSPECTION

Date of Assignment:	10/06/2019	
Date Inspected:	07/06/2019	Inspected At:
		Fastech Auto Pte Ltd (HQ)
		1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jul 2019)
Parts:	143	MERCEDES-BENZ C180 BLUE EFFICIENCY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS32R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	2,481.10 F	*- FL
2	1		*BOOTLID REAR LOGO	Necessary	60.00 F	*60.00 FL
3	1		*BOOTLID G-TRONIC EMBLEM	Necessary	82.00 F	*82.00 FL
4	1		*BOOTLID C180 EMBLEM	Necessary	85.00 F	*85.00 FL
5	1		*BOOTLID C & C EMBLEM	Necessary	45.00 F	*45.00 FL
6	1		*BOOTLID CHROME MOULDING	Not Necessary	361.10 F	*- FL
7	1		*BOOTLID WEATHERSTRIP	Twisted	366.20 F	*299.00 FL
8	1		*BOOTLID INNER LOCK	Not Necessary	491.10 F	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	650.20 F	*- FL
10	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	60.00 F	*- FL
11	2		*BOOTLID HINGES	Not Necessary	370.00 F	*- FL
12	2		*TAILLAMPS	O/s Cracked	1,700.00 F	*595.00 FL
13	2		*TAILLAMP SIDE GARNISHS	Not Necessary	60.00 F	*- FL
14	1		*REAR BUMPER	Dented / Deformed	1,906.10 F	*1,315.30 FL
15	1		*SET REAR BUMPER CENTRE CHROME MOULDING	Necessary	488.20 F	*425.00 FL
16	1		*REAR BUMPER TOW COVER	Not Necessary	60.00 F	*- FL
17	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	500.00 F	*- FL
18	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
19	1		*REAR BUMPER LOWER GARNISH	Not Necessary	620.00 F	*- FL
20	1		*REAR BUMPER REINFORCEMENT	Dented / Bent	815.00 F	*605.00 FL
21	1		*REAR BUMPER TOP RETAINER	Twisted	216.90 F	*184.00 FL
22	2		*REAR BUMPER LOWER BRACKETS	Not Necessary	210.00 F	*- FL
23	1		*REAR BUMPER PDC SENSOR WIRE	Not Necessary	388.00 F	*- FL
24	1		*REAR BUMPER INNER CENTRE GUIDE	Not Necessary	266.20 F	*- FL
25	1		*REAR END PANEL	Repair	1,506.00 F	*- FL
26	1		*REAR END PANEL TOP GARNISH	Not Necessary	485.12 F	*- FL
27	1		*REAR FLOOR PANEL	Not Necessary	1,140.60 F	*- FL
28	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	820.60 F	*- FL
29	1		*REAR FLOOR PANEL FIBRE WELL	Not Necessary	1,020.00 F	*- FL
30	1		*REAR EXHAUST	Not Necessary	2,115.00 F	*- FL
31	1		*REAR EXHAUST HEAT SHIELD N/S	Not Necessary	388.00 F	*- FL
32	2		*REAR FENDERS	Not Necessary	3,600.00 F	*- FL
33	2		*REAR FENDER INNER TRIMS	Not Necessary	1,240.00 F	*- FL
34	1		*REAR BUMPER PDC SENSORS (SET)	Shorted	1,500.00 FS	*250.00 FS
35	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
36	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 26,367.42 4,005.30
 - List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 375.53

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)						26,367.42 3,629.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGE.	New	120.00	0.00
2	TO CHECK WIRING.	New	80.00	30.00
3	TO DISMANTLE & REPLACING PDC SENSOR.	New	100.00	50.00
4	TO DISMANTLE & REFIX REAR EXHAUST.	New	150.00	0.00
5	TO DISMANTLE & REFIX PETROL TANK.	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.	New	120.00	100.00
7	TO DISMANTLE & REFIX BOOTLID MECHANISM.	New	100.00	0.00
8	TO DISMANTLE & REFIX REAR WINDSCREEN.	New	150.00	0.00
9	TO SPRAY RUST PROOFING.	New	120.00	0.00
10	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED & REPLACING PARTS.	New	1,800.00	600.00
11	TO PUTTY & SPRAY PAINTING.	New	1,800.00	600.00
Gross Labour Cost (S\$)			4,640.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >