Spark Car Care
ComfortDelgro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bil :	AXA		Vehic	cle Number	S.	JE7691P
Attn to : LK	KK - KENNET	ГН	Туре	Of Claim	:	TP
A. Spare parts		\$	355.00	F. Total P	arts	\$ 425.50
B. Supplementary	,	\$	<u> </u>	G. Total I	Labour	\$ 415.00
C. Nett Price		\$	De 19 g. Delevent De 19 g. Delevent De 19 g. Delevent	H. Total R	Repair	\$ 840.50
D. Supp Nett Price	е	\$	(A. 0-1457401) (A. 0-1457401)	I. Excess		
E. S/Nett		\$	35.00	P/P Total		840.50
Total Spare Parts Price	o remi	\$	355.00			
Cost plus / List Down	10%		35.50			•
	Total		390.50	Lump Sum Les	s	\$ -
Total Nett Price		\$	•	Total Section 16		
Nett Price Less		\$		Lump Sum F	tounding	
	Total			Total Fina	lized	\$ 840.50
N.B. If we DO NOT rec	eive your reply	within	2 weeks, we shall t	reat the above finalize	d amount as co	nfirmed L correct.
Remarks : Please comfirm a	and revert by Fa	x or Ema	ail			
Date In :		Total	Repair Day			
Date Survey :		LOU	J/ Day			
Date Out :		Tota	al LOU	Sea Interna		
Sat/Sun/Ph. :		Ren	ntal/Day			
Authorized Repair Day		Tota	al Rental			
Submitted By / Date :		Conf	firmed By / Date ;	Total Hine		

Spark Car Care
ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701) Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No	: SJE7691P	Case Owner	PATRICK
Make & Model	: HONDA CROSSROAD	Year Manufacture	: 2008 /EXP. 2023
Chassis No	: RT11007731	Engine No	L13A4054292
Sales Order	:	Supplier	;
Order By	1	Type of Claim	: <u>TP</u>

S/No	Part Description	QTY		Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	FRONT BUMPER	1		To be at				
2	FRONT NUMBER PLATE W/CASING	1					\$ 35.00	
3	RADIATOR GRILLE	1	\$	190.00				
4	RADIATOR GRILLE GARNISH	1	\$	165.00				
5	0	1						
6	0	1				S.F. V. L. I	Here to your	
7	0	1						
8	0	1				11511/01/2		With the second
9	0	1						
10	0	1		V 16.				
11	0	1			Richard In			
12	0	1		964 50				
	0	1						Male
14	0	1					June Van	Statement of the last
15	0	1				The second		THE PARTY OF
	0	1						
17	0	1						
18	0	1		74271				
19	0	1	-	2 1 2 1				
20	0	1						
21	0	1						
22	0	1						
23	0	1				1		
24	0	2						
25	0	1						
26	0	1						
27	0	1					Tes tes	
28	0	1	77.5					
29	0	1				FRANCE		
30	0	1						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd 205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No.	:	SJE7691P	Case Owner	:	PATRICK
Make & Model	:	HONDA CROSSROAD 1.8L	Year of Manufacture		2008 /EXP. 2023

Adjusted Price	Esimated Price	Labour Description	S/No
FIICE	FIICE		
\$ 200.0	\$600.00	TO PANEL BEAT ON FRONT AFFECTED AREAS, REPLACE	1
		DAMAGE PARTS AND REALIGNMENT	
\$ 200.0	\$600.00	TO PUTTY, RESPRAY ON FRONT BUMPER, PANEL AND	2
		AFFECTED AREAS	
\$ 15.0	\$50.00	CHECK LIGHTING AND WIRING	3

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.