

ASS. REC. BY:

REF:

CS/CTI/90/0063/6d3/1/1

Special Instruction:

Survey: Wong Chong

ASSIGNMENT (Office)

Mentor:

From (Location): Tan Koh Leong

of

CTI

Date/Time: 6/6/19 @ 5.20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBF 3883T

Insured:

SJH 1519D

at Workshop n/s

Sin Sheng Engineering
3 Teck Park Crescent

Tel:

68639595

of

Policy No:

DMHCSN17 40651700

Claim No:

SNM19D01949C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14/04/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:17pm @ 7/6/19

Person Contacted:

SugenVehicle IN/OUT


Date/Time

Action/Instruction

IshtimulGBF 3883T-XSJH 1519D - C13/CTI/18/00219/G2462DOA: 2/5/2018

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Sin Sheng
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: GBF3883T Yr Regn: 27 Sep 2016
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Cargo
 Make: Fiat Doblo C.C. 1598
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 88550 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: 2FA 26 3 0000 6D 26217
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: 11 / SiRim / STD A/Rim or
 Tyre Size: F: 195/60 R16
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 07-06-19
 Survey held at w/s 523-0 pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Tot
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction
07/6 Finalised \$400 with Boss
11/06/19 (\$ 350/- Red - 47%)
 RECEIVED 11 JUN 2019

Date/Time, File Pass to? 11/06/19
 1) Typist
 Date/Time, File Return to? _____
 2) _____

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 2
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format :
 Lump Sum / I.B. (\$ 400/- p/c)

Survey Fee:
 Transportation: _____
 Photos _____
 Others _____
 TOTAL _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Author	Est. Submitter	Act Assigned	Act Rpt	Act Submitted	Fix Author	Status
Main	16 Apr 2018		06 Jun 2019 17:20 Assign				New Assignment Cancel Case

Plans

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GOLDBELL LEASING PTE LTD		
Main Claimant:			
Vehicle Reg. No.:	GBF3883T	Date of Loss:	14/04/2018 00:00 - :59
Claim Type:	TP / SNM18D01949C02	Policy/Cover Note No.:	DMHCSN1740651700
Vehicle Reg. No. (Insured):	SJH1519D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/06/2019]		
Adj Asg. Remarks:	NO EST, ASSIGN TAY BENG HEE AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	More
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Details	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBF3883T
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jun 2019
Vehicle Make:	FIAT
Vehicle Model:	DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	263A50007652037
Chassis No.:	ZFA26300006D26217
Maximum Power Output:	-
Open Market Value:	\$18,516.00
Original Registration Date:	27 Sep 2016
First Registration Date:	27 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$926.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,809.00
COE Rebate Amount:	\$3,509.00
Total Rebate Amount:	\$3,509.00

The information contained herein is correct as at 09 Jun 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 11 June 2019 11:54 AM
To: 'sinsheng engineeringservices'
Cc: SUR; Guo Qiang (LKKAuto)
Subject: RE: OUR REF: SNM18D01949 -SJH1519D -Accident involving GBF3883T with SJH1519D on 14/04/2018

Dear Susan,

Confirmed final fig \$ 400.00 @ 2 days of repairs before GST.

Final invoice and all supporting documents sent over to China Taiping Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: sinsheng engineeringservices [mailto:sinsheng1981@gmail.com]
Sent: Saturday, 8 June 2019 9:58 AM
To: LKK_Surveyor <sur@lkkauto.com>; Guo Qiang <GuoQiang@lkkauto.com>
Subject: Re: OUR REF: SNM18D01949 -SJH1519D -Accident involving GBF3883T with SJH1519D on 14/04/2018

Hi Mr Guo Qiang,

Please find attached.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE 638892 WITH IMMEDIATE EFFECT ****

*Thank You
Regards*

*Susan
Sin Sheng Engineering Services
No 8 Tuas Ave 18
Singapore 638892
(Level 3_Office)
(Level 5_Workshop)
Tel: 6863 9595
Fax: 6863 6477*

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2018 15:35
Date Of Accident	14/04/2018 11:15
Exact Location Of Accident	ALONG PIE (TUAS)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF3883T
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL LEASING PTE LTD
Co Reg No	199001196N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64942833
Vehicle Particulars	
Manufacturer	FIAT
Model	DOBLO CARGO MAXI-1.6 D MTJ AMT GLAZE (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	29004183
Cover Note Number	

Driver

Name of Driver	SUN CHENGFEI
Passport No/FIN	G2446391K
Date Of Birth	21/01/1988
Occupation	OUTDOOR
Date Of Driving Pass	17/02/2015
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-83635447
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON MENTIONED DATE/TIME, I WAS TRAVELLING IN THE 2ND LANE ALONG PIE TOWARDS TUAS. VEHICLE B WAS ON MY LEFT. I HAD JUST PASSED BEDOK NORTH ROAD EXIT WHEN I SAW VEHICLE B FROM THE LEFT ATTEMPTING TO ENCROACH INTO MY LANE TO OVERTAKE A SLOW MOVING VEHICLE AT THE LEFT LANE. I APPLIED MY BRAKES IMMEDIATELY BUT I DIDN'T FELT ANY IMPACT. THUS I CONTINUED WITH MY JOURNEY BUT I WAS STOPPED BY VEHICLE B SOMEWHERE AFTER PAYA LEBAR EXIT. VEHICLE B'S DRIVER THEN ALIGHTED FROM HIS VEHICLE AND ASKED IF I REALIZED THAT I HAD COLLIDED INTO HIS VEHICLE WHILE AT THE BEDOK NORTH ROAD EXIT. I ALIGHTED FROM MY VEHICLE AND WENT TO THE LEFT TO CHECK. I SAW SOME SCRATCHES AT MY VEHICLE'S LEFT. THE DRIVER OF VEHICLE B JUST LEFT AFTER INFORMING ME THAT HIS VEHICLE IS EQUIPPED WITH AN IN-CAR CAMERA. I MANAGED TO TAKE A PHOTO OF HIS CR AFTER FOLLOWING HIM AT A DISTANCE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SIN SHENG ENGINEERING SERVICES

NO 8 TUAS AVE 18
SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002860

Date : 31/05/2019
Vehicle Num. : GBF3883T
Make/Model : FIAT DOBLO 1.6MJTD-2016
Chassis/Eng# : ZFA26300006D26217/263A5000765;
Accident Date : 14/04/2018
Claim No. :
Reference : SJH1519D
Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO PANEL BEAT/REPAIR LH BODY

250.00 100

SPRAY PAINTING

500.00 200

LOSS OF USE : 3 DAYS @ \$ 120/DAY

(Exclude)

Labour Total S\$:

750.00

2 Days.

Total : \$400

Guo Qiang - 82880282

Guo Qiang @ Ikk Auto, com

07/6/19.

After repair photos.

Total S\$: 750.00

SIN SHENG ENGINEERING SERVICES

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Apr 2018		06 Jun 2019 17:20 Edit Adj Rpt	S\$400.00 Edit Estimates	S\$400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	GOLDBELL LEASING PTE LTD								
Vehicle Reg. No.:	GBF3883T	Date of Loss:	14/04/2018 00:00 - :59 [18 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D01949C02	Policy/Cover Note No.:	DMHCSN1740651700						
Vehicle Reg. No. (Insured):	SJH1519D	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park, 638129 Tuas - Tel: 68639595								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 17/06/2019]								
Adj Asp. Remarks:	NO EST, ASSIGN TAY BENG HEE AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF3883T (SNM18D01949C02)
[SJH1519D]






































TP

GOLDBELL LEASING PTE LTD

Apr 14 2018 12:00AM

[0]

Sin Sheng Engineering Services

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
3	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
4	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
5	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
6	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
7	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
8	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
9	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
10	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
11	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
12	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
13	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
14	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
15	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
16	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
17	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
18	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
19	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
20	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
21	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
22	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
23	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
24	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
25	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
26	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
27	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
28	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
29	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
30	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
31	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
32	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
33	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
34	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
35	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
36	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>
37	10/06/19 09:58	General View		Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/06/19 09:58	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
39	10/06/19 09:58	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/04/18 13:12	PRS	 Load PDF	
2	17/04/18 13:12	TP GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010063/GSD3

Date: 13/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1740651700
Claimant Vehicle No :	GBF3883T	Insured Vehicle No :	SJH1519D
Date of Loss:	14/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01949C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF3883T		
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M)	Engine No:	263A50007652037
Reg. Date:	27/09/2016 (Man. Year: 2016)	Chassis No:	ZFA26300006D26217
Colour:	White	Odometer:	88550 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	400.00	350.00	46.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	750.00	400.00	350.00	46.67
+ GST 7.00/7.00% (S\$)	52.50	28.00	24.50	46.67
Nett Amount (S\$)	802.50	428.00	374.50	46.67

INSPECTION

Date of Assignment:	06/06/2019	
Date Inspected:	07/06/2019	Inspected At: Sin Sheng Engineering Services (HQ) 3 Tech Park Crescent, Tuas Tech Park Singapore 638129
Estimated Period of Repair:	2.0 days	

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2019)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3883T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT/REPAIR LH BODY	New	250.00	100.00
2	SPRAY PAINTING	New	500.00	300.00
Gross Labour Cost (S\$)			750.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >