

ASS. REC. BY:

REF: CS / AIG / 19010066 / Bsd3m

Special Instruction:

Sender:

Mr Chen

## ASSIGNMENT (Office)

From (Person):

Hor Yinnul

of

AIG

Date/Time:

7/6/19011:28am

Estimated Cost:

Bill to:

4 OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 4483L

Insured:

GBF 5493Y

at Workshop m/s

Yee Auto

Tel:

64575768 / 6457

2625  
KQ: X.A

of

160 Sin Ming Drive # 02-17

Policy No:

Claim No:

969771625059003

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03/06/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

207pm @ 7/6/19

Person Contacted:

Mr Chen

Vehicle: IN / OUT

Date/Time

Action/Instruction

Estimate (✓)

SLP 4483L - X

GBF 5493Y - X

ASS. REC. BY:

REF


AIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: 7/6/19  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLP 4483 L  
 at Workshop m/s Yee Auto  
 of 160 Sin Ming Drive #02-17  
 Insured: \_\_\_\_\_  
 Policy No. 6457 5768  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLP 4483 L Yr Regn: 5/6/2017  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Fielden C.C. 1496  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 103859 T/Radio: Insured / Std / NI / NA

Eng/No: 2NR8532921C/No: NRE1618005028Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60/15R: 195/60/15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 4/6/19D.O.I. 7/6/19Survey held at Yee AutoDes. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/09/19 Confirmed HS @ 2,250/- @ 5 days with LTG  
(5,740.70 Red - 72%)

HS 2,250/2

Confirmed finalize case with workshop  
owner @ HS 2,250/2 with 5 days  
repair. HS 2250/2

MV 68,000/2

PV 40,786/2

NV 27,214/2

Time 0930

27/9/19 Terence Ng

T. G. Lim  
26/7/19

RECEIVED 30 SEP 2019

Days Of Repair: 5Resurvey No. of Trip: 1

Date/Time, File Pass to?

27/09/19☐ : Preli. Report☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$) 45 @ 2250/2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)Survey Fee: 260Transportation: S + RS, SI



Photos

Others

TOTAL

261

**PRE-REPAIR INSPECTION REQUEST – SLP4483L vs GBF5493Y (OI) on D.O.A.: 03/06/2019**

From: Hor, Yinrul  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tor  
Sent: 6/7/2019 11:23:44 AM  
Attachments:  PRI-YEE-SLP4483L.pdf  PRI-YEE-SLP4483L.PDF

Hi,

Please refer to the enclosed request from **K. Krishna & Partners**.

Claim no : 9697716250SG003  
Case Owner : Norsiah Bte Md Noor

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** kkrishna [mailto:kkrishna@singnet.com.sg]  
**Sent:** Friday, June 07, 2019 11:14 AM  
**To:** Hor, Yinrul  
**Cc:** Fong, Andy-SY; Chin, Lee-Ying; yeeautopteltd@gmail.com; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin  
**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF5493Y AND SLP4483L ON 03/06/2019

This message is from an external sender; be cautious with links and attachments.

Dear Sirs

Our client proposes LKK Auto Consultants Pte Ltd.

Regards

Daphne on behalf of K. Krishna & Partners

On 07-Jun-19 9:49 AM, Hor, Yinrul wrote:

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยข้อความที่เข้ารหัสลับ เพื่ออ่านมันให้เปิดไฟล์ที่แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2019-06-14 09:49 +08 to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

**From:** Yinrul.Hor@aig.com  
**To:** kkrishna@singnet.com.sg  
**Cc:** Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahxin.Tong@aig.com  
**Subject:** aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBF5493Y AND SLP4483L ON 03/06/2019  
**Date:** Fri, 7 Jun 2019 01:49:40 +0000  
[Without Prejudice](#)

Your Reference : SLP4483L  
Our Reference : 9697716250SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawfence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** kkrishna [mailto:kkrishna@singnet.com.sg]

**Sent:** Friday, June 07, 2019 9:35 AM

**To:** AIG SGP, Claims-Survey

**Subject:** [EXTERNAL] Fwd: PRE-REPAIR INSPECTION OF VEHICLE SLP 4483L - ACCIDENT ON 03.06.2019 INVOLVING SLP 4483L & GBF 5493Y AT VIVA BUSINESS PARK CARPARK

This message is from an external sender; be cautious with links and attachments.

Our Ref: SM.PRI-YEE-SLP 4483L (dap)

Dear Sirs

Please see attached letter herein and revert urgently for the PRI to be arranged as soon as possible.

Regards

Daphne on behalf of K. Krishna & Partners

----- Forwarded Message -----

**Subject:**PRE-REPAIR INSPECTION OF VEHICLE SLP 4483L - ACCIDENT ON 03.06.2019 INVOLVING SLP 4483L & GBF 5493Y AT VIVA BUSINESS PARK CARPARK

**Date:**Thu, 6 Jun 2019 12:18:59 +0800

**From:**kkrishna <kkrishna@singnet.com.sg>

**To:**Mohdfitri.hassim@aig.com, Imran.ishak@aig.com

**CC:**yeeautopteltd@gmail.com <yeeautopteltd@gmail.com>

Our Ref: SM.PRI-YEE-SLP 4483L (dap)

Dear Sirs

We attached herewith our letter dated 6 June 2019 for your attention.

Regards

Daphne on behalf of K. Krishna & Partners

# K. KRISHNA & PARTNERS

Advocates & Solicitors  
Commissioner for Oaths/Notary Public  
(UEN No. 53131210X)

GST Registration No. M90371530C

101 Cecil Street #24-03/04 Tong Eng Building, Singapore 069533  
Tel : 6323 3038 Fax : 6323 2120 (not for service of Court documents)  
E-mail : [kkrishna@singnet.com.sg](mailto:kkrishna@singnet.com.sg)

---

K. Krishnamoorthi  
LLB (Hons) (London)  
Barrister-at-Law (Gray's Inn)  
B.Sc (Hons) (Est. Man) (S'pore)

S. Manohar  
LLB (Hons) (S'pore)

---

Vengadesh s/o Kumaravelu  
LLB (Hons)

Our Ref : SM.PRI-YEE- SLP 4483L (dap)

6<sup>th</sup> June 2019

**IMMEDIATE ATTENTION**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

**PRE-REPAIR INSPECTION**

Attention: Motor Claims Department

Email : [MohdFitri.Hassim@aig.com](mailto:MohdFitri.Hassim@aig.com)  
[Imran.ishak@aig.com](mailto:Imran.ishak@aig.com)

Dear Sirs

**PRE-REPAIR INSPECTION OF VEHICLE SLP 4483L**  
**ACCIDENT ON 03.06.2019 INVOLVING SLP 4483L & GBF 5493Y AT VIVA BUSINESS**  
**PARK CARPARK**

We act for M/s Sanyuan Geomancy, the owner of motor vehicle no. **SLP 4483L** which was involved in the above captioned accident.

We are instructed that the accident was caused by the negligence of the driver of motor vehicle no. **GBF 5493Y**. Our search shows that you are the insurers of motor vehicle no. **GBF 5493Y**.

We are requested to inform you that our client's vehicle is available for pre-repair inspection at the following address :-

**M/S YEE AUTO PTE LTD**  
160 Sin Ming Drive  
#02-17 Sin Ming AutoCity  
Singapore 575722  
Tel: 64575768 Fax: 6252 8459

**K. KRISHNA & PARTNERS**  
Advocates & Solicitors

---

6<sup>th</sup> June 2019

**AIG ASIA PACIFIC INSURANCE PTE LTD**

---

Please request your assessor to contact **Mr Chan Kal Yee of M/s Yee Auto Services** at his mobile no. **96874031** within **forty-eight (48) hours** from receipt of this email to arrange for the inspection.

Yours faithfully



cc. workshop - (by email)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	318X
Vehicle Details	
Vehicle No.:	SLP4483L
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA FIELDER 1.5X CVT ABS AIRBAG 2WD
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2NR8532921
Chassis No.:	NRE1618005028
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,675.00
Original Registration Date:	05 Jun 2017
First Registration Date:	05 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,675.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jun 2027
PARF Rebate Amount:	\$4,256.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,489.00
COE Rebate Amount:	\$36,530.00
<b>Total Rebate Amount:</b>	<b>\$40,786.00</b>

The information contained herein is correct as at 26 Jul 2019

OK

Dep 8,310/yr

MV 68,000/2  
PV 40,786/2  
NV 27,214/2

Tim  
26/7/19


**Toyota Corolla Axio 1.5A X  
(New 5-yr COE)**
**\$31,800****\$6,350 /yr****28-Sep-2009****1,496 cc****110,229 km****Sedan****Available**

Downpayment \$5k, Monthly \$628 x 48, Servicing And Maintanance Done, New Coat Of Paintwork, Excellent Condition!

Posted: 26-Jul-2019

Tags: 2009 Toyota Corolla, 2009 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A (COE  
till 08/2028)**
**\$41,500****\$4,590 /yr****06-Aug-2008****1,598 cc****134,000 km****Sedan****Available**

Low Mileage Done, Well Kept Condition, Excellent Condition Interior And Exterior. View To Believe. In House/Bank Loan Available, Call Now For Viewing.

Posted: 26-Jul-2019

Tags: 2008 Toyota Corolla, 2008 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Fielder Hybrid  
1.5A G**
**\$69,800****\$8,310 /yr****29-Aug-2017****1,496 cc****27,000 km****Stationwagon****Available**

**Fuel Type:** Petrol-Electric

Interest Rate Promotion At 2.48%! Free 1 Year Engine And Gearbox Warranty! Free 1x Servicing! High Loan Approval Rate! In House Financing Available, Higher Spec G Model, 1 Owner, 100% Accident Free! Low Mileage, Big Boot Space, Super Great Fuel Efficient, Ideal...

Posted: 26-Jul-2019

Tags: 2017 Toyota Corolla, 2017 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota


**Toyota Corolla Altis 1.6A**
**\$27,800****\$12,660 /yr****24-Feb-2011****1,598 cc****138,200 km****Sedan****Available**

First Owner Car! Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To Make An Appointment To Viewing.

**PREMIUM AD**

Posted: 25-Jul-2019

Tags: 2011 Toyota Corolla, 2011 toyota corolla, Toyota Corolla, toyota corolla, Toyota, Corolla, corolla, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make:

Model:

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

« Back ( 1 2 3 4 5 ... 56 ) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota, Toyota Singapore, used Toyota Singapore, used Toyota, used vehicles Singapore or even buy used Toyota Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)



**MOTOR CAR (LH)****Left Portion**

NAC	INC	Item	CON	AC	Qty
1255	995326	Frt LH Door	DD	✓	
1256	995140	Frt LH Door Protector	NEC	✓	
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1259	995102	Frt LH Door Garnish			
1260	991593	Frt LH Door Glass Outer Moulding			
1261	991588	Frt LH Door Glass Inner Moulding			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1267	991607	Frt LH Door Inner Handle			
1268	991625	Frt LH Door Lock w/Key			
1269	991624	Frt LH Door Lock			
1270	991562	Frt LH Door Central Lock			
1271	991675	Frt LH Door Switch			
1272	991617	Frt LH Door Inner Trim Board			
1273	991568	Frt LH Door Checker			
1274	991575	Frt LH Door Felt			
1275	991688	Frt LH Door Wire Harness			
1276	991683	Frt LH Door Window Glass Pillar			
1277	991640	Frt LH Door Outer Pillar			
1278	991613	Frt LH Door Inner Pillar			
1279	991646	Frt LH Door Pillar Inner Garnish			
1280	990554	Centre Pillar LH			
1281	990542	Centre Inner Pillar LH			
1282	990517	Centre Pillar Upper Garnish LH			
1283	990564	Centre Pillar Lower Garnish LH			
1284	991670	Frt LH Door Step Garnish			
1285	994052	Rocker Panel LH			
1286	994049	Rocker Panel Inner Panel LH			
1287	994046	Rocker Panel Garnish LH			
1288	994055	Rocker Panel Outer Side Skirt LH			
1004	991300	Frt Bumper			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1029	995153	Frt LH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1096	995070	Frt LH Fender	DD	✓	
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			

Vehicle No: **SLP 4483L**

NAC	INC	Item	CON	AC	Qty
1289	995156	Rear LH Door			
1290	993282	Rear LH Door Protector			
1291	995194	Rear LH Door Hinge			
1292	993228	Rear LH Door Garnish			
1293	993278	Rear LH Door Glass Outer Moulding			
1294	993231	Rear LH Door Glass Inner Moulding			
1295	995190	Rear LH Door Glass			
1296	993238	Rear LH Door Glass Regulator			
1297	995192	Rear LH Door Glass Regulator Motor			
1298	993294	Rear LH Door Rubber			
1299	993275	Rear LH Door Outer Handle			
1300	993250	Rear LH Door Inner Handle			
1301	993261	Rear LH Door Lock			
1302	993256	Rear LH Door Inner Trim Board			
1303	993218	Rear LH Door Checker			
1304	993230	Rear LH Door Glass Channel			
1305	993242	Rear LH Door Glass Triangle Garnish			
1306	993285	Rear LH Door 1/4 Glass			
1307	993288	Rear LH Door 1/4 Glass Rubber			
1308	993287	Rear LH Door 1/4 Glass Pillar			
1309	993305	Rear LH Door Step Garnish			
1310	993309	Rear LH Door Switch			
1311	994070	Roof Top Panel			
1312	994098	Roof Top Moulding			
1313	994085	Roof Top Air-bag			
1314	994084	Roof Top Air-bag Sensor			
1315	994083	Roof Top Air-bag Control Unit			
1141	992958	Rear Bumper			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1151	993077	Rear Bumper Sponge			
1153	993040	Rear Bumper Protector			
1155	993026	Rear Bumper Moulding			
1157	993023	Rear Bumper Lower Spoiler			
1163	993851	Rear LH Taillamp			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1136	990247	Sticker - Door	NEC	✓	
		Frt LH Fender inner shield	ECT	✓	
		Fender inner shield clips	NEC	✓	
		Frt LH Fender rim	R	X	

No of Items: 6Assessor: TTCM

*Signature*  
26/7/19

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/06/2019 18:03
Date Of Accident	03/06/2019 15:40
Exact Location Of Accident	VIVA BUSINESS PARK CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP4483L
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SANYUAN GEOMANCY
Co Reg No	<del>NA</del> 53002318X
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90261550

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA FIELDER
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V04559/VPL/R00
Cover Note Number	

### Driver

Name of Driver	LIM KAI MENG
NRIC No	S1657760Z
Date Of Birth	13/08/1964
Occupation	OUTDOOR
Date Of Driving Pass	24/10/2000
Driving Experience	18 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90261550
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 408 WOODLANDS STREET 41 #02-13
Postcode	730408
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	AFTER-RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NA GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	THOMSON NPP 25 SIN MING ROAD
Police Station Address	ROAD: 25 SIN MING ROAD #01-180 , POSTCODE: 570025 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF5493Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	OTHMAN BIN SALIM
NRIC/Passport Number	S7039479J
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	LIM KAI MENG
Approximate Age	54
Injuries Sustain	REFER TO REPORT
Injured person in which vehicle?	SLP4483L
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

**SKETCH PLAN**

**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

San Yuan Geomancy

Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2 Pg. 1

### SKETCH PLAN

A: SLP 4483L

B: GBF54934



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report NO: T/2490604/2110

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

## San Yuan Geomancy

Policyholder's Signature  
Date & Time:

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20190604/2110

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

1 of 3

Report No. T/20190604/2110

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 04/06/2019 13:54		Vide Report No.:	Station Diary No.: 9
<b>Informant's Particulars</b>			
Name of Informant: LIM KAI MENG		Address: APT BLK 408 WOODLANDS STREET 41 #02-13 SINGAPORE 730408	
ID Type / ID No.: NRIC NO / S1657760Z		Contact No.: Home/Office: Mobile: 90261550	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 54	Date of Birth: 13/08/1964	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 03/06/2019 15:40	Type of Location: Viva Business Park
Location: Along Road 1 CHAI CHEE ROAD				
In Viva Business Park, before exit to Chai Chee Road				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Rear to Side				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
GBF5493Y	Van					0
SLP4483L	Car				Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20190604/2110

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

2 of 3

Report No. T/20190604/2110

## CONTINUATION OF REPORT

<b>Driver 1</b>			
Name	OTHMAN BIN SALIM		ID No. S7039479J
Related Vehicle	GBF5493Y (Van)		Contact No. NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver 2</b>			
Name	LIM KAI MENG		ID No. S1657760Z
Related Vehicle	SLP4483L (Car)		Contact No. 90261550
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	03/06/2019	Date Discharge	03/06/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On 03/06/2019 at about 1540hrs, I was traveling along Viva Business Park out to Chai Chee Road. While I was queueing to exit the Viva Business Park to Chai Chee Road, suddenly one Van from front left side reversed toward my left side when my vehicle was stationary. However, there were vehicle behind me, as such I could not reverse to avoid the collision. After the collision, I took some photos and exchanged the particular with the van driver. I then feel pain on my back and neck. As such, I sought medical treatment at Mount Alvernia Hospital and was given 5 days MC.





**SINGAPORE  
POLICE FORCE**



T/20190604/2110

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999

3 of 3

Report No. T/20190604/2110

## CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 ZHU JIANBIN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

04/06/2019 13:54

Officer In Charge Of Case:

TP / AEIT /

SSI 2 JUREMAH BINTE AHMAD

Contact No.: 65472076

Classification Of Case:

Authentication Stamp

NP168

<p><b>SINGAPORE POLICE FORCE</b></p>	<b>SN 070</b>
<p><b>SIGNATURE</b></p>	



# YEE AUTO PTE LTD.

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 03/06/2019

TP Veh Reg No: GBF5493Y

Estimate No: ES1900015

Date: 07 Jun 2019

Policy No:

Veh Reg No: SLP4483L

Make/Model: TOYOTA COROLLA  
FIELDER 1.5X CVT ABS  
AIRBAG 2WD

Chassis No: NRE1618005028

Engine No: 2NR8532921

Reg. Date: 05/06/2017

## Estimate Repair Cost to Vehicle No :SLP4483L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>Net Price</b>				
1 FRONT TYRE - LH	250.00	1 PC	180 250.00	NNX
2 FRONT WHEEL RIM - LH	850.00	SN 1 PC	200.00 850.00	Cut (local repair)
		@10%	200.00 1,100.00	1,100.00
			20.00	
			180.00	
3 FRONT DOOR - LH	1,269.50	1 PC	1,148.00 1,269.50	DD ✓
4 FRONT DOOR OUTER MOULDING - LH	195.50	1 PC	✓ 195.50	NECV ✓
5 FRONT DOOR STICKER - LH	85.10	1 PC	✓ 85.10	DD ✓
6 FRONT FENDER - LH	425.10	1 PC	✓ 425.10	DD ✓
7 FRONT FENDER INNER SHIELD - LH	225.10	1 PC	185.00 225.10	CUT ✓
8 FRONT FENDER INNER SHIELD CLIPS	50.00	1 SET	30.00 50.00	NECV ✓
9 FRONT KNUCKLE ARM - LH	468.20	1 PC	468.20	
10 FRONT LOWER ARM - LH	382.00	1 PC	382.00	NNX
11 FRONT SHOCK ABSORBER - LH	422.10	1 PC	422.10	
12 FRONT WHEEL BEARING - LH	218.10	1 PC	218.10	
			2068.70 3,740.70	3,740.70
		@25%	517.18	
			1551.53	
13 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,200.00	1 JOB	1,200.00	500.00
14 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,400.00	1 JOB	1,400.00	500.00
15 TO REMOVE/REPLACE UNDERCARRIAGE LABOUR.	280.00	1 JOB	280.00	NNX
16 WHEEL ALIGNMENT	150.00	1 T	60.00 150.00	
17 TO CHECK WIRING FUNCTIONS.	120.00	1 JOB	50.00 120.00	
			3,150.00	3,150.00
			1110.00	



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16  
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 03/06/2019  
TP Veh Reg No: GBF5493Y

Estimate No: ES1900015  
Date: 07 Jun 2019  
Policy No:  
Veh Reg No: SLP4483L  
Make/Model: TOYOTA COROLLA  
FIELDER 1.5X CVT ABS  
AIRBAG 2WD  
Chassis No: NRE1618005028  
Engine No: 2NR8532921  
Reg. Date: 05/06/2017

## Estimate Repair Cost to Vehicle No :SLP4483L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 7,990.70
			Add GST @ 7%	559.35
			Total Amount Payable	<u>S\$ 8,550.05</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FIVE HUNDRED FIFTY AND CENTS FIVE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

Yee Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TC Lim Lin #

? photo

teowguan@1k1c auto.com

Lump sum

Repair days 5

7/6/19 1700hrs

Parts 1551.53

SN 180.00

Labour 1110.00

2841.53

@20% 568.31

2273.22

L/S 2250/2

TC Lim  
Lin - 18/9/19

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

**CLAIM SUBFOLDER TRACKING**























Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2019 <a href="#">Edit Reg</a>		07 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$2,250.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,250.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	GOLDBELL CAR RENTAL PTE LTD, Co. Reg. No.: 200710651D		
Main Claimant:	SANYUAN GEORMANCY, Co. Reg. No.: 53002318X		
Vehicle Reg. No.:	SLP4483L	Date of Loss:	03/06/2019 00:00 - :59 [23 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 9697716250SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	GBF5493Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Yee Auto Services (HQ) BLK 15 #01-107, SIN MING INDUSTRIAL ESTATE, 575673 Sin Ming - Tel: 64575768		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 18/06/2019]		
Claimant's Solicitor:	K. Krishna & Partners - Tel: 63233038		
<b>ASSOCIATED MAIL RECEIVED</b>			
		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
<ul style="list-style-type: none"> <li>AIG_SG (10/06/2019): Request To Upload TP GIA Report</li> </ul>			
<b>ALL ASSOCIATED TASKS</b>			
		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

## Claim Documents

\*SLP4483L (9697716250SG)  
[GBF5493Y]  
TP  
SANYUAN GEORMANCY  
Jun 3 2019 12:00AM  
[GOLDBELL CAR RENTAL PTE LTD]  
Yee Auto Services

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
2	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
3	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
4	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
5	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
6	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
7	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
8	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
9	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
10	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
11	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
12	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
13	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
14	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
15	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
16	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
17	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
18	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
19	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
20	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
21	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
22	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
23	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
24	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
25	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
26	27/09/19 13:09	General View		Load JPG	<input checked="" type="checkbox"/>	
Documentation					1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	27/09/19 13:25	SLP 4483L GIA.pdf		Load PDF		
2	27/09/19 13:25	POLICE REPORT.pdf		Load PDF		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print	
1	10/06/19 09:58	OI GIA REPORT		Load PDF		

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG19010066/BSD3E2

Date: 11/10/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

#### Claimant

Vehicle No : SLP4483L

Insured Vehicle No : GBF5493Y

Date of Loss: 03/06/2019

Nature of Claim: TP

Claim No: 9697716250SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP4483L

Make &amp; Model: TOYOTA COROLLA FIELDER, 1.5 X (A)

Engine No: 2NR8532921

Reg. Date: 05/06/2017 (Man. Year: 2015)

Chassis No: NRE1618005028

Colour: Black

Odometer: 103859 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size:

195/60 R15

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,840.70	1,731.52	3,109.18	64.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,110.00	2,040.00	64.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,990.70</b>	<b>2,841.52</b>	<b>5,149.18</b>	<b>64.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,250.00</b>		
<b>(S\$)</b>	7,990.70	2,250.00	5,740.70	71.84
<b>+ GST 7.00/7.00% (S\$)</b>	559.35	157.50	401.85	71.84
<b>Nett Amount (S\$)</b>	<b>8,550.05</b>	<b>2,407.50</b>	<b>6,142.55</b>	<b>71.84</b>

### INSPECTION

Date of Assignment: 07/06/2019

Date Inspected: 07/06/2019 Inspected At:

160 Sin Ming Drive #02-17

Repairer : Yee Auto Services (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: Lim Teow Guan

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - LH	Dented	1,269.50 F	*1,148.00 FL
2	1		*FRONT DOOR OUTER MOULDING - LH	Necessary	195.50 F	*195.50 FL
3	1		*FRONT DOOR STICKER - LH	Necessary	85.10 F	*85.10 FL
4	1		*FRONT FENDER - LH	Dented	425.10 F	*425.10 FL
5	1		*FRONT FENDER INNER SHIELD - LH	Cut	225.10 F	*185.00 FL
6	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 F	*30.00 FL
7	1		*FRONT KNUCKLE ARM - LH	Not Necessary	468.20 F	*- FL
8	1		*FRONT LOWER ARM - LH	Not Necessary	382.00 F	*- FL
9	1		*FRONT SHOCK ABSORBER - LH	Not Necessary	422.10 F	*- FL
10	1		*FRONT WHEEL BEARING - LH	Not Necessary	218.10 F	*- FL
11	1		*FRONT TYRE - LH	Not Necessary	250.00 FS	*- FS
12	1		*FRONT WHEEL RIM - LH (LOCAL REPAIR)	Cut	850.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,840.70</b>	<b>2,248.70</b>
<b>- List Item Discount on L Items 0.00/25.00% (\$\$)</b>	<b>0.00</b>	<b>517.18</b>
<b>Total Parts (\$\$)</b>	<b>4,840.70</b>	<b>1,731.52</b>

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	1,200.00	500.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,400.00	500.00
3	TO REMOVE / REPLACE UNDERCARRIAGE LABOUR	New	280.00	0.00
4	WHEEL ALIGNMENT	New	150.00	60.00
5	TO CHECK WIRING FUNCTIONS	New	120.00	50.00
Gross Labour Cost (S\$)			<b>3,150.00</b>	<b>1,110.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >