

228032002

ASS. REC. DMV

REF: CS3/116/1900069/ACD3SM

Special Instruction:

Assigner: Adrian
From (Person): Man Ken

ASSIGNMENT (Office)

of MG

Date/Time: 7/6/19

Estimated Cost:

OP/PP/TP/RES/OD/RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKL 2317E

Insured:

SJP 7228 L

at Workshop m/s

JD Motorsports

Tel:

9237 3644

of

25 Kaki Bukit Rd 4 #06-38 synergy

Policy No:

1900019949

Claim No:

183005230286

Sum Insured:

Excess:

D.O.A. 2/6/2019

Make of Veh:
(Client's Record)

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

1201pm 7/6/19

Person Contacted:

Ronnie

Vehicle IN/OUT

Date/Time	Action/Instruction Estimated (X)
	<u>SKL 2317E - X</u>
	<u>SJP 7228 L - X</u>
	<u>Dismantle: 7/6/2019</u>
	<u>After repair: 11/6/2019</u>

ASSIGNED BY:

REF:

ASSIGNMENT

06/10/09

Adrian

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKL2317E Yr Regn: 2009 , OctType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Rush c.c. 1495Colour: Red A/C: Insured / Std / Nil / NASp. Reading: 174580 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: J200E0029554Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/65R16R: 215/65R16BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u> mm		R/Bal. <u>06</u> mm	
L/Bal. <u>06</u> mm		L/Bal. <u>06</u> mm	
D.O.A. _____		D.O.I. <u>07/06/19</u>	

Survey held at JP MotorsportDes. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP NIG. PRS.

MV: 14K. (Before Renewal)

PV: 10.2K

Nett: 3.8K

Date/Time, File Pass to?

1) DNR

3)

5)

Prel. Report:

Final Report:

Date/Time, File Return to?

2)

4)

6)

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	07 Jun 2019 Edit Reg		07 Jun 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
[Created by adjuster]									
CLAIM SUBFOLDER DETAILS									
Insured:	ANBALAGAN S/O JAYARAMAN, ID: S72290561								
Main Claimant:	TENG KIN ENG, ID: S0011087F								
Vehicle Reg. No.:	SKL2317E	Date of Loss:	02/06/2019 07:00 - :59						
Claim Type:	TP / 1820252302SG	Policy/Cover Note No.:	1900019949						
Vehicle Reg. No. (Insured):	SJP7228L	Policy No. (Claimant):							
		Excess:							
Repairer:	Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/06/2019]								
Claimant's Solicitor:	HIN TAT AUGUSTINE & PARTNERS - Tel: 65330212								
				View All Compose Case Mail					
ASSOCIATED MAIL RECEIVED									
<ul style="list-style-type: none"> AIG_SG (10/06/2019): Request To Upload TP GIA Report AIG_SG (10/06/2019): No OI GIA Report 									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 6/7/2019 11:21:44 AM

Hi LKK,

Kindly assist to survey after 2pm today.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Anil Kumar [mailto:anil@htapartners.com.sg]

Sent: Tuesday, June 04, 2019 9:11 AM

To: Hor, Yinrul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; Ronnie Tay (wei_845@outlook.com); jd.motorsports@outlook.com

Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJP7228L AND SKL2317E ON 02/06/2019

This message is from an external sender; be cautious with links and attachments.

Without Prejudice

Save As To Cost

Dear Sir,

We refer to your email dated even date .

Our client regret to reject your list of surveyors and append below our client's list of surveyors for your consideration.

- | | |
|-------------|---------------------|
| 1. Mr Bok | - Prudent Adjusters |
| 2. Kelvin | - KAAS |
| 3. Terrence | - KAAS |

If your end is not agreeable with the above list of surveyors , kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : JD Motorsports Pte Ltd
25 Kaki Bukit Road 4
#06-38 Synergy@KB

Singapore 417800
Contact Person : Mr Ronnie : 9237 3644

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference

Best regards,
Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212
Direct Fax: 63383536
Fax : 63383536

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

MSME19072193 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 03/06/2019 15:26
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 03/06/2019 15:26
Date Of Accident 02/06/2019 07:15
Exact Location Of Accident ALONG WOODLANDS CHECKPOINT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKL2317E
Insured/Policyholder
Name Of Registered Owner TENG KIN ENG
NRIC No S0011087F
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97891518
Alternative Phone No OFFICE-97891518

Vehicle Particulars

Manufacturer TOYOTA
Model RUSH

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company LIBERTY INSURANCE PTE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number SI19V03017/VPE/R01
Cover Note Number

Driver

Name of Driver TENG KIN ENG
NRIC No S0011087F
Date Of Birth 31/03/1954
Occupation OUTDOOR
Date Of Driving Pass 27/06/1978
Driving Experience 40 YEARS AND 11 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97891518
Fax Number
Contact Number OFFICE-97891518
Email Address NOEMAIL

Address BLK 48 BENDEMEER ROAD #11-1487
 Postcode 330048
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG WOODLANDS CHECKPOINT. SUDDENLY, I FELT A HUGE IMPACT FROM THE REAR. I ALIGHTED FROM MY VEHICLE AND REALISED VEHICLE B HAD HIT ONTO THE REAR OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJP7228L
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver RANF MIKHAEL ARISH J
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

JD MOTORSPORTS

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along woodlands checkpoint, suddenly I felt a huge impact from the rear, I alighted from my vehicle and realise veh B had hit onto the rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	1087F

Vehicle Details

Vehicle No.:	SKL2317E
Vehicle to be Exported:	Yes
Intended Deregistration Date:	07 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	RUSH 1.5X A
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	3SZ2400349
Chassis No.:	J200E0029554
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$19,325.00
Original Registration Date:	06 Oct 2009
First Registration Date:	06 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$19,325.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Oct 2019
PARF Rebate Amount:	\$9,662.00

Intended COE Rebate Details

COE Expiry Date:	05 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,589.00
COE Rebate Amount:	\$510.00
Total Rebate Amount:	\$10,172.00

The information contained herein is correct as at 07 Jun 2019

OK

SKL2317E (JD Motorsports)

(1)Best (2)Denied (3)Distorted (4)Cracked (5)Cut (6)Scratched
(7)Deformed (8)Shifted (9)Buckled (10)Broken (11)Necessary
(12)Missing (13)Torn (14)Unconfirmed (15)Not Working

MOTORCAR (Rear)

(1)Repairs (✓) (2)Repaired (3)Check (✓)
(4)Not Consistent (N/C)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DC	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	N/C	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	N/C	✓	02
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	PD	Repair	
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CC	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	PD	✓	
1182	991328	Tailgate Emblem	N/C	✓	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	N/C	✓	
1196	994607	Tailgate Glass Sealant	N/C	✓	
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

06 Days. Vehicle No:

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre Outer Cover	CC	✓	
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover Inner Cover	DC	✓	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	PD	Repair	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items:

Assessor:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2019 Edit Reg		07 Jun 2019 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS				[Created by adjuster]	
Insured:	ANBALAGAN S/O JAYARAMAN, ID: S72290561				
Main Claimant:	TENG KIN ENG, ID: S0011087F				
Vehicle Reg. No.:	SKL2317E	Date of Loss:	02/06/2019 07:00 - :59 [115 Months and 27 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 1820252302SG	Policy/Cover Note No.:	1900019949		
Vehicle Reg. No. (Insured):	SJP7228L	Policy No. (Claimant):			
		Excess:			
Repairer:	Jd Motorsports Pte Ltd (HQ) 25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB, 417800 Kaki Bukit - Tel:				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 18/06/2019]				
Claimant's Solicitor:	HIN TAT AUGUSTINE & PARTNERS - Tel: 65330212				

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (10/06/2019): Request To Upload TP GIA Report
- AIG_SG (10/06/2019): No OI GIA Report

ALL ASSOCIATED TASKS



























[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKL2317E (1820252302SG)
[SJP7228L]
TP
TENG KIN ENG
Jun 2 2019 7:00AM
[ANBALAGAN S/O JAYARAMAN]
Jd Motorsports Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser ▼	
Photos/Images											3 per page ▼		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
2	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
3	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
4	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
5	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
6	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
7	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
8	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
9	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
10	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
11	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
12	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
13	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
14	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
15	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
16	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
17	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
18	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
19	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
20	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
21	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
22	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
23	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
24	17/06/19 13:06	General View										Load JPG	<input checked="" type="checkbox"/>	
25	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
26	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
27	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
28	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
29	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
30	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
31	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
32	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
33	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
34	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
35	17/06/19 13:06	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/06/19 13:06	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/06/19 13:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	17/06/19 13:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	17/06/19 13:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	17/06/19 13:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	17/06/19 13:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	17/06/19 13:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	17/06/19 13:06	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010069/ACD3S2
Date: 18/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900019949
Claimant Vehicle No: SKL2317E Insured Vehicle No: SJP7228L
Date of Loss: 02/06/2019 Nature of Claim: TP Claim No: 1820252302SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKL2317E Engine No: 3SZ2400349
Make & Model: TOYOTA RUSH, 1.5 (A) Chassis No: J200E0029554
Reg. Date: 06/10/2009 (Man. Year: 2009) Odometer: 124580 km
Colour: Red
Engine Capacity: 1495 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65R16 Rear Tyre Size: 215/65R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/06/2019
Date Inspected: 07/06/2019 Inspected At: Jd Motorsports Pte Ltd (HQ)
25 KAKI BUKIT ROAD 4, #06-38 SYNERGY@KB
Singapore 417800
Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
6	1		*TAILGATE	Dented	0.00 F	*- F
7	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
8	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
10	1		*SPARE TYRE OUTER COVER	Cracked	0.00 F	*- F
11	1		*SPARE TYRE INNER COVER	Deformed	0.00 F	*- F
12	1		*REAR LH FENDER	Repair	0.00 F	*- F
				Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >