

2007002

ASS. REC. BY:

REF (S3) / MSG 1901017 / Ucd3er

Special Instruction:

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Katherine Wongof MSL4Date/Time: 7.6.19 17:02 p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 1531E

Insured:

SJR 7433Aat Workshop m/s Ace Autolubon

Tel:

9657 2134of B Kaki Bukit Road 4 #03-29/30Policy No: 20466274

Claim No:

595703

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.6.2019 9.38 a.m

Person Contacted:

AnnaVehicle IN/OUT

Date/Time	Action/Instruction Estimate (✓)
	SLA 1531E -X
	SJR 7433A -X
	Diamond: 11/6/2019
	After repair: 12/6/2019

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MS10/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLA1531E

at Workshop m/s

Aze

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

27A35717

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLA1531E

Yr Regn:

216

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

97

Make:

Toyota Corolla 1496

Colour

Beige

A/C: Insured / Std / NI / NA

Sp. Reading

254743

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR E161 0005146

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

3/6/19

D.O.I.

10/6/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

AP.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRS no sealant.

2500 - 3800

RECEIVED 19 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

PRS

Lump. Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

120

11

131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2019		07 Jun 2019 17:02 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	SYED MAHDHAR BIN MOHAMED ALMUSYAYYAKH, ID: S8223884J	
Main Claimant:	SAM CAR RENTAL & TRANSPORT SERVICES, Co. Reg. No.: 53326995D	
Vehicle Reg. No.:	SLA1531E	Date of Loss: 03/06/2019 14:00 - :59 [39 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 595703	80466274 (Comprehensive) Coverage: 14/01/2019 - 13/01/2020
Vehicle Reg. No. (Insured):	SJR7433A	Policy No. (Claimant): Excess:
Repairer:	Ace Autolution Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/06/2019]	
Driver/Custodian (Insured):	SYED MAHDHAR BIN MOHAMED ALMUSYAYYAKH (36 / Male) , NRIC: S8223884J Email:	
Adj Asg. Remarks:	on WP. Liab: 100%. TP lawyer agree on SJE - requested for Adrian Ling from LKK Auto. Contact: Ms Anna @ 6844 1184 / 9657 2134	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS									
		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6995D
Vehicle Details	
Vehicle No.:	SLA1531E
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X CVT ABS D/AIRBAG 2WD
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	2NR8480545
Chassis No.:	NRE1610005146
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,196.00
Original Registration Date:	23 Feb 2016
First Registration Date:	23 Feb 2016
Transfer Count:	1
Actual ARF Paid:	\$9,196.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Feb 2026
PARF Rebate Amount:	\$6,897.00
Intended COE Rebate Details	
COE Expiry Date:	22 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$43,000.00
COE Rebate Amount:	\$28,820.00
Total Rebate Amount:	\$35,717.00

The information contained herein is correct as at 10 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	04/06/2019 16:24
Date Of Accident	03/06/2019 14:25
Exact Location Of Accident	ALONG TAMPINES ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLA1531E
Insured/Policyholder	
Name Of Registered Owner	SAM CAR RENTAL & TRANSPORT SERVICES
Co Reg No	53326995D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91994461
Alternative Phone No	OFFICE-91994461
Vehicle Particulars	
Manufacturer	TOYOTA
Model	AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
Driver	
Name of Driver	LEOW LIM ENG
NRIC No	S7240279J
Date Of Birth	27/01/1972
Occupation	OUTDOOR
Date Of Driving Pass	03/03/2014
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91994461
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	APT BLK 334B ANCHORVALE CRESCENT #10-128 SINGAPORE
Postcode	542334
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : PAX A GENDER: : MALE
Passenger 2	NAME: : PAX B GENDER: : MALE
Passenger 3	NAME: : PAX C GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH SKETCH PLAN & STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR7433A
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LEOW LIM ENG

Approximate Age 46

Injuries Sustain NECK

Injured person in which vehicle? SLA1531E

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address APT BLK 334B ANCHORVALE CRESCENT #10-128 SINGAPORE

Postcode 542334

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

M CAR RENTAL & TRANSPORT SERVICES

Reg No. 53326996D

SAM CAR RENTAL & TRANSPORT SERVICES

Date & Time Reg No. 53326935D

(if driver is not the policyholder)
Date & Time


Reporting Centre Personnel's Signature

Name

NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date / time, I was travelling along the stated venue as I was about to turn into the mosque, I stopped behind Veh B as it was waiting in front of me as well from the mosque, there was a vehicle turning out and Veh B reversed to give way while reversing, Veh B hit onto my vehicle and it was captured on my on board camera.

DECLARATION

I/We declare the foregoing particulars are true to my best knowledge.

A CAR RENTAL & TRANSPORT SERVICES
Reg No. 83326995D

Policyholder's Signature

SAM CAR RENTAL & TRANSPORT SERVICES
Reg No. 83326995D

Driver's Signature

(If driver is not the policyholder)
Date: 8/1/2018

Reporting Centre Personnel's Signature

Name:

NRC/PIA No:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2019		07 Jun 2019 17:02 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SYED MAHDHAR BIN MOHAMED ALMUSYAYYAKH , ID: S8223884J									
Main Claimant: SAM CAR RENTAL & TRANSPORT SERVICES , Co. Reg. No.: 53326995D									
Vehicle Reg. No.: SLA1531E		Date of Loss: 03/06/2019 14:00 - :59 [39 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 595703		Policy/Cover Note No.: 80466274 (Comprehensive) Coverage: 14/01/2019 - 13/01/2020							
Vehicle Reg. No. (Insured): SJR7433A		Policy No. (Claimant):							
		Excess:							
Repairer: Ace Autolotion Pte Ltd (KAKI BUKIT) 13 Kaki Bukit Road 4, #03-29/30 Bartley Biz Centre, 417807 Kaki Bukit - Tel: 68441184									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 08/06/2019]									
Driver/Custodian (Insured): SYED MAHDHAR BIN MOHAMED ALMUSYAYYAKH (36 / Male), NRIC: S8223884J Email:									
Adj Asg. Remarks: on WP. Liab: 100%. TP lawyer agree on SJE - requested for Adrian Ling from LKK Auto. Contact: Ms Anna @ 6844 1184 / 9657 2134									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA1531E (595703)

[SJR7433A]






































TP

SAM CAR RENTAL & TRANSPORT SERVICES

Jun 3 2019 2:00PM

[SYED MAHDHAR BIN MOHAMED ALMUSYAYYAKH]

Ace Autolution Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/06/19 18:55	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 18:55	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
4	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
5	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
6	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
7	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
8	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
9	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
10	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
11	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
12	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
13	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
14	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
15	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
25	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
26	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
27	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
29	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/06/19 18:56	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/06/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	11/06/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	11/06/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	11/06/19 17:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	11/06/19 17:08	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
71	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
72	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
75	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
76	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
77	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	12/06/19 20:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	06/06/19 18:08	OI Accident Report	Load PDF	
2	06/06/19 18:08	TP SLA1531E E-REPORT	Load PDF	
3	07/06/19 12:37	TP agree on SJE - Workshop details	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19010117/UCD3E2

Date: 20/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80466274

Claimant Vehicle No : SLA1531E

Insured Vehicle No : SJR7433A

Date of Loss: 03/06/2019

Nature of Claim: TP Claim No: 595703

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA1531E

Make & Model: TOYOTA AXIO, 1.5 (A)

Engine No: 2NR8480545

Reg. Date: 23/02/2016 (Man. Year: 2015)

Chassis No: NRE1610005146

Colour: Beige

Odometer: 254743 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15

Rear Tyre Size: 195/60 R15

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 07/06/2019

Date Inspected: 10/06/2019 Inspected At:

Ace Autolution Pte Ltd (KAKI BUKIT)
13 Kaki Bukit Road 4, #03-29/30 Bartley
Biz Centre
Singapore 417807

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,500.00 -\$3,800.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
Parts:	143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA1531E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >