

ASS. REC. BY:

REF: (S/MSG) 9010121 / Vqd302

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Irene Tan Get Ing

of MSG

Date/Time: 10.6.19 9.57a.m.

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PBN 672M

Insured: Ym 1727

at Workshop m/s Ban Hock Hin

Tel: 62816520

of M6 Defu Lan 4

Policy No: 28701187 MKC

Claim No: 595759

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29.5.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.6.19 10.38a.m.

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction
	Estimate (✓)
	PBN 672M - X
	Ym 1727 - X
17/6/19	revised preli advice via men'men

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBV 672M

at Workshop m/s 3/1/11

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 1951 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

LA6888

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBV 672M

Yr Regn: 7.18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Yamaha

NMAF c.c 155

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 9401

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH356431000006028

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110-70-13

R: 130-70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. mm

L/Bal. mm

D.O.A. 29/5/19

D.O.I. 10/6/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/7/19 Confirmed final by 905.40 with Raymond. (Ref 336.60, 29/6)

RECEIVED 31 JUL 2019

30/7/2019

Date/Time, File Pass to?

1) 31/7/2019

Date/Time, File Return to?

2) _____



Preli. Report



Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$

Survey Fee: 150

Transportation: _____



Interview (\$

Photos



Tech. Invs (\$

Others



Weekend (\$

TOTAL

Report Format: MER-TP

Lump Sum / I.B.I. (\$

905.40

161

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019		10 Jun 2019 09:57 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JFE CONSOLIDATORS PTE LTD , Co. Reg. No.: 199403480G		
Main Claimant:	SINGAPORE POST LIMITED , Co. Reg. No.: 199201623M		
Vehicle Reg. No.:	FBN672M	Date of Loss:	29/05/2019 00:00 - :59 [10 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 595759	Policy/Cover Note No.:	28701187MKC (TP, Fire & Theft) Coverage: 27/04/2019 - 26/04/2020
Vehicle Reg. No. (Insured):	YM172Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/06/2019]		
Adj Asg. Remarks:	(Manual assign) on WP, Liability:Dispute,NR case. SJE case		

ASSOCIATED MAIL RECEIVED

[View All](#)

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 10 June 2019 9:25 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: PRI REQUEST.pdf

Importance: High

PRI OF FBN672M (YOUR REF: YM172Y) (MSIG)

Manual Assigned

Dear LKK

Refer to the attachment, please survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 12 Jun 2019

Preliminary Advice

Insured Vehicle No	: YM172Y	Accident Date	: 29/05/2019
TP Vehicle No	: FBN672M	Assignment Date	: 10/06/2019
Make	: YAMAHA NMAX155	Est. Duration of Repair	: 3.00
Date of Inspection	: 10/06/2019		
Inspection At	: BAN HOCK HIN CO. PTE LTD (HQ) NO. 6 DEFU LANE 4 SINGAPORE 539410		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and o/s body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,267.00
Revised Amount	:S\$	743.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	743.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	29/05/2019 15:18
Date Of Accident	29/05/2019 13:10
Exact Location Of Accident	OUTSIDE UNIT #03-01 OF 70 ALPS AVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FBN672M
Insured/Policyholder	
Name Of Registered Owner	SINGAPORE POST LIMITED
Co Reg No	199201623M
Email Address	NOEMAIL
Mobile Phone No	(FOREIGN) +601-7411653
Alternative Phone No	OFFICE-68412000
Vehicle Particulars	
Manufacturer	YAMAHA
Model	NMAX155-155CC
Exact Purpose for which vehicle was being used at time of accident	MAIL DELIVERY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	GREAT EASTERN GENERAL INSURANCE LIMITED
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	V0107670
Cover Note Number	
Driver	
Name of Driver	MUHAMMAD SYAHMI BIN BAHARIN
Passport No/FIN	G2596857W
Date Of Birth	30/04/1993
Occupation	OUTDOOR
Date Of Driving Pass	23/04/2016
Driving Experience	3 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(FOREIGN) +601-7411653
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	NO 27 JALAN ZAPIN 8 TAMAN SKUDAI BARU SKUDAI JOHOR
Postcode	81300
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 29 MAY 2019 AT 1310HRS, I CAME TO UNIT #03-01 TO SEND MAIL TO THE COMPANY. AFTER SENDING THE MAIL, I CAME BACK TO THE BIKE (VEH A), I REALISED MY BIKE FELL SIDEWAYS ONTO THE FLOOR. THE DRIVER OF VEH B APPROACHED ME, SAID THAT HE DIDN'T PUT HIS LORRY HANDBRAKE PROPERLY. IT RESULTED IN THE LORRY ROLLING FORWARD AND HITTING MY BIKE. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YM172Y
Vehicle Make/Model/Colour	MITSUBISHI
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	GWEE YEOW SENG
NRIC/Passport Number	S0029318J
Contact Number	+6596602011
Address	70 ALPS AVE #03-01 / #04-01
Postcode	498801
Insurance Company Name	
Nature Of Damage	FRONT LEFT BUMP SCRATCH
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Scanned with
CamScanner

Driver's Signature
(If driver is not the policyholder)
Date & Time:


29/5/19
14 40 hrs

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/5/19 @ 1310hrs, I came to unit #03-01 to send mail to the company. After sending the mail, I came back to the bike (VEN A), I realized my bike fell side way onto the floor. The driver of Ven B approached me and said that he didn't put his long handbrake properly resulted the long rolled forward and hit my bike. No one was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Scanned with
CamScanner

29/5/19
@ 1440hrs

[Signature]

[Signature]

[>Back to OneMotoring](#)**Enquire Transfer Fee**

Vehicle Details			
Vehicle No. :	FBN672M		
Vehicle Type :	P01 - Passenger Scooter		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	NMAX155 ABS		
Chassis No. :	MH3SG431000006028		
Propellant :	Petrol		
Engine No. :	G3H6E0007781		
Engine Capacity :	155 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	295 kg		
Unladen Weight :	128 kg		
Year Of Manufacture :	2018		
Original Registration Date :	03 Jul 2018		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$7,602.00		
COE Expiry Date :	02 Jul 2028		
Road Tax Expiry Date :	02 Jul 2019		
Inspection Due Date :	02 Jul 2021		
Intended Transfer Date :	10 Jun 2019		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 02 Jul 2019. You may renew the road tax from 03 Apr 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 02 Jul 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 03 Jul 2019 to 02 Jan 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	32.00	-	32.00
Total Amount Payable :			57.00
Amount Payable (From 03 Jul 2019 to 02 Jul 2020)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	64.00	-	64.00
Total Amount Payable :			89.00
Message			
From 18 Feb 2019, the Government has further reduced the annual special tax by \$100 and \$850 for diesel and diesel-hybrid cars and taxis respectively. The Government will also grant road tax rebates for diesel and diesel-hybrid buses and goods vehicles for a 3-year period from 1 Aug 2019. The current enquiry result does not include the revised special tax reduction and road tax rebate commencing 1 Aug 2019. Please refer to the Press Release for more information.			

You may print this page for reference.

OK

Print

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1623M

Vehicle Details

Vehicle No.:	FBN672M
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX155 ABS
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	G3H6E0007781
Chassis No.:	MH3SG431000006028
Maximum Power Output:	-
Open Market Value:	\$2,350.00
Original Registration Date:	03 Jul 2018
First Registration Date:	03 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$353.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	02 Jul 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$7,602.00
COE Rebate Amount:	\$6,888.00
Total Rebate Amount:	\$6,888.00

The information contained herein is correct as at 10 Jun 2019

OK



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

MSIG INSURANCE (S) PTE LTD

4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

MOTOR CLAIMS DEEPT

NO. : 34247

DATE : 07/06/2019

CLAIM NO. : 11352

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBN0672M

MAKE/MODEL : YAM / NMAX155 ABS

*Not Admit
w/c
take up to 3 days
10/6/19
p/p*

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094	REPLACE	1.00	\$35.00 ✓	cut 35.00
2	BOARD FOOTREST LH P/N: 59588	REPLACE	1.00	\$50.00 ✓	cut n/c 50.00 X
3	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$50.00 ✓	cut 50.00
4	BOX FILTER AIR OUTER P/N: 58141	REPLACE	1.00	\$18.00	n/c sen 18.00 X
5	BOX FILTER AIR OUTER FRONT P/N: 58164	REPLACE	1.00	\$10.00	n/c sen 10.00 X
6	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$68.00	n/c sen 68.00 X
7	COVER SIDE CENTRE LH (WHITE) P/N: 58097	REPLACE	1.00	\$28.00	n/c sen 28.00 X
8	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$28.00	17 28.00 X
9	COVER SIDE REAR LH (WHITE) P/N: 58170	REPLACE	1.00	\$35.00	n/c sen 35.00 X
10	FENDER INNER P/N: 59583	REPLACE	1.00	\$28.00	17 28.00 X
11	LABOUR P/N: 06766	↑	6.00	\$35.00	180 210.00
12	LEVER BRAKE RH P/N: 58185	REPLACE	1.00	\$18.00	cut 18.00
13	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00	cut 35.00



bizSAFE



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-140383
ISO 9001: 2015

<u>S/N</u>	<u>Description'</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
14	MUDGUARD FRONT (WHITE) P/N: 58087	REPLACE	1.00	\$49.00	49.00
15	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00	38.00
16	SPRAY PAINTING - BOX SPRAY PAINTING	Respray	1.00	\$350.00	350.00
17	STICKER (SINGPOST) BOX REAR 2018 P/N: 58517	REPLACE	1.00	\$182.00	182.00
18	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833	Supply/Install	1.00	\$35.00	35.00

SUB TOTAL

\$1,267.00

GST @ 7 %

\$88.69

GRAND TOTAL

\$1,355.69

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



P. 176

$$\begin{array}{r} 102 \\ \hline 15840 \\ 747 \\ 905.40 \end{array}$$

bizSAFE



Address: No. 6, Defu lane 4, Singapore 539410 | **Telephone:** +65 6281 6520 | **Web:** www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO : 2002-1-0383
ISO 9001 : 2015



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 34247

- Rev. 1

MSIG INSURANCE (S) PTE LTD

4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

MOTOR CLAIMS DEEPT

DATE : 07/06/2019

CLAIM NO. : 11352

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBN0672M

MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
2	LABOUR P/N: 06766		6.00	\$30.00	180.00
3	LEVER BRAKE RH P/N: 58185	REPLACE	1.00	\$18.00 Disc %: 10.00	16.20
4	MIRROR RH P/N: 58187	REPLACE	1.00	\$35.00 Disc %: 10.00	31.50
5	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00 Disc %: 10.00	34.20
6	SPRAY PAINTING - BOX SPRAY PAINTING		1.00	\$350.00	350.00
7	STICKER (SINGPOST) BOX REAR 2018 P/N: 58517	REPLACE	1.00	\$182.00	182.00
8	TRANSPORT CHARGES (MOTORCYCLE/SCOOTER) STD P/N: 45833	Supply/Install	1.00	\$35.00	35.00
9	BOARD FOOTREST RH P/N: 59589	Replace	1.00	\$50.00 Disc %: 10.00	45.00
SUB TOTAL					\$905.40
GST @ 7 %					\$63.38
GRAND TOTAL					\$968.78

50% deposit required before ordering of parts.

Validity: 30 days



bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001:2015

...CLAIM SUBFOLDER...(Pending for Survey Report)









































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jun 2019		10 Jun 2019 09:57 Edit Adj Rpt	S\$905.40 Edit Estimates	S\$905.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JFE CONSOLIDATORS PTE LTD , Co. Reg. No.: 199403480G								
Main Claimant:	SINGAPORE POST LIMITED , Co. Reg. No.: 199201623M								
Vehicle Reg. No.:	FBN672M	Date of Loss:	29/05/2019 00:00 - :59 [10 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 595759	Policy/Cover Note No.:	28701187MKC (TP, Fire & Theft) Coverage: 27/04/2019 - 26/04/2020						
Vehicle Reg. No. (Insured):	YM172Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Ban Hock Hin Co. Pte Ltd (HQ) No. 6 Defu Lane 4, 539410 Defu Lane - Tel: 62816520								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 10/07/2019]								
Adj Asg. Remarks:	(Manual assign) on WP. Liability:Dispute,NR case. SJE case								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN672M (595759)
[YM172Y]
TP
SINGAPORE POST LIMITED
May 29 2019 12:00AM
[JFE CONSOLIDATORS PTE LTD]
Ban Hock Hin Co. Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser		▼	
Assessment Reports									1 per page		▼		☑	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print			
1	19/07/19 16:18	Accident Statement From:SC - Reg. No: YM172Y, Claimant: JFE CONSOLIDATORS PTE LTD							1		Load HTM			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	12/06/19 10:52	Adjuster Immediate Advice							1		Load HTM			
Photos/Images									3 per page		▼		☑	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	30/07/19 08:57	Odometer Reading							1		Load JPG		☑	
2	30/07/19 08:57	General View							1		Load JPG		☑	
3	30/07/19 08:57	General View							1		Load JPG		☑	
4	30/07/19 08:57	General View							1		Load JPG		☑	
5	30/07/19 08:57	General View							1		Load JPG		☑	
6	30/07/19 08:57	General View							1		Load JPG		☑	
7	30/07/19 08:57	General View							1		Load JPG		☑	
8	30/07/19 08:57	General View							1		Load JPG		☑	
9	30/07/19 08:57	General View							1		Load JPG		☑	
10	30/07/19 08:57	General View							1		Load JPG		☑	
11	30/07/19 08:57	General View							1		Load JPG		☑	
12	30/07/19 08:57	General View							1		Load JPG		☑	
13	30/07/19 08:57	General View							1		Load JPG		☑	
14	30/07/19 08:57	General View							1		Load JPG		☑	
15	30/07/19 08:57	General View							1		Load JPG		☑	
16	30/07/19 08:57	General View							1		Load JPG		☑	
17	30/07/19 08:57	General View							1		Load JPG		☑	
18	30/07/19 08:57	General View							1		Load JPG		☑	
19	30/07/19 08:57	General View							1		Load JPG		☑	
20	30/07/19 08:57	General View							1		Load JPG		☑	
21	30/07/19 08:57	General View							1		Load JPG		☑	
22	30/07/19 08:57	General View							1		Load JPG		☑	
23	30/07/19 08:57	General View							1		Load JPG		☑	
24	30/07/19 08:57	General View							1		Load JPG		☑	
25	30/07/19 08:57	General View							1		Load JPG		☑	
26	30/07/19 08:57	General View							1		Load JPG		☑	
27	30/07/19 08:57	General View							1		Load JPG		☑	
28	30/07/19 08:57	General View							1		Load JPG		☑	
29	30/07/19 08:57	General View							1		Load JPG		☑	
30	30/07/19 08:57	General View							1		Load JPG		☑	
31	30/07/19 08:57	General View							1		Load JPG		☑	
32	30/07/19 08:57	General View									Load JPG			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
38	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
44	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
45	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
46	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
47	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
48	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
49	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
50	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
51	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
52	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
53	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
54	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
55	30/07/19 08:57	General View	 Load JPG	<input checked="" type="checkbox"/>
56	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
61	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
62	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
63	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
64	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
65	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
66	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
67	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
68	30/07/19 08:58	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/06/19 09:22	PRI	 Load PDF	
2	19/07/19 16:21	TP FBN672M E-FILE REPORT	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	10/06/19 09:53	email - manual assign	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010121/UQD3E2

Date: 06/08/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28701187MKC

Claimant Vehicle No : FBN672M

Insured Vehicle No : YM172Y

Date of Loss: 29/05/2019

Nature of Claim: TP

Claim No: 595759

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN672M**

Make & Model: YAMAHA NMAX155, 155cc

Engine No: G3H6E0007781

Reg. Date: 03/07/2018 (Man. Year: 2018)

Chassis No: MH3SG431000006028

Colour: White

Odometer: 9401 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110-70-13

Rear Tyre Size: 130-70-13

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	672.00	340.40	331.60	49.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	595.00	565.00	30.00	5.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,267.00	905.40	361.60	28.54
+ GST 7.00/7.00% (S\$)	88.69	63.38	25.31	28.54
Nett Amount (S\$)	1,355.69	968.78	386.91	28.54

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Aug 2019)	
Parts:	N/A	YAMAHA NMAX155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN672M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BELLY PAN	Cut	35.00 F	*35.00 FL
2	1		*BOARD FOOTREST LH (CUT)	Not Consistent With The Impact	50.00 F	*- FL
3	1		*BOARD FOOTREST RH	Cut	50.00 F	*50.00 FL
4	1		*BOX FILTER AIR OUTER (SCRATCHED)	Not Consistent With The Impact	18.00 F	*- FL
5	1		*BOX FILTER AIR OUTER FRONT (SCRATCHED)	Not Consistent With The Impact	10.00 F	*- FL
6	1		*COVER CLUTCH OUTER (SCRATCHED)	Not Consistent With The Impact	68.00 F	*- FL
7	1		*COVER SIDE CENTRE LH (WHITE) (SCRATCHED)	Not Consistent With The Impact	28.00 F	*- FL
8	1		*COVER SIDE CENTRE RH (WHITE)	Not Necessary	28.00 F	*- FL
9	1		*COVER SIDE REAR LH (WHITE) (SCRATCHED)	Not Consistent With The Impact	35.00 F	*- FL
10	1		*FENDER INNER	Not Necessary	28.00 F	*- FL
11	1		*LEVER BRAKE RH	Cut	18.00 F	*18.00 FL
12	1		*MIRROR RH	Cut	35.00 F	*35.00 FL
13	1		*MUDGUARD FRONT (WHITE)	Repair	49.00 F	*- FL
14	1		*PROTECTOR EXHAUST	Scratched	38.00 F	*38.00 FL
15	1		*STICKER (SINGPOST) BOX REAR 2018	Necessary	182.00 FS	*182.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	672.00	358.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	17.60
Total Parts (S\$)	672.00	340.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR	New	210.00	180.00
2	SPRAY PAINTING - BOX SPRAY PAINTING	New	350.00	350.00
3	TRANSPORT CHARGES (MOTORCYCLE / SCOOTER) STD	New	35.00	35.00
Gross Labour Cost (S\$)			595.00	565.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >