#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

atoresaid.	
	ACCIDENT STATEMENT
Date Of Report	10/06/2019 09:07
Date Of Accident	08/06/2019 22:50
Exact Location Of Accident	BLK 865 TAMPINES ST 83 OPEN SPACE CARPARK
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	PA7733C
Insured/Policyholder	
Name Of Registered Owner	JMJ TRANSPORT SERVICES
Co Reg No	53221303C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	HIACE COMMUTER 3.0GL A
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5097217032-01
Cover Note Number	
Driver	
Name of Driver	HAMIS BIN ARIFFIN

Name of Driver HAMIS BIN ARIFFIN

NRIC No S1440099J
Date Of Birth 21/07/1960
Occupation OUTDOOR
Date Of Driving Pass 14/11/1989

Driving Experience 29 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-90027353

Fax Number

Contact Number OFFICE-90027353

EMail Address NOEMAIL

**BLK 44 SIMS DRIVE** Address

#03-169

Postcode 380044

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured **SPOUSE** 

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

**General Information of the Accident** 

HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED Type Of Accident

Weather Conditions **CLEAR** Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

YES

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Police Station Name **EUNOS NEIGHBOURHOOD POLICE POST** 

ROAD: BLK 629 BEDOK RESERVOIR ROAD #01-1620, POSTCODE: Police Station Address

470629, COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-4439999 - FAX NO: 62444376

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### **Circumstances of Accident**

REFER TO POLICE REPORT - T/201906092100.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? NO Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number SLP5936R

Vehicle Make/Model/Colour

**Details Of Properties** 

PRIVATE CAR Vehicle Category

Name of Driver

NRIC/Passport Number

**Contact Number** 

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### **Accident Sketch Plan**

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholde s

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personner's Sig Name:

NRIC/FIN No.:

#### **Accident Sketch Plan**

BE CIRCUMSTANCES OF THE ACCIDENT  To page (2 page - 7   2019 days) 2100-	A: PA 7733C B: SEPS 936R
BE CIRCUMSTANCES OF THE ACCIDENT	
to patre report-7/wigabog) 2100.	
OATION .	
RATION  clare to force only particulars are true in every respect.	
1.97	
S (2505/25030) 25	
	m
Driver's Signature Report  (If driver is not the policyholder) Name:	ng Centre Personne Signature

#### Police Report





Police Station Of Origin: Eunos NPP 629 Bedok Reservoir Road #01-1620 SINGAPORE 470629 Tel No: 1800-4439999

1 of 3 Report No. T/20190609/2100

# REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/06/2019 17:38		fade:	Vide Report No.:	Station Diary No.: 19	
Informa	nt's Partice	ulars			
Name of Informant: HAMIS BIN ARIFFIN			Address: APT BLK 44 SIMS DRIVE #03-169 SINGAPORE 380044		
ID Type / ID No.; NRIC NO / S1440099J			Contact No.: Home/Office:	Mobile: 90027353	
National SINGAP	ity: ORE CITIZ	EN	Email:		
Sex: Male	Age: 58	Date of Birth: 21/07/1960	Type of Informant: Vehicle Owner		
Race: Malay			Language: English	Institution / School Name:	
Occupation: Van driver			Driving Licence Information: Class: 2B,2A,2,3,4	Date of Expiry:	

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 08/06/2019 22:50	Type of Location Car Park	
Location: Along Road 1 TAMPINES S Open space of Weather:		npines Street 83, Lot r		oad Speed Limit:	
Clear		Dry		rioda opeca Emine	
Traffic Flow: Two Way		Traffic Control:	T	Traffic Volume: No Traffic	
		Not Controlled	1.53		

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenge
PA7733C	Van	ТОУОТА	COMMUTER 3.0GL A	White	Slightly Damaged	0

#### **Police Report**



T/20190609/2100

Police Station Of Origin: Eunos NPP 629 Bedok Reservoir Road #01-1620 SINGAPORE 470629 Tel No: 1800-4439999

Report No. T/20190609/2100

CONTINUATION OF REPORT

#### Brief Details.

On the above mentioned date and time, I discovered a white in colour note on my windscreen. The note informed me that my vehicle was grazed by a Toyota car bearing plate number SLP5936R and droved off. The note does not leave any contact number for me to call. Thus, I decided to lodge this report. I made a check on my van and discovered a long stretch of scratched mark on left side body of my van near to the left rear tyre.

I wish to state that the lot that I parked my van was a parallel lot and the left side of my van is facing moving traffic.

#### **Police Report**





Police Station Of Origin: Euros NPP 629 Bedok Reservoir Road #01-1620 SINGAPORE 470629 Tel No: 1800-4439999 3 of 3 Report No. T/20190609/2100

CONTINUATION OF REPORT

SI				D.	-	_
-	(0)	m	n	-	-	n

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 3 RADIN SALIHUL 'IMRAN BIN RADIN FADLI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 09/06/2019 17:38
Officer In Charge Of Case: TP / HRT / SI KALESWARI PALANI Contact No.: 65476902	Classification Of Case:
Authentication Stamp	































