

ASS. REC. BY:

REF: CS3/MSG 19010126 / UC d307 Special Instruction:

Surveyor: MARCUSASSIGNMENT (Office)From (Person): Muhamd Ashik B Madiof MS16Date/Time: 10.6.19 10.15 a.m

Estimated Cost: \_\_\_\_\_

Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 1422AInsured: PBM 68594at Workshop m/s KH POWERTel: 97469262of BK 9002 Tampine street 93 #01-56Policy No: MSD-VMS 19-393903Claim No: MSC/V/19-0006207

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh:

(Client's Record)

D.O.A. 26.5.1911.6.19

CA / REV / REP. / REV 24 HRS

(rwp)

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10.6.19 10.20 a.mPerson Contacted: Ah HapVehicle IN (OUT)

Date/Time	Action/Instruction
	<u>Following (x)</u>
	<u>SLH 1422A - X</u>
	<u>PBM 68594 - NA / MSG 19009296 / E4</u>
	<u>DOA - 26 / 05 / 2019.</u>

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

*MSIA***ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLH 1422A*at Workshop m/s *LM Power*of *01-56*

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_


Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: *2* days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

*LTA 43816*

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *SLH 1422A*Yr Regn: *7, 14*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*Make: *Mer Benz B180*c.c. *1595*Colour: *Red*

A/C: Insured / Std / NI / NA

Sp. Reading: *61508*

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: *WDD 2462422 J 234343*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *205/55R16*

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6*Rear *6*

R/Bal. \_\_\_\_\_ mm

R/Bal. \_\_\_\_\_ mm

L/Bal. *6* mmL/Bal. *6* mmD.O.A. *20/5/18*D.O.I. *11/6/18*

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*Rear N/S.*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*No search.**1500 - 2500*

RECEIVED 19 JUN 2019

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *2*Resurvey No. of Trip: *-*

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee:

☐

: Site Insp (\$ \_\_\_\_\_)

) \_\_\_\_\_ S + RS, \_\_\_\_\_ SI

☐

: Interview (\$ \_\_\_\_\_)

) Photos

☐

: Tech. Invs (\$ \_\_\_\_\_)

) Others

☐

: Weekend (\$ \_\_\_\_\_)

) \_\_\_\_\_

Report Format: *PRE*

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL

*131**120**11*

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 May 2019		10 Jun 2019 10:15 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FUAD BIN IBRAHIM, ID: S9149037D		
Main Claimant:	NG LAY YEN JELINE, ID: S7702570G		
Vehicle Reg. No.:	SLH1422A	Date of Loss:	26/05/2019 12:00 - :59 [58 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/19-000629	Policy/Cover Note No.:	MSD/VMS/19-393903 (TP, Fire & Theft) Coverage: 03/02/2019 - 02/02/2020
Vehicle Reg. No. (Insured):	FBM6859H	Policy No. (Claimant):	
		Excess:	
Repairer:	Kh Power (HQ) BLK 9002 TAMPINES STEET 93 #01-56, 528838 Tampines - Tel: 62603137		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 11/06/2019]		
Driver/Custodian (Insured):	FUAD BIN IBRAHIM (27 / Male) , NRIC: S9149037D Email:		
Adj Asg. Remarks:	on WP, Liab: 100%. TP lawyer disagree on SJE - assign LKK Auto Consultants. Contact: Mr. Tan / Tel: 6782 7988, H/p: 9746 9262		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

## View Sent Message

This mail is associated with :

**\*SLH1422A (MSC/V/19-000629)**

**[FBM6859H]**

TP

NG LAY YEN JELINE

May 26 2019 12:00PM

[FUAD BIN IBRAHIM]

Kh Power

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 12/06/2019 11:43 AM.

**To** ashik\_madi@sg.msg-asia.com

**Subject** SLH1422A (MSC/V/19-000629) [FBM6859H]

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLH 1422A on 11/6/2019  
We are pending estimate from repairer.

Regards,  
Denise  
LKK Auto

### DOCUMENTS SUMMARY

There are no documents.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2570G

**Vehicle Details**

Vehicle No.:	SLH1422A
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2019
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	B180 (R16 BI)
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	27091030335200
Chassis No.:	WDD2462422J234343
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$24,674.00
Original Registration Date:	10 Jul 2014
First Registration Date:	10 Jul 2014
Transfer Count:	1
Actual ARF Paid:	\$16,544.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2024
PARF Rebate Amount:	\$12,408.00

**Intended COE Rebate Details**

COE Expiry Date:	09 Jul 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,899.00
COE Rebate Amount:	\$31,408.00
<b>Total Rebate Amount:</b>	<b>\$43,816.00</b>

The information contained herein is correct as at 12 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/05/2019 15:14
Date Of Accident	26/05/2019 12:30
Exact Location Of Accident	TAMPINES AVE 5 SLIP RD TO PIE CHANGI AIRPORT
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLH1422A
Insured/Policyholder	
Name Of Registered Owner	NG LAY YEN JELINE
NRIC No	S7702570G
Email Address	JELINE66@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98377502
Alternative Phone No	OFFICE-98377502
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	B180 (R16 BI)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	DIRECT ASIA INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT/000439587/01
Cover Note Number	10/01/2019-09/01/2020
Driver	
Name of Driver	NG LAY YEN JELINE
NRIC No	S7702570G
Date Of Birth	11/02/1977
Occupation	INDOOR
Date Of Driving Pass	23/12/1998
Driving Experience	20 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98377502
Fax Number	
Contact Number	OFFICE-98377502
EMail Address	JELINE66@YAHOO.COM

Address	BLK 266 TAMPINES ST 21 #09-20 SINGAPORE 520266
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : KEEGAN TAN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM6859H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	FAUN BIN IBRAHIM
NRIC/Passport Number	S9149037D
Contact Number	96793953
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:




Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was filtering right <sup>to go to</sup> the highway, signalled right & stopped for road to be clear before filter driving onto the highway. But the motorist didn't stop and banged into the rear left of my car.

<p>You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a <b>Fourteen (14) days clause</b> whereby the claim must be made within the stipulated timeframe from the day of occurrence.</p>	Reporting Only
	Claim OD
	Claim TP
	Claim OD / TP at other workshop

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 28/5/19  
3:05pm

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 28/5/19  
3:05pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

# INSURANCE CERT



Contact us at  
Hotline: (65) 6532 2888  
E-mail: CustomerService@DirectAsia.com

## CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act")  
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore)  
Road Transport Act, 1987 (Malaysia)  
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

<b>Certificate No.</b>	: MT/00439587/01
<b>Type of Coverage / Driver Plan</b>	: Car Comprehensive (Value Plus Plan)
<b>1) Vehicle Registration No.</b>	: SLH1422A
<b>Chassis No.</b>	: WDD2462422J234343
<b>2) Name of Policy Holder</b>	: NG, LAY YEN
<b>3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act</b>	: 10/01/2019 00:00
<b>4) Date/Time of Expiry of Insurance</b>	: 09/01/2020 23:59
<b>5) Persons or Classes of Persons Entitled to Drive</b>	<p>(a) Any named person under the policy who is driving on the Policyholder's permission.</p> <p>(b) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Policyholder's permission</p> <p>The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.</p>
<b>6) Limitations as to use*</b>	<p>Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business.</p> <p>*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.</p>
<b>Sum Insured</b>	: Market Value
<b>Own Damage Excess</b>	: S\$ 900.00 (before any applicable GST)
<b>Windscreen Excess</b>	: S\$ 100.00 (before any applicable GST)
<b>Choice of workshop</b>	: DirectAsia approved workshops
<b>Finance company / Hire Purchase</b>	:
<b>Main driver</b>	: NG, LAY YEN
<b>Named driver</b>	: None
<b>Important Note:</b> This policy does not cover the Policyholder/drivers below the age of 30 and Policyholder/drivers who hold a valid driving licence of less than 2 years with the exception of the main/named drivers above.	

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on: 21/12/2018

Direct Asia Insurance (Singapore) Pte. Ltd.

Edip Okur  
Chief Underwriting Officer

Direct Asia Insurance (Singapore) Pte Ltd  
20 Anson Road #08-01 Twenty Anson Singapore 079917  
www.DirectAsia.com

Company Registration: 200822511G

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 May 2019		10 Jun 2019 10:15 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span>[Created by insurer]</span>									
Insured:	<b>FUAD BIN IBRAHIM</b> , ID: S9149037D								
Main Claimant:	<b>NG LAY YEN JELINE</b> , ID: S7702570G								
Vehicle Reg. No.:	<b>SLH1422A</b>	Date of Loss:	26/05/2019 12:00 - :59 [58 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MSC/V/19-000629</b>	Policy/Cover Note No.:	MSD/VMS/19-393903 (TP, Fire & Theft) Coverage: 03/02/2019 - 02/02/2020						
Vehicle Reg. No. (Insured):	<b>FBM6859H</b>	Policy No. (Claimant):							
		Excess:							
Repairer:	<b>Kh Power (HQ)</b> BLK 9002 TAMPINES STEEET 93 #01-56, 528838 Tampines - Tel: 62603137								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Muhd Ashik B Madi</b> - 6594 2548]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Imm.Advice due 11/06/2019]								
Driver/Custodian (Insured):	FUAD BIN IBRAHIM (27 / Male) , NRIC: S9149037D Email:								
Adj Asg. Remarks:	on WP. Liab: 100%. TP lawyer disagree on SJE - assign LKK Auto Consultants. Contact: Mr. Tan / Tel: 6782 7988, H/p: 9746 9262								
<b>ASSOCIATED MAIL RECEIVED</b> <span><a href="#">View All</a></span> <span><a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span><a href="#">View All</a></span> <span><a href="#">Search Tasks</a></span> <span><a href="#">Create New Task</a></span> <span><a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLH1422A (MSC/V/19-000629)  
[FBM6859H]  
TP  
NG LAY YEN JELINE  
May 26 2019 12:00PM  
[FUAD BIN IBRAHIM]  
Kh Power

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

**View** [View in Browser](#)

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
2	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
3	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
4	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
5	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
6	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
7	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
8	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
9	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
10	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
11	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
12	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
13	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
14	17/06/19 11:32	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	07/06/19 10:19	OI Accident Report	Load PDF	
2	07/06/19 10:19	TP SLH1422A E-REPORT	Load PDF	
3	07/06/19 15:38	TP disagree on SJE - workshop details	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	10/06/19 10:15	Outsource Instruction	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
There are no document checklists configured.	
<div style="border: 1px solid black; padding: 5px; margin-top: 10px;"> <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div> </div> <div style="margin-top: 10px;"> <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer  <small>Note: Remarks are private unless you show it to other parties.</small> </div>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19010126/UCD3E2

Date: 20/06/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/19-393903
Claimant Vehicle No :	SLH1422A	Insured Vehicle No :	FBM6859H
Date of Loss:	26/05/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000629

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLH1422A	Engine No:	27091030335200
Make & Model:	MERCEDES-BENZ B180, 1.6 (R16 BI) (A)	Chassis No:	WDD2462422J234343
Reg. Date:	10/07/2014 (Man. Year: 2013)	Odometer:	61508 km
Colour:	Red		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment:	10/06/2019	
Date Inspected:	11/06/2019 Inspected At:	Kh Power (HQ) BLK 9002 TAMPINES STEET 93 #01-56 Singapore 528838
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 - \$2,500.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
<b>Parts:</b>	144	MERCEDES-BENZ B180 1.6 (R16 BI) (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLH1422A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >