

22/03/2002

ASS. REC. BY:

REF: CS3/CTI 19010132/ JC d302 Special Instruction:

Surveyor: Hwee Jie

**ASSIGNMENT (Office)**

From (Person): Tan Kah Loong

of CTI

Date/Time: 10.6.19 1206 PM

Estimated Cost:

Bill to:

**OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS**

To Inspect Vehicle No: GBD 7382 G

Insured: GBA 1832E

at Workshop m/s Eng Soon Painting

Tel: 67606271

of 393J Woodland Road

Policy No: DM CVS N 3023201902

Claim No: SNM19D 202526 C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.6.19 1.17 PM

Person Contacted: Mr Teo

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	GBD 7382 G -X
	GBA 1832 E -X
	Dismantle: 11/6/2019

ASS. REC. BY: Huailin


REF CT1

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GBD 7382G Yr Regn: 31 mar 2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV200 c.c. 1597  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 164917 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VM20061395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70 R14

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 7/6/19 D.O.I. 10/6/19

Survey held at Eng Soon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PPS
	Range: \$6000-\$7000 6 days.
	<u>12/6/2019</u>
	RECEIVED 19 JUN 2019

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\_\_\_\_ S + RS. \_\_\_\_ \$

Photos

Others

TOTAL

Report Format : PR2

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019		10 Jun 2019 12:06 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	BLUE RIBBON FLORIST & GIFTS, Co. Reg. No.: 50402300D		
Vehicle Reg. No.:	GBD7382G	Date of Loss:	07/06/2019 17:00 - :59
Claim Type:	TP / SNM19D202526C02	Policy/Cover Note No.:	DMCVSN3023201902
Vehicle Reg. No. (Insured):	GBA1832E	Policy No. (Claimant):	5100540177
		Excess:	S\$0.00
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2019]		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Sent:** Monday, 10 June 2019 12:01 PM  
**To:** bonnie kwok; assignments  
**Subject:** RE: Urgent: Pre-Repair Inspection: Your Vehicle: GBA 1832 E; EngSoon's Vehicle: GBD 7382 G; Accident Involving GBD 7382 G & GBA 1832 E on 7 June 2019

**WITHOUT PREJUDICE  
SAVE AS TO COSTS**

Dear ST,

We refer to your email of 10.06.2019.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK.

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

**Tan Kah Leong**  
Assistant Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6193 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** bonnie kwok [mailto:litigation@bonniekwok.com]  
**Sent:** Monday, 10 June, 2019 11:21 AM  
**To:** Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>  
**Subject:** Re: Urgent: Pre-Repair Inspection: Your Vehicle: GBA 1832 E; EngSoon's Vehicle: GBD 7382 G; Accident Involving GBD 7382 G & GBA 1832 E on 7 June 2019

Dear Sirs,

Hwee Sie

Your list of surveyors is rejected.

We have been instructed to propose the following list of surveyors for the Single Joint Expert:-

1. Fong Kok Heng
2. Danny Yap
3. Willy Goh
4. Francis Ng
5. Dennis Yap
6. Louis Ng
7. Michael Yap
8. Lim Yong Tian
9. Patrick Ng
10. Philip Foo

Kindly contact the repairers, M/s Eng Soon Painting Services at 6760 6271 for pre-repair inspection arrangements.

Regards,  
ST  
--

**BONNIE KWOK LLC**

Advocates & Solicitors  
101A Upper Cross Street  
#08-12 People's Park Centre  
Singapore 058358  
TEL: 6536 6026  
FAX: 6536 2279  
email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)  
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Mon, 10 Jun 2019 at 10:51, Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)> wrote:

**Without Prejudice**

Dear Sirs,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
LOW SAR HUEI
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
HONG FOOK CHOY
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Regards

**Tan Kah Leong**

Assistant Executive

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6193 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/)

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Claims Dept of CTI

**Sent:** Monday, 10 June, 2019 10:46 AM

**To:** Tan Kah Leong <[KahLeong.Tan@sg.cntaiping.com](mailto:KahLeong.Tan@sg.cntaiping.com)>; [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)

**Cc:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Subject:** FW: Urgent: Pre-Repair Inspection: Your Vehicle: GBA 1832 E; EngSoon's Vehicle: GBD 7382 G; Accident Involving GBD 7382 G & GBA 1832 E on 7 June 2019

Dear Kah Leong,

Please conduct PRS – TP: GBD7382G (SNM19D202526) soonest possible.

File with OIC – Kah Leong - 63896193

**From:** bonnie kwok [<mailto:litigation@bonniekwok.com>]

**Sent:** Monday, 10 June 2019 10:34 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** Urgent: Pre-Repair Inspection: Your Vehicle: GBA 1832 E; EngSoon's Vehicle: GBD 7382 G; Accident Involving GBD 7382 G & GBA 1832 E on 7 June 2019

**Urgent**

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. GBD 7382 G at M/s Eng Soon Painting Services, Block 4 Yew Tee Industrial Estate 393-J Woodlands Road Singapore 677978.

Regards,

ST

--

**BONNIE KWOK LLC**

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)

GST Reg. No.: 201203547Z

✂ We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	2300D

**Vehicle Details**

Vehicle No.:	GBD7382G
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV200 DX 1.6 A
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	HR16011381D
Chassis No.:	VM20061395
Maximum Power Output:	-
Open Market Value:	\$15,715.00
Original Registration Date:	31 Mar 2015
First Registration Date:	31 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$786.00

**Intended PARF Rebate Details**

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

**Intended COE Rebate Details**

COE Expiry Date:	30 Mar 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$51,166.00
COE Rebate Amount:	\$29,668.00
<b>Total Rebate Amount:</b>	<b>\$29,668.00</b>

The information contained herein is correct as at 12 Jun 2019

OK

**SINGAPORE ACCIDENT STATEMENT****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report 10/06/2019 09:58  
 Date Of Accident 07/06/2019 17:30  
 Exact Location Of Accident ALONG PIE TWDS KJE  
 Country/State of Loss SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number GBD7382G  
**Insured/Policyholder**  
 Name Of Registered Owner BLUE RIBBON FLORIST & GIFTS  
 Co Reg No 50402300D  
 Email Address NOEMAIL  
 Mobile Phone No  
 Alternative Phone No Office-96658517

**Vehicle Particulars**

Manufacturer NISSAN  
 Model NV200 DX 1.6 A

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

**Insurance Company**

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number 5100540177  
 Cover Note Number

**Driver**

Name of Driver LEE LIAK SENG  
 NRIC No S1184387E  
 Date Of Birth 05/11/1955  
 Occupation OUTDOOR  
 Date Of Driving Pass 19/03/1975  
 Driving Experience 44 YEARS AND 2 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-97802673

Fax Number

Contact Number

EMail Address

JIMMYAPPLELEE@GMAIL.COM

Address

APT BLK 113 PENDING ROAD #10-100

Postcode

670113

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own Vehicle

-

-

-

Insurance Company of Driver's Own Vehicle

-

-

-

**General Information of the Accident**

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

**Other Information**

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

**Circumstances of Accident**

REFER SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

GBA1832E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

KOEY JIN LEONG

NRIC/Passport Number

S9079236I

Contact Number

98321734

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Accident Sketch Plan

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:




  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Accident Sketch Plan

## SKETCH PLAN



A - GBD 7302 G

B - GBA 1832 E

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Accident Date &amp; Time: 7/6/2019 @ 1730 hrs

Accident Location: PIE towards KJE

I was driving along the mentioned location.  
 Traffic was very heavy & slow.  
 Suddenly I felt an impact on the rear portion.  
 Vehicle B had collided onto my vehicle.

☐ Reporting Only ☐ Own Damage ☐ Third Party ☒ Claim at other workshop (OD/TP)

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

\* IMPORTANT NOTE:  
 You must lodge a claim within 14 days of the accident. If you fail to do so, you may be liable to pay the full amount of the claim. This is a FOURTEEN (14) days period starting from the date of the accident.

Policyholder's Signature

Date &amp; Time:



Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

### ...CLAIM SUBFOLDER...(Pending for Survey Report)





































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jun 2019		10 Jun 2019 12:06 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>BLUE RIBBON FLORIST &amp; GIFTS</b> , Co. Reg. No.: 50402300D									
Vehicle Reg. No.:	<b>GBD7382G</b>	Date of Loss:	07/06/2019 17:00 - :59 [50 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D202526C02</b>	Policy/Cover Note No.:	DMCVSN3023201902						
Vehicle Reg. No. (Insured):	<b>GBA1832E</b>	Policy No. (Claimant):	5100540177						
		Excess:	S\$0.00						
Repairer:	<b>Eng Soon Painting Services (HQ)</b> 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Tan Kah Leong</b> - 63896193]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ONG HWEE JIE</b> ] ... <b>[Final Rpt due 19/06/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBD7382G (SNM19D202526C02)  
[GBA1832E]  
TP  
BLUE RIBBON FLORIST & GIFTS  
Jun 7 2019 5:00PM  
[-]  
Eng Soon Painting Services

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
2	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
3	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
4	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
5	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
6	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
7	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
8	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
9	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
10	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
11	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
12	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
13	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
14	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
15	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
16	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
17	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
18	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
19	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
20	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
21	12/06/19 08:50	General View					 Load JPG	<input checked="" type="checkbox"/>	
22	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
23	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
24	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
25	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
26	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
27	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
28	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
29	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
30	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
31	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
32	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
33	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
34	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
35	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	
36	12/06/19 08:50	Dismantled Parts					 Load JPG	<input checked="" type="checkbox"/>	

### Linked Accident Report Documents

Assessment Reports			View <span>View in Browser</span>	
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/06/19 10:19	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/06/19 10:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 10:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	10/06/19 10:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	10/06/19 10:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	10/06/19 10:04	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Hua Hong Pte Ltd (Sungei Kadut)	Thumbnail	Print
1	10/06/19 10:18	Accident Sketch Plan	Load TIF	
2	10/06/19 10:18	Accident Sketch Plan	Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119010132/JCD3E2

Date: 20/06/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN3023201902

Claimant Vehicle  
No : GBD7382GInsured Vehicle  
No : GBA1832E

Date of Loss: 07/06/2019

Nature of Claim: TP

Claim  
No: SNM19D202526C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GBD7382G

Make &amp; Model: NISSAN NV200, 1.6 DX (A)

Engine No: HR16011381D

Reg. Date: 31/03/2015 (Man. Year: 2014)

Chassis No: VM20061395

Colour: Silver

Odometer: 164917 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 175/70 R14

Rear Tyre Size: 175/70 R14

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Eng Soon Painting Services (HQ)  
393J WOODLANDS ROAD  
Singapore 677978

Estimated Period of Repair: 6.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000.00 -\$7,000.00

## REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 20 Jun 2019)
Parts:	N/A	NISSAN NV200 1.6 DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBD7382G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >