

22/03/2002

ASS. REC. BY:

REF: CS 3/SMD 190101331 GC d307

Special Instruction:

Surveyor: GA **ASSIGNMENT (Office)**

From (Person): Hwang Shiang Yi of SMD Date/Time: 10.6.19 12.14 p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLP 8556J Insured: FBE 10852

at Workshop m/s Alpha car Tel: 9807 3304

of BIC C, Kaki Bukit Ave 6 #01-59

Policy No: D18MTM01005950 Claim No: CMTD190 2748

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 4.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{or up} H.O.D. Endorsement: _____

Date/Time: 10.6.19 1.10 p.m Person Contacted: An Yap Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLP 8556J - x
	FBE 10852 - x
	Dismantle: 13/6/2019
	After repair: 18/6/2019

Surveyor: Brl.

REF: Smo

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Alpha Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/> N/S	<input type="checkbox"/> O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value: _____
 IDAC Accident Rpt.: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SLP 85561 Yr Regn: 28 Mar 201
 Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or 1.6
 Make: Volvo S60 T4 c.c. 1596
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 162117 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: YV1FS 485BC2126857
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45 2R17
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 10-06-19
 Survey held at w/s 5pm
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$2000 - \$4000</u>
	<u>17/6/2019</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 4
 Resurvey No. of Trip: 2

1) _____
 Date/Time, File Return to?
 2) _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>100</u>
Transportation:	<u>60</u>
S + RS, SI	<u>60</u>
Photos	
Others	<u>11</u>
TOTAL	<u>231</u>

Report Format : PRC
 Lump Sum / I.B.I: (\$ _____)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		10 Jun 2019 12:14 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ARUMUGAM SARAVANAN, ID: S8085954F		
Main Claimant:	CHAN KAH SOON DANNY, ID: S6935924H		
Vehicle Reg. No.:	SLP8556J	Date of Loss:	04/06/2019 13:00 - :59
Claim Type:	TP / CMTD1902748	Policy/Cover Note No.:	D18MTMC01005950 (Third Party Only)
Vehicle Reg. No. (Insured):	FBE1085Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2019]		
Adj Asg. Remarks:	WS: CAI LING 65098258/ AH YAP98073304/ AH HWA 91368884 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5924H
Vehicle Details	
Vehicle No.:	SLP8556J
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2019
Vehicle Make:	VOLVO
Vehicle Model:	S60 T4 1.6 AT ABS D/AB 2WD 4DR TC
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	B4164T1073254
Chassis No.:	YV1FS485BC2126857
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$35,461.00
Original Registration Date:	28 Mar 2012
First Registration Date:	28 Mar 2012
Transfer Count:	1
Actual ARF Paid:	\$35,461.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Mar 2022
PARF Rebate Amount:	\$21,276.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$56,501.00
COE Rebate Amount:	\$15,735.00
Total Rebate Amount:	\$37,011.00

The information contained herein is correct as at 14 Jun 2019

OK

▶ Volvo S60 Used Vehicle List (11 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Volvo S60 T4	\$43,800	\$9,850 /yr	10-Feb-2012	1,596 cc	98,000 km	GD Carz Trading Pte Ltd	Availal

Selling At Low Depreciation, Almost New Condition, Warranty, High Paper Value, Don't Miss It, Call Now, Trade-In Welcome.

Office No. - 64649355

Jay - 97810867 | Ronnie - 90077238 | Eric Tay - 98804444 | Steven - 90097159

Volvo S60 T4	\$48,500	\$11,450 /yr	24-Feb-2012	1,596 cc	-	360 VR Cars	Availal
---------------------	-----------------	--------------	-------------	----------	---	-------------	----------------

Accident Free, Car Is Serviced Every 5000Km With Servicing Record, New Lowered Spring, Front Lips And Boot Lips, All Sealed Newly Replac 8 Months Old Tyres On 18 Inch Rim, New Rotor And Pads, Radia...

Office No. - 69310005

Andrew Goh - 97719077 | James Tan - 90700005

Volvo S60 T4	\$44,500	\$9,940 /yr	28-Feb-2012	1,596 cc	-	Prime Motor & Leasing	Availal
---------------------	-----------------	-------------	-------------	----------	---	-----------------------	----------------

Elegant Volvo S60, Renowned For Safety, Serviced By Agent, Very Well Maintained, Easy Financing, Flexible In-house Loan Packages Availab

Office No. - 64440088

Mark - 84995146 | Andy - 91086443 | Jordan - 91168032 | Pauline - 97810269

Volvo S60 T4	\$45,800	\$10,340 /yr	28-Feb-2012	1,596 cc	85,000 km	Motor Universe Credit Pte Ltd	Availal
---------------------	-----------------	--------------	-------------	----------	-----------	-------------------------------	----------------

No Repair Needed, Perfect Engine Condition, Clean And Pristine Interior, Low Mileage Done At 85,000km, Price Negotiable, View The Car At Showroom.

Office No. - 64655595

Jackson Lim - 82012885 | Alvan - 84995363 | John Tan - 98895558 | Benson Hu - 97997507

Volvo S60 T4	\$47,800	\$10,770 /yr	28-Mar-2012	1,596 cc	188,935 km	F1 Auto Cars Pte Ltd	Availal
---------------------	-----------------	--------------	-------------	----------	------------	----------------------	----------------

Accident-Free, Well Maintained. In Good Condition. View The Car At Our Showroom.

Office No. - 62506696

Bobby - 91910882 | Mark - 96375329

Volvo S60 T4	\$45,800	\$9,510 /yr	25-May-2012	1,596 cc	104,928 km	Fave Auto International Pte Ltd	Availal
---------------------	-----------------	-------------	-------------	----------	------------	---------------------------------	----------------

Low Mileage Done At 104,928 Km Only! Beautiful Original White Paintwork With Clean And Neat Black Leather Interior. Fully Well Maintained Previous Owner With Diligent Care. 100% Accident Free With ...

Office No. - 69090152

Ken Tung - 81133145

Volvo S60 T4	\$48,800	\$10,370 /yr	13-Jun-2012	1,596 cc	106,000 km	Highline Automotive	Availal
---------------------	-----------------	--------------	-------------	----------	------------	---------------------	----------------

Immaculate Condition And In Showroom Condition. Buy With Extra Peace Of Mind! High Paper Value, Selling Near Export Price, High Trade I Welcome, In House And Bank Loan Available! Price Negotiable, Ca...

Office No. - 67778887

JC Chua - 87115663 | Harris Tan - 96881515 | Henry Ong - 98516566

Volvo S60 T4	\$49,800	\$10,550 /yr	29-Jun-2012	1,596 cc	98,000 km	StarBright Auto	Availal
---------------------	-----------------	--------------	-------------	----------	-----------	-----------------	----------------

6 Months Warranty, New Aircon Compressor, Rear Brake Pad, Heater Hose & Outer Hose Just Replaced, Loan Available, Trade In Welcome.

Office No. - 67930080

Jeff - 97955598 | Richard - 81667779

Volvo S60 T4	\$49,800	\$10,300 /yr	25-Sep-2012	1,596 cc	108,000 km	StarBright Auto	Availal
---------------------	-----------------	--------------	-------------	----------	------------	-----------------	----------------

6 Months Warranty, Brand New Engine Mounting & Front Anti Roll Bar Replaced, Loan Available, Trade In Welcome.

Office No. - 67930080

Soh - 97955598 | Richard - 81667779

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/06/2019 12:10
Date Of Accident	04/06/2019 13:05
Exact Location Of Accident	ALONG PIE BEFORE EXIT WOODLANDS RD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLP8556J
Insured/Policyholder	
Name Of Registered Owner	CHAN KAH SOON DANNY
NRIC No	S6935924H
Email Address	DANCK69@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96866999
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	
Manufacturer	VOLVO
Model	S60-1.6 T4 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN1744761801
Cover Note Number	
Driver	
Name of Driver	CHAN KAH SOON DANNY
NRIC No	S6935924H
Date Of Birth	18/10/1969
Occupation	INDOOR
Date Of Driving Pass	13/09/2005
Driving Experience	13 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96866999
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	DANCK69@GMAIL.COM

Address	BLK 327 JURONG EAST ST 31 #07-160 #07-160
Postcode	600327
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 04/06/2019 AT ABOUT 1305 HRS. WHILE I WAS TRAVELLING ON FIRST LANE ALONG PIE BEFORE EXIT WOODLANDS RD . THERE WAS RAINING , TRAFFIC IS VERY HEAVY JAM . WHEN TRAFFIC CAME TO A STOP. WHEN I SLOW DOWN MY SPEED AND MANAGE TO STOP MY VEHICLE . SUDDENLY I FEEL AN IMPACT FROM MY REAR LEFT PORTION . I NOTICED THAT A MOTORBIKE (FBF1085Z) LOST CONTROL AND HIT ONTO MY VEHICLE REAR LEFT AND LEFT SIDE PORTION . AFTER THAT HE FELL DOWN AND HIT ONTO MY FRT LEFT PORTION .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBE1085Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	ARUMUGAM SARAVANAN
NRIC/Passport Number	S8085954F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

 06/06/2019

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		10 Jun 2019 12:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	ARUMUGAM SARAVANAN, ID: S8085954F								
Main Claimant:	CHAN KAH SOON DANNY, ID: S6935924H								
Vehicle Reg. No.:	SLP8556J	Date of Loss:	04/06/2019 13:00 - :59 [86 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1902748	Policy/Cover Note No.:	D18MTMC01005950 (Third Party Only)						
Vehicle Reg. No. (Insured):	FBE1085Z	Policy No. (Claimant):							
		Excess:							
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 19/06/2019]								
Adj Asg. Remarks:	WS: CAI LING 65098258/ AH YAP98073304/ AH HWA 91368884 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All	Search Tasks	Create New Task	Complete		
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLP8556J (CMTD1902748)**
[FBE1085Z]
TP
CHAN KAH SOON DANNY
Jun 4 2019 1:00PM
[ARUMUGAM SARAVANAN]
Alpha Car Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View View in Browser <input type="button" value="v"/>	
Photos/Images						3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
2	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
3	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
4	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
5	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
6	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
7	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
8	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
9	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
10	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
11	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
12	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
13	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
14	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
15	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
16	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
17	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
18	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
19	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
20	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
21	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
22	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
23	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
24	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
25	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
26	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
27	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
28	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
29	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
30	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
31	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
32	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
33	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
34	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
35	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
36	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		
37	20/06/19 18:27	General View		Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/06/19 18:27	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/06/19 18:27	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/06/19 18:27	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/06/19 18:27	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/06/19 18:27	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/19 18:27	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/06/19 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	20/06/19 18:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
85	20/06/19 18:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
86	20/06/19 18:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
87	20/06/19 18:28	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
89	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
90	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
91	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
92	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
93	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
94	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
95	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
96	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
97	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
98	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
99	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
100	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
101	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
102	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
103	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
104	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
105	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
106	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
107	20/06/19 18:28	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
108	20/06/19 18:29	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
109	20/06/19 18:29	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/06/19 09:32	Pre-Repair Survey+GIA	Load PDF	
2	10/06/19 12:13	Pre-Repair Survey - AGREED LKK/Marcus	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO19010133/GCD3E2

Date: 21/06/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01005950

Claimant Vehicle No : SLP8556J **Insured Vehicle No :** FBE1085Z

Date of Loss: 04/06/2019 Nature of Claim: TP Claim No: CMTD1902748

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP8556J	Engine No:	B4164T1073254
Make & Model:	VOLVO S60, 1.6 T4 (A)	Chassis No:	YV1FS485BC2126857
Reg. Date:	28/03/2012 (Man. Year: 2012)	Odometer:	162117 km
Colour:	White		
Engine Capacity:	1596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R17	Rear Tyre Size:	225/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Alpha Car Services Pte Ltd (HQ)
Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
Parts: 143	VOLVO S60 1.6 T4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP8556J)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >