

ASS. REC. BY:

REF: CS3 / CT1 19010142 / R / C0302

Special Instruction:

Survivor: (Rashu)

**ASSIGNMENT (Office)**

From (Person): Elaine chong

of

CT1

Date/Time: 10.6.19 14.31pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMC 810Z

Insured:

GX 7484G

at Workshop m/s SK Garage

Tel:

85881117

of F. Sion Lee Street A01-31

Policy No: DM CVSIR 1654821802

Claim No:

SNM 1902025 08C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.6.19 2.36pm

Person Contacted:

Jonathan

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

SMC 810Z - X

GX 7484G - X

Dismantle: 11/6/2019

708/11/134

Surveyor Zame

REF:

71534

106 APR 9: 2027/PRC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SME 8102at Workshop m/s SK GARAGEof 7, SOON LEE ST #01-31Insured: CTI

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 76K

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SME 8102 Yr Regn: 2008 / JANType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda CIVIC TYPE R 2.0M c.c : 1998Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 257501 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: FD 21203539Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R17R: ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 04/06/19 D.O.I. 10/06/19Survey held at SK GARAGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair RATE - (8k - 10K) / 6 days

  
12/6/2019

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 6

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Survey Fee: 150

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRC

Lump Sum / I.B.I. (\$) \_\_\_\_\_ )

150

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2019		10 Jun 2019 14:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

## CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:

Main Claimant:

LOW CHI SIANG, ID: S8319193G

Vehicle Reg. No.:

SME810Z

Date of Loss:

04/06/2019 15:00 - :59

Claim Type:

TP / SNM19D202508C02

Policy/Cover Note No.:

DMCVSN1654821802

Vehicle Reg. No. (Insured):

GX7484G

Policy No. (Claimant):

GA436733

Excess:

S\$0.00

Repairer:

Sk Garage Motorsports - Soon Lee (HQ) 5 SOON LEE STREET, #01-34, 627607 Pioneer - Tel:

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

Claimant's Insurer:

AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... **[Final Rpt due 19/06/2019]**

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

## Nivitha (LKK Auto)

---

**From:** Elaine Cheong <elaine.cheong@sg.cntaiping.com>  
**Sent:** Monday, 10 June 2019 1:51 PM  
**To:** winnie  
**Cc:** pamela@yoga-legal.com; assignments@lkkauto.com  
**Subject:** FW: Pre-repair inspection: Our Ref : CY.SME810Z.19.SK.wp(PT) Your Insured Vehicle GX7484G (CLAIM REF: SNM19D202508C02/4)  
**Attachments:** 20190607113826.pdf

WITHOUT PREJUDICE

Dear Winnie,

FYI. Thanks.

Regards,

**Elaine Cheong**  
Executive (Motor Claims)  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6530  
Fax: 6224 7478 / 6224 7175  
Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Elaine Cheong  
**Sent:** Monday, 10 June, 2019 1:48 PM  
**To:** 'pamela@yoga-legal.com' <pamela@yoga-legal.com>; assignments@lkkauto.com  
**Subject:** FW: Pre-repair inspection: Our Ref : CY.SME810Z.19.SK.wp(PT) Your Insured Vehicle GX7484G (CLAIM REF: SNM19D202508C02/4)

WITHOUT PREJUDICE  
SAVE AS TO COSTS

Dear Pamela,

We refer to your email of 07.06.19.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below with attachment and liaise with third party workshop accordingly.

Thank you.

Regards,

**Elaine Cheong**

Executive (Motor Claims)

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID 6389 6530

Fax: 6224 7478 / 6224 7175

Email: [elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)

Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

---

**From:** Claims Dept of CTI

**Sent:** Friday, 7 June, 2019 11:54 AM

**To:** Elaine Cheong <[elaine.cheong@sg.cntaiping.com](mailto:elaine.cheong@sg.cntaiping.com)>; [pamela@yoga-legal.com](mailto:pamela@yoga-legal.com)

**Cc:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Subject:** FW: Pre-repair inspection: Our Ref : CY.SME810Z.19.SK.wp(PT) Your Insured Vehicle GX 7484G

Dear Elaine,

Please conduct PRS – TP: SME810Z (SNM19D202508) soonest possible.

File with OIC – Elaine - 63896530

**From:** Pamela Pamela [<mailto:pamela@yoga-legal.com>]

**Sent:** Friday, 7 June 2019 11:40 AM

**To:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>

**Subject:** Pre-repair inspection: Our Ref : CY.SME810Z.19.SK.wp(PT) Your Insured Vehicle GX 7484G

Dear Sirs,

We enclosed herewith our letter (Pre-repair Inspection) dated 07 June 2019 for your attention and information.

Best regards,

Pamela

C.YOGARAJAH LLC

---

This email has been scanned by the Symantec Email Security.cloud service.

For more information please visit <http://www.symanteccloud.com>

---

Our Ref : CY.SME810Z.19.SK.wp(PT)  
Your Ref : Your Insured Vehicle **GX 7484G**

07 June 2019

**Kong Tyre & Battery Services**  
**C/O China Taiping Insurance (Singapore) Pte Ltd**  
(The Motor Claims Department)  
105 Cecil Street  
#20-00 The Octagon  
Singapore 069534

**BY EMAIL**

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS  
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD  
TRAFFIC ACCIDENT INVOLVING SME 810Z & GX 7484G ON 04.06.2019 @ 15:45HRS ALONG  
AYE EXIT CLEMENTI AVE 2**

We are instructed by Low Chi Siang to notify you of a road traffic accident on **04.06.2019 & 15:45hrs** Along **AYE Exit Clementi Ave 2** involving our client's vehicle registration number **SME 810Z** and vehicles **GX 7484G** driven by your insured / you / authorised driver at the material time. A copy of the Singapore accident statement is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:

2. Lee Kok Weng
3. Seah Kwang Boon

As the appointed workshop is a small workshop, we are unable to provide you with more than the above listed motor surveyors. We trust you will able to choose a surveyor from above.

Yours faithfully,



**C.YOGARAJAH LLC**  
Enc

cc: M/s. SK Garage  
7 Soon Lee Street  
#01 – 31 ispace  
Singapore 627608  
Contact: Jonathan (8588 1117)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9193G
Vehicle Details	
Vehicle No.:	SME810Z
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC TYPE-R 2.0 M
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	K20A5803654
Chassis No.:	FD21203539
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$27,654.00
Original Registration Date:	15 Jan 2008
First Registration Date:	15 Jan 2008
Transfer Count:	5
Actual ARF Paid:	\$30,420.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Dec 2027
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$51,850.00
COE Rebate Amount:	\$44,351.00
Total Rebate Amount:	\$44,351.00
Message	

Transfer of ownership or deregistration is not allowed for this vehicle.

The information contained herein is correct as at 11 Jun 2019

OK

76,000  
44,351  

---

31,649



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/06/2019 17:18
Date Of Accident	04/06/2019 15:45
Exact Location Of Accident	ALONG AYE EXIT CLEMENTI AVE 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME810Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LOW CHI SIANG
NRIC No	S8319193G
Email Address	LCS@BESPOKEID.SG
Mobile Phone No	(LOCAL) +65-85222633
Alternative Phone No	Office-NOPHONE

### Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-2.0 TYPE-R (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA436733
Cover Note Number	

### Driver

Name of Driver	LOW CHI SIANG
NRIC No	S8319193G
Date Of Birth	21/06/1983
Occupation	INDOOR
Date Of Driving Pass	09/01/2010
Driving Experience	9 YEARS AND 4 MONTHS



Gender	MALE
Mobile Number	(LOCAL) +65-85222633
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	LCS@BESPOKEID.SG
Address	14 ANG MO KIO CENTRAL 3 #11-24
Postcode	567747
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	Name: : BRIAN ANTHONY YAP Gender: : Male

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TECK GHEE NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 321 ANG MO KIO STREET 31 , POSTCODE: 560321 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4599999 - FAX NO: 64574478
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT T/20190605/2056

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX7484G
-----------------------------	---------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ERIC KONG

NRIC/Passport Number

S0225987G

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

BRIAN ANTHONY YAP

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SME810Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

**DETAILS OF INJURED PERSON 2**

Name

LOW CHI SIANG

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SME810Z

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

I AM AWARED THAT MY INSURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

# SKETCH PLAN



A-SME8102

B-GX7484G

AYE Exit Clementi Ave 2

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to T/20190605/2056

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

☐ Claim own policy  
☐ Claim third party  
☒ Claim OD (TP) at other works hop SK Gang?  
☐ For record purpose  
Policy No. GA436733  
Insurer AXA Veh.No. SME8102

ACKNOWLEDGE



**POLICYHOLDER ACKNOWLEDGEMENT FORM**

Date: 06/06/2019

To: Owner of Vehicle Number: SME8102

The following has been advised to you via your workshop, Sing Ah Teo Motor & Cycle through their staff, Boyle

Please tick the applicable box if you had been advised on any of the following:

- ☒ You had been advised by the workshop that in the case that you wish to claim against your own policy, there is a Fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.
- ☐ You had been advised by the workshop on the liability and merits of the case accordingly.
- ☒ You had been advised by the workshop on the claims procedure for the type of claim that you will be making due to this accident.
- ☐ There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to indent it from overseas.
- ☐ There will be no cancellation/withdrawal of the Own Damage claim once the order of spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.
- ☐ The estimated waiting time for the spare parts to arrive is \_\_\_\_\_. The estimated arrival time does not include the repair period.
- ☐ You will be driving the vehicle out despite being advised by the workshop mechanic/ personnel that the vehicle may not be road worthy.
- ☐ For vehicles below three (3) years old or under warranty with a local distributor, your insurance company will use only original parts to repair your vehicle.
- For vehicles above three (3) years old and no longer under warranty with a local distributor, your insurance company will be carrying out repairs where any damaged part that can be repaired will be repaired and any part that needs to be replaced will be replaced using any combination of original parts and/or original equipment manufacturer (OEM) parts and/or second-hand parts.
- ☐ You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.
- ☐ For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.
- ☐ Others \_\_\_\_\_

Signed and acknowledged by:

Name and signature of policyholder/ authorized driver\* and company stamp (where applicable)

\*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial vehicles, permitted drivers who are permitted to drive the insured Vehicle.

Name and signature of workshop personnel including company stamp

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8319193G

Name: LOW CHI SIANG (LIU ZHIXIANG)

Birth Date: 21 Jun 1983

Issue Date: 10 Jan 2011

10019271558

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8319193G

LOW CHI SIANG (LIU ZHIXIANG)

刘治翔

Race: CHINESE

Date of Birth: 21-06-1983

Sex: M

Country of Birth: SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 3500kg 09 Jan 2010

Licence No: S8319193G

NRIC No: S8319198G

Date of issue: 02-05-2006

14 ANG MO KIO CENTRAL 3 #11-24 SINGAPORE 567747

NRIC No: S8319193G

Date: 02/12/2018

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190605/2056

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

1 of 3  
Report No. T/20190605/2056

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 05/06/2019 15:38		Vide Report No.:		Station Diary No.: 25	
<b>Informant's Particulars</b>					
Name of Informant: LOW CHI SIANG			Address: 14 ANG MO KIO CENTRAL 3 #11-24 SINGAPORE 567747		
ID Type / ID No.: NRIC NO / S8319193G			Contact No.: Home/Office: Mobile: 85222633		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 35	Date of Birth: 21/06/1983	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Interior designer			Driving Licence Information: Class: 3 Date of Expiry:		

<b>General Information of the Accident</b>					
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 04/06/2019 15:50	Type of Location:	
Location: Along Road 1 AYER RAJAH EXPRESSWAY CLEMENTI AVENUE 2 Exit 10A slip road into Clementi Avenue 2 near Nan Hua Primary School.					
Weather: Clear		Road Surface: Dry		Road Speed Limit:	
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GX7484G	Van				Slightly Damaged	0
SME810Z	Car	HONDA	CIVIC TYPE-R 2.0 M	White	Seriously Damaged	1

<b>Details of Vehicle Insurance</b>				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SME810Z	AXA INSURANCE SINGAPORE PTE LTD	GA436733	16/01/2019	15/01/2020





**SINGAPORE  
POLICE FORCE**



T/20190605/2056

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

2 of 3

Report No. T/20190605/2056

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	ERIC KONG	ID No.	S0225987G
Related Vehicle	GX7484G (Van)	Contact No.	97765053
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	LOW CHI SIANG	ID No.	S8319193G
Related Vehicle	SME810Z (Car)	Contact No.	85222633
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	05/06/2019	Date Discharge	05/06/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On 4/6/19 at about 1550hrs, I was driving my car along AYE. When I was at the 10A Exit slip road moving off into Clementi Avenue 2, suddenly this van came from behind and collided into the rear of my car. We did not suffer any injury during the time of the incident. My car suffered a big dent at the rear and the rear wheels were jammed. My car had to be towed away. The van suffered a dent on the front and the driver drove away after the incident. There is no car camera in my vehicle. On 5/6/19 at about 1000hrs, I felt pain on my back, neck, and right knee after waking up, thus I went to Mount Alvernia Hospital and was given 5 days' MC. I contacted my passenger colleague and he informed that he was also suffering from neck and back pain after waking up and would be proceeding to see doctor at a later time.



**SINGAPORE  
POLICE FORCE**



T/20190605/2056

Police Station Of Origin:  
Teck Ghee NPP  
321 Ang Mo Kio Street 31 SINGAPORE  
560321  
Tel No: 1800-4599999

3 of 3

Report No. T/20190605/2056

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 ONG KOK CHUAN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

05/06/2019 15:38

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt ONG YONG HOCK

Contact No.: 65476436

Classification Of Case:

SN 085

Authentication Stamp

NP168



Signature:

Singapore Police Force

## ...CLAIM SUBFOLDER...(Pending for Survey Report)































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		10 Jun 2019 14:31 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



















































  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	LOW CHI SIANG, ID: S8319193G								
Vehicle Reg. No.:	SME810Z	Date of Loss:	04/06/2019 15:00 - :59 [136 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202508C02	Policy/Cover Note No.:	DMCVSN1654821802						
Vehicle Reg. No. (Insured):	GX7484G	Policy No. (Claimant):	GA436733						
		Excess:	S\$0.00						
Repairer:	Sk Garage Motorsports - Soon Lee (HQ) 5 SOON LEE STREET, #01-34, 627607 Pioneer - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 19/06/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**\*SME810Z (SNM19D202508C02)**  
**[GX7484G]**  
**TP**  
**LOW CHI SIANG**  
**Jun 4 2019 3:00PM**  
**[-]**  
**Sk Garage Motorsports - Soon Lee**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>		
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	06/06/19 18:11	<b>Accident Statement</b>	 Load HTM		
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
3	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
4	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
5	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
6	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
7	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
8	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
9	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
10	06/06/19 18:10	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
2	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
3	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
4	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
5	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
6	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
7	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
8	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
9	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
10	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
11	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
12	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
13	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
14	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
15	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
16	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
17	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
18	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	
19	17/06/19 14:03	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
20	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/06/19 14:03	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 14:03	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/06/19 14:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/06/19 14:31	PRS - SME810Z		Load PDF	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	06/06/19 18:10	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	06/06/19 18:11	ACKNOWLEDGE [Linked Accident Report Documents]		Load TIF	
3	06/06/19 18:11	IC,DL [Linked Accident Report Documents]		Load TIF	
4	06/06/19 18:11	POLICE REPORT [Linked Accident Report Documents]		Load TIF	

## Linked Accident Report Documents

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	06/06/19 18:11	Accident Statement		Load HTM	
				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	06/06/19 18:10	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)		Thumbnail	Print
1	06/06/19 18:10	Sketch Plan		Load TIF	
2	06/06/19 18:11	ACKNOWLEDGE		Load TIF	
3	06/06/19 18:11	IC,DL		Load TIF	
4	06/06/19 18:11	POLICE REPORT		Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset Save Print
There are no document checklists configured.	
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI19010142/R1CD3E2

Date: 20/06/2019

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1654821802

Claimant Vehicle  
No: SME810ZInsured Vehicle  
No: GX7484G

Date of Loss: 04/06/2019

Nature of Claim: TP

Claim  
No: SNM19D202508C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SME810Z

Make &amp; Model: HONDA CIVIC, 2.0 TYPE-R (M)

Reg. Date: 15/01/2008 (Man. Year: 2007)

Colour: White

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: K20A5803654

Chassis No: FD21203539

Odometer: 257501 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/40 R17

Front Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Tyre Size: 245/40 R17

Rear Left Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

7 SOON LEE STREET #01-31

Repairer : Sk Garage Motorsports - Soon  
Lee (HQ)

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000.00 -\$10,000.00

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 20 Jun 2019)

**Parts:** 144      HONDA CIVIC 2.0 TYPE-R (M) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SME810Z)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >