



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/06/2019

User ID : GohKK2

Section A - Accident Details

Registration Number	SG5608S
Case Reference Number	BUS/05/19/7033
Registration Date	6/6/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Teo Poh Wat
Type of Accident	Side Swipe
Accident Date and Time	27/5/2019 11:35 AM
Accident Reported Date and Time	28/5/2019 4:16 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG5608S - RIGHT CENTRE TO REAR PORTION XD9274L (TP) - INSURED WITH CHINA CHAIN COLLISION
Prepared Date and Time	3/6/2019 3:31 PM
Chassis Number	WMAA95Z3G7003455
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,770.00	\$0.00
Total Spray Cost	\$728.00	\$0.00
Total Spare Part Cost	\$6,901.10	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$12,399.10	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	
Prepared / Adjusted By	Kok Khoo Goh	
ARC / Surveyor Sign Off Date	04/06/2019 1:24 PM	
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/06/2019

User ID : GohKK2

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS		\$4,770.00 3710							
Total Labour		\$4,770.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS		\$728.00 616							
Total Spray Painting & Panel Beating		\$728.00							
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		G20 07.04.26 1 22	SIDE PANEL R8	1.00	\$537.50	10.00	\$483.75	Replace	/ DD
		124-2-2-001-042	WHEELARCH TRIM	1.00	\$250.00	10.00	\$225.00	Replace	/ DD
		G20 05.14.16	SIDE GLASS R11	1.00	\$425.00	10.00	\$382.50	Replace	/ DR
		G20 05.14.17	SIDE GLASS R12	1.00	\$641.00	10.00	\$576.90	Replace	/ BR
		AOTH-0226-00	WINDOW CAPPING L2780	1.00	\$550.00	10.00	\$495.00	Replace	/ DD
		AOTH-0227-00	WINDOW CAPPING 990mm	1.00	\$488.00	10.00	\$437.40	Replace	/ DD
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	/ APC
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	/ APC
4006314			SEALANT SIKAFLEX	12.00	\$37.00	0.00	\$444.00	Replace	/ APC
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	/ APC
		81-45303-0345	TYRE RIM	1.00	\$2,560.06	10.00	\$2,304.05	Replace	/ DD
			TYRE	1.00	\$1,325.00	10.00	\$1,192.50	Replace	/ TN
Total					\$7,171.56		\$6,901.10		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:
Date:

Hwee Jie - LKK
7/6/19
P6/SP 9 days.
2



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/08/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG5808S
Case Reference Number	BUS/05/19/7033
Registration Date	6/6/2017
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Teo Poh Wat
Type of Accident	Side Swipe
Accident Date and Time	27/5/2019 11:35 AM
Accident Reported Date and Time	28/5/2019 4:16 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101882
Special Instruction to ARC, if any	SG5808S - RIGHT CENTRE TO REAR PORTION XD8274L (TP) - INSURED WITH CHINA CHAIN COLLISION
Prepared Date and Time	3/6/2019 3:31 PM
Chassis Number	WMAA95ZZ3G7003455
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$4,770.00	\$3,710.00
Total Spray Cost	\$728.00	\$616.00
Total Spare Part Cost	\$6,901.10	\$6,901.10
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$12,399.10	\$11,227.10
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	12.0	9.0
Prepared / Adjusted By	Kok Khoon Goh	Hwee Jie
ARC / Surveyor Sign Off Date	04/06/2019 1:24 PM	07/06/2019 2:28 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 19/08/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$4,770.00	\$3,710.00
Total Labour	\$4,770.00	\$3,710.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$728.00	\$616.00
Total Spray Painting & Panel Beating	\$728.00	\$616.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		G20.07.04.26.122	SIDE PANEL R8	1.00	\$537.50	10.00	\$483.75	Replace	Replace
		124-2-2-001-042	WHEELARCH TRIM	1.00	\$250.00	10.00	\$225.00	Replace	Replace
		G20.05.14.16	SIDE GLASS R11	1.00	\$425.00	10.00	\$382.50	Replace	Replace
		G20.05.14.17	SIDE GLASS R12	1.00	\$641.00	10.00	\$576.90	Replace	Replace
		AOTH-0226-00	WINDOW CAPPING L2780	1.00	\$550.00	10.00	\$495.00	Replace	Replace
		AOTH-0227-00	WINDOW CAPPING 995mm	1.00	\$486.00	10.00	\$437.40	Replace	Replace
			STICKER SG LOVE	1.00	\$200.00	0.00	\$200.00	Replace	Replace
4006315			ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314			SEALANT SIKAFLEX	12.00	\$37.00	0.00	\$444.00	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
		81.45303-0345	TYRE RIM	1.00	\$2,560.06	10.00	\$2,304.05	Replace	Replace
			TYRE	1.00	\$1,325.00	10.00	\$1,192.50	Replace	Replace
Total					\$7,171.56		\$6,901.10		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									