

A&S REC. BY:

REF: CS3 / C12 19010175 / JC d307

Special Instruction:

Surveyor: Hwa Jie

ASSIGNMENT (Office)

From (Person): chong Boon Sen

of C12

Date/Time: 10.6.19 15.39P.M

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBE 533D

Insured:

SLW 1237P

at Workshop m/s Eng Soon Pannang

Tel:

67 606271

of 3939 woodland Road

Policy No: DMPCSA 3612 9519011

Claim No:

SNM 1901025 2808

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10.6.19 3.41P.M

Person Contacted:

Mr Teo

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (X)
	PBE 533D - X	
	SLW 1237P - X	
	Dismantle: 12/6/2019	

ASSIGNMENT

From:

Date: 11.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBE 533Dat Workshop n/s Eng soon Paintingof 3931 Woodlands Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

2.2k \$500/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

rup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBE533DYr Regn: 28 Oct 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BajajPulsar 200 DTS-1

c.c.

200

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

99999

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MD2DHJCZZSCC4222

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 100/70-17R: 120/80-17BS / DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

-

mm

L/Bal.

-

mm

B.O.A

6/6/19

D.O.I.

11/6/19

Survey held at

Eng SoonDes. of Damages: Tr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRSWill email GIA.\$1,500 - \$2,200Range: ~~\$2500~~ ~~\$3500~~3 days.26/6/2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

150

Transportation:

S + RS, SI

Photos

Other:

TOTAL

150

Report Format :

PRS

Lump Sum / I.B.I. (\$))

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jun 2019		10 Jun 2019 15:39 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	MOHAMMAD NAHAR BIN HASSAN		
Vehicle Reg. No.:	FBE533D	Date of Loss:	06/06/2019 00:00 - :59
Claim Type:	TP / SNM19D202528C02	Policy/Cover Note No.:	DMPCSN30129519011
Vehicle Reg. No. (Insured):	SLW1237P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3454G
Vehicle Details	
Vehicle No.:	FBE533D
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	BAJAJ
Vehicle Model:	PULSAR 200 DTS-I
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	JCGBSC72613
Chassis No.:	MD2DHJCZZSCC44222
Maximum Power Output:	-
Open Market Value:	\$1,652.00
Original Registration Date:	28 Oct 2009
First Registration Date:	28 Oct 2009
Transfer Count:	7
Actual ARF Paid:	\$248.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2019
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$931.00
COE Rebate Amount:	\$75.00
Total Rebate Amount:	\$75.00

The information contained herein is correct as at 26 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/06/2019 11:57
Date Of Accident	06/06/2019 07:45
Exact Location Of Accident	ALONG DAIRY FARM ROAD TO UPP BUKIT TIMAH LP26
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBE533D
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD NAHAR BIN HASSAN
NRIC No	S9533454G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81005842
Alternative Phone No	OFFICE-81005842
Vehicle Particulars	
Manufacturer	BAJAJ
Model	PULSAR-200CC DTS-I (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MSD/VMT/19-397532-CA
Cover Note Number	
Driver	
Name of Driver	MOHAMMAD NAHAR BIN HASSAN
NRIC No	S9533454G
Date Of Birth	16/09/1995
Occupation	INDOOR
Date Of Driving Pass	15/03/2018
Driving Experience	1 YEAR AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81005842
Fax Number	
Contact Number	OFFICE-81005842
Email Address	NOEMAIL

Address	BLK 216 PETIR ROAD #04-403
Postcode	670216
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - U-TURN
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BUKIT PANJANG
Police Station Address	ROAD: 1 SEGAR ROAD , POSTCODE: 677738 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW1237P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

SKETCH PLAN



A - SMF 5147S
B - SGB4154U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report attached

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Driver's Signature

(If driver is not the policyholder)

Reporting Centre Personnel's Signature

Name



SINGAPORE POLICE FORCE



1/20190607/2102

Police Station Of Origin

Bukit Panjang N.P.C

1 Blegit Road #01-05 SINGAPORE 677738

Tel No. 1800-8929899

2 of 3

Report No. 1/20190607/2102

CONTINUATION OF REPORT

Details of Person Involved

Any Pedestrian Involved No

No. of Pedestrians Injured NIL

Use of Pedestrian Crossing NA

Rider

Name	MOHAMMAD NAHAR BIN HASSAN	ID No.	S9533454G
Related Vehicle	FDE533D (Motorcycle)	Contact No.	81005842
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class 2B Date of Expiry NIL
Date Treatment	06/06/2019	Date Discharge	06/06/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Driver

Name	MITA HIROKO	ID No.	S7178372C
Related Vehicle	SLW1237P (Car)	Contact No.	96579975
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 06/06/19 at 0745hrs, I was travelling along Dairy Farm road towards Upper Bukit Timah road. Suddenly, one vehicle SLW1237P, did a u-turn near lamppost 26. As such, I did an emergency brake and as a result, my motorcycle self skidded. I hit onto the said vehicle rear bumper.






































...CLAIM SUBFOLDER...(Pending for Survey Report)






























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jun 2019		10 Jun 2019 15:39 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	MOHAMMAD NAHAR BIN HASSAN								
Vehicle Reg. No.:	FBE533D	Date of Loss:	06/06/2019 00:00 - :59 [115 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D202528C02	Policy/Cover Note No.:	DMPCSN30129519011						
Vehicle Reg. No. (Insured):	SLW1237P	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Eng Soon Painting Services (HQ) 393J WOODLANDS ROAD, 677978 Woodlands - Tel: 67606271								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 19/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBE533D (SNM19D202528C02)
[SLW1237P]
TP
MOHAMMAD NAHAR BIN HASSAN
Jun 6 2019 12:00AM
[-]
Eng Soon Painting Services

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
2	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
3	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
4	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
5	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
6	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
7	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
8	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
9	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
10	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
11	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
12	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
13	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
14	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
15	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
16	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
17	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
18	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
19	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
20	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
21	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
22	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
23	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
24	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
25	12/06/19 09:18	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
27	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	26/06/19 16:45	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/06/19 15:40	PRI CONTACT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119010175/JCD3E2

Date: 27/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN30129519011

Claimant Vehicle
No : FBE533DInsured Vehicle
No : SLW1237P

Date of Loss: 06/06/2019

Nature of Claim: TP

Claim
No: SNM19D202528C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBE533D

Make & Model: BAJAJ PULSAR, 200cc DTS-i (M)

Engine No: JCGBSC72613

Reg. Date: 28/10/2009 (Man. Year: 2009)

Chassis No: MD2DHJCZZSCC44222

Colour: Black

Odometer: 99999 km

Engine Capacity: 199 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/70-17

Rear Tyre Size: 120/80-17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 11/06/2019 Inspected At:

Eng Soon Painting Services (HQ)
393J WOODLANDS ROAD
Singapore 677978

Estimated Period of Repair: 3.0 days

Adjuster: ONG HWEE JIE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,800.00 - \$2,200.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 27 Jun 2019)	
Parts:	N/A	BAJAJ PULSAR 200cc DTS-i (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE533D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >