

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305300667
Date : 4-6-19
Time of Fax: 0900hr

Via Fax : 62962706
Your Insured: SDE 83L
Date of Acc : 31-5-19

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

6761E

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811	} Fax no. 6546 8156
◆ Larry Ng Nyuk Phin	Tel: 6214 8316 or HP: 9230 2824	
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
◆ Fauzy Bin Mokhtar	Tel: 6214 8319 or HP: 8125 9176	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

FAUZY

for Vice President
Crash Repairs & Claims Recovery

Reply | ▾ Delete Junk | ▾ ...

Y ref:- 18/19/19/VP05/021902 O ref:- SH 6761E - Accident Involving SH 6761E & SDE 83L on 31/05/19 (External General)

Kazali Haji Selahudin

Thu 6/6/2019 3:05 PM

To: Ong Li Li - LonPac <llong@lonpac.com>

Cc: Fauzy Bin Mokhtar; ▾ Lim Kwok Eng ^

🔄 📧 Reply | ▾

Inbox

This message was sent with high importance.



📎 Show all 8 attachments (4 MB) Download all Save all to OneDrive - ComfortDelGro Corporation Limited

Dear Li Li,

We refer to your email of 06/06/19 (@ 1255 PM).

We attach the photos as requested. As this is a head to rear collision, we are unable to send you the VF. We also attach the scene photos for your easy reference.

Kindly assist to finalise the figure or alternatively arrange for our taxi to be surveyed by your appointed surveyor before we proceed with repairs. Thank you.

Best Regards

Kazali Hj Selahudin

Claims Department / ComfortDelGro Engineering Pte Ltd

Off: 6214 8736 / Fax: 6214 1843

06.49:27

ONG LI LI


From: ONG LI LI
Sent: Thursday, 6 June, 2019 12:55 PM
To: 'fauzybm@cdge.com.sg'
Cc: MT_Claim_SG
Subject: Your Ref: SH6761E Our Ref: 18/19/19/VP05/021902 Accident involving SDE83L and SH6761E on 31.05.19 [External General]

Lonpac External - General
Without Prejudice

Our Insured has not reported the accident.

Please provide colour photographs of your taxi showing the damages and video footage.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

ApeosPort-IV C5570

Transmission Report

G3-ID
Local Name
Company Logo

Date & Time : 04/06/2019 9:05
Page : 1 (Last Page)

The job has been sent.
Original Size: A4

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508959

LONPAC

Our Ref : 305300667
Date : 4-6-19
Time of Fax : 0900hr

Via Fax : 62962706
Your Insured : SDE 83L
Date of Acc : 31-5-19

Attn: Motor Claims Department

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH 6761E

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident

In accordance to the motor claims framework, we hereby request your presence at 58 Loyang Drive, Singapore 508959 to survey our client's damaged vehicle.

Enclosed, please find:

- Our Initial estimate of repairs of the damaged vehicle;
- Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

- Lim Kwok Eng Tel: 8214 8355 or HP: 9824 0811
 - Larry Ng Nyuk Phin Tel: 8214 8318 or HP: 9230 2824
 - Lim Tien Siong Tel: 8214 8398 or HP: 9835 6548
 - Chiang Liat Choon Tel: 8214 8314 or HP: 8298 6008
 - Jumani Bin Masudin Tel: 8214 8315 or HP: 9635 6305
 - Fauzy Bin Mokhtar Tel: 8214 8319 or HP: 8126 9176
- } Fax no. 6548 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.

Thank you.

Yours faithfully

FAUZY

for Vice President
Crash Repairs & Claims Recovery

#	Job	Remote Station	Start Date & Time	Duration	Pages	Protocol	Contents	Status
1	1627	62962706	6- 4; 9:03	1:10	9/9	Super G3		Completed