COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE
VEHICLE NO: SH 6761E

REAK

LUNDAC

4/6/2019 8:38

MAKE

| | PARTS DESCRIPTION | QTY | UNIT PRICE | A | MOUNT | |
|----|---------------------------------------|------------|--|----------------|----------|----------|
| Į. | REAR BUMPER X 14 1- | | | \$ | 458.60 | 0 |
| 1 | REAR BUMPER UNDER COVER | | | \$ | 552.60 | 0 |
| | REAR BUMPER SIDE RETAINER ★ | | | \$ | 112.70 | 0 |
| | REAR BUMPER CLIPS × | | | \$ | 22.00 | |
| | KEAK BOIM EK OEM O | | | | | |
| | SUB TOTAL | | | \$ | 1,145.90 | |
| | | | | | | - 1 |
| | LESS 25% | | | \$ | 286.48 | \neg |
| | DISCOUNTED TOTAL | | | \$ | 859.43 | 3 |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | REAR BUMPER REVERSE SENSOR X | | | \$ | 135.70 | 0 1 |
| | REAR BUMPER RUBBER MAT | | | \$ | 50.00 | 0 |
| | | | | | | |
| | | | | \$ | 185.70 | |
| | | | | Ψ | 100.70 | \dashv |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | LABOUR CHARGE | | | | 200 | |
| | Panel Beating | | | \$ | 400.00 | 0 |
| | Spray Painting Charge | | | \$ | 300.00 | 0 3 |
| | Wiring Charge | | | \$ | 30.00 | U) |
| | Remove/Refix Reverse Sensor | | | \$ | 80.00 | 0) |
| | TOTAL LABOUR | | | \$ | 810.00 | 0 |
| | 101/12 2/2001 | | | - | 010.00 | |
| | ESTIMATE TOTAL | | | \$ | 1,855.13 | 3 |
| | | | | | -1 | |
| | 61:111 | | ance no | tify | \ | |
| | Call 1000 | LVK AUD | Consultants hence no | | \ | |
| | 11 | the Rep | Consultants flerior pirer of the following: yey before after spray painting to | ng no invev | | |
| | 1/ 2/6/19 1/10 5 | • To resur | sirer of the following way before after spray painting way damaged part(s) during way damaged part(s) during ways are subject to confirmations are subject to confirmations. | tion | is | |
| | // // // // | . TO 000 | was are subject to co | e ejudice | , pazia | |
| | 2.1 | . Third | party survey is on a | d | and | |
| | Kaki 111115 8/ 2/6/19 11106 2km | · No I | party survey is on a "yyuloo party survey is on a "yyuloo pala modification(s) is silowe ementary item(s) must be to ementary item(s) must be to ementary item(s) must be to ementary item(s). | surance | Combana | |
| | pro per pl | . 507 | med to final approve | | 1 | |
| | f T | 15.0 | owledged by Repairer | | | 1 |
| | A 1 1 1/1. | ACK | CMI6030 | | | 1 |
| | 111. 1/20 1015 | 1 | ature: | | 1,000 | |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.