SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	06/06/2019 14:11
Date Of Accident	06/06/2019 00:45
Exact Location Of Accident	ECP(CITY) AFTER STILL ROAD EXIT
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	XE320R
Insured/Policyholder	
Name Of Registered Owner	CHYE THIAM MAINTENANCE PTE LTD
Co Reg No	198801700E
Email Address	DARREN@COMPLETEVMS.COM.SG
Mobile Phone No	(LOCAL) +65-87814020
Alternative Phone No	OFFICE-NOPHONE
Vehicle Particulars	1,111
Manufacturer	NISSAN
Model	CWB4CLL00058-13.1 D (M)
Exact Purpose for which vehicle was being used a time of accident	t COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5108281586
Cover Note Number	
Driver	
Name of Driver	OH BOON CHYE
NRIC No	S6838965H
Date Of Birth	03/10/1968
Occupation	OUTDOOR
Date Of Driving Pass	25/06/2002
Driving Experience	16 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87814020
Fax Number	
Contact Number	

DARREN@COMPLETEVMS.COM.SG

Address

109 ANG MO KIO AVE 4 #10-10 SINGAPORE

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

2

Number of vehicles (including own vehicle) involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

NO

1

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

Police Station Name

HOUGANG NEIGHBOURHOOD POLICE CENTRE

Police Station Address

ROAD: 60 HOUGANG AVE 9, POSTCODE: 538775, COUNTRY:

SINGAPORE

Police Station Contact

TEL NO: 1800-4890999 - FAX NO: 63128989

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

FILE SIZE TOO BIG

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC667R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Passenger 1

2

NAME:

GENDER:

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHC667R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GtA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose of the purpo
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary
 investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - [lii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve displayer of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' (awyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile daims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, low enforcement and government agencies as reasonably required for the purposes stated, or
 - (II) for complying with requirements under any regulations, laws or court orders.

* ~//


Policyholder's Signature Date & Time: Oriver's Signature
(If driver is not the policyholder)
Date & Time: 06/06/ 20/8

0300

Reporting Centre Personnel's Signature Name: 19-19(1) LIH

NRIC/FIN No.: SBE34 CS JA

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ESCHIBE CIN	COMPTANACES OF	THE ACCIDENT						
co th	e 06106	+2 P10C	around	48400	né —	l <i>ઇ</i> વક	travelli	<u>, 9</u>
24 a	20869 02	6kph pr	ouding	30शि <u>य</u>	Consuc	<i>ું</i> લ્ક ક	-pr- my	
ভোধিবনুদধ্য	ansad.	subseq	vently,	the.	ナロメ	LEGIL	ensite	wid
vehicle	1 might	be seein	g mid	ו'כבן ב-	liention	7.5	1 am	
feeling	canael) 9	Hen the	qaid in	٠	7			
				- Control of the Cont				
(4.94)	W							
							1	

DECLARATION

I/We declare the foregoing particulars are true in every respect.

*. 6l

Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)
Date & Time: o6/o6/ 50/S
03.00



Reporting Centre Personnel's Signature Name: (GHOTIN) 2171 NRIC/FIN No.: 58534652A





Damaged Seriously

Damaged

1 of 3

Report No. T/20190606/2018

Police Station Of Origin: Hougang N.P.C 60 Hougang Avenue 9 SINGAPORE 538775 Tel No: 1800-4890999

TAXI

Lorry

SHC667R

XE320R

Date/Time Report Made: 06/06/2019 03:39			Vide Report No.:				Station Diary No.: 12		
	777	new week.							
Informant's Particulars Name of Informant: OH BOON CHYE		Address: APT BLK 109 ANG MO KIO AVENUE 4 #10-10 SINGAPORE 560109							
ID Type / ID No.: NRIC NO / \$6838965H			Contact No.: Home/Office: Mobile:				: 87814020		
Nationality: SINGAPORE CITIZEN			Email:						
Sex: Male	Age: 50	Date of Birth: 03/10/1968	Type of Informant: Driver					sheed Name:	
Race: Chinese	ace:			Language.			tion / School Name:		
Occupation: Other car and light goods vehicle drivers nec				Driving Licence Information: Class: 3,4,5 Date			of Expiry:		
eneral in Type of Accident:		n of the Accident Ion-Injury		Drink Drive: No	Date/Tim Accident 06/06/20			Type of Location	
Location: Along Roa EAST CO	ad 1 AST PAR	KWAY						8	
Along ECP towards MCE Weather:		Road	Road Surface:				Road Speed Limit:		
Traffic Flow			Traffic Control:				Traffic Volume:		
Type of Collision: Between Moving Vehicles - Head To I			Rear	Rear				Anyone conveyed by ambulance:	
Details o	f Vehicle	Involved - 5							
Vehicle N	o. Type	Make		Mode	Color	The state of the s	ngition tally	n No of Passeng 1	





2 of 3

Report No. T/20190606/2018

Police Station Of Origin: Hougang N.P.C 60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999

CONTINUATION OF REPORT

Brief Details.

On 06/06/2019 at about 0045hrs, I was travelling in my lorry (XE 320R, Truck Mounted Attenuator) escorting one my another company's lorry for picking up litter Along ECP. Everything was in order. During this time, I was slowly following the other of my company's lorry when I felt an impact after seeing a taxi speeding from the rear. It was when I realized that one taxi (SHC 667R) had crashed onto my lorry with Truck Mounted Attenuator.

I wish to state that traffic police came down to the scene. Furthermore, my lorry was damaged by the accident and after the accident, i felt giddy. This is the first time such an incident had happened and I lodging this report for record and insurance purposes. I also wish to state that I have yet to see a doctor.





Police Station Of Origin: Hougang N.P.C

60 Hougang Avenue 9 SINGAPORE 538775

Tel No: 1800-4890999

CONTINUATION OF REPORT

3 of 3

Report No. T/20190606/2018

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:	Signature Of Informant:
F / Sgt 1 ONG YU HAN	
	50
Signature Of Interpreter: Not applicable	Date/Time: 06/06/2019 03:39
8	
Officer In Charge Of Case:	Classification Of Case:
TP / GIA /	
Staff Sgt WONG SIEU LUI Contact No.: 65476151 SN 995	
Authentication Stamp NP168 Signature:	
Singapore Police Force	