

ASS. REC. BY:

REF:

CS/FCI19010198/GSD3¹²

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Joanne

of FCI

Date/Time: 10/6/2019 4:38pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: CB2883J

Insured: SHD4937E

at Workshop m/s Bedok Transport.

Tel: 62863032 Shu Den

of 30 & 32 Defu Lane 9.

82222669 De Vrien

Policy No:

Claim No: D19003753MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/5/2019

CA / REV / REP. / REV 24 HRS

12/6/2019 10:15am

H.O.D. Endorsement:

Date/Time: 10/6

Person Contacted: Shu Den

Vehicle IN/OUT

Date/Time	Action/Instruction Estimate ()
	CB2883J-X
	SHD4937E-X
14/06/19	@ 16:41 pm revised PA to Joanne via email.

(09/11/13)

ASS. REC. BY:

REF

Fcl

C1654W

ASSIGNMENT

From:

Date:

12/6/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

CB2883J

at Workshop m/s

Bedok Transport

of

30/33 Debu Lane 9

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

12/6/2019 10/15am.

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

CB2883J

Yr Regn:

22 Oct 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yutong ZK6930H C.C. 6693

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

127295

T/Radio:

Insured / Std / NI / NA

Eng/No:

CZ YTC TD 64C 1058250

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/70R 22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MARSHAL

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

12-06-19

Survey held at

w/s

10:30

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/10

Finalized \$2500 with Perrin.

(\$7,126.94 Red - 74%)

RECEIVED 18 OCT 2019

17/10/2019

Date/Time, File Pass to?

18/10/19

1)

Typist

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

3 + RS, \$1

Photos

Others

TOTAL

170

50

50

32

302

Report Format:

Lump Sum / I.B.I. (\$ 2,500/- U/S)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19003753MFSH

Date: 14 June 2019

Our Ref: CS/FCI19010198/Gsd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. CB 2883J

Please be informed that we had conducted the inspection of the abovementioned vehicle on 12/06/2019 at the premises of M/s Bedok Motor Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 9,626.94
Revised Estimate Amount	: S\$ 6,865.55
"Check" Items Amount	: S\$
Total	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the o/s body.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 days

Yours faithfully,
Xing Guo Qiang
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-06-2019	Our Ref No. D19003753MFSH
Accident Date	31-05-2019	Claim Type. Third Party
Insured Vehicle	SHD4937E	Third Party Vehicle. CB2883J
Survey Location	30 & 32 DEFU LANE 9	
Contact Person.	SHU WEN (MS)	
Contact No.	62863032/ 0	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	BEDOK TRANSPORT PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 14 June 2019 4:41 PM
To: 'Joanne Yong Lai fong'; 'CWS Motor Claims'
Cc: Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19003753MFSH/1
Attachments: CB 2883J - Preli Advise .pdf

Dear Joanne,

Enclosed preliminary revised of vehicle CB 2883J.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 14 June 2019 4:30 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: FW: SURVEY ASSESSMENT - D19003753MFSH/1

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Monday, 10 June, 2019 2:41 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong Lai fong <JoanneYong@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19003753MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	1654W
Vehicle No.:	CB2883J
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2019
Vehicle Make:	YUTONG
Vehicle Model:	ZK6930H
Primary Colour:	Green
Manufacturing Year:	2012
Engine No.:	ISBE425022054495
Chassis No.:	LZYTCTD64C1058250
Maximum Power Output:	-
Open Market Value:	\$92,316.00
Original Registration Date:	22 Oct 2013
First Registration Date:	22 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$4,616.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 12 Jun 2019

OK



Bedok Motor Engineering Pte Ltd
30 Defu Lane 9 Singapore 539270
<http://www.bedokmotor.com>
enquire@bedokmotor.com
+65 6286 3032

Estimate To Repair CB2883J YUTONG ZK6930H

Chassis No : LZYTCTD64C1058250

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
1	1pc	Rear wheel mudguard R/H / <i>DE</i>	\$ 1,214.13 <i>X</i>
2	1pc	Rear wheel mudguard arch garnish / <i>mis</i>	\$ 314.26 <i>X</i>
3	1pc	Rear wheel rim R/H <i>X</i> <i>NN</i>	\$ 649.75 <i>X</i>
4	1pc	Rear wheel hub cap R/H <i>X</i> <i>NN</i>	\$ 302.69 <i>X</i>
5	1pc	Side compartment door R/H <i>X</i> <i>NN</i> <i>repair</i>	\$ 1,812.72 <i>X</i>
6	1 set	Side compartment door hinge <i>X</i> <i>NN</i>	\$ 169.72 <i>X</i>
			\$ 4,463.27 <i>1528.39</i>
Less 10%			\$ 446.33
			\$ 4,016.94 <i>1375.55</i>
<u>SPECIAL NETT ITEAMS</u>			
7	1 set	Rear mudflap <i>X</i> <i>NN</i>	\$ 120.00 <i>X</i>
8	1 pc	Rear wheel tire R/H / <i>CRA</i> <i>(400 x 60%)</i>	\$ 750.00 <i>X</i> <i>240</i>
			\$ 870.00
<u>LABOUR & MISC CHARGE</u>			
1		Panel beating.	\$ 1,600.00 <i>250.700</i>
2		Spray painting.	\$ 2,800.00 <i>400.800</i>
3		To transfer of R/H wheel rim, tire and balancing.	\$ 180.00 <i>30</i>
4		To rust proof.	\$ 160.00 <i>X NN</i>
			\$ 4,740.00 <i>1530</i>
Total			\$ 9,626.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display car during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Guo Qiang
Total
Guo Qiang @lkkauto.com

3 Days.
ump sum Repair.
After repair photos.
Guo Qiang - 8288 0282
12/6/19

3/45.55
20%: 2500



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19010198/Gsd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4937E	Veh. Inspected	CB 2883J
Policy No.		Coverage (\$)	0.00
Claim No.	D19003753MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	10/06/2019
2. Vehicle Particulars & Condition			
Make & Model	YUTONG ZK6930H	c.c	6693
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	LZYTCTD64C1058250	Colour	WHITE
Odometer	127295	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	MARSHAL	6 mm
L/H Front Tyre	275/70 R22.5	MARSHAL	6 mm
R/H Rear Tyre	275/70 R22.5	MARSHAL	6 mm
L/H Rear Tyre	275/70 R22.5	MARSHAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/05/2019	Inspection Date	12/06/2019
Survey held at	BEDOK TRANSPORT PTE LTD 30/32 DEFU LANE 9 SINGAPORE 539270		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. CB 2883J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WHEEL MUDGUARD R/H	DEFORMED	1,214.13	1,214.13
1	REAR WHEEL MUDGUARD ARCH GARNISH	MISSING	314.26	314.26
1	REAR WHEEL RIM R/H	NOT NECESSARY	649.75	-
1	REAR WHEEL HUB CAP R/H	NOT NECESSARY	302.69	-
1	SIDE COMPARTMENT DOOR R/H	TO REPAIR SEE LABOUR	1,812.72	-
1	SET SIDE COMPARTMENT DOOR HINGE	NOT NECESSARY	169.72	-
	LESS 10% DISCOUNT		-446.33	-152.84
			4,016.94	1,375.55
SPECIAL NETT ITEMS				
1	SET REAR MUDFLAP (SN)	NOT NECESSARY	120.00	-
1	REAR WHEEL TIRE R/H (\$400.00)(60%)(SN)	CRACKED	750.00	240.00
			870.00	240.00
LABOUR				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF SIDE COMPARTMENT DOOR R/H.		1,600.00	700.00
	SPRAY PAINTING.		2,800.00	800.00
	TO TRANSFER OF R/H WHEEL RIM,TIRE AND BALANCING.		180.00	30.00
	TO RUST PROOF.	NOT NECESSARY	160.00	-
			4,740.00	1,530.00
GRAND TOTAL			9,626.94	3,145.55
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,500.00

Report Ref No. CS/FCI19010198/Gsd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.