

22/02/2003

ASS. REC. BY:

REF:

C83/A1919010205/11cd317

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Winnie Fan

of

A19

Date/Time:

10/6/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 5TH2Y

Insured:

SGX 2669Z

at Workshop m/s

PopMax

Tel:

6744 2653 Carmen

of Blk 3007 Ubi Rd 1 #01-410

Policy No:

Claim No:

5397895657 SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

1/6/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10/6

Person Contacted:

Cayman

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate ( )

SMK 5TH2Y - X

SGX 2669Z - X

Dismantle; 12/6/2019

After repair; 14/6/2019

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMK 5742Yat Workshop m/s Topmaxof Blk 3007 Ubi Rd 1 #01-410

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SMK 5742YYr Regn: 2016 AprilType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Harrier Premium c.c 1986Colour: BlackA/C: Insured / Std / NI / NASp. Reading: 47250T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: ZSY 600075081Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 255/45R20R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 1/6/19D.O.I. 10/6/19 4:30pmSurvey held at TopmaxDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV - 93900

PV - 55143

NV - 38700

MV - 92-93

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

180

11

191

Report Format: DAR

Lump Sum / I.B.I: (\$

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Jun 2019 <a href="#">Edit Reg</a>		11 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	SHARINITA D/O MOHD ISMAIL, ID: S7838786F		
Main Claimant:	TAN POH CHUAN, ID: S6905368H		
Vehicle Reg. No.:	SMK5742Y	Date of Loss:	01/06/2019 17:00 - :59
Claim Type:	TP / 5397895657SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SGX2669Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Topmax Auto Body Shop (HQ) Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 20/06/2019]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (12/06/2019): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

-#5397895657SG003#027# FW: PRE-REPAIR INSPECTION - ACCIDENT IN...

From: Fan, Winnie-LW  
To:  
Cc: Fong, Andy-SY, Chin, Lee-Ying  
Sent: 6/10/2019 10:44:22 AM

---

Hi LKK,

Kindly assist to survey.

Workshop detail:

We have just be informed by the workshop that our client's vehicle is only available for PRI on next Monday, 10th June 2019 after 12.30p.m.

We would appreciate if you could assist to inform your surveyors to carry out the PRI on the above-stated date and time located at:

Topmax

Auto Body Shop  
Blk 3007 Ubi Road 1 #01-410 Singapore 408701  
Contact Person: Ms Carmen Chang  
Contact No.: 6744 2653

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

**IMPORTANT NOTICE:**

*The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	5368H
<b>Vehicle Details</b>	
Vehicle No.:	SMK5742Y
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	3ZRB756849
Chassis No.:	ZSU600075081
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$31,296.00
Original Registration Date:	11 Apr 2016
First Registration Date:	11 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$30,815.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Apr 2026
PARF Rebate Amount:	\$23,111.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	10 Apr 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,000.00
COE Rebate Amount:	\$32,032.00
<b>Total Rebate Amount:</b>	<b>\$55,143.00</b>

The information contained herein is correct as at 17 Jun 2019

OK Balance : 6 yrs 10 months

Depreciation: 11.500 yrs

$11.500 \div 12 = 958 \text{ months}$

$69000 + 9580 + 15407.5$

$= 93900$

MV - 93900

PV - 55143

NV - 38700

MV - 92977

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

**HURRY, BOOK BY 12 SEPTEMBER 2019**

Book now

Toyota Harrier

Price Range

Depreciation

2016

Vehicle Type

Advanced Search

Home » Used Cars » AutoPrestige Gallery Pte Ltd » Toyota Harrier 2.0A Premium Panoramic

## Toyota Harrier 2.0A Premium Panoramic

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

**Price** \$92,500**Depreciation** \$12,070 /yr  
View models with similar depre **Reg Date** 23-Feb-2016  
(6yrs 5mths 17days COE left)**Mileage** N.A. **Manufactured** 2015**Road Tax** \$1,196 /yr **Transmission** Auto**Dereg Value** \$50,760 as of today (change) **OMV** \$29,889**COE** \$45,009 **ARF** \$28,845**Engine Cap** 1,986 cc **Power** 111.0 kW (148 bhp)**Curb Weight** 1,610 kg **No. of Owners** 1**Type of Vehicle** SUV**Features**

Reliable And Fuel Efficient 2.0A DOHC Engine, Super CVT-I Transmission, Keyless Start/Stop, Climate Control Aircon, Auto Headlights, Airbags, ABS. View specs of the Toyota Harrier (2014)

**Accessories**

Leather Seats, Sports Rims, Retractable Side Mirrors, Electric Tailgate, Reverse Camera, Panoramic Sunroof.

**Description**

Premium Model! Popular Luxury Full-Size SUV That Has Both Style And Comfort! Car As Good As New! Drop By To See It With Your Own Eyes! Flexible Loan And Competitive Insurance Packages. Excellently Maintained By Owner. Speak To Us Today! Act Fast Before It's Gone Again. Immediate Hand Over Upon Loan Approval.

**Category**

PARF Car

**Status**

Available

**Resources****Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more

**Car Valuation - Free**

Find out the market value of your existing car for free. Get started

Posted on: 04-Sep-2019 | Last Updated on: 04-Sep-2019

**Upfront Payment**

» more Financial Info

**Transfer Fee** \$25**Down Payment** \$27,750 (change)

Maximum 70% Loan


**1st** \$1,002

Based on 2.98% interest rate

Compare



Location Map

**Price Chart****Summary**

Click on the point to view the vehicle

Shortlist

Compare

Add note

Report Error

More Actions

**Seller Information**

<b>Company</b>	<b>AutoPrestige Gallery Pte Ltd</b> » dealer's pricelist » 67 vehs sold   22 vehs available
<b>Address</b>	210 Turf Club Road Lot B42/B56 Search cars nearby this location
<b>Location</b>	Car Mall @ The Grandstand
<b>Office No</b>	69098044
<b>Contact Person(s)</b>	Alex 98533834

**SINGAPORE ACCIDENT STATEMENT**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**ACCIDENT STATEMENT**

Date Of Report	04/06/2019 10:53
Date Of Accident	01/06/2019 17:10
Exact Location Of Accident	EASR COAST ROAD
Country/State of Loss	SINGAPORE

**DETAILS OF OWN VEHICLE**

Vehicle Registration Number	SMK5742Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN POH CHUAN
NRIC No	S6905368H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87677845
Alternative Phone No	OFFICE-NOPHONE

**Vehicle Particulars**

Manufacturer	TOYOTA
Model	HARRIER-2.0 PREMIUM (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

**Insurance Company**

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MS003170
Cover Note Number	

**Driver**

Name of Driver	TAN POH CHUAN
NRIC No	S6905368H
Date Of Birth	10/02/1969
Occupation	OUTDOOR
Date Of Driving Pass	12/01/1995
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87677845
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	NOEMAIL

Address	BLK 91 BEDOK NORTH STREET 4 #10-1529
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN AND POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGX2669Z <i>Toyota Corolla Autos 16 AT</i>
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1



Name

TAN POH CHUAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

BLK 91 BEDOK NORTH STREET 4 #10-1529

Postcode

460091

## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:


  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan #2

A - SM1K5742Y  
B - 86Y 2669X

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20190603/2169

Police Station Of Origin:  
Joo Chiat NPP  
267 Onan Road SINGAPORE 424773  
Tel No: 1800-3459999

1 of 4

Report No. T/20190603/2169

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 03/06/2019 18:29	Vide Report No.:	Station Diary No.: 26
--	------------------	--------------------------

<b>Informant's Particulars</b>			
Name of Informant: TAN POH CHUAN		Address: APT BLK 91 BEDOK NORTH STREET 4 #10-1529 SINGAPORE 460091	
ID Type / ID No.: NRIC NO / S6905368H		Contact No.: Home/Office: Mobile: 87677845	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 50	Date of Birth: 10/02/1969	Type of Informant: Driver
Race: Chinese		Language: Chinese	Institution / School Name:
Occupation: PERSONAL DRIVER		Driving Licence Information: Class: 3 Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/06/2019 17:10	Type of Location: Straight Road
Location: Along Road 1 EAST COAST ROAD				
Towards Upper East Coast Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGX2669Z	Car	TOYOTA	ALTIS	Red		1
SMK5742Y	Car	TOYOTA	HARRIER PREMIUM 2.0 A	Black		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date



**SINGAPORE  
POLICE FORCE**



T/20190603/2169

2 of 4

Police Station Of Origin:  
Joo Chiat NPP  
267 Onan Road SINGAPORE 424773  
Tel No: 1800-3459999

Report No. T/20190603/2169

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SMK5742Y	TOKIO MARINE INSURANCE SINGAPORE LTD.	MS003170	15/03/2019	14/03/2020

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	FARRAH D/O MOHD ISMAIL		ID No.	S9217706H
Related Vehicle	SGX2669Z (Car)		Contact No.	97346563
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	TAN POH CHUAN		ID No.	S6905368H
Related Vehicle	SMK5742Y (Car)		Contact No.	87677845
Hospital/Clinic	CASSIA CLINIC & SURGERY		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	03/06/2019		Date Discharge	NIL
No. of Days granted Medical Leave		03	Degree of Injury	NIL

**Brief Details.**

On the 01/06/2019 at about 1710hrs, I was driving along East Coast towards Upper East Road near to the Junction of I12 Katong Shopping Centre. I was waiting behind several cars as the traffic junction light was showing red.

Out of a sudden, I felt an impact from the rear of my vehicle. When I got off, I realized a Red Toyota ( SGX2669Z ) hit onto the rear of my vehicle.

I would like to state that there were no traffic police or Ambulance arrived at scene. The other does not appear to be injured at the point of time. Both of us exchange particulars and I drove off afterwards. I also state that I have a In Car camera in my vehicle.

On 03/06/2019, I felt an strain on my back area and therefore I went to see a doctor at Cassia Clinic & Surgery. I was given 3 days MC by the Doctor.



**SINGAPORE  
POLICE FORCE**



T/20190603/2169

Police Station Of Origin:  
Joo Chiat NPP  
267 Onan Road SINGAPORE 424773  
Tel No: 1800-3459999

3 of 4

Report No. T/20190603/2169

**CONTINUATION OF REPORT**



**SINGAPORE  
POLICE FORCE**



T/20190603/2169

Police Station Of Origin:  
Joo Chiat NPP  
267 Onan Road SINGAPORE 424773  
Tel No: 1800-3459999

4 of 4

Report No. T/20190603/2169

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 MICHAEL LEE CHOON WEE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

03/06/2019 18:29

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE SYED

MOHD SAID

Classification Of Case:

Contact No.: 65476172

Authentication Stamp

NP168



**SINGAPORE  
POLICE FORCE**

SIGNATURE







### ...CLAIM SUBFOLDER...(Pending for Survey Report)












































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2019 <a href="#">Edit Reg</a>		10 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>





























  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>SHARINITA D/O MOHD ISMAIL</b> , ID: S7838786F									
Main Claimant: <b>TAN POH CHUAN</b> , ID: S6905368H									
Vehicle Reg. No.: <b>SMK5742Y</b>		Date of Loss: 01/06/2019 17:00 - :59 [37 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / 5397895657SG</b>		Policy/Cover Note No.: (Comprehensive)							
Vehicle Reg. No. (Insured): <b>SGX2669Z</b>		Policy No. (Claimant):							
		Excess:							
Repairer: <b>Topmax Auto Body Shop (HQ)</b> Blk 3007 Ubi Road 1 #01-410, 408701 Ubi - Tel: 90622722									
Handling Insurer: <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 20/06/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (12/06/2019): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SMK5742Y (5397895657SG)  
[SGX2669Z]  
TP  
TAN POH CHUAN  
Jun 1 2019 5:00PM  
[SHARINITA D/O MOHD ISMAIL]  
Topmax Auto Body Shop

<a href="#">Upload Documents</a>			<a href="#">Upload Photos</a>			<a href="#">Compose New Letter</a>			<a href="#">Upload Video</a>			<a href="#">Upload Audio</a>			<a href="#">View</a>		<a href="#">View in Browser</a>		<a href="#">v</a>
<b>Photos/Images</b>															3 per page		<a href="#">v</a>	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print		
1	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
2	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
3	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
4	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
5	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
6	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
7	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
8	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
9	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
10	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
11	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
12	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
13	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
14	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
15	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
16	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
17	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
18	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
19	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
20	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
21	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
22	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
23	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
24	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
25	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
26	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
27	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
28	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
29	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
30	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
31	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
32	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
33	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
34	04/09/19 15:57	General View														Load JPG	<input checked="" type="checkbox"/>		
35	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
36	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
37	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
38	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
39	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
40	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
41	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
42	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		
43	04/09/19 15:57	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	04/09/19 15:57	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	04/09/19 15:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	04/09/19 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	04/09/19 15:58	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/06/19 09:59	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010205/T1CD3E2

Date: 16/09/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

## Claimant

Vehicle No : SMK5742Y

Insured Vehicle No : SGX2669Z

Date of Loss: 01/06/2019

Nature of Claim: TP

Claim No: 5397895657SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMK5742Y

Make &amp; Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZRB756849

Reg. Date: 11/04/2016 (Man. Year: 2016)

Chassis No: ZSU600075081

Colour: Black

Odometer: 47650 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 255/45 R20

Rear Tyre Size: 255/45 R20

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At: Topmax Auto Body Shop (HQ)  
Blk 3007 Ubi Road 1 #01-410  
Singapore 408701

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	0.00 F	*- F
2	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER LH / RH	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
5	1		*REAR BUMPER LOWER GARNISH	Crumpled	0.00 F	*- F
6	2		*REAR BUMPER REFLECTOR LH / RH	Crumpled	0.00 F	*- F
7	1		*SET REVERSE SENSOR	Shorted	0.00 F	*- F
8	1		*REAR END PANEL	Repair	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Crumpled	0.00 F	*- F
10	1		*REAR RH TAILLAMP	Crumpled	0.00 F	*- F
11	1		*TAILGATE	Repair	0.00 F	*- F
12	1		*TAILGATE EMBLEM (HARRIER)	Necessary	0.00 F	*- F
13	1		*TAILGATE EMBLEM (TURBO)	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >