

ASS. REC. BY:

REF:

CS3/AIG19010217/Gcd327

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Winnie Fan of AIG Date/Time: 10/6/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKQ 6104A Insured: SKF5522X

at Workshop in/s Motor Intelligence Tel: 62810087 hy.

of No. 13 Kari Bulat Rd 4 # 01-20.

Policy No: Claim No: 303359881686

Sum Insured: Excess:

Make of Veh: D.O.A. 6/6/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10/6 Person Contacted: hy Vehicle IN/OUT

Date/Time	Action/Instruction Estimate (X)
	SKQ 6104A - X
	SKF 5522X - X
	Disassemble: 10/6/2019
	After repair: 13/6/2019

PRS
EAL

REF:

ALG

ASSIGNMENT

(-2022)

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

Motor Intel

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SKQ6104A

Yr Regn:

28 Nov 2007

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Vios

C.C

1497

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

194154

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053HY9305042174

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

185/65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

10-06-19

Survey held at

W/S

1:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~\$2000 - \$2000~~

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

180

Transportation:

S + RS, SI

Photos

Others

TOTAL

191

Report Format :

DAR

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jun 2019 Edit Reg		11 Jun 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	TAY PENG HONG, ID: S0017275H		
Main Claimant:	UDRIVE AUTOMOBILE, Co. Reg. No.: 53396901L		
Vehicle Reg. No.:	SKQ6104A	Date of Loss:	06/06/2019 00:00 - :59
Claim Type:	TP / 3303598816SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SKE5522X	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/06/2019]		

ASSOCIATED MAIL RECEIVED	View All Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (12/06/2019): Request To Upload TP GIA Report 	

ALL ASSOCIATED TASKS	View All Search Tasks Create New Task Complete																				
<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">Due Date</th> <th style="text-align: left;">Priority</th> <th style="text-align: left;">Type</th> <th style="text-align: left;">Task Group</th> <th style="text-align: left;">Subject</th> <th style="text-align: left;">Handler</th> <th style="text-align: left;">Assigned By</th> <th style="text-align: left;">Completed On</th> <th style="text-align: left;">Created On</th> <th style="text-align: left;">Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table>	Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?												
No results.																					

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHI...

From: Fan, Winnie-LW

To:

Cc: Fong, Andy-SY, Chin, Lee-Ying

Sent: 6/10/2019 12:17:14 PM

Attachments:  SKQ 6104 A - LTA Search.pdf  SKQ 6104 A - AIG SJE list.pdf

Hi LKK,

Kindly assist to survey.

Winnie Fan

AIG

Claims Service Associate

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

XGQ

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKE5522X AND SKQ6104A ON 06/06/2019

From: Hor, Yinnul
 To: litigation@bonniekwok.com
 Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Manesa, Azlan, Syazairina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tor
 Sent: 6/7/2019 8:57:46 AM
 Attachments:  SKQ 6104 A - LTA Search.pdf

Without Prejudice

Your Reference : SKE5522X
 Our Reference : 3303598816SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)
 AIG
 Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Yinnul.Hor@aig.com | www.aig.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]
 Sent: Thursday, June 06, 2019 4:50 PM
 To: AIG SGP, Claims-Survey
 Subject: [EXTERNAL] PRI - Acc Inv: SKQ 6104 A & SKE 5522 X ON 6 JUNE 2019

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SKQ 6104 A at M/s Motor Intelligence Automo Pte Ltd., No. 13 Kaki Bukit Road 4 #01-20 Bartley Biz Centre Singapore 417807.

Please contact Ms Ivy at 62810087. If Ms Ivy is uncontactable, you may contact Mr. Wilson at 88383318.

Regards,
 June

BONNIE KWOK LLC
 Advocates & Solicitors
 101A Upper Cross Street
 #08-12 People's Park Centre
 Singapore 058358
 TEL: 6536 6026
 FAX: 6536 2279
 email : litigation@bonniekwok.com
 GST Reg. No.: 201203547Z

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6901L
Vehicle Details	
Vehicle No.:	SKQ6104A
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS E AUTO
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	1NZX668847
Chassis No.:	MR053HY9305042174
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,498.00
Original Registration Date:	28 Nov 2007
First Registration Date:	28 Nov 2007
Transfer Count:	2
Actual ARF Paid:	\$13,748.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$20,997.00
COE Rebate Amount:	\$14,546.00
Total Rebate Amount:	\$14,546.00
Message	

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 10 Jun 2019

OK

► Vios Used Vehicle List (19 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Vios 1.5A G (COE till 05/2024)	\$26,800	\$5,410 /yr	22-May-2009	1,497 cc	-	GV Credit Pte Ltd	Available

Office No. - 63443344
Henry - 93838689

3.18% Per Annum \$448 Monthly. \$0 Admin Fees For All GV Purchase. Extra Add On Items: New 2 Years Warranty For Engine And Gearbox. New 2k Metallic Paint. New Pure Leather. New Rims, 16" Tyres. New Pio...

Toyota Vios 1.5A E (COE till 08/2020)	\$10,800	\$8,980 /yr	23-Aug-2005	1,497 cc	207,888 km	GV Credit Pte Ltd	Available
--	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------	------------------

At Is Condition! New Arrival! Cheapest In Town! Ideal For Short Term Usage! Powerful And Responsive Engine! Best Fuel Efficient Car! Selling Cheap! Dealers Are Welcome! Hurry! Call For Viewing Today B...

Office No. - 63443344
Tan - 90210087 | Lawrence - 87003137

Toyota Vios 1.5A E (COE till 10/2020)	\$12,555	\$9,130 /yr	25-Oct-2005	1,497 cc	-	Cars Premium	Available
--	-----------------	--------------------	--------------------	-----------------	----------	---------------------	------------------

Owned By A Careful Lady Owner. Service Done Every 10k Km Without Fail. Accident Free, Original Paint And Beautiful Leather Seats. Suitable For All Ages, Idea For Short Term Drive. Dream Of Owning It? ...

Office No. - 63654321
Chan - 93387838

Toyota Vios 1.5M E (COE till 12/2020)	\$10,800	\$7,230 /yr	07-Dec-2005	1,497 cc	-	88 Motor Trading	Available
--	-----------------	--------------------	--------------------	-----------------	----------	-------------------------	------------------

Well Known For It's Fuel Economy, Reliable And Low On Maintenance, New Coat Of Paintwork And Free Servicing Will Be Given, STA Evaluation Can Be Arrange For Peace Of Mind Purchase, Easy Financing.

Office No. - 62911187
Nic - 81001945 | Jeremy - 97625070 | Lek - 87555787 | Mr Ho - 96811390

Toyota Vios 1.5A E (COE till 12/2020)	\$13,500	\$8,930 /yr	14-Dec-2005	1,497 cc	-		Available
--	-----------------	--------------------	--------------------	-----------------	----------	--	------------------

Driven By An Adult Male For The Past 1 Year. Regular Servicing Done Every 15km Without Fail. Painted A New Coat Of Black Paint About A Year Ago. Car Has Not Given Me Any Problems At All. Work Doesn't ...

Office No. - -
Jack Kwong - 94501935

Toyota Vios 1.5A E (COE till 12/2020)	\$15,000	\$9,610 /yr	06-Jan-2006	1,497 cc	-		Available
--	-----------------	--------------------	--------------------	-----------------	----------	--	------------------

Comfy And Fuel Efficient Car. Drive Till COE Expires. Suitable For Those Who Are Looking For Short Term Drive And Cost Efficient Car.

Office No. - -
Mr Ang - 85220403

Toyota Vios 1.5M E (COE till 03/2021)	\$11,999	\$6,820 /yr	14-Mar-2006	1,497 cc	-	Trans Express	Available
--	-----------------	--------------------	--------------------	-----------------	----------	----------------------	------------------

COE Vios Manual At \$11999! Left 21 Months To Drive. Regularly Serviced And Maintained. Affordable Depreciation. Sell As It Is Condition. Probably Most Practical, Reliable 1.5L Engine, With Good Fuel E...

Office No. - 67473818
Adrian Chua - 98182884

Toyota Vios 1.5A E (COE till 05/2021)	\$11,600	\$5,870 /yr	12-Jun-2006	1,497 cc	-	Fei Yang Auto	Available
--	-----------------	--------------------	--------------------	-----------------	----------	----------------------	------------------

Leather Seats, Reverse Sensors, Well Maintained, Call Before Coming.

Office No. - 65561611
Jackson - 86990013 | Jeffrey Lim - 90255015

Toyota Vios 1.5A E (COE till 05/2021)	\$12,800	\$6,480 /yr	28-Jun-2006	1,497 cc	-	Takashima Auto Enterprise	Available
--	-----------------	--------------------	--------------------	-----------------	----------	----------------------------------	------------------

1 Owner, Good Condition, Low Mileage, Good For Short Term Used, Loan Available, Trade In Welcome.

Office No. - 64658772
Johnny - 81138285

Toyota Vios 1.5A E (COE till 06/2021) **\$15,999** \$7,780 /yr 06-Jul-2006 1,497 cc 140,855 km Trans Express **Available**

Reliable Toyota Vios, For Short Term. Low Mileage. Regularly Serviced. COE Rebate Above \$11k Now. Nice '2900' Plate. Leather Replaced. Sell As It Is Condition. Probably Most Practical, Reliable 1.5L E...

Office No. - 67473818

Adrian Chua - 98182884

Toyota Vios 1.5M E (COE till 06/2021) **\$15,800** \$7,680 /yr 17-Jul-2006 1,497 cc 200,000 km Elite Autostyle Pte Ltd **Available**

Be The Next Owner! Most Popular Toyota Vios For Your Family. Well Maintained And Serviced. Good Fuel Consumption. No Repairs Needed. 100% Accident Free. Hurry! Call Now For Viewing And Test Drive Appo...

Office No. - 69700160

Gracia - 82883039 | Zhi Rong - 93654050

Toyota Vios 1.5A E (COE till 06/2021) **\$16,800** \$8,170 /yr 18-Jul-2006 1,497 cc - Car Search **Available**

One Of The Popular Sedan Among Its Class. Smooth Drive With Very Good Fuel Consumption. Low Maintenance Cost. Consignment Unit. Flexible Loan Scheme Available. Trade In Welcome! Call Us Now!

Office No. - 62620728

Rachel - 91126538 | Justin - 91827511 | Ken - 93388994 | Jack - 91416611

Toyota Vios 1.5M E (COE till 06/2021) **\$10,800** \$5,250 /yr 21-Jul-2006 1,497 cc - Phoenix Motor Trading Enterprise **Available**

100% Loan COE 5 Years Or 10 Years View At Phoenix Motor Trading Enterprise.

Office No. - 62766662

Patrick - 93881918 | Mr Ng - 91456234 | Eng Jie - 91000173 | Cindy - 91841055

Toyota Vios 1.5A E (COE till 06/2026) **\$35,500** \$5,030 /yr 01-Aug-2006 1,497 cc - Prem Roy Motoring **Available**

Sport Rims. Leather Seats. Fog Lamps. Remote Key. Retractable Side Mirror Extremely Well Maintained Unit. No Second Doubt! Please Call Our Sales Consultants To View It Today. A Deal Not To Be Missed. ...

Office No. - 66028046

Vanan - 94609241

Toyota Vios 1.5A E (COE till 06/2021) **\$16,800** \$8,170 /yr 11-Aug-2006 1,497 cc - 77 Motors Pte Ltd **Available**

Consignment Unit.

Office No. - -

RC - 87145435 | Jen - 83835997

Toyota Vios 1.5M E (COE till 06/2026) **\$36,740** \$5,200 /yr 14-Aug-2006 1,497 cc 110,000 km **Available**

All Parts Has Been Just Change Pass 6 Month Only. Clutch Set, Air Con Compress, Condenser And Cooling Coil, Front And Rear Shock Absorber, Spark Plug, Open Port, Rear Boot Led Light And With Rear Boot...

Office No. - -

Wei Ming - 93376962

Toyota Vios 1.5A E (COE till 08/2021) **\$15,500** \$6,960 /yr 27-Sep-2006 1,497 cc 156,394 km Bliss Auto **Available**

New Arrival! Cheapest In Town! Genuine Price! Ideal For Short Term Usage! Genuine Low Mileage Of 12000km Clocked Annually! Powerful & Responsive Engine! 100% Accident-Free With Original Paintwork! Bes...

Office No. - 67542808

Boon Hong - 81266344

Toyota Vios 1.5M E (COE till 11/2021) **\$16,500** \$6,680 /yr 29-Nov-2006 1,497 cc - **Available**

Left 29 Months To Drive. Regularly Serviced And Maintained. 2 Years A Go, Changed Many Parts To Have A Better Drive For Next 5 Years. Sell As It Is Condition. Reliable 1.5L Engine, Road Tax Renew Till...

Office No. - -

Steven Tan - 96477726

Toyota Vios 1.5A J (COE till 05/2022) **\$25,555** \$8,780 /yr 08-May-2007 1,497 cc - Cars Premium **Available**

Don't Miss It! In House Financing Options Available. Buy With A Peace Of Mind. Well Maintained. Immaculate Condition. Free Car Spa Polishing, Free Servicing! Highest Trade In For Your Car. Call Now To...

Office No. - 63654321

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/06/2019 22:00
Date Of Accident	06/06/2019 08:35
Exact Location Of Accident	ASIA SQUARE TOWER 1 DRIVE WAY(8 MARINE VIEW)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKQ6104A
Insured/Policyholder	
Name Of Registered Owner	UDRIVE AUTOMOBILE
Co Reg No	53396901L
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-84286663
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS E AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5109749943
Cover Note Number	
Driver	
Name of Driver	SOH KENG CHONG
NRIC No	S1655944Z
Date Of Birth	08/09/1964
Occupation	OUTDOOR
Date Of Driving Pass	18/04/1986
Driving Experience	33 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90268488
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	788 YISHUN AVENUE 02 #08-1497
Postcode	760788
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKE5522X
Vehicle Make/Model/Colour	MERCEDES BENZ E200 AVG (R18 LED)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: _____



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: _____

IDAC KAKI BUKIT (VAC)
 23 KAKI BUKIT AVE 4
 Reporting Centre Personnel's Signature
 Singapore 415933
 Name: _____
 NRIC/FIN No.: _____
 Tel: 67416697
 Fax: 67492305
 Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 06/06/2019 at about 0835hrs I stopped my vehicle SKR6104A at the drive way of Asia Square Tower 1 to drop off a passenger the traffic was heavy & came to a still stop out of sudden I felt a strong impact from the rear of my vehicle. I alighted & found out a vehicle SKE5522X had fail to stop in time & rear ended the back of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT
23 KAKI BUKIT AVE 4
Singapore 415933

Reporting Centre Phone: 67492305

Name:

Fax: 67492305

NRIC/FIN No:

Email: vackb@singnet.com.sg

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (X) (3) Check (C)
(4) Not Consistent (NC)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Re	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NC	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	Re	/ 2	
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Repair	X	
1160	993339	Rear End Panel Top Garnish	Re	/	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CR	/	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	BT	/	
1171	991328	Bootlid Emblem	NC	/ 3	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	BT	/	
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SKQ 6104A

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

SKQ 6104A

...CLAIM SUBFOLDER...(Pending for Survey Report)



























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Jun 2019 Edit Reg		10 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	TAY PENG HONG , ID: S0017275H								
Main Claimant:	UDRIVE AUTOMOBILE , Co. Reg. No.: 53396901L								
Vehicle Reg. No.:	SKQ6104A	Date of Loss:	06/06/2019 00:00 - :59 [138 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3303598816SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SKE5522X	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intelligence Automo Pte Ltd (HQ) 13 KAKI BUKIT ROAD 4, #01-20 BARTLEY BIZ CENTRE, 417807 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (12/06/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKQ6104A (3303598816SG)
[SKE5522X]
TP
UDRIVE AUTOMOBILE
Jun 6 2019 12:00AM
[TAY PENG HONG]
Motor Intelligence Automo Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
2	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
3	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
4	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
5	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
6	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
7	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
8	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
9	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
10	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
11	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
12	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
13	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
14	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
15	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
16	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
17	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
18	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
19	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
20	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
21	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
22	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
23	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
24	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
25	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
26	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
27	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
28	17/06/19 10:51	General View										Load JPG	<input checked="" type="checkbox"/>	
29	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
30	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
31	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
32	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
33	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
34	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
35	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
36	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	
37	17/06/19 10:51	Photographs of Damaged Parts										Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	17/06/19 10:51	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
39	17/06/19 10:51	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
40	17/06/19 10:51	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
41	17/06/19 10:51	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
42	17/06/19 10:51	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
43	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
44	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
45	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
46	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
47	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
48	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
49	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
50	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
51	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
52	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
53	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
54	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
55	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
56	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
57	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
58	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
59	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
60	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
61	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
62	17/06/19 10:52	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	12/06/19 10:08	OI GIA REPORT		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010217/GCD3E2

Date: 31/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SKQ6104A

Insured Vehicle No : SKE5522X

Date of Loss: 06/06/2019

Nature of Claim: TP

Claim No: 3303598816SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKQ6104A

Make & Model: TOYOTA VIOS EA, 1.5 (A)

Engine No: 1NZX668847

Reg. Date: 28/11/2007 (Man. Year: 2007)

Chassis No: MR053HY9305042174

Colour: Blue

Odometer: 194154 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 10/06/2019 Inspected At:

Motor Intelligence Automo Pte Ltd (HQ)
13 KAKI BUKIT ROAD 4, #01-20
BARTLEY BIZ CENTRE
Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*REAR END PANEL	Repair	0.00 F	*- F
5	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
6	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
7	1		*BOOTLID	Bent	0.00 F	*- F
8	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
9	1		*BOOTLID LOCK	Bent	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >