	ASSIGNMENT	
Various de	Prom (Person); Pherica Vimala of INC.	Date/Time: 10 6 2019
	Estimated Cost: Bi	Ill to:
	OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS	
	To Inspect Vehicle No: FBP 1975 Y	Insured:
	at Workshop m/s JC Moloce	Tol: 6584 6914.
	of 13 Kaki Butit Rd 4 #01-16.	
-	Policy No:	Claim No: MT 10 47565 - 001
	Sum Insured:	Excess:
	Make of Veh: (Clicat's Record)	D.O.A. 21 5 2019
	CA / REV / REP. / REV 24 HRS  Date/Time: 10 C. Person Contacted:	H.O.D. Endorsement:
	Date/Time . Action/Instruction Followith ( )	
	FBP 1978Y-NA INC19008903	13 SOA: 21 5 2019
	27/09/19 @ 14: 24 pm d. 6.1	with Jimmy, Owner withdrawing
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	

# Nivitha (LKK Auto)

From:

Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Monday, 10 June 2019 6:18 PM

FW: TP CASES FARMED OUT TO LKK ON 10/06/2019 assignments@LKKauto.com; admin-d@LKKauto.com

Sent: ö

**Subject:** 

Dear LKK

I have inserted the OIC, DOA and the claim ref nbr for your info.

Thank you.

With Regards

www.income.com.sg Senior Administrator Motor Insurance T+65 6430 7898 Theresa Vimala









Find out more at income.com.sg/careers

D you Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. At Income, we are 'In with You' on Performance, Growth,

From: Theresa Vimala D/O Balagangadharan

Sent: Monday, 10 June 2019 10:07 AM

Fo: assignments@LKKauto.com; admin-d@LKKauto.com

Cc: Susan Ting <susan.ting@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>

Subject: FW: TP CASES FARMED OUT TO LKK ON 10/06/2019

Please assist to survey the following vehicles as per Mr Teng's instruction :-

N	JIC OIL	Claim No.	Vehicle	WorkShop	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
		MT/1046211-	SLP8887D	MUNICH AUTOMOBILES PTE LTD	30 TEBAN GARDENS CRESCENT SINGAPORE 608927	Tan Kok Ting / 9051 5581	10:30-	FBK1941X	25/5/19	
	ENG	MT/1047953-	SU3955E	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Gan Ping / 63621776		SHD1504R	7/6/19	
, ,	JULIANA	MT/1047555-	FBP1975Y	JC MOTORS (PTE. LTD.)	13 KAKI BUKIT ROAD 4 #01-16 BARTLEY BIZ CENTRE SINGAPORE 417807	Jimmy Boey / 6584- 6914	10:00-	SJS5499T	21/5/19	
4	HELENA	MT/1048061-	LEXBUILD INTERNAT SBS64838 PTE. LTD.	LEXBUILD INTERNATIONAL PTE. LTD.	2 LOYANG WAY Loyang Bus Depot SINGAPORE 508776	Yong Shun / 9029 6574	14:00-	YP9918M	1/6/19	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Senior Administrator Motor Insurance Theresa Vimala

www.income.com.sg T+65 6430 7898













Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. At Income, we are 'In with You' on Performance, Growth, Find out more at income.com.sg/careers

# Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you. · eBaoTech

Hello, NAC\_PAYA\_UBI\_800601

· Change Language

· Change Password

Log Out

GeneralClaim

My Desktop Notice of Loss Policy Query

Policy No.

Vehicle No.(For Motor)

FBP1975Y

Date of Accident

Certificate Number

21/05/2019 11:50

Search

Select

Policy No.

5107737374

Certificate Number

Policyholder Name HO KWANG HUAY (HE GUANGHUI)

SB135276C

Policyholder Product Cover Type
NRIC Third Party, Fire & Theft FBP1975Y FBP1975Y

Vehicle No.

Commence Date Insured Object

Expiry Date

23/02/2019 22/02/2020

Continue

GMC

MNA119065608 / National Assessment Centre Services - Ubl ENTRY DATE & TIME: 21/05/2019 16:37 SUBMITTED BY: Roelinda Binte Abdul Wahab

# 3P AIG 68411972

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report

21/05/2019 16:37

Date Of Accident

21/05/2019 11:50

Exact Location Of Accident

UPP PAYA LEBAR RD BESIDE OLD STREET BAK KUT TEH

Country/State of Loss

SINGAPORE

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

FBP1975Y

Insured/Policyholder

Name Of Registered Owner

HO KWANG HUAY (HE GUANGHUI)

NRIC No

S8135276C

Email Address

NOEMAIL

Mobile Phone No

(LOCAL) +65-91293040

Alternative Phone No

OTHERS-98318880

Vehicle Particulars

Manufacturer

YAMAHA

Model

**NMAX 155** 

Exact Purpose for which vehicle was being used at

time of accident

WORK

Are you claiming under your own insurance policy

NO

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

MOTORCYCLE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

NO

Policy Number

5107737374

AND ASSESSED AND ASSESSED.

Cover Note Number

Driver

YAP JUN HONG

NRIC No

S9335740Z

D 1 0/10:41

Name of Driver

25/09/1993

Date Of Birth

23/08/1883

Occupation

OUTDOOR

Date Of Driving Pass

13/02/2017

Driving Experience

2 YEARS AND 3 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-98318880

Fax Number

Contact Number

EMail Address

(200.11)

JONALDYAP@GMAIL.COM

Page 1 of 16

Address

BLK 77 BEDOK NORTH ROAD

#04-210

Postcode

460077

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - SUB-RIDER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

.

7080 S

-

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Maria Carlos Maria

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident?
Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I PARKED MY VEH OUTSIDE BAK KUT TEH SHOP AT UPP PAYA LEBAR RD TO COLLECT MY ORDER, AFTER I COLLECTED MY ORDER, I HEARD A BANG SOUND THAN I SAW MY MOTORCYCLE LAY DOWN ON THE GROUND. WHEN THE DRIVER OF VEH B CAME OUT, I ASKED HIM WHAT'S HAPPENING. THAN VEH B DRIVER SAID THAT HE DIDN'T SEE MY BIKE WHEN HE WAS REVERSING.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SJS5499T

Vehicle Make/Model/Colour

KIA SPORTAGE

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

TAY KENG LOO

NRIC/Passport Number

S1284294E

Contact Number

81829728

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 16

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

the transfer over the

Driver's Signature


(If driver is not the policyholder)

Date & Time: 2151 MAY 2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

				cross-common
Pls izhi	to the	statement.		
1				
			- talle	
	9000 - 10000 - 100			
		······································		
	41-			
7-17 Page 1				
<del></del>				
		01 - 1 in 1		

#### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time: 2141 MAY '2011 Reporting Centre Personnel's Signature

Name: NRIC/FIN No.:

#### > Back to OneMotoring


Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC	
Owner ID:	5276C	
Vehicle Details of some services		USS.
Vehicle No.:	FBP1975Y	
Vehicle to be Exported:	No	
ntended Deregistration Date:	10 Jun 2019	
Vehicle Make:	YAMAHA	
Vehicle Model:	NMAX155 ABS	
Primary Colour:	Grey	
Manufacturing Year:	2019	
Engine No.:	G3H6E0012476	
Chassis No.:	MH35G431000009831	
Maximum Power Output:	\$100 miles	
Open Market Value:	\$2,469.00	
Original Registration Date:	22 Feb 2019	
First Registration Date:	22 Feb 2019	
Transfer Count:	1	
Actual ARF Paid:	\$371.00	
Intended PARE Repare Details		40.44
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	•	
PARF Rebate Amount:	\$0.00	
Invented COE Rebate Details	21 Feb 2029	100
COE Expiry Date:	D - Motorcycle	
COE Category: COE Period(Years):	10	
QP Paid:	\$2,889.00	
	\$2,802.00	
COE Rebate Amount:	\$2,802.00	

The information contained herein is correct as at 10 Jun 2019

ОК









# JC MOTORS PTE LTD

Blk 13 Kaki Bukit Road 4 #01-16 S'pore 417807 Tel 65846914 Fax 65846912

LKK Auto Consultants hence notify

the Repairer of the following:

- . To resurvey before/after spray painting To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation

. Third party survey is on a "Without Prejudice" basis

May 24, 2019 DATE

Sub-Total

\$3,060.00

. No illegal modification(s) is allowed

FBP1975Y Quotation #

· Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

May 28, 2019 Quotation valid until: Acknowledged by Repairer Jimmy Boey Prepared by: Make/Model: YAMAHA N-MAX155 Signature: Price Discount Price Part Date: S/No \$162.00 Na \$180.00 Handle Bar 🗡 \$234.00 \$260.00 10% Front fender / \$342.00 10% \$380.00 Front Fork Assy 1 \$36.00 10% \$40.00 Brake Lever R/H

1 3	Wandle Ber Belenser	\$60.00	10%	\$54.00	
1	Handle Bar Balancer		10%	\$45.00	
1	View Mirror Set	\$50.00	10%	\$108.00	
1	Exhaust Muffler Protector	\$120.00		\$180.00	ı
1	Side Lower Cowling R/H	\$200.00	10%	131	
1	Front Side Lower Cowling R/H	\$210.00	10%	\$189.00	١
1	Front Side Lower Cowling R/H Front Rim Assy	\$280.00	10%	\$252.00	l
	Front couding R/H	\$170.00	10%	\$153.00	١
	Front Inner Panel R/H × NN	\$220.00	10%	\$198.00	١
	Floodband Danol D/H / /4-/	\$190.00	10%	\$171.00	ı
1 8	Front Side Lower Cowling L/H >	\$210.00	10%	\$189.00	١
	Front Side Lower Cowling Lift	\$170.00	10%	\$153.00	١
8	Front cowling L/H X / C/LA	\$280.00	10%	\$252.00	1
	1 Headlamp Assy ?	\$80.00	10%	\$72.00	1
	1 Steeding Cone ?	\$300.00	10%	\$270.00	1
	1 Steedring Stem ?	ψοσσ.σσ	1,374	28709-00-000000	1
					1
					١
					1
					-
		1			

QTY	Description	UNIT PRICE	DISCOUNT	LINE TOTAL
1 1	Service Paint-Work/ Spary Body and cover set with sticker set Labour 4-Days Towing	\$550.00 \$500.00 \$40.00	NA NA NA	\$550.00 ? \$500.00 Y \$40.00 /
- 1	US INTE		Total	\$4,150.00

Completion Time: 14 Days.

part by part.

part by part.

before and after report photos.

nefore parint photos.

Guo Quany - 8288 0282

(c) 6/19.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE	ASSESSMENT	REPORT
--------	------------	--------

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19010282/Gsd3s2

73 BRAS BASAH ROAD

Date:

09-10-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Code: INC ATTN: JULIANA LEE

1.	Policy Particula	ars :- THIRD PARTY CLA	MI
Insured Veh.	SJS 5499T	Veh. Inspected	FBP 1975Y
Policy No.	5107737374	Coverage (\$)	0.00
Claim No.	MT/1047555-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	10/06/2019
2.	Vehicle P	articulars & Condition	
Make & Model	YAMAHA NMAX155	c.c	155
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	MH3SG431000009831	Colour	GREY
Odometer	11590 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3.	Cor	nditions of Tyres	wall from the course of
	Size	Make	Balance
R/H Front Tyre	110/70-13	DUNLOP	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/70-13	DUNLOP	6 mm
L/H Rear Tyre			mm
4.	Desc	ription of Damages	

THE VHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.

DAMAGES SEE DETAILS.

5.	General Information							
NOTE AND DESCRIPTION OF THE PERSON OF THE PE	Accident Date	21/05/2019	Inspect Date / Time	10/06/2019 ( 01:00 PM )				
	Survey held at	JC MOTORS PTE, LTD.	•					
		13 KAKI BUKIT ROAD 4 #01-16 BARTLEY BIZ CENTRE SINGAPORE 417807						
- Company	The second second	A STATE OF THE PARTY OF THE PAR	Demarks					

5a.	Remarks
AND AND RESIDENCE OF THE PARTY	

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR.

B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b.	Estimate Da	ays of Repair	
ESTIMATED NORMA	AL PERIOD FOR REPAIR:	4 Working Days	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 1975Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	HANDLE BAR	NOT NECESSARY	180.00	-
1	FRONT FENDER	CUT	260.00	260.00
1	FRONT FORK ASSY	TO REPAIR SEE LABOUR	380.00	-
1	BRAKE LEVER R/H	CUT	40.00	40.00
1	HANDLE BAR BALANCER	CUT	60.00	60.00
1	SET VIEW MIRROR	CUT	50.00	50.00
1	EXHAUST MUFFLER PROTECTOR	CUT	120.00	120.00
1	SIDE LOWER COWLING R/H	CUT	200.00	200.00
1	FRONT SIDE LOWER COWLING R/H	CUT	210.00	210.00
1	FRONT RIM ASSY	NOT NECESSARY	280.00	,
1	FRONT COWLING R/H	CRACKED	170.00	170.00
1	FRONT INNER PANEL R/H	NOT NECESSARY	220.00	1 15
1	FLOORBOARD PANEL R/H	CUT	190.00	190.00
1	FRONT SIDE LOWER COWLING L/H	NOT NECESSARY	210.00	
1	FRONT COWLING L/H	CRACKED	170.00	170.00
1	HEADLAMP ASSY	* CHECK	280.00	
1	STEERING CONE	* CHECK	80.00	9
1	STEERING STEM	* CHECK	300.00	
	LESS 10% DISCOUNT		-340.00	-147.00
			3,060.00	1,323.00
	LABOUR			
	PAINT WORK / SPRAY BODY AND COVER SET WITH STICKER SET.	* CHECK	550.00	0.0000
	LABOUR. INCLUSIVE OF THE REPAIR OF FRONT FORK ASSY.		500.00	400.00
	TOWING		40.00	40.00
			1,090.00	440.00
	GRAND TOTAL		4,150.00	1,763.0

Report Ref No. CS/INC19010282/Gsd3s2



Page No.: 2 of 2

1,763.00 RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$1,084.60 NETT)

Report Ref No. CS/INC19010282/Gsd3s2

XING GUO QIANG

M.MATAI, AMSAE-A

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.