

ASS. REC. BY:

REF: CS3/CT119010309 / Gcd30k

Special Instruction:

Surveilor: G6**ASSIGNMENT (Office)**From (Person): Cheng Boon Sen

of

CT1Date/Time: 11.6.19 11.30am

Estimated Cost: _____

Bill to: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SKS 2618AInsured: GBF 7827at Workshop m/s A-Tec AutomobileTel: 90626929of 8 Kati Bulat Avenue 4 #04-20Policy No: DMCKSA 30155219000Claim No: SMM 19102023 38102

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 8.6.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 11.6.19 11.30amPerson Contacted: JamesVehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate	Inspection at: 8 Kati Bulat Avir 4 # 04-20
	SKS 2618A - NA / MSG 19010227 / 24	D.O.A - 08/06/2019
	GBF 7827 - NA / MSG 19010227 / 24	D.O.A - 08/06/2019
	Diamond: 12/6/2019	

(08/11/13)

ASS. REC. BY:

REF CT1

84971

ASSIGNMENT

From: Date: 11.6.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 2618A

at Workshop m/s A-Tec Automotive
of 8 km Bukit Avenue 4 #04-20

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA ! REV ! REP. ! 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SKS2618A Yr Regn: 01 Apr 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry C.C. 2494

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 106780 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053 AK 500 400 8629

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size: F: 215/55 R17

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$4000 - \$5000
12/6/2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)



: Preli. Report



: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: PRS

Lump Sum / I.B.I: (\$)

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2019		11 Jun 2019 11:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	SNG YI TYNG, ID: S13684971		
Vehicle Reg. No.:	SKS2618A	Date of Loss:	08/06/2019 09:00 - :59
Claim Type:	TP / SNM19D202538C02	Policy/Cover Note No.:	DMCVSN30155819000
Vehicle Reg. No. (Insured):	GBF7822T	Policy No. (Claimant):	A28704163QMY
		Excess:	\$0.00
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929, (2) 97103383		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 11 June 2019 11:27 AM
To: Weng Kit
Cc: jerone@chiaarul.com; assignments
Subject: RE: Our Ref: SKS 2618A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKS 2618A & GBF 7822T ALONG LAKE POINT DRIVE ON 8 JUNE 2019 / our ref: snm19d202538

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Weng Kit [mailto:wengkit@chiaarul.com]
Sent: Monday, 10 June, 2019 5:33 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Cc: jerone@chiaarul.com
Subject: RE: Our Ref: SKS 2618A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKS 2618A & GBF 7822T ALONG LAKE POINT DRIVE ON 8 JUNE 2019 / our ref: snm19d202538

Dear Sirs,

We refer to your email below.

Our client is not agreeable to your list of motor surveyors.

We are instructed by our client to propose the attached list of their surveyor as the mutual surveyor / single joint expert for your consideration.

Best Regards,

Weng Kit (Mr.)

Paralegal
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Monday, June 10, 2019 5:26 PM

To: wengkit@chiaarul.com; jerone@chiaarul.com

Subject: RE: Our Ref: SKS 2618A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKS 2618A & GBF 7822T ALONG LAKE POINT DRIVE ON 8 JUNE 2019 / our ref: snm19d202538

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Monday, 10 June, 2019 5:25 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; wengkit@chiaarul.com; jerone@chiaarul.com

Cc: Angie Foo <angie.foo@sg.cntaiping.com>

Subject: FW: Our Ref: SKS 2618A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKS 2618A & GBF 7822T ALONG LAKE POINT DRIVE ON 8 JUNE 2019

Dear Boon Sen,

Please conduct PRS – TP: SKS2618A (SNM19D202538) soonest possible.
File with OIC – Boon Sen -63896171

From: Weng Kit [<mailto:wengkit@chiaarul.com>]

Sent: Monday, 10 June 2019 4:57 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>

Cc: 'Jerone' <jerone@chiaarul.com>

Subject: Our Ref: SKS 2618A (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING SKS 2618A & GBF 7822T ALONG LAKE POINT DRIVE ON 8 JUNE 2019

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 10 June 2019 for your attention.

Best Regards,

Weng Kit (Mr.)

Paralegal
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	8497I
Vehicle No.:	SKS2618A
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	2ARU189481
Chassis No.:	MR053AK5004008629
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$27,619.00
Original Registration Date:	01 Apr 2015
First Registration Date:	01 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$30,667.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2025
PARF Rebate Amount:	\$23,000.00
COE Expiry Date:	31 Mar 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$71,889.00
COE Rebate Amount:	\$41,722.00
Total Rebate Amount:	\$64,722.00

The information contained herein is correct as at 11 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/06/2019 20:02
Date Of Accident	08/06/2019 09:50
Exact Location Of Accident	JUNC LAKE POINT DR & CORPORATION RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS2618A
Insured/Policyholder	
Name Of Registered Owner	SNG YI TYNG
NRIC No	S1368497I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96362573
Alternative Phone No	Office-96362573

Vehicle Particulars

Manufacturer	TOYOTA
Model	CAMRY 2.5 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28704163QMY
Cover Note Number	

Driver

Name of Driver	SNG YI TYNG
NRIC No	S1368497I
Date Of Birth	29/05/1959
Occupation	INDOOR
Date Of Driving Pass	03/06/1977
Driving Experience	42 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96362573

Fax Number

Contact Number

OFFICE-96362573

EMail Address

NOEMAIL

Address

BLK 90 CORPORATION ROAD
#01-20

Postcode

649824

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own
Vehicle-
-
-

Insurance Company of Driver's Own Vehicle

-
-
-**General Information of the Accident**

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved
in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by
ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)
soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBF7822T

Vehicle Make/Model/Colour

TOYOTA DYNA

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

87002808

Address

Postcode

6/17/2019

E-FILE

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Accident Sketch Plan


SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


I am travelling along Corporation Road. Suddenly Veh B just came out from the side road and hit onto the side of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2019		11 Jun 2019 11:30 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	SNG YI TYNG , ID: S1368497I	
Vehicle Reg. No.:	SKS2618A	Date of Loss: 08/06/2019 09:00 - :59 [50 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM19D202538C02	Policy/Cover Note No.: DMCVSN30155819000
Vehicle Reg. No. (Insured):	GBF7822T	Policy No. (Claimant): A28704163QMY
		Excess: S\$0.00
Repairer:	A-Tec Automotive Pte Ltd (Kaki Bukit) 8 Kaki Bukit Avenue 4 # 05-27 Premier, 415875 Kaki Bukit - Tel: (1) 90626929 , (2) 97103383	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]	
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 20/06/2019]	









































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKS2618A (SNM19D202538C02)
[GBF7822T]
TP
SNG YI TYNG
Jun 8 2019 9:00AM
[-]
A-Tec Automotive Pte Ltd











Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print			
1	10/06/19 20:08	Accident Statement								Load HTM				
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	National Assessment Centre Services (Ubi)								Thumbnail	Print			
1	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
2	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
3	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
4	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
5	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
6	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
7	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
8	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
9	10/06/19 20:06	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
2	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
3	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
4	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
5	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
6	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
7	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
8	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
9	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
10	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
11	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
12	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
13	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
14	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
15	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
16	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
17	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
18	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
19	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
20	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			
21	17/06/19 15:27	General View								Load JPG	<input checked="" type="checkbox"/>			

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
22	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
33	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
34	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
35	17/06/19 15:27	General View	 Load JPG	<input checked="" type="checkbox"/>
36	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/06/19 15:27	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/19 11:30	pri contact	 Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	10/06/19 20:07	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 20:07	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	10/06/19 20:08	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	10/06/19 20:06	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
1	10/06/19 20:07	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	10/06/19 20:07	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT119010309/GCD3E2

Date: 25/06/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30155819000

Claimant Vehicle
No : SKS2618AInsured Vehicle
No : GBF7822T

Date of Loss: 08/06/2019

Nature of Claim: TP

Claim
No: SNM19D202538C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS2618A**

Make & Model: TOYOTA CAMRY, 2.5 (A)

Engine No: 2ARU189481

Reg. Date: 01/04/2015 (Man. Year: 2014)

Chassis No: MR053AK5004008629

Colour: Silver

Odometer: 106780 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Goodyear 5 mm

Rear Left Side: Goodyear 5 mm

Front Right Side: Goodyear 5 mm

Rear Right Side: Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/06/2019

Date Inspected: 11/06/2019 Inspected At:

8 Kaki Bukit Ave 4 #04-20

Repairer : A-Tec Automotive Pte Ltd (Kaki Bukit)

Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Jun 2019)	
Parts:	143	TOYOTA CAMRY 2.5 (A)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS2618A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >