

2/03/2007

ASS. REC. BY:

REF: CS/Smo 19010314 / Ag, d3

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Agnes Chan Shui Hui of SmoDate/Time: 10.6.19 7:18 pm

Estimated Cost: _____ Bill to: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 996BInsured: YP 430Rat Workshop m/s People Vehicle RepairTel: 67433246of DIC 3023A UB Kd 1 # 01-60Policy No: DI8MTHCUE00 2442Claim No: CMTD 196 2773

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 7.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 11.6.19 11.46a.m Person Contacted: AppleVehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	GBE 996B - NA / CT1 190101001 74	D.O.A - 07/06/2019
	YP 430R - NA / CT1 190101001 24	D.O.A - 07/06/2019

12/6@16.21pm - Composed via menmen pending estimate
16/8/19 @ 5.04pm revised to Agnes Chan via menmen.
USP 4350, 6 days cred @ 6010.30, 57%.

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBE996B Yr Regn: 2015 / August

Type: M.Car / M.Cycle / Bus / Van / Corr Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar c.c. 2953

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 184731 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1SC2F2420857213

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C Cordor

R: 165 R13C Journey

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. <u>86</u> mm	R/Bal. <u>86</u> mm
L/Bal. <u>86</u> mm	L/Bal. <u>86</u> mm
D.O.A. _____	D.O.I. <u>12/06/19</u>

Survey held at People

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Sampo

RECEIVED 19 AUG 2019

MV:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1) 19/8 10:00

2)

IN

OUT

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

350

11

361

Prel. Report:

Final Report:

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 16 Aug 2019

Preliminary Advice

Insured Vehicle No	: YP4330R	Accident Date	: 07/06/2019
TP Vehicle No	: GBE996B	Assignment Date	: 10/06/2019
Make	: NISSAN CABSTAR	Est. Duration of Repair	: 6.00
Date of Inspection	: 12/06/2019		
Inspection At	: PEOPLE'S VEHICLE RECOVERY SERVICE (HQ) BLK 3023A UBI RD 1, #01-60 SINGAPORE 408717		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,560.30
Revised Amount	:S\$	5,724.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,724.28
Lump Sum Repair	:S\$	4,550.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019		10 Jun 2019 17:18 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	WINSPEC LOGISTICS SERVICES PTE. LTD., Co. Reg. No.: 200602675D								
Main Claimant:	M/S SAFETY INNOVATORS (INTERNATIONAL) PTE LTD, Co. Reg. No.: 200312801G								
Vehicle Reg. No.:	GBE996B	Date of Loss:	07/06/2019 13:00 - :59						
Claim Type:	TP / CMTD1902773	Policy/Cover Note No.:	D18MTHCVE002442 (Comprehensive)						
Vehicle Reg. No. (Insured):	YP4330R	Policy No. (Claimant):							
Repairer:	Excess:								
Handling Insurer:	People's Vehicle Recovery Service (HQ) Blk 3023A Ubi Rd 1, #01-60, 408717 Ubi - Tel: 67433246								
Adjuster:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]								
Adj. Asg. Remarks:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2019] WS: APPLE 67433246 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***GBE996B (CMTD1902773)
[YP4330R]**

TP

M/S SAFETY INNOVATORS (INTERNATIONAL) PTE LTD

Jun 7 2019 1:00PM

[WINSPEC LOGISTICS SERVICES PTE. LTD.]

People's Vehicle Recovery Service

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/06/2019 16:21 PM.

To agnes.chan@sompo.com.sg

Subject GBE996B (CMTD1902773) [YP4330R] TP

Dear Sir/Madam,

Please be informed that we have inspected the vehicle GBE 996B on 12/06/2019
We are pending estimate from repairer.

Regards,

Denise
LKK auto

DOCUMENTS SUMMARY

There are no documents.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/06/2019 11:06
Date Of Accident	07/06/2019 13:30
Exact Location Of Accident	6 TUAS AVE 6
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE996B
Insured/Policyholder	
Name Of Registered Owner	M/S SAFETY INNOVATORS (INTERNATIONAL) PTE LTD
Co Reg No	200312801G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65060111

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN1652591802
Cover Note Number	

Driver

Name of Driver	LI YUHE
Passport No/FIN	G2874100L
Date Of Birth	08/02/1970
Occupation	OUTDOOR
Date Of Driving Pass	31/10/2016
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84093609
Fax Number	
Contact Number	OFFICE-84093609
Email Address	NOEMAIL

Address	90 TUAS AVENUE 11
Postcode	639101
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS PARKED ALONG THE STATED VENUE AS DELIVERING GOODS. WHEN I COME BACK RETRIEVE MY VEHICLE AND SAW THAT VEHICLE B REVERSED AND HIT ONTO MY VEHICLE FRONT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP4330R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LEE TENG CHAI
NRIC/Passport Number	S1439335H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: :

GENDER: :

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel Signature
Name:
NRIC/FIN No.:

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717

Tel No. : 67433246/ 67438552 Fax No. : 67430013

E-Mail : peoplevehicle@gmail.com

Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

JNISC2F2420857213

SOMPO INSURANCE (S) PTE LTD
50 RAFFLES PLACE #05-01/06
S'PORE LAND TOWER 048623

Xiao Chan.

Estimate : ES19017

Date : 12/06/2019

Vehicle Num. : GBE 996 B

Make/Model : NISSAN CABSTAR F24

Chassis/Eng# :

Accident Date : 07/06/2019

Claim No. : TT 349-19

Reference : YP 4330 R

Policy No. : CHINA DMCVSN1652591802

Attention : Motor Claim Department

Contact : 6461 6555 Fax No. : 6221 3147

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	WINDSCREEN FRT <i>crackd.</i>		991.00 ✓
2.	1	WINDSCREEN MOULDING FRT <i>3 new</i>		324.40 ✓
3.	1	WINDSCREEN INNER SEAL FRT		161.20 ✓
4.	1	HEAD LAMP R/H <i>crackd.</i>		473.40 ✓
5.	1	CORNER PANEL R/H <i>Repair</i>		389.90 x.
6.	1	SIDE MIRROR ARM R/H <i>But</i>		191.90 ✓
7.	1	SIDE MIRROR R/H <i>ut</i>		171.80 ✓
8.	1	SIDE MIRROR COVER R/H <i>missing</i>		22.90 ✓
9.	1	SIDE MIRROR INNER GARNISH R/H <i>missing</i>		131.20 ✓
10.	1	DOOR PILLAR R/H FRT <i>Dark</i>		1,646.40 ✓
11.	1	DOOR R/H FRT <i>Repair</i>		1,396.50 x.
12.	2	DOOR HINGE R/H FRT <i>new</i>	65.10	130.20 x.
13.	1	WIPER PANEL FRT <i>Repair</i>		111.30 x.
14.	1	DASHBOARD <i>new</i>		1,689.90 x.
15.	1	SIDE MIRROR ARM L/H <i>But</i>		191.90 ✓
16.	1	SIDE MIRROR L/H <i>ut</i>		171.80 ✓
17.	1	ROUND MIRROR <i>ut</i>		121.30 ✓
Nett Total S\$:				8,317.00
10.00% Discount S\$:				831.70
				7,485.30

4558.20

4138.28

CONTINUE / ...

PEOPLE'S VEHICLE RECOVERY SERVICE

BLK 3023-A UBI ROAD 1 #01-60 SINGAPORE 408717
 Tel No. : 67433246/ 67438552 Fax No. : 67430013
 E-Mail : peoplevehicle@gmail.com
 Tax Reg. No. : M90001895E Buss. Reg. No. : 31800200X

SOMPO INSURANCE (S) PTE LTD
 50 RAFFLES PLACE #05-01/06
 S'PORE LAND TOWER 048623

Attention : Motor Claim Department

Contact : 6461 6555 Fax No. : 6221 3147

Estimate : ES19017

Date : 12/06/2019
 Vehicle Num. : GBE 996 B
 Make/Model : NISSAN CABSTAR F24
 Chassis/Eng# :
 Accident Date : 07/06/2019
 Claim No. : TT 349-19
 Reference : YP 4330 R
 Policy No. : CHINA DMCVSN1652591802

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	SPECIAL NETT ITEMS :		
2.	1	ERP CASING		15.00 ✓
		WINDSCREEN GUM } new	75	60.00 ✓
Special Nett Total S\$:				75.00
LABOUR :				
REMOVE & REPLACE ACCIDENT DAMAGED PARTS				1510
SPRAY PAINTING ACCIDENT EFFECT PARTS				1,800.00 600 ✓
REMOVE AND REFIX DASHBOARD AND CHECK WIREING				800.00 600 ✓
UNDERCOAT				280.00 250 ✓
Labour Total S\$:				120.00 60 ✓
				3,000.00

SingDollars : Ten Thousand Five Hundred Sixty & Cents Thirty Only

E. & O.E. Total S\$: 10,560.30

for PEOPLE'S VEHICLE RECOVERY SERVICE

Computer Generated Invoice No. Signature Required:

- LKK Auto Consultants hence notify the Repairee Requiring:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 5724.28
 4/s: 4550
 Admin King
 4/s 12/06/19.
 06 Days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19010314/AQD3N2

Date: 20/08/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTHCVE002442
Claimant Vehicle No :	GBE996B	Insured Vehicle No :	YP4330R
Date of Loss:	07/06/2019	Nature of Claim:	TP
		Claim No:	CMTD1902773

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE996B	Engine No:	ZD30347027K
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Chassis No:	JN1SC2F24Z0857213
Reg. Date:	31/08/2015 (Man. Year: 2015)	Odometer:	184731 km
Colour:	Grey		
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	165 R13C
Front Left Side:	Condor 6 mm	Rear Left Side:	Journey 6 mm
Front Right Side:	Condor 6 mm	Rear Right Side:	Journey 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,560.30	4,214.28	3,346.02	44.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,510.00	1,490.00	49.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,560.30	5,724.28	4,836.02	45.79
Approved Total (Overridden) (\$\$)		4,550.00		
(\$\$)	10,560.30	4,550.00	6,010.30	56.91
+ GST 7.00/7.00% (\$\$)	739.22	318.50	420.72	56.91
Nett Amount (\$\$)	11,299.52	4,868.50	6,431.02	56.91

INSPECTION

Date of Assignment: 10/06/2019
Date Inspected: 12/06/2019 Inspected At:

People's Vehicle Recovery Service
(HQ)
Blk 3023A Ubi Rd 1, #01-60
Singapore 408717

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Aug 2019)	
Parts:	N/A	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE996B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN FRT	Cracked	991.00 FN	*991.00 FN
2	1		*WINDSCREEN MOULDING FRT	Necessary	324.40 FN	*324.40 FN
3	1		*WINDSCREEN INNER SEAL FRT	Necessary	161.20 FN	*161.20 FN
4	1		*HEAD LAMP RH	Cracked	473.40 FN	*473.40 FN
5	1		*CORNER PANEL R/H	Repair	389.90 FN	*- FN
6	1		*SIDE MIRROR ARM R/H	Bent	191.90 FN	*191.90 FN
7	1		*SIDE MIRROR R/H	Cut	171.80 FN	*171.80 FN
8	1		*SIDE MIRROR COVER R/H	Missing	22.90 FN	*22.90 FN
9	1		*SIDE MIRROR INNER GARNISH R/H	Missing	131.20 FN	*131.20 FN
10	1		*DOOR PILLAR R/H FRT	Dented	1,646.40 FN	*1,646.40 FN
11	1		*DOOR R/H FRT	Not Necessary	1,396.50 FN	*- FN
12	2		*DOOR HINGE R/H FRT	Not Necessary	130.20 FN	*- FN
13	1		*WIPER PANEL FRT	Repair	111.30 FN	*- FN
14	1		*DASHBOARD	Not Necessary	1,689.90 FN	*- FN
15	1		*SIDE MIRROR ARM L/H	Bent	191.90 FN	*191.90 FN
16	1		*SIDE MIRROR L/H	Cut	171.80 FN	*171.80 FN
17	1		*ROUND MIRROR	Cut	121.30 FN	*121.30 FN
18	1		*ERP CASING	Necessary	15.00 FS	*15.00 FS
19	1		*WINDSCREEN GUM	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	8,392.00	4,674.20
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	831.70	459.92
Total Parts (\$\$)	7,560.30	4,214.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE ACCIDENT DAMAGED PARTS	New	1,800.00	600.00
2	SPRAY PAINTING ACCIDENT EFFECT PARTS	New	800.00	600.00
3	REMOVE AND REFIX DASHBOARD AND CHECK WIREING	New	280.00	250.00
4	UNDERCOAT	New	120.00	60.00
Gross Labour Cost (\$\$)			3,000.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >