

22/03/2002

ASS. REC. BY:

REF: CS3/MSG19010317/Gcd 302 Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): Kathryn Wong

of

MSG

Date/Time: 11.6.19 9.35am

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKU 6295K

Insured: SKB 173T

at Workshop m/s Apex motoring

Tel: 91690825

of 25 kaki Bukit Road 4 #01-55

Policy No: 290110956mx

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.6.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement:

Date/Time: 11.6.19 11.10am

Person Contacted:

Pei Jie

Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SKU 6295K - X
	SKB 173T - X
	Disassemble: 12/6/2019
	After repair: 13/6/2019

Mehrun

ASS. REC. BY:

REF MS19

PRS

ASSIGNMENT

From: _____ Date: 11.6.2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 6295K

at Workshop m/s Apex Motors
of 25 Kaki Bukit Road 4 #01-55

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKU 6295K

Regn: Aug / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz 1.5

c.c

1498

Colour: Red

A/C:

Insured / Std / NI / NA

Sp. Reading: 113119

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK5850GX 200050

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

185/55 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

Survey held at

w/s

11-06-19

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$3000

12/6/2019

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

120

11

131

Report Format: PRE

Lump Sum / I.B.I. (\$))

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2019		11 Jun 2019 09:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LI AIFENG, ID: S2760272Z		
Main Claimant:	MOHAMMAD FARHAN BIN JASMIN, ID: S8741413B		
Vehicle Reg. No.:	SKU6295K	Date of Loss:	07/06/2019 08:00 - :59 [46 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29099095QMX (Comprehensive) Coverage: 16/10/2018 - 20/10/2019
Vehicle Reg. No. (Insured):	SKB173T	Policy No. (Claimant):	
		Excess:	
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/06/2019]		
Driver/Custodian (Insured):	CHEN QIANG (28 / Male) , NRIC: S9076260E Email:		
Adj Asg. Remarks:	on WP. Liab: cleared. Disagreed on SJE, Assign to LKK. Peijie 91690825		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1413B
Vehicle Details	
Vehicle No.:	SKU6295K
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L15B31020005
Chassis No.:	JHMGK5850GX200050
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$14,526.00
Original Registration Date:	05 Aug 2015
First Registration Date:	05 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$9,526.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Aug 2025
PARF Rebate Amount:	\$7,144.00
Intended COE Rebate Details	
COE Expiry Date:	04 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,700.00
COE Rebate Amount:	\$35,945.00
Total Rebate Amount:	\$43,089.00

The information contained herein is correct as at 20 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/06/2019 18:39
Date Of Accident	07/06/2019 08:30
Exact Location Of Accident	KJE EXPRESSWAY TOWARDS TUAS
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKU6295K
Insured/Policyholder	
Name Of Registered Owner	MOHAMMAD FARHAN BIN JASMIN
NRIC No	S8741413B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98006133
Alternative Phone No	OFFICE-98006133
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA226208/1
Cover Note Number	
Driver	
Name of Driver	MOHAMMAD FARHAN BIN JASMIN
NRIC No	S8741413B
Date Of Birth	24/12/1987
Occupation	INDOOR
Date Of Driving Pass	30/07/2007
Driving Experience	11 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98006133
Fax Number	
Contact Number	OFFICE-98006133
EMail Address	NOEMAIL

Address	APT BLK 506B YISHUN AVENUE 4 #05-132
Postcode	762506
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NURIRSYIDAH BINTE MD RAZALI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	KAKI BUKIT NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 526 BEDOK NORTH STREET 3 #01-448 , POSTCODE: 460526 COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4429999 - FAX NO: 62444377
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB173T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEN QIANG
NRIC/Passport Number	S9076260E
Contact Number	98511959

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MOHAMMAD FARHAN BIN JASMIN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKU6295K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address APT BLK 506B YISHUN AVENUE 4 #05-132
Postcode 762506

DETAILS OF INJURED PERSON 2

Name NURIRSYIDAH BINTE MD RAZALI
Approximate Age
Injuries Sustain
Injured person in which vehicle? SKU6295K
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address APT BLK 506B YISHUN AVENUE 4 #05-132
Postcode 762506

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 7/6/19, 16:53 HRS

Driver's Signature
(If driver is not the policyholder)
Date & Time: 7/6/19, 16:53 HRS

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 07/06/2019 at about 0830HRS, I was driving my vehicle SKU6295K along KJE towards Tuas on the right most lane. My wife was my passenger at that time. The weather was clear however the road surface was wet and the traffic volume was heavy. All of a sudden, I felt an impact from the rear of my vehicle hence I got down to make a check. I discovered that the front of vehicle, SKB173T has collided onto the rear of my vehicle. We exchanged particulars and no one was injured at that time. We decided to go for insurance settlement and left the scene. After a few hours, both my wife and I felt pain at our back, neck and foot (wife) area, therefore we want to seek medical treatment at Tan Tock Seng Hospital. Both of us were given 5 days of outpatient sick leave. Hence, I am lodging this injury traffic accident report. I wish to state that I have a rear in car camera which captured the whole incident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 7/6/19, 1653HRS

Driver's Signature
(If driver is not the policyholder)

Date & Time: 7/6/19, 1653HRS.

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190607/2119

1 of 4

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

Report No. T/20190607/2119

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/06/2019 16:11	Vide Report No.:	Station Diary No.: 12
--	------------------	--------------------------

Informant's Particulars

Name of Informant: MOHAMMAD FARHAN BIN JASMIN			Address: APT BLK 506B YISHUN AVENUE 4 #05-132 SINGAPORE 762506		
ID Type / ID No.: NRIC NO / S8741413B			Contact No.: Home/Office: Mobile: 98006133		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 31	Date of Birth: 24/12/1987	Type of Informant: Driver		
Race: Malay			Language: English		Institution / School Name:
Occupation: SENIOR SUPPLY CHAIN OFFICER			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/06/2019 08:30	Type of Location: Straight Road
Location: Along Road 1 KRANJI EXPRESSWAY ALONG KJE TOWARDS TUAS				
Weather: Clear		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKB173T	Car	TOYOTA	CAMRY 2.0 AUTO ABS AIRBAG	White		0
SKU6295K	Car	HONDA	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD	Red	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190607/2119

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

2 of 4

Report No. T/20190607/2119

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SKU6295K	AXA INSURANCE SINGAPORE PTE LTD	GA226208	05/08/2018	04/08/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	CHEN QIANG		ID No.	S9076260E
Related Vehicle	SKB173T (Car)		Contact No.	98511959
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	MOHAMMAD FARHAN BIN JASMIN		ID No.	S8741413B
Related Vehicle	SKU6295K (Car)		Contact No.	98006133
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	07/06/2019	Date Discharge	07/06/2019	
No. of Days granted Medical Leave	05	Degree of Injury	Slight	
Passenger				
Name	NURIRSYIDAH BINTE MD RAZALI		ID No.	S9128754D
Related Vehicle	SKU6295K (Car)		Contact No.	93211737
Hospital/Clinic	TAN TOCK SENG HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	07/06/2019	Date Discharge	07/06/2019	
No. of Days granted Medical Leave	05	Degree of Injury	Slight	



**SINGAPORE
POLICE FORCE**



T/20190607/2119

3 of 4

Report No. T/20190607/2119

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

CONTINUATION OF REPORT

Brief Details.

On the 07/06/2019 at about 0830hrs, I was driving my vehicle SKU6295K, along KJE towards Tuas on the right most lane. My wife was my passenger at that time. The weather was clear however the road surface was wet and the traffic volume was heavy. All of a sudden, I felt an impact from the rear of my vehicle hence I got down to make a check. I discovered that the front of vehicle, SKB173T has collided onto the rear of my vehicle. We exchanged particulars and no one was injured at that time. We decided to go for insurance settlement and left the scene. After a few hours, both my wife and I felt pain at our back and neck area, therefore we went to seek medical treatment at Tan Tock Seng Hospital. Both of us were given 5 days of outpatient sick leave. Hence, I am lodging this injury traffic accident report. I wish to state that I have a rear in car camera which captured the whole incident.



**SINGAPORE
POLICE FORCE**



T/20190607/2119

4 of 4

Report No. T/20190607/2119

Police Station Of Origin:
Kaki Bukit NPP
526 Bedok North Street 3 #01-448
SINGAPORE 460526
Tel No: 1800-4429999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /
Sgt 2 KOH WEN RUI

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
07/06/2019 16:11

Officer In Charge Of Case:

TP / AEIT7
SI ANG Y TING
Contact No. 65476414

Classification Of Case:

Authentication Stamp
NP168

SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)




CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		11 Jun 2019 09:35 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LI AIFENG, ID: S2760272Z								
Main Claimant:	MOHAMMAD FARHAN BIN JASMIN, ID: S8741413B								
Vehicle Reg. No.:	SKU6295K	Date of Loss:	07/06/2019 08:00 - :59 [46 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	29099095QMX (Comprehensive) Coverage: 16/10/2018 - 20/10/2019						
Vehicle Reg. No. (Insured):	SKB173T	Policy No. (Claimant):							
		Excess:							
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 12/06/2019]								
Driver/Custodian (Insured):	CHEN QIANG (28 / Male) , NRIC: S9076260E Email:								
Adj Asg. Remarks:	on WP. Liab: cleared. Disagreed on SJE, Assign to LKK. Peijie 91690825								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU6295K
[SKB173T]
TP
MOHAMMAD FARHAN BIN JASMIN
Jun 7 2019 8:00AM
[LI AIFENG]
Apex Motoring

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
2	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
3	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
4	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
5	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
6	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
7	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
8	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
9	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
10	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
11	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
12	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
13	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
14	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
15	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
16	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
17	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
18	20/06/19 18:39	General View		Load JPG	<input checked="" type="checkbox"/>					
19	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
20	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
21	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
22	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
23	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
24	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
25	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
26	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
27	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
28	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
29	20/06/19 18:39	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>					
30	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>					
31	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>					
32	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>					
33	20/06/19 18:40	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>					
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print					
1	10/06/19 15:38	PRI		Load PDF						
2	10/06/19 15:38	OI Accident Report		Load PDF						

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
3	10/06/19 15:38	TP SKU6295K E-REPORT	 Load PDF	
4	10/06/19 17:48	EMAIL DISAGREED	 Load PDF	
5	10/06/19 17:49	EMAIL LIABILITY CLEAR	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19010317/GCD3E2

Date: 21/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29099095QMX

Claimant Vehicle No : SKU6295K

Insured Vehicle No : SKB173T

Date of Loss: 07/06/2019

Nature of Claim: TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU6295K

Make & Model: HONDA JAZZ, 1.3 (A)

Engine No: L15B31020005

Reg. Date: 05/08/2015 (Man. Year: 2015)

Chassis No: JHMGK5850GX200050

Colour: Red

Odometer: 113119 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16

Rear Tyre Size: 185/55 R16

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/06/2019

Date Inspected: 11/06/2019 Inspected At:

Apex Motoring
25 Kaki Bukit Road 4, #01-55 Synergy @
KB
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 -\$3,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2019)
Parts: 144	HONDA JAZZ 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKU6295K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >