

22/03/2003

ASS. REC. BY:

REF: CS/CT1 19010320/KSD352

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CT1Date/Time: 10.6.2019 15:34 PM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 4103CInsured: GBF 3943Dat Workshop m/s TTS EurocareTel: ~~63602845 / 9077928~~of 383 Sin Ming Drive.Policy No: DM CSR30963418022Claim No: SYM 190702513102

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_

D.O.A. 4.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"up"

Kavi

8292 7422

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 10.6.19 3:32pmPerson Contacted: RonaldVehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

SLV 4103C - X

GBF 3943D - ✓

20/01/20 @ 10:46 am checked with Kavi, pending liability from insurance. Vehicle repaired under OD claim.

ASS. REC. BY:

REF: C12 /

Kennerh

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

days

Res.: \_\_\_\_\_

Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: \_\_\_\_\_

Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

To-vy

Date / Time

Action / Instruction

1 / File pass to

Veh No: \_\_\_\_\_

SLV 4103C

Yr Regn: \_\_\_\_\_

12, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Mer E250

c.c

1991

Colour

n-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

26299

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

WDD 2130452A 297409

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: \_\_\_\_\_

F:

245/40R19

R: \_\_\_\_\_

R:

275/35R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

7

mm

R/Bal. \_\_\_\_\_

7

mm

L/Bal. \_\_\_\_\_

7

mm

L/Bal. \_\_\_\_\_

7

mm

D.O.A. \_\_\_\_\_

4/6/19

D.O.I. \_\_\_\_\_

11/6/19

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rm

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 20 JAN 2020

Date/Time, File Pass to?

20/01/20

1) \_\_\_\_\_

Type: 4

Date/Time, File Return to?

2) \_\_\_\_\_



Prell. Report



Final Report

Days Of Repair: \_\_\_\_\_

4

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

220

Transportation: \_\_\_\_\_

S - RS - St

Fixes

Others

Add Fee: ☐

Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format: \_\_\_\_\_

Prell

Lump Sum / I.B.I. (\$

TOTAL

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019		10 Jun 2019 15:31 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:									
Main Claimant: <b>TAN BOON CHEE</b> , ID: S6833228A									
Vehicle Reg. No.:		<b>SLV4103C</b>	Date of Loss:	04/06/2019 18:00 - :59					
Claim Type:		<b>TP / SNM19D202513C02</b>	Policy/Cover Note No.:	DMCVSN30963418022					
Vehicle Reg. No. (Insured):		<b>GBF3943D</b>	Policy No. (Claimant):	PNPV2017-00009529-01					
			Excess:	S\$0.00					
Repairer: <b>Trans Eurokars Pte Ltd (Sungei Kadut)</b> 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... <b>[Final Rpt due 19/06/2019]</b>									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Nivitha (LKK Auto)

---

**From:** Kavi <kavi@tts.com.sg>  
**Sent:** Monday, 10 June 2019 7:24 PM  
**To:** 'Chong Boon Sen'  
**Cc:** 'assignments'  
**Subject:** RE: OUR REF: SNM19202513 / TTS EUROCARs PTE LTD THIRD PARTY CLAIM SLV4103C AND SLV4103C

**Expires:** Sunday, 19 July 2020 12:00 AM

Dear Chong,

It's a Merc E250

Address as per below. Thank you.

Best Regards

Ms.Kavi

**Motor Claims Officer**



**TTS EUROCARs** pte ltd  
A member of the TTS Motor Group

We are committed to the preservation of the environment. Please print this email only if it is absolutely necessary.

TTS Motor Group Pte Ltd (Co Reg No: 198702999Z)  
TTS Eurocars Pte Ltd (Co Reg No: 200413930H)  
383 Sin Ming Drive TTS Centre Singapore 575717  
Tel: (65) 82927422 Fax: (65) 6741 1626  
Email: [kavi@tts.com.sg](mailto:kavi@tts.com.sg)  
Website: [www.tts.com.sg](http://www.tts.com.sg)

Disclaimer: The information contained in this email, including any attachments, may contain confidential information of TTS Motor Group Pte Ltd / TTS Eurocars Pte Ltd. This email is intended only for the use of the addressee(s) listed above. Unauthorized review, dissemination or any other use of the information contained in this email is strictly prohibited. If you have received this email in error or have reason to believe that you are not authorized to receive it, please notify the sender by return email and promptly delete this email .\*\*\*\*

---

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]  
**Sent:** 10 June, 2019 3:32 PM  
**To:** kavi@tts.com.sg  
**Cc:** assignments <assignments@lkkauto.com>  
**Subject:** RE: OUR REF: SNM19202513 / TTS EUROCARs PTE LTD THIRD PARTY CLAIM SLV4103C AND SLV4103C

Pls advise on make and model and also contact details of workshop.

**Chong Boon Sen**  
Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Chong Boon Sen  
**Sent:** Monday, 10 June, 2019 3:27 PM  
**To:** 'kavi@tts.com.sg' <kavi@tts.com.sg>  
**Cc:** assignments <assignments@lkkauto.com>  
**Subject:** RE: OUR REF: SNM19202513 / TTS EUROCARS PTE LTD THIRD PARTY CLAIM SLV4103C AND SLV4103C

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Kavi [mailto:kavi@tts.com.sg]  
**Sent:** Monday, 10 June, 2019 12:07 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM19202513 / TTS EUROCARS PTE LTD THIRD PARTY CLAIM SLV4103C AND SLV4103C

Dear Chong,

In that case, we would like to choose MARCUS CHUA.

Thank you.

Regards,  
*Ms. Kavi*  
Motor Claims Officer

**From:** Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]  
**Sent:** 10 June, 2019 10:30 AM

To: [kavi@tts.com.sg](mailto:kavi@tts.com.sg)

Subject: RE: OUR REF: SNM19202513 / TTS EUROCARS PTE LTD THIRD PARTY CLAIM SLV4103C AND SLV4103C

Without Prejudice

Dear Kavi,

Only got LKK, LBS, STA.

No other 10 surveyors name according to protocol.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

From: Kavi [<mailto:kavi@tts.com.sg>]

Sent: Friday, 7 June, 2019 5:28 PM

To: Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

Subject: RE: OUR REF: SNM19202513 / TTS EUROCARS PTE LTD THIRD PARTY CLAIM SLV4103C AND SLV4103C

Dear Chong,

Kindly provide 10 other surveyor's names for our consideration. Thank you.

Regards,

*Ms. Kavi*

Motor Claims Officer

---

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: 7 June, 2019 5:07 PM

To: [kavi@tts.com.sg](mailto:kavi@tts.com.sg)

Subject: OUR REF: SNM19202513 / TTS EUROCARS PTE LTD THIRD PARTY CLAIM SLV4103C AND SLV4103C

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang

SEE, CHEW SENG
LOW SAR HUEI
HONG FOOK CHOY
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	05/06/2019 16:02
Date Of Accident	04/06/2019 18:30
Exact Location Of Accident	ALONG HARBOURFRONT WALK VIVOCITY BMENT 2 CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV4103C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN BOON CHEE
NRIC No	S6833228A
Email Address	WXYZ20090818@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97493499
Alternative Phone No	OTHERS-97493499

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250 AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2017-00009529-01
Cover Note Number	NA

### Driver

Name of Driver	TAN BOON CHEE
NRIC No	S6833228A
Date Of Birth	27/08/1968
Occupation	INDOOR
Date Of Driving Pass	25/02/2005
Driving Experience	14 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97493499
Fax Number	
Contact Number	OTHERS-97493499
EMail Address	WXYZ20090818@HOTMAIL.COM



Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	CLEMENTI NPC
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT NO: T/20190605/2003 LODGED AT CLEMENTI NPC. ON 05/06/2019 AT ABOUT 1832 HRS, I WAS DRIVING MY VEHICLE (SLV4013C) AT VIVOCITY BASEMENT 2 CAR PARK. I WAS BEHIND A LORRY (GBF3943D). I WAS APPROACHING A CORNER AND THE LORRY WAS ALREADY COMPLETE THE RIGHT TURN. STRAIGHT IN FRONT OF ME SLIGHTLY ON THE LEFT, THERE WAS A WORKER STANDING IN FRONT OF A DOOR WAVING TO ME DRAMATICALLY WHICH CAUSED ME TO FOCUS ON HIM AND I ASSUMED HE WAS TELLING ME NOT TO PARK. THEREFORE I PROCEEDED TO MOVE FORWARD AND AT THE SAME TIME TURNING RIGHT. ALL OF A SUDDEN, I COLLIDED WITH THE LORRY THAT WAS IN FRONT OF ME. THE LORRY WAS REVERSING AND DID NOT SEE ME AND I DID NOT SEE THE LORRY AS THERE WAS A PILLAR ON MY RIGHT BLOCKING THAT AREA. IN ADDITION, I WAS FOCUSED AT THE WORKER THAT WAS WAVING AT ME. I GOT OUT OF THE CAR TO TALK TO THE DRIVER AND THE WORKER AND HE INFORMED HE WAS ASKING ME TO STOP. I FELT THAT HE WAS DISTRACTING ME AND WE GOT INTO A DISPUTE AND CALLED FOR POLICE WITH REFERNCE D/20190604/0094. WE MANAGED TO EXCHANGE PARTICULARS AND LEFT SEPARATELY AFTER. THE DAMAGES ON MY CAR IS CRACKED RIGHT HEADLIGHT, DENTED BONNET AND RIGHT BUMPER WITH SCRATCHES. THE DAMAGES ON HIS LORRY IS HUST A BENT REAR SIGNAL LIGHT. THERE WAS NO INJURIES ON EITHER OF US AND I HAVE AN IN-VEHICLE CAMERA THAT CAPTURED THE WHOLE INCIDENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3943D
Vehicle Make/Model/Colour	TOYOTA DYNA 3.0 MANUAL
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver	KANAGARAJ ARULKUMAR
NRIC/Passport Number	G2285191N
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

# Sketch Plan

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available Application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 

I understand, acknowledge, agree and consent that:

  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS  
REPORTING OFFICER

Muhammad Faizal


Bin Pabla

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel

### Sketch Plan



## POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190605/2003

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-6729999

1 of 4

Report No: T/20190605/2003

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/06/2019 00:30	Vide Report No.:	Station Diary No.: 13
--	------------------	--------------------------

## Informant's Particulars

Name of Informant: TAN BOON CHEE			Address: 977 BUKIT TIMAH ROAD #08-33 SINGAPORE 589626		
ID Type / ID No.: NRIC NO / S6833228A			Contact No.: Home/Office: Mobile: 97493499		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 50	Date of Birth: 27/08/1968	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Semi Retired			Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Non-Injury	Drink Drive: No	Date/Time of Accident: 04/06/2019 18:30	Type of Location: Car Park
Location: Along Road 1 HARBOURFRONT WALK				
Vivacity Basement 2 Carpark near to Lobby H				
Weather:	Road Surface:		Road Speed Limit:	
Traffic Flow:	Traffic Control:		Traffic Volume:	
Type of Collision:				Anyone conveyed by ambulance: No

## Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBF3943D	Lorry				Slightly Damaged	0
SLV4103C	Car	MERCEDES BENZ	E250 AUTO	Black	Slightly Damaged	0

## Details of Vehicle Insurance

Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SLV4103C	FWD Singapore Pte. Ltd	PNPV2017-00009529-01	28/12/2018	27/12/2019

**POLICE REPORT**



**SINGAPORE  
POLICE FORCE**



T/20190605/2003

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

2 of 4  
Report No. T/20190605/2003

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	TAN BOON CHEE	ID No.	S6833228A
Related Vehicle	NIL	Contact No.	97493499
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	KANAGARAJ ARULKUMAR	ID No.	G2285191N
Related Vehicle	NIL	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 05/06/2019 at about 1832hrs, I was driving my vehicle(SLV4103C) at Vivocity Basement 2 Carpark. I was behind a lorry(GBF3943D). I was approaching a corner and the lorry has already completed the right turn. Straight in front of me slightly on the left there was a worker standing in front of a door waving to me dramatically which caused me to focus on him and I assumed he was telling me not to park therefore I proceeded to move forward and at the same time turning right.

All of a sudden, I collided with the lorry that was in front of me. The lorry was reversing and did not see me and I did not see the lorry as there was a pillar on my right blocking that area. In addition, I was focused at the worker that was waving at me. I got out of the car to talk to the driver and the worker and he informed he was asking me to stop. I felt that he was distracting me and we got into a dispute and called for police with reference D/20190604/0094.

We managed to exchange particulars and left separately after. The damages on my car is cracked right headlight, dented bonnet and right bumper with scratches. The damages on his lorry is just a bent rear signal light. There was no injuries on either of us and I have an in vehicle camera that captured the whole incident.



POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190605/2003

3 of 4

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Report No: T/20190605/2003

CONTINUATION OF REPORT

POLICE REPORT



**SINGAPORE  
POLICE FORCE**



T/20190605/2003

4 of 4

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Report No. T/20190605/2003

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:  
D /  
Sgt 3 BRENBAN LIM WEI JIE

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
05/06/2019 00:30

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No. 65476151

Classification Of Case:

Authentication Stamp  
SP150



SINGAPORE  
POLICE FORCE

SG 32

SIGNATURE

# TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 18/2/2016

## RE: VEHICLE REPAIR QUOTATION

Insurance Company  
Vehicle Reg No  
Name of Insured  
Policy Number  
Date of Accident  
Tyre of Claim  
Model  
Chassis No

AXA Insurance Pte Ltd  
**SLV4103C**  
Tan Boon Chee  
  
04.06.2019  
Third Party Claim  
Mercedes Benz E250  
WDD2130452A297409

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	BONNET	<i>Bz</i> \$ 2,092.53	✓
2	FRONT RH HEADLAMP	<i>cm</i> \$ 3,037.82	✓
3	HEADLAMP CONTROL MODULE	\$ 654.38	?
4	FRONT BUMPER	<i>Bu</i> \$ 1,662.71	✓
5	HEADLAMP LOWER BRACKET	\$ 81.79	?
6	FRONT BUMPER SIDE RETAINER	<i>m</i> \$ 25.00	✓
7	FRONT RH FENDER	<i>Bz</i> \$ 968.29	✓
8	BONET LOGO	<i>m</i> \$ 78.82	✓
9	SUPPORT PANEL TOP	\$ 734.13	?

Sub Total Parts \$ 9,335.47

Less 10% \$ 933.55

Total Parts \$ 8,401.92

*Not Notified*  
*Resurvey Bk paint*  
*4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal discounts are allowed
- Supplemental survey must be resurveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date:



1	Sundries	\$	80.00	?
2	Wiring connection and check.	\$	120.00	301
3	Tuff kote and spray anti rust proofing	\$	120.00	301
4	Labour charges to dismantle & refix RHF fender bonnet, front bumper, front headlamp To repair and adjust affected portion to specific dimension.	\$	1,500.00	5001
5	To spray paint front bonnet, front bumper, front RH fender and all other accident affected portion	\$	1,500.00	7501
7	To conduct and adjust headlamp focus and angle, calibration and coding for steering radius	\$	380.00	?
11	Remove and replace front bumper sensor	\$	150.00	601
12	Remove and replace front support panel, top up air con gas, check for leaks, vacuum refill	\$	550.00	?
13	To remove and refix radiator, conduct pressur test, check for leaks	\$	350.00	?
15	Sealant for body panel, front bonnet and front rh fender	\$	150.00	22 X
16	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	550.00	?
Total (Labour)		\$	5,450.00	
Sub Total :		\$	13,851.92	✗
GST 7%		\$	969.63	
<b>Grand Total :</b>		\$	<b>14,821.56</b>	

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019		10 Jun 2019 15:31 <a href="#">Edit Adj Rpt</a>	<b>S\$8,448.65</b> <a href="#">Edit Estimates</a>	<b>S\$8,448.65</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	<b>TAN BOON CHEE</b> , ID: S6833228A		
Vehicle Reg. No.:	<b>SLV4103C</b>	Date of Loss:	04/06/2019 18:00 - :59 [17 Months and 7 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM19D202513C02</b>	Policy/Cover Note No.:	DMCVSN30963418022
Vehicle Reg. No. (Insured):	<b>GBF3943D</b>	Policy No. (Claimant):	PNPV2017-00009529-01
		Excess:	S\$0.00
Repairer:	<b>Tts Eurocars Pte Ltd (HQ)</b> 383 SIN MING DRIVE, 575717 Sin Ming - Tel: 6842 222		
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]		
Claimant's Insurer:	<b>FWD Singapore Pte. Ltd. (HQ)</b> - Tel: 6727 5700		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 19/06/2019]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA\_TAIPING (16/07/2019): Alert - Adj Mandate Approved (S\$0.00) - SLV4103C - Claim Handler: Chong Boon Sen

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SLV4103C (SNM19D202513C02)**  
**[GBF3943D]**

**TP**  
**TAN BOON CHEE**  
**Jun 4 2019 6:00PM**  
**[-]**  
**Tts Eurocars Pte Ltd**

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

**View** [View in Browser](#) ▼

### Video

1 per page ▼ ☒

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	07/06/19 00:59	<b>Video - Accident</b> [Linked Accident Report Documents]	Load MP4	

### Assessment Reports

1 per page ▼ ☒

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	05/06/19 19:04	<b>Accident Statement</b>	Load HTM	
2	07/06/19 00:59	<b>Addendum Sheet</b>	Load TIFF	

### Photos/Images

3 per page ▼ ☒

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	05/06/19 16:44	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	05/06/19 16:44	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
8	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
9	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
10	05/06/19 16:45	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
11	05/06/19 16:46	<b>Identification Card</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
12	05/06/19 16:46	<b>Identification Card</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
13	05/06/19 16:46	<b>Driving License</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
14	05/06/19 16:46	<b>Driving License</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	20/01/20 13:36	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
9	20/01/20 13:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	20/01/20 13:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	20/01/20 13:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	20/01/20 13:36	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/19 09:06	pri contact	Load PDF	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	05/06/19 16:43	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	05/06/19 16:47	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	05/06/19 16:47	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	05/06/19 16:47	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	05/06/19 16:47	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

View View in Browser

Video			1 per page	
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	07/06/19 00:59	Video - Accident	Load MP4	

Assessment Reports

1 per page

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	29/06/19 12:11	Addendum Sheet	Load TIFF	
2	04/09/19 01:17	Accident Statement	Load HTM	
3	04/09/19 01:17	Accident Statement	Load HTM	
4	04/09/19 01:28	Accident Statement	Load HTM	

Photos/Images

3 per page

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	05/06/19 16:44	Accident Photo	Load JPG	
2	05/06/19 16:44	Accident Photo	Load JPG	
3	05/06/19 16:45	Accident Photo	Load JPG	
4	05/06/19 16:45	Accident Photo	Load JPG	
5	05/06/19 16:45	Accident Photo	Load JPG	
6	05/06/19 16:45	Accident Photo	Load JPG	
7	05/06/19 16:45	Accident Photo	Load JPG	
8	05/06/19 16:45	Accident Photo	Load JPG	
9	05/06/19 16:45	Accident Photo	Load JPG	
10	05/06/19 16:45	Accident Photo	Load JPG	
11	05/06/19 16:46	Identification Card	Load JPG	
12	05/06/19 16:46	Identification Card	Load JPG	
13	05/06/19 16:46	Driving License	Load JPG	
14	05/06/19 16:46	Driving License	Load JPG	

Documentation

1 per page

No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	05/06/19 16:43	Sketch Plan	Load JPG	
2	05/06/19 16:47	POLICE REPORT	Load JPG	

Video			1 per page ▾	✓
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
3	05/06/19 16:47	POLICE REPORT	Load JPG	✓
4	05/06/19 16:47	POLICE REPORT	Load JPG	✓
5	05/06/19 16:47	POLICE REPORT	Load JPG	✓
6	29/06/19 12:11	Email Attachment	Load TIFF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19010320/KSD3S2

Date: 04/02/2020

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30963418022
Claimant Vehicle No :	SLV4103C	Insured Vehicle No :	GBF3943D
Date of Loss:	04/06/2019	Nature of Claim:	TP
		Claim No:	SNM19D202513C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLV4103C	Engine No:	27492031145062
Make & Model:	MERCEDES-BENZ E250, 1.8 (A)	Chassis No:	WDD2130452A297409
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	26299 km
Colour:	Metallic Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	275/35 R19
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,481.92	7,078.65	1,403.27	16.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,370.00	1,370.00	4,000.00	74.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,851.92</b>	<b>8,448.65</b>	<b>5,403.27</b>	<b>39.01</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>969.63</b>	<b>591.41</b>	<b>378.22</b>	<b>39.01</b>
<b>Nett Amount (S\$)</b>	<b>14,821.55</b>	<b>9,040.06</b>	<b>5,781.49</b>	<b>39.01</b>

## INSPECTION

Date of Assignment:	10/06/2019		
Date Inspected:	11/06/2019	Inspected At:	Tts Eurocars Pte Ltd (HQ) 383 SIN MING DRIVE Singapore 575717
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.





(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$3,233.27 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Feb 2020)
<b>Parts:</b>	143	MERCEDES-BENZ E250 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLV4103C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,092.53 FL	*2,092.53 FL
2	1		*FRONT RH HEADLAMP	Cracked	3,037.82 FL	*3,037.82 FL
3	1		*HEADLAMP CONTROL MODULE	*Check	654.38 FL	*- FL
4	1		*FRONT BUMPER	Buckled	1,662.71 FL	*1,662.71 FL
5	1		*HEADLAMP LOWER BRACKET	*Check	81.79 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINER	Necessary	25.00 FL	*25.00 FL
7	1		*FRONT RH FENDER	Bent	968.29 FL	*968.29 FL
8	1		*BONNET LOGO	Necessary	78.82 FL	*78.82 FL
9	1		*SUPPORT PANEL TOP	*Check	734.13 FL	*- FL
10	1		*SUNDRIES	*Check	80.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>9,415.47</b>	<b>7,865.17</b>
<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	933.55	786.52
<b>Total Parts (S\$)</b>	<b>8,481.92</b>	<b>7,078.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	WIRING CONNECTION AND CHECK.	New	120.00	30.00
2	TUFF KOTE AND SPRAY ANTI RUST PROOFING.	New	120.00	30.00
3	LABOUR CHARGES TO DISMANTLE & REFIX RHF FENDER BONNET, FRONT BUMPER, FRONT HEADLAMP. TO REPAIR AND ADJUST AFFECTED PORTION TO SPECIFIC DIMENSION.	New	1,500.00	500.00
4	TO SPRAY PAINT FRONT BONNET, FRONT BUMPER, FRONT RH FENDER AND ALL OTHER ACCIDENT AFFECTED PORTION.	New	1,500.00	750.00
5	TO CONDUCT AND ADJUST HEADLAMP FOCUS AND ANGLE, CALIBRATION AND CODING FOR STEERING RADIUS. (*Check)	New	380.00	0.00
6	REMOVE AND REPLACE FRONT BUMPER SENSOR.	New	150.00	60.00
7	REMOVE AND REPLACE FRONT SUPPORT PANEL, TOP UP AIR CON GAS, CHECK FOR LEAKS, VACUUM REFILL. (*Check)	New	550.00	0.00
8	TO REMOVE AND REFIX RADIATOR, CONDUCT PRESSURE TEST, CHECK FOR LEAKS. (*Check)	New	350.00	0.00
9	SEALANT FOR BODY PANEL, FRONT BONNET AND FRONT RH FENDER.	New	150.00	0.00
10	TO CONDUCT ECU PROGRAMMING, CHECK AND CLEAR FAULT CODES, RESTORE PROGRAMME MODULES. (*Check)	New	550.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>5,370.00</b>	<b>1,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >