

ASS. REC. BY:

REF: CS/SMD19010326 | U+D3N2 | Special Instruction:

SUPERVISOR

marcus

ASSIGNMENT (Office)

From (Person): Hwang shiang Yi of SMD Date/Time: 10.6.19 16.10p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 580 L Insured: SL C 293 M

at Workshop m/s New Te Automobile Tel: 6702 3113

of B1C 25 Kaki Bukit Road 4, #01-61

Policy No: D18MTPV01016301 Claim No: CMTD 1902769

Sum Insured: Excess:

Make of Veh: D.O.A. 31.5.19
(Client's Record) 12.6.19 3.00pm

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 11.6.19 10.53a.m Person Contacted: M/V Vehicle: IN (OUT)

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|-----------------------------------|
| | SKS 580 L-x |
| | SLC 293 M-x |
| 14/6- | Revised via merimen preli advise |
| | |
| | |

ASS. REC. BY:

ASSIGNMENT

From: Date: 12.6.2019

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SKS 580L

at Workshop m/s Yew Tee Automobile
of Blk 25 Kaki Bukit Road 4, #01-61

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 3.00 p.m

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value: 50

IDAC Accident Rpt: Consistent? : Yes or No

GIA PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

MAY 17 43314

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKS 580L Yr Regn: 3115

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Sylphy C.C. 1598

Colour: Brown AC: Insured / Std / NI / NA

Sp. Reading: 1100 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. mm

D.O.A. 3.15/19

Survey held at

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Restop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Syrs 9th. End part derect need 1 more day.

26/6/19 4/5 @ 2200 confirmed with my - (Red: 3110.09: 58%)

RECEIVED 27 JUN 2019

Date/Time, File Pass to?

1) 27/6 Typst

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 2200

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

3 + RS, SI

Photos

Others

TOTAL

250

11

261

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hwang Shiang Yi

Date: 14 Jun 2019

Preliminary Advice

| | | | |
|--------------------|---|-------------------------|--------------|
| Insured Vehicle No | : SLC293M | Accident Date | : 31/05/2019 |
| TP Vehicle No | : SKS580L | Assignment Date | : 10/06/2019 |
| Make | : NISSAN SYLPHY | Est. Duration of Repair | : 3.00 |
| Date of Inspection | : 12/06/2019 | | |
| Inspection At | : YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT) BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800 | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 5,310.09 |
| Revised Amount | :S\$ | 2,176.14 |
| Check Items (Estimated) | :S\$ | 425.61 |
| Total | :S\$ | 2,601.75 |

| | |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|-------------|---------------|--|---------|---------------|------------|--|
| Main | 01 Jun 2019 | | 10 Jun 2019 16:10 Assign | | | | New Assignment Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

NEVIN NATH S/O RAJA SEKARAN, ID: S8004407J, Tel: +6590043261, Email: NERINNATH@YAHOO.COM

Main Claimant:

CHAN PUI LOON, ID: S7203762F

Vehicle Reg. No.:

SKS580L

Date of Loss:

31/05/2019 18:00 - :59

Claim Type:

TP / CMTD1902769

Policy/Cover Note No.:

D18MTPV01016301 (Comprehensive)

Vehicle Reg. No. (Insured):

SLC293M

Policy No. (Claimant):

Excess:

Repairer:

Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT, 417800 Kaki Bukit - Tel: 67023113

Handling Insurer:

Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Hwang Shiang Yi - 6329 5205]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2019]

Driver/Custodian (Insured):

NEVIN NATH S/O RAJA SEKARAN (39 / Male), NRIC: S8004407J, Tel: +6590043261 Email: NERINNATH@YAHOO.COM

Adj Asg. Remarks:

WS: MAY 6702 3113

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F

SELL YOUR CAR YOURSELF

Get listed until it's sold + we will handle all the paperwork!



Nissan Sylphy

Price Range ▼

Depreciation ▼

2015 ▼

Vehicle Type ▼



Home » Used Cars » Ritz Auto » Nissan Sylphy 1.6A

Nissan Sylphy 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$54,800

Depreciation ? \$8,740 /yr
View models with similar depre

Reg Date 13-Feb-2015
(5yrs 7mths 30days COE left)

Mileage 56,122 km (13k /yr)

Manufactured ? 2014

Road Tax ? \$742 /yr

Transmission Auto

Dereg Value ? \$43,002 as of today (change)

OMV ? \$15,430

COE ? \$62,002

ARF ? \$10,430

Engine Cap 1,598 cc

Power 85.0 kW (113 bhp)

Curb Weight ? 1,205 kg

No. of Owners ? 1

Type of Vehicle Mid-Sized Sedan

Features

Power 1.6L DOHC 16 Valves Twin C-VTC Engine, X-Tronic CVT Automatic, Keyless Entry/Start/Stop, Digital Climatic Aircon Controls, SRS Airbags, ABS. View specs of the Nissan Sylphy (2013-2016)

Accessories

Sports Rims, Leather Seats, Built In Audio System With Steering Controls, Reverse Sensors And Camera And GPS, Auto Retractable Side Mirrors. Rear Air.

Description

Accident Free! 1 Owner! Can Loan \$47K x 70 Months = \$760! Very Well Kept Low Mileage, Full Agent Maintained. High Paper Value At \$45K! Please Do Not Hesitate To Contact Sale Person To Arrange For A Viewing, Many Thanks!

Category

PARF Car

Status


Available

Compare



Location Map

Price Chart



Click on the point to view

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 3762F |
| Vehicle Details | |
| Vehicle No.: | SKS580L |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 13 Jun 2019 |
| Vehicle Make: | NISSAN |
| Vehicle Model: | SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR |
| Primary Colour: | Grey |
| Manufacturing Year: | 2014 |
| Engine No.: | HR16958770B |
| Chassis No.: | MNTBBAB17Z0022752 |
| Maximum Power Output: | 85.0 kW (113 bhp) |
| Open Market Value: | \$15,430.00 |
| Original Registration Date: | 25 Mar 2015 |
| First Registration Date: | 25 Mar 2015 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$10,430.00 <i>5/2/15</i> |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 24 Mar 2025 |
| PARF Rebate Amount: | \$7,822.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 24 Mar 2025 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$61,410.00 |
| COE Rebate Amount: | \$35,492.00 |
| Total Rebate Amount: | \$43,314.00 |

The information contained herein is correct as at 13 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|----------------------------|--------------------|
| Date Of Report | 01/06/2019 11:27 |
| Date Of Accident | 31/05/2019 18:40 |
| Exact Location Of Accident | PIE TOWARDS CHANGI |
| Country/State of Loss | SINGAPORE |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKS580L |
| Insured/Policyholder | |
| Name Of Registered Owner | CHAN PUI LOON |
| NRIC No | S7203762F |
| Email Address | NOEMAIL |
| Mobile Phone No | (LOCAL) +65-96948621 |
| Alternative Phone No | OFFICE-96948621 |

Vehicle Particulars

| | |
|--|-------------|
| Manufacturer | NISSAN |
| Model | SYLPHY 1.6 |
| Exact Purpose for which vehicle was being used at time of accident | PRIVATE USE |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO |
| If No, Please state action to be taken | THIRD PARTY |
| Vehicle Category | PRIVATE CAR |

Insurance Company

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | MSIG INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage | COMPREHENSIVE |
| Fleet Policy | NO |
| Policy Number | A80468150QMX |
| Cover Note Number | |

Driver

| | |
|----------------------|-----------------------|
| Name of Driver | CHAN PUI LOON |
| NRIC No | S7203762F |
| Date Of Birth | 12/02/1972 |
| Occupation | INDOOR |
| Date Of Driving Pass | 04/10/1996 |
| Driving Experience | 22 YEARS AND 7 MONTHS |
| Gender | MALE |
| Mobile Number | (LOCAL) +65-96948621 |
| Fax Number | |
| Contact Number | OFFICE-96948621 |
| EMail Address | NOEMAIL |

| | |
|---|---|
| Address | APT BLK 770 BEDOK RESERVOIR ROAD #11-05 |
| Postcode | 479250 |
| Was driver an employee of the Insured's Company | NO |
| If No, Relationship of the Driver with the Insured | OWNER |
| Vehicle Registration Number of Driver's Own Vehicle | - |
| | - |
| | - |
| Insurance Company of Driver's Own Vehicle | - |
| | - |
| | - |

General Information of the Accident

| | |
|--------------------|--------------------------|
| Type Of Accident | COLLISION - HEAD TO REAR |
| Weather Conditions | CLEAR |
| Road Surface | DRY |

Other Information

| | |
|---|-----|
| Was any foreign vehicle involved in this accident? | NO |
| Number of vehicles (including own vehicle) involved in the accident | 2 |
| Was any body injured in the Accident? | NO |
| Was any injured conveyed to hospital by ambulance? | NO |
| Was any other material or property damaged? | YES |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO |
| Number of Passengers (Including Driver) | 1 |

Details of Police Action

| | |
|---|----|
| Was the accident reported to the police? | NO |
| If Yes, Please state which Police Station | |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom? | |

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

| | |
|---|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera? | YES |
| Was there any audio recorded? | NO |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-------------------------------------|-------------|
| Vehicle Registration Number | SLC293M |
| Vehicle Make/Model/Colour | |
| Details Of Properties | |
| Vehicle Category | PRIVATE CAR |
| Name of Driver | |
| NRIC/Passport Number | |
| Contact Number | |
| Address | |
| Postcode | |
| Insurance Company Name | |
| Nature Of Damage | |
| No. Of Passenger (Including Driver) | |

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A - SKS 580L
B - SLC 293M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Front car slowing down due to traffic jam, and I slowing down as well. Out of sudden, I'm felt an impact from my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : SOMPO INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

| | | | |
|-------------------|----------------|--------------------------|------------------|
| Claim Type: | TP | Ref. No: | YTKB/TP/1906/001 |
| Policy No: | A80468150QMX | Date of Loss: | 31/05/2019 |
| Vehicle Reg. No.: | SKS580L | Driveable? | yes |
| Driver Age: | 12/02/1972 | Third Party Vehicle No.: | SLC293M |
| Any Injuries? | no | Contact No: | 96948621 |
| Insured/Claimant: | CHAN PUI LOON | Driver: | CHAN PUI LOON |

| | | | |
|-----------------|-------------------|------------------------------|-------------|
| Make/Model: | Nissan, Sylphy - | Vehicle Reg. Date: | 25 Mar 2015 |
| | MNTBBAB17Z0007460 | | |
| Vehicle Colour: | | Engine Number: | |
| Chassis No: | MNTBBAB17Z0022752 | Odometer: | |
| Total Loss? | | Est. Duration of Repair(Day) | |

Description of Accident/loss: COLLISION - HEAD TO REAR
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

| | Amount |
|---------------------|----------|
| Parts | 3,090.09 |
| Miscellaneous Items | 245.00 |
| Labour | 1,090.00 |
| Paintwork Labour | 885.00 |
| Towing | 0.00 |

| | |
|--------------------------|-----------------|
| Gross Total(S\$): | 5,310.09 |
| GST 7.00%(S\$): | 371.71 |
| Nett Amount(S\$): | 5,681.80 |

This claim is handled by: Shaun Toh L M

YTKB Auto Consultants hence notify the Receiver of the following:

- To resurvey & refinish spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Receiver
Signature:
Date:

not signed
2200
427
12/6/19
Whipke Ateng

REPAIR DETAILS**Estimates On Parts**

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|---|------|-----------------|--------|-----------------|
| 1 | 1 | REAR BUMPER <i>OK ✓</i> | 0.00 | 607.80 <i>✓</i> | -30.00 | 425.46 <i>✓</i> |
| 2 | 1 | REAR BUMPER SIDE RETAINER LH <i>11 X</i> | 0.00 | 33.60 | -10.00 | 30.24 <i>X</i> |
| 3 | 1 | REAR BUMPER SIDE RETAINER RH <i>11 X</i> | 0.00 | 33.60 | -10.00 | 30.24 <i>X</i> |
| 4 | 1 | REAR TAILGATE <i>2 X</i> | 0.00 | 846.00 <i>✓</i> | -30.00 | 592.20 <i>X</i> |
| 5 | 1 | REAR TAILGATE LOWER PROTECTOR <i>11 X</i> | 0.00 | 260.00 | -10.00 | 234.00 <i>X</i> |
| 6 | 1 | REAR TAILGATE LOCK <i>11 X</i> | 0.00 | 135.00 | -10.00 | 121.50 <i>X</i> |
| 7 | 1 | REAR TAILGATE LOCK CATCH <i>11 X</i> | 0.00 | 83.30 | -10.00 | 74.97 <i>X</i> |
| 8 | 1 | REAR TAILGATE RUBBER <i>2w1 ✓</i> | 0.00 | 83.30 | -10.00 | 74.97 <i>✓</i> |
| 9 | 1 | REAR TAILGATE REFLECTOR RH <i>11 X</i> | 0.00 | 58.00 | -10.00 | 52.20 <i>X</i> |
| 10 | 1 | REAR TAILGATE REFLECTOR LH <i>11 X</i> | 0.00 | 58.00 | -10.00 | 52.20 <i>X</i> |
| 11 | 1 | REAR TAILGATE LOWER CHROME <i>11 X</i> | 0.00 | 123.10 | -10.00 | 110.79 <i>X</i> |
| 12 | 1 | REAR END PANEL <i>OK X</i> | 0.00 | 428.40 <i>✓</i> | -30.00 | 299.88 <i>X</i> |
| 13 | 1 | REAR END PANEL INNER GARNISH <i>OK X</i> | 0.00 | 91.70 | -10.00 | 82.53 <i>X</i> |
| 14 | 1 | REAR BUMPER SPOILER <i>OK ✓</i> | 0.00 | 961.90 | -10.00 | 865.71 <i>✓</i> |
| 15 | 1 | REAR BUMPER SPONGE <i>OK</i> | 0.00 | 48.00 | -10.00 | 43.20 <i>X</i> |

Total Parts (\$\$) 3,090.09

Estimates of Miscellaneous Items

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|--------------|--------------------------------------|------|-------------------|-------|------------|
| 1 | 1 <i>set</i> | REAR BUMPER CLIPS <i>OK</i> | 0.00 | 45.00 <i>40</i> | 0.00 | 45.00 |
| 2 | 1 <i>set</i> | REAR BUMPER REVERSE SENSOR <i>OK</i> | 0.00 | 200.00 <i>200</i> | 0.00 | 200.00 |

Sub Total (\$\$) 245.00

Estimates On Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|---|--------|-----------------|---------------|-----------------------------|
| 1 | 1 | To Remove and Refit Rear Bumper Sensor. | 80.00 | 80.00 <i>50</i> | 0.00 | 80.00 |
| 2 | 1 | To Transfer Rear Tailgate. | 80.00 | 80.00 <i>11</i> | 0.00 <i>X</i> | 80.00 |
| 3 | 1 | To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools. | 800.00 | 800.00 | 0.00 | <i>800.00</i> <i>520</i> |
| 4 | 1 | To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts. | 30.00 | 30.00 | 0.00 | <i>20</i> 30.00 |
| 5 | 1 | To Remove And Refit Carpet And Trims On The Rear Section To Give Way To The Repair on The Rear Section. | 100.00 | 100.00 | 0.00 | <i>60</i> 100.00 |

Gross Labour Cost (\$\$) 1,090.00

Estimates On Paint Work Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|--|--------|--------|----------------|----------------|
| 1 | 1 | To Carry-Out Body Cavity Preservation. | 40.00 | 40.00 | 0.00 <i>11</i> | 40.00 <i>X</i> |
| 2 | 1 | To Apply Undercoating On The Repaired and Replaced Panels For Rust Protection. | 45.00 | 45.00 | 0.00 <i>11</i> | 45.00 <i>X</i> |
| 3 | 1 | To Spray painting on the Replaced and Repair | 800.00 | 800.00 | 0.00 | 800.00 |

600

Estimates On Paint Work Labour

| No. | Qty | Particulars | Rate | Amount | %Disc | After Disc |
|-----|-----|---|------|--------|-------|------------|
| | | Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available. | | | | |

Gross Labour Cost (\$\$) 885.00

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

List Net
 P- 607.80 933.30 S.W 16hr
 32 102 240 1250
 425.46 839.97 240 1250
 TOTAL 2755.43
 207
 2204.34

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19010326/UTD3N2

Date: 28/06/2019

REFERENCE

| | | | |
|-----------------------|-------------------------------------|----------------------|-----------------|
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. | Policy No: | D18MTPV01016301 |
| Claimant Vehicle No : | SKS580L | Insured Vehicle No : | SLC293M |
| Date of Loss: | 31/05/2019 | Nature of Claim: | TP |
| | | Claim No: | CMTD1902769 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SKS580L | Engine No: | HR16958770B |
| Make & Model: | NISSAN SYLPHY, 1.6 (A) | Chassis No: | MNTBBAB17Z0022752 |
| Reg. Date: | 25/03/2015 (Man. Year: 2014) | Odometer: | 81018 km |
| Colour: | Brown | | |
| Engine Capacity: | 1598 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 205/55R16 | Rear Tyre Size: | 205/55R16 |
| Front Left Side: | Hankook 6 mm | Rear Left Side: | Hankook 6 mm |
| Front Right Side: | Hankook 6 mm | Rear Right Side: | Hankook 6 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 3,335.09 | 1,505.43 | 1,829.66 | 54.86 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,975.00 | 1,250.00 | 725.00 | 36.71 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 5,310.09 | 2,755.43 | 2,554.66 | 48.11 |
| Approved Total (Overridden) (S\$) | | 2,200.00 | | |
| (S\$) | 5,310.09 | 2,200.00 | 3,110.09 | 58.57 |
| + GST 7.00/7.00% (S\$) | 371.71 | 154.00 | 217.71 | 58.57 |
| Nett Amount (S\$) | 5,681.80 | 2,354.00 | 3,327.80 | 58.57 |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 10/06/2019 | |
| Date Inspected: | 12/06/2019 | Inspected At: |
| | | Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT Singapore 417800 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|---|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 28 Jun 2019) |
| Parts: 143 | NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SKS580L) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|-----------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Dented/Deformed | 607.80 FL | *607.80 FL |
| 2 | 1 | | *REAR TAILGATE | Repair | 846.00 FL | *- FL |
| 3 | 1 | | *REAR END PANEL | Repair | 428.40 FL | *- FL |
| 4 | 1 | | *REAR BUMPER SIDE RETAINER LH | Not Necessary | 33.60 FN | *- FN |
| 5 | 1 | | *REAR BUMPER SIDE RETAINER RH | Not Necessary | 33.60 FN | *- FN |
| 6 | 1 | | *REAR TAILGATE LOWER PROTECTOR | Not Necessary | 260.00 FN | *- FN |
| 7 | 1 | | *REAR TAILGATE LOCK | Not Necessary | 135.00 FN | *- FN |
| 8 | 1 | | *REAR TAILGATE LOCK CATCH | Not Necessary | 83.30 FN | *- FN |
| 9 | 1 | | *REAR TAILGATE RUBBER | Twisted | 83.30 FN | *83.30 FN |
| 10 | 1 | | *REAR TAILGATE REFLECTOR RH | Not Necessary | 58.00 FN | *- FN |
| 11 | 1 | | *REAR TAILGATE REFLECTOR LH | Not Necessary | 58.00 FN | *- FN |
| 12 | 1 | | *REAR TAILGATE LOWER CHROME | Not Necessary | 123.10 FN | *- FN |
| 13 | 1 | | *REAR END PANEL INNER GARNISH | Not Necessary | 91.70 FN | *- FN |
| 14 | 1 | | *REAR BUMPER SPOILER | Cracked | 961.90 FN | *850.00 FN |
| 15 | 1 | | *REAR BUMPER SPONGE | Not Necessary | 48.00 FN | *- FN |
| 16 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 45.00 FS | *40.00 FS |
| 17 | 1 | | *SET REAR BUMPER REVERSE SENSOR | Shorted | 200.00 FS | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$\$) | 4,096.70 | 1,781.10 |
| - List Item Discount on L Items 30.00/30.00% (\$\$) | 564.66 | 182.34 |
| - Nett Item Discount on N Items 10.00/10.00% (\$\$) | 196.95 | 93.33 |
| Total Parts (\$\$) | 3,335.09 | 1,505.43 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REFIT REAR BUMPER SENSOR | New | 80.00 | 50.00 |
| 2 | TO TRANSFER REAR TAILGATE | New | 80.00 | 0.00 |
| 3 | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS | New | 800.00 | 520.00 |
| 4 | TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS | New | 30.00 | 20.00 |
| 5 | TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GAVE WAY TO THE REPAIR ON THE REAR SECTION | New | 100.00 | 60.00 |
| 6 | TO CARRY-OUT BODY CAVITY PRESERVATION | New | 40.00 | 0.00 |
| 7 | TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION | New | 45.00 | 0.00 |
| 8 | TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE | New | 800.00 | 600.00 |
| Gross Labour Cost (S\$) | | | 1,975.00 | 1,250.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >