

ASS. REC. BY:

REF: CS/CT119010328/ Afd3n2 Special Instruction:

Surveyor: Adrian ASSIGNMENT (Office)From (Person): Chong Boon Sen of CTI Date/Time: 10.6.19 16.22p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GZ 68614 Insured: SKU 6914Hat Workshop m/s Sue Cross United Tel: 67461515of 2 Kaki Bukit Ave 2 #01-33Policy No: DMPCSN 30980518011 Claim No: SNM19020 2507102

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 11.6.19 9.19 a.m Person Contacted: An Giang H.O.D. Endorsement: _____Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>GZ 68614 - NBA/AWA15006314 1e1</u> <u>D.O.A - 10/04/2015</u>
	<u>SKU 6914H - CS/EG1170034091 Agh 3n2</u> <u>D.O.A - 12/02/2017</u>
	<u>lump sum \$2200- (Red. 2085.20; 48%)</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jun 2019		10 Jun 2019 16:22 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	PEH AIK CONTRACTOR PTE LTD, Co. Reg. No.: 201312860W		
Vehicle Reg. No.:	GZ6861Y	Date of Loss:	05/06/2019 10:00 - :59
Claim Type:	TP / SNM19D202507C02	Policy/Cover Note No.:	DMPCSN30880518011
Vehicle Reg. No. (Insured):	SKU6914H	Policy No. (Claimant):	D19MCV0000725
		Excess:	\$0.00
Repairer:	Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub, 417921 Kaki Bukit - Tel: 6746 1515		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

2860W

Vehicle Details

Vehicle No.:

GZ6861Y

Vehicle to be Exported:

No

Intended Deregistration Date:

06 Jun 2019

Vehicle Make:

KIA

Vehicle Model:

K2700 S/C

Primary Colour:

White

Manufacturing Year:

2006

Engine No.:

J2447320

Chassis No.:

KNCSE011267154120

Maximum Power Output:

-

Open Market Value:

\$11,583.00

Original Registration Date:

31 Jul 2006

First Registration Date:

31 Jul 2006

Transfer Count:

3

Actual ARF Paid:

\$580.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

30 Jul 2021

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

5

PQP Paid:

\$22,247.00

COE Rebate Amount:

\$9,556.00

Total Rebate Amount:

\$9,556.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 06 Jun 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	2860W

Vehicle Details

Vehicle No.:	GZ6861Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	KIA
Vehicle Model:	K2700 S/C
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	J2447320
Chassis No.:	KNCSE011267154120
Maximum Power Output:	-
Open Market Value:	\$11,583.00
Original Registration Date:	31 Jul 2006
First Registration Date:	31 Jul 2006
Transfer Count:	3
Actual ARF Paid:	\$580.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,247.00
COE Rebate Amount:	\$9,425.00
Total Rebate Amount:	\$9,425.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 17 Jun 2019

OK

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909 079909

Attention : Motor Claim Department

Contact : 6389 6111 (main) Fax No. : 6222 1033

Estimate : TP19-074

Date : 07/06/2019

Vehicle Num. : GZ6861Y

Make/Model : Kia K2700-2006

Chassis/Eng# : KNCSE011267154120/J2447320

Accident Date : 07/06/2019

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Frt Headlamp LH <i>could</i>		392.00 ✓
2.	1 pc	Frt Bumper LH <i>could</i>		473.00 ✓
3.	1 pc	Frt Bumper Side Holder LH <i>re</i>		48.00 ✓
4.	1 pc	Frt Bumper Corner Panel LH <i>could</i>		141.00 ✓
5.	1 pc	Frt Door LH <i>could</i>		861.00 ✓
6.	2 pcs	Frt Door Hinge (Top/ Lower) <i>re</i>	55.00	110.00 +
7.	1 pc	Frt Door Center Checker LH <i>re</i>		48.00 +
8.	1 pc	Frt Door Weatherstrip LH <i>re</i>		150.00 +
9.	1 pc	Frt Door Pillar LH <i>re</i>		805.00 +

List Total S\$:

10.00% Discount S\$:

3,028.00

302.80

2,725.20

LABOUR :

To remove, rearrange electrical wirings, check lighting

60.00 30

To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident

600.00 500

To putty and respray painting on affected area.

900.00 500

Labour Total S\$:

1,560.00

Total S\$: 4,285.20

=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2733.50

L/S : 2.2K

Adrian L
H/s 16/04/19.
05 days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119010328/ATD3N2

Date: 19/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30880518011	
Claimant Vehicle No :	GZ6861Y	Insured Vehicle No :	SKU6914H	
Date of Loss:	05/06/2019	Nature of Claim:	TP	Claim No: SNM19D202507C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ6861Y	Engine No:	J2447320
Make & Model:	KIA K2700, 2.7 D B31 (M)	Chassis No:	KNCSE011267154120
Reg. Date:	31/07/2006 (Man. Year: 2006)	Odometer:	300359 km
Colour:	Green		
Engine Capacity:	2665 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185 R14C	Rear Tyre Size:	155 R12C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	CHARMHOO 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	CHARMHOO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,725.20	1,723.50	1,001.70	36.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,560.00	1,030.00	530.00	33.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,285.20	2,753.50	1,531.70	35.74
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	4,285.20	2,200.00	2,085.20	48.66
+ GST 7.00/7.00% (S\$)	299.96	154.00	145.96	48.66
Nett Amount (S\$)	4,585.16	2,354.00	2,231.16	48.66

INSPECTION

Date of Assignment:	10/06/2019	
Date Inspected:	14/06/2019	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Sep 2019)	
Parts:	N/A	KIA K2700 2.7 D B31 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GZ6861Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT HEADLAMP LH	Cracked	392.00 FL	*392.00 FL
2	1		*FRT BUMPER	Deformed	473.00 FL	*473.00 FL
3	1		*FRT BUMPER SIDE HOLDER LH	Necessary	48.00 FL	*48.00 FL
4	1		*FRT BUMPER CORNER PANEL LH	Dented	141.00 FL	*141.00 FL
5	1		*FRT DOOR LH	Dented	861.00 FL	*861.00 FL
6	2		*FRT DOOR HINGE (TOP/LOWER)	Not Necessary	110.00 FL	*- FL
7	1		*FRT DOOR CENTER CHECKER LH	Not Necessary	48.00 FL	*- FL
8	1		*FRT DOOR WEATHERSTRIP LH	Not Necessary	150.00 FL	*- FL
9	1		*FRT DOOR PILLAR LH	Repair	805.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,028.00	1,915.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	302.80	191.50
Total Parts (\$\$)	2,725.20	1,723.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	60.00	30.00
2	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	600.00	500.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	900.00	500.00
Gross Labour Cost (\$\$)			1,560.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >