



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Mr Ho Kok Soon	Cust No/Name /Mr Ho Kok Soon
Blk 80 Bedok North Road	Reg No/Reg Date SLE6774S / 29/07/201
#14-280	Date In/Mileage / 0
Singapore 460080	Chassis No MMBSTA13AHH001574
Contact No Mobile: 98501575	Engine No 3A92UDG3209
	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	08/06/2019/ 16:21	QUE	261 / Edwin Caina	40756		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							3000.00
RENEW & RE-ALIGN RR DAMAGED PORTION:							1100
-RENEW RR BUMPER							1470
-REPAIR RR FENDER LH , RR END PNL & BOOTLID							1700.00
E PNT98000							275.00
RESPRAY RR BUMPER , RR END PNL , BOOTLID & RR FENDER LH							50.00
E PNT88000							200.00
REMOVE & REFIT RR FLR BOARD,TRIM & CARPET TO FACILITATE REPAIR							80
A 54900099							80
CHECK WIRING ELECTRICAL SYSTEM							100.00
A 10028901							220.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							40
USING HI-SCAN PRO TEST							40
M SUNDRY							40.00
APPLY ANTI CORROSION ON AFFECTED AREAS							40.00
E PNT88000							40.00
REMOVE & REFIT REVERSE SENSOR							40.00
M SUNDRY							40.00
SUPPLY REVERSE SENSOR							40.00
M SUNDRY							40.00
SUPPLY C&C BADGE							40.00
M SUNDRY							40.00
SUPPLY MIVEC EMBLEM							40.00
M SUNDRY							40.00
Sundries							40.00
M FACE,RR BUMPER				1.00	740.00	00.00	740.00
M CLIP,RR BUMPER				4.00	3.00	00.00	12.00
M BRACKET,RR BUMPER,LH				1.00	27.00	00.00	27.00
M BRACKET,RR BUMPER,RH				1.00	27.00	00.00	27.00
M LAMP ASSY,COMB,RR LH				1.00	332.00	00.00	332.00
M MARK,THREE-DIA				1.00	45.00	00.00	45.00
M MARK,ATTRAGE				1.00	21.00	00.00	21.00

Estimate

SURVEYOR NAME: Rahul - Hy 9000065

SURVEYOR SIGNATURE: [Signature]

DATE: 22/07/19 @ 1300

REMARKS: 5 days

Reay before print

SURVEYOR NAME: Rahul - H 98501575SURVEYOR SIGNATURE: [Signature]DATE: 22/07/19 @ 1300REMARKS: 5 daysReady before print

Confirm & accepted by

7% GST on **Nett** 6,999.00 6,999.00

Total Payable 7,488.93

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Exceptional Journeys

Surveyor : Rasul - LKK
Company : India
DOA : 07/06/2019
CSE : Edwin
Date of Survey : 22/07/2019

VEHICLE NO : SLE6774S
MODEL : MIT/ 17MY ATTRAGE 1.2 CVT
WIP : 40756

Material	:	\$	1,152.00
Labour	:	\$	3,325.00
Sub-Total	:	\$	4,477.00
Less Excess	:	\$	-
Total	:	\$	4,477.00
GST 7%	:	\$	313.39
Grand Total	:	\$	4,790.39
Finalise By/Date	:	JoJo dtd 10/09/2019	

Email :

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 5 WORKING DAYS + 2 Days (1) Weekends
+ Days () Public Holiday
+ 1 Survey - 22/07/2019 - Mon
TOTAL DAYS REPAIR TOOK = 8

☒ TP Claim India - SH9952B

☐ Claim GIA / LTA fee

☒ Claim Loss ☐ Use ☒ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04-05 IOB BUILDING SINGAPORE 049711 Contact No	Cust No/Name /Ho Kok Soon Reg No/Reg Date SLE6774S / 29/07/2016 Date In/Mileage 22/07/2019/ 94890 Chassis/Package MMBSTA13AHH001574 /FS315N Engine No 3A92UDG3209 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	10/09/2019/ 11:36	TLE	881 / Jojo Cheng	40756
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER, REPAIR RR FENDER LH, RR END PANEL & BOOTLID					✓ 1100.00
E PNT98000 RESPRAY RR BUMPER, RR END PANEL, BOOTLID & RR FENDER LH					✓ 1470.00
E PNT88000 REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR					✓ 275.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM					✓ 50.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					✓ 200.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS					✓ 80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR					✓ 80.00
M SUNDRY SUPPLY C&C BADGE					✓ 40.00
M SUNDRY SUNDRIES					✓ 30.00
X FACE, RR BUMPER		1.00	740.00	00.00	✓ 740.00
X CLIP, RR BUMPER		4.00	3.00	00.00	✓ 12.00
X BRACKET, RR BUMPER, LH		1.00	27.00	00.00	✓ 27.00
X BRACKET, RR BUMPER, RH		1.00	27.00	00.00	✓ 27.00
X MARK, THREE-DIA		1.00	45.00	00.00	✓ 45.00
X MARK, ATTRAGE		1.00	21.00	00.00	✓ 21.00
X BUZZER, KEYLESS OPERATIO, RR		1.00	90.00	00.00	✓ 90.00
X ANT, KEYLESS OPERATION, RR		1.00	84.00	00.00	✓ 84.00
X COVER, RR VENTILATOR		1.00	40.00	00.00	✓ 40.00
X DUCT, RR VENTILATOR		1.00	30.00	00.00	✓ 30.00
X DECAL, MIVEC		1.00	36.00	00.00	✓ 36.00
Z TEXT INDIA TP CLAIM SH9952B					

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE PTE LTD MOTOR CLAIM DEPARTMENT 64 CECIL STREET #04-05 IOB BUILDING SINGAPORE 049711 Contact No 22/07/	Cust No/Name /Ho Kok Soon Reg No/Reg Date SLE6774S / 29/07/2016 Date In/Mileage 22/07/2019/ 94890 Chassis/Package MMBSTA13AHH001574 /FS315N Engine No 3A92UDG3209 Make/Model MIT/17MY ATTRAGE 1.2 CVT Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00040	Cash	10/09/2019/ 11:36	TLE	881 / Jojo Cheng	40756

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
DOA: 07/06/2019 SURVEYOR: RASUL LKK 22/07/2019				
Pro Forma				
Cycle & Carriage celebrates 120 years. Visit www.cyclecarriage.com/120 for more info!				

Parts	1,152.00			
Labour	3,175.00			
Standard Menu	0.00	7% GST on	4477.00	4,477.00
Specialist Job	0.00			313.39
Diagnostics Job	0.00			
Sundry/Others	150.00			
Total(w/o GST)	4,477.00		Total Payable	4,790.39

This is not an official tax invoice.
This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : INDIA INTERNATIONAL INSURANCE PTE LTD

REGISTRATION NO : SLE6774S

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>PARTS</u>					
1	BUZZER, KEYLESS OPERATIO, RR <i>ca</i>	1.00	90.00	0.00	90.00
2	ANT, KEYLESS OPERATION, RR <i>ca</i>	1.00	84.00	0.00	84.00
3	COVER, RR VENTILATOR <i>ca</i>	1.00	40.00	0.00	40.00
4	DUCT, RR VENTILATOR <i>ca</i>	1.00	30.00	0.00	30.00
5	DECAL, MIVEC <i>ca</i>	1.00	36.00	0.00	36.00
Total					280.00
7 % GST					19.60
Grand Total					299.60

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

JoJo Cheng

Customer Service

Tel : +65 6568 4554

Car No: SLE6774S WIP 40756

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	Tail Lamp Panel LH <u>Repair</u>	? /Supp			
2	Rear End Panel	? /Supp			
3	Keyless Buzzer	? /Supp			8637 B366
4	Keyless Antenna	? /Supp			8637 A526
5	Cover Ventilation	? /Supp			7835 A032
6	Rear Ventilation	? /Supp			7835 A023
7		? /Supp			
8		? /Supp			
9		? /Supp			
10		? /Supp			
11		? /Supp			
12		? /Supp			
13		? /Supp			
14		? /Supp			
15		? /Supp			
16		? /Supp			
17		? /Supp			
18		? /Supp			
19		? /Supp			
20		? /Supp			

DATE	TAKEN BY
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF DAMAGED PARTS (DPS)	
PHOTO OF CEILETE BENCH	
REMOVE & INSTALL ENGINE	
REMOVE & INSTALL DASHBOARD	
PHOTO 34 SUSP & U/C REMOVE	

Model: ATTRAGESurveyor: RASUL