



Our Ref : CS/QW19010366/K1td3s2

Date: 13<sup>th</sup> June 2019

**Comfort Transportation Pte Ltd**

383 Sin Ming Drive

Singapore 575717

Attn: Doris Lim

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO.: SH 9827E  
ACCIDENT ON 30/05/2019**

Instruction was received to inspect the vehicle Reg. No. SH 9827E. The inspection was conducted on 11/06/2019 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SH 9827E
Make/Model	: Toyota Prius
Year of Registration	: 2017
Body Colour	: Blue
Chassis Number	: JTDKB3FU903564100

The following are our comments:-

- (a) The vehicle sustained damages at the front portion and undercarriage. (Details see photographs enclosed)

(b) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:

*no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.*

and we therefore recommend it to be written off as **"Total Loss"**

Vehicle Inspected By:



KALVIN ANG WEI KUN  
*Automotive Assessor / Investigator*

K.K.LAU

*MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),  
Licensed Appraiser*

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.