

090000

INS. CASE OWNER:

CC 4/AIG1901 0380, Bdb79

LKK:  
IDAC:

Surveyor:

Mr Lim

DOI:

ASSIGNMENT

12/6/19

Date / Time:

12/6/19

Registered in Merimen:

12/6/19

Pre-assign / CCU / FTE



Insured Vehicle No. : GBG 6774X  
Name of Insured : FULLO LEASING P/L  
Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
Excess Sec II :SS \_\_\_\_\_ D.O.A.: 6/6/19

Claim No. : \_\_\_\_\_  
Policy No. : AAA944292(1005)29-00000  
Make / Model : NISSAN  
Place of Accident : 56 WYANG WANG MSCP

Is driver the owner? ( YES / NO ) Nature of Accident:

If NO, Driver Name / Age : WAW WAKFADLY 21W WAW ANHAD  
Driver Tel No. : \_\_\_\_\_ (VA YES/NO) OI GIA REPORT YES/NO : TP GIA REPORT YES/NO

594 1274



INSRS: \_\_\_\_\_  
WSP: Team Auto Pro  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_



INSRS: \_\_\_\_\_  
WSP: \_\_\_\_\_  
Tel: \_\_\_\_\_  
Liability: \_\_\_\_\_  
RMKS: \_\_\_\_\_

Date/ Time	STAGE	DATE / PIC
25/6/19	Called OZ to inform TP claim	128/06/19 - SUMMY - OZ
6/11/19	AUE PASS TO LSP TO CLOTH	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/>
	After call ltr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/>
	LT / GIA :	<input checked="" type="checkbox"/>
	Medical Bill:	<input type="checkbox"/>
	PR:	<input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/>
	Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: \_\_\_\_\_ Sent By: \_\_\_\_\_

FINALIZATION Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Confirm by: \_\_\_\_\_

Repair Cost: \$5 ( days) Reduction: % Email  Call

FINAL SETTLEMENT Date/Time: 31/10/19 Confirm with: Ade Email  Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: NIL

Repair Cost: \$5 4450.00 O/D REVERSE AND

Loss of Rental (LOR): \$5 1200.00 ( 10 days) x \$120 HIT PARKBO VEHICLE

Loss of Use (LOU): \$5 - (5 x days)

Loss of Income (LOI): \$5 - (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LO  [Tick only one]

GIA/LTA Search: \$5 36.75

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 5686.45 Global Sum \$5: 5680.00

FINAL PAYMENT Date/Time: \_\_\_\_\_ Confirm with: \_\_\_\_\_ Email  Call

Payee 1: \$5 5680.00 Name 1: Team Auto Pro Pte Ltd

Payee 2: (Strike if N.A.) \$5 Name 2: \_\_\_\_\_

Payee 3: (Strike if N.A.) \$5 Name 3: \_\_\_\_\_

9/11/19 SENT

REF:

AIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: 12/6/19

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SGU 19374

at Workshop n/s: Jean Autopro  
at 160 San Ming Dr

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: • \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

6 days Res.: Yes or No

Lump Sum: \_\_\_\_\_

20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: SGU 19374 Yr Regt: 4/9/2007

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream cc 1799

Colour: Blue AC: Insured / Std / NI / NA

Sp. Reading: 177084 T/Radio: Insured / Std / NI / NA

Eng/No: R18A1730646

C/No: RN61027214

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rin / STD A/Rin or

Tyre Size: F: 215/45R19

R: 215/45R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 6/6/19

D.O.I. 12/6/19

Survey held at Jean Autopro

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

L/S 4,450/- Term Inv (Red \$ 3186.45/421)  
13/7/19

MV 22,000/-

PV 14,995/-

NV 7,005/-

Term Inv  
13/6/19

Date/Time, File Pass to?

 : Prol. Report : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$ : Interview (\$ : Tech. Invs (\$ : Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_\_ + RD, SR

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ \_\_\_\_\_)

SJE :	<u>LKK Mr Lim T. G</u>	Vehicle Nos :	<u>SGU 1937Y</u>
Date of Survey :	_____	Model :	<u>Honda Stream</u>
Date of ReSurvey:	<u>After-Paint:</u>	Year :	_____
Contacts :	_____	Chassis No :	_____

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_ Working Day: \_\_\_\_\_

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Front grille	1	\$ 195.54	\$ 195.54	BRV
2	Front grille logo	1	\$ 48.50	\$ <del>48.50</del>	Cuiv
3	Front grille chrome	1	\$ 250.35	\$ <del>250.35</del>	Cuiv
4	Front bumper	1	\$ 685.70	\$ 685.70	BRV
5	Front bumper side retainer	2	\$ <del>56.80</del> 68.50	\$ 113.60	NECV
6	Front bumper center grille	1	\$ 95.20	\$ 95.20	BRV
7	Front bumper reinforcement	1	\$ 318.90	\$ 318.90	BTV
8	Front fender RH	1	\$ 572.00	\$ <del>572.00</del>	PPD
9	Headlamp LH	1	\$ 689.30	\$ 689.30	BRV
10	Headlamp RH	1	\$ 689.30	\$ 689.30	BRV
11	Headlamp lower bracket RH	1	\$ 56.50	\$ 56.50	BRV
12	Headlamp lower bracket LH	1	\$ 56.50	\$ 56.50	BRV
13	Bonnet	1	\$ 686.90	\$ 686.90	DDV
14	Bonnet insulator	1	\$ 187.64	\$ 187.64	NNX
15	Bonnet inner lock	1	\$ 56.33	\$ 56.33	BTV
16	Bonnet inner rubber	1	\$ 33.00	\$ <del>33.00</del>	NNX
17	Front support panel	1	\$ 466.30	\$ 466.30	DDV
18	Front support panel top garnish	1	\$ 170.60	\$ 170.60	BRV

Parts Sub Total :	\$ 4554.63	\$ 5,395.56
20% Discount	\$ 910.93	1,079.11
<b>PARTS TOTAL :</b>	<b>\$ 3643.70</b>	<b>4,316.45</b>

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ <del>60.00</del>	NNA
2	Front grille clip	1	\$ 50.00	\$ <del>50.00</del>	NEC
3	Front bumper clip	1	\$ 50.00	\$ <del>50.00</del>	NEC
4	Bonnet insulator clips	1	\$ 50.00	\$ <del>50.00</del>	NNA
5	Front fender sealant	1	\$ 100.00	\$ <del>100.00</del>	NEC
6	Front support panel top garnish clips	1	\$ 50.00	\$ <del>50.00</del>	NEC
<b>SPECIAL NETT TOTAL :</b>				<b>\$ 150.00</b>	<b>360.00</b>

Nos.	LABOUR	S\$
1	R&R bonnet component	\$ 50.00 100.00
2	R&R wire harness and check function	\$ 50.00 80.00
3	Headlamp adjustment and alignment	\$ 50.00 80.00
4	Panel beat	\$ 800.00 1,400.00
5	Rust proofing	\$ 60.00 100.00
6	Spray painting	\$ 800.00 1,200.00
<b>LABOUR TOTAL :</b>		<b>\$ 1810.00 2,960.00</b>

PARTS TOTAL :	\$ 4,316.45
SPECIAL NETT TOTAL :	\$ 360.00
LABOUR TOTAL :	\$ 2,960.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Leap suns repair  
Repair days 6

Resurvey on 13/6/19  
1350 hrs  
TGLin lin

Parts	3643.70
S/N	150.00
Labour	1810.00
	<u>5603.70</u>
@ 20%	1120.74
	<u>4482.96</u>

L/S 4450/2

TGLin lin  
17/7/19

**MOTOR CAR (Frt)**

**Front Portion**

Vehicle No: SGU 1924

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	WTV		
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	DD	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	NEC	✓	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	BR	✓	
1022	991328	Frt Grille Emblem	NEC	✓	
1023	991799	Frt Grille Chrome Moulding	WTV		
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	WTV	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	DD	✓	
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990220	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender	WTV	R	X
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: 12

APPROVED: T. C. Lim

13/6/19

## FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?



Post an Advertisement  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Mini One 1.4i - Limited Version 2-Door Design.



Accident Free/Well Kept/By A  
Canada Award Winning Sales  
Entrepreneur  
Direct Owner Thanks!

**KA-HUP**  
VALUE FOR MONEY  
VALUE FOR TIME  
A PEACE OF MIND

**HOTLINE: 6741 9997** [View our cars](#)

Browse by Category

« Back ( 1 2 3 4 5 ... 13 ) Next »

Sort by Date Posted

20 results/page

251 vehicles

Honda Stream

Advanced Search

None	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status	
<b>Search Selection</b>	Honda Stream	Any	Any	> 10 year(s) old	Any	Any	All	
	<b>Honda Stream 1.8A (COE till 04/2022)</b>	-	N.A	26-Apr-2007	1,799 cc	-	MPV	<b>SOLD</b>
Regular Serviced And Well Maintained By Owner. Still In Original Condition. Easy To Maintain And Reliable! Loan Available. Call Our Friendly Sales Executive For More Information Or Schedule For A View...								<a href="#">View more</a>
Universe Motoring								
Posted: 09-Apr-2019								
Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	<b>Honda Stream 1.8A (COE till 05/2022)</b>	<b>\$28,800</b>	<b>\$9,900 /yr</b>	10-May-2007	1,799 cc	178,866 km	MPV	Available
Very Reliable MPV With Great Aerodynamics, Combined With Space And Comfort. Regularly Serviced And Maintained. Selling Due To Upgrading. Consignment Unit! Trade In Welcome! Loan And Insurance Availabl...								<a href="#">View more</a>
Prem Roy Motoring								
Posted: 08-Jun-2019								
Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	<b>Honda Stream 1.8A RSZ (COE till 05/2022)</b>	<b>\$23,888</b>	<b>\$8,120 /yr</b>	22-May-2007	1,799 cc	-	MPV	Available
Original Condition And Lowest Price In The Market, Accident-Free, Very Well Maintained Interior And Exterior, With No Wear And Tear To Be Replaced, Low Mileage, New Tyres, Trade In Welcome, Call Our F...								
Posted: 05-Jun-2019								
Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	<b>Honda Stream 1.8A (COE till 05/2027)</b>	-	N.A	22-May-2007	1,799 cc	-	MPV	<b>SOLD</b>
1 Owner. Very Well Maintained By Previous Owner. Original Condition, 6 Months Warranty, Accident-Free, Bank Loan/In House Loan Available. Trade In Welcome. Call Our Senior Consultant For More Photos A...								
Posted: 24-May-2019								
Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	<b>Is your COE expiring? Let us help you renew it!</b>							
Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	<b>Honda Stream 1.8A RSZ (COE till 05/2022)</b>	<b>\$23,800</b>	<b>\$8,070 /yr</b>	25-May-2007	1,799 cc	133,000 km	MPV	Available
Just Arrived! Well Maintained And Very Good Condition, High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.								
Posted: 26-May-2019								
Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								
	<b>Honda Stream 1.8A (COE till 06/2022)</b>	<b>\$22,998</b>	<b>\$7,700 /yr</b>	07-Jun-2007	1,799 cc	123,992 km	MPV	Available
Drive With Assurance! 2 Year Warranty! Genuine And Transparent Deal! Bank/In House Up To 100% \$23.9k Full Loan Monthly At \$728. All Our Quality Cars Are Selling At The Most Reasonable Price With A Pea...								
CarQuotz Singapore								
Posted: 09-Jun-2019								
Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda, Stream, stream, Used Honda								

Compare

-Pre repair inspection request - SGU1937Y VS GBG6374X (O) DOA: 06/06/2019

From: Abu Kassim, Noor Marissa

To: admin-a@kkauto.com, assignments@kkauto.com

Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Azlen, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashri, Tong, Wahain, Ho, Yinnal

Sent: 6/12/2019 12:04:35 PM

Attachments: 1937GBG6374X.pdf

Hi,

Please refer to the enclosed request from **Team AutoPro Pte Ltd.**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thank you

Regards,

Marissa Abu Kassim (Marissa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

[NoorMarissa.AbuKassim@aig.com](mailto:NoorMarissa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

From: teamautopi@gmail.com

To: AIGSGP\_ClaimsSurvey@aig.com

Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, ShengYang.Lim@aig.com, xxximran.tahak@aig.com, yokeshi.chan@aig.com

, Darshene.Supramaniam@aig.com, NoorMarissa.AbuKassim@aig.com

Subject: [EXTERNAL] 2 Days Notice: Involving SGU 1937 Y (Our Ref) and GBG 6374 X (Your Ref) Dated 06th June 2019

Date: Fri, 7 Jun 2019 05:11:51 +0000

This message is from an external sender; be cautious with links and attachments.

Dear Sir/Madam,

Road Traffic Accident Involving SGU 1937 Y (Our Ref) and GBG 6374 X (Your Ref)

Dated 06<sup>th</sup> June 2019, Time around 16:45

@ 56 Loyang Way Carpark

We represent our client; Lim Yoke Sin, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SGU 1937 Y and your insured's vehicle registration number:

GBG 6374 X. Enclosed herewith a copy of the Singapore Accident Statement filed for your reference.

Enclosed herewith a copy of our 2 Days Notice Letter and the relevant Singapore Accident Statement filed for your reference.

For efficiency purpose, we are agreeable with the appointment of **Mr Lim - LKK** as the SJE for subject claim. Please let us know within **2 working days** from today your agreeing to the above otherwise kindly send us your list of at least **ten (10) motor surveyors, via email to the following personnel:-**

Contact Person	Alan Koh	9092 7279
	Frederick Lim	9674 6635
Email Address	<a href="mailto:teamautopi@gmail.com">teamautopi@gmail.com</a>	
Survey Address	160 Sin Ming Dr, #01-14 Sin Ming AutoCity Singapore 575722	

Thank you for your attention to this email and we look forward to your earliest reply.

\* The above settlement is in respect of our client for damage pertaining to his motor vehicle and shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.\*

Cheers,

Peach Ang

Team AutoPro Pte Ltd

Tel: 6258 1955

Fax: 6258 1956

385 Sin Ming Drive

#01-02 Vicom Inspection Centre

Singapore 575718

1.04pm 12/6/19  
vehicle in  
melaka  
sur @ Mr Lim.

# TEAM AUTO PRO

06<sup>th</sup> June 2019

**AIG Asia Pacific Insurance Pte Ltd**  
Attn : Motor Claim Department

Dear Sir/Madam,

**Road Traffic Accident Involving SGU 1937 Y (Our Ref) and GBG 6374 X (Your Ref)**  
**Dated 06<sup>th</sup> June 2019, Time around 16:45**  
**@ 56 Loyang Way Carpark**

We represent our client; Lim Yoke Sin, to notify you of the aforesaid road traffic accident involving our client's vehicle registration number: SGU 1937 Y and your insured's vehicle registration number: GBG 6374 X

We hereby give you **NOTICE** that we are claiming against GBG 6374 X for damages, costs and disbursements as a result of the aforesaid road traffic accident.

Please let us know within 2 working days from today, your insured's and your intention to conduct a pre-repair survey on our client's vehicle, along with your list of at least ten (10) motor surveyors.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

<b>Contact Person</b>	Alan Koh	9092 7279
	Frederick Lim	9674 6635
<b>Email Address</b>	teamauto1@gmail.com	
<b>Survey Address</b>	160 Sin Ming Dr, #01-14 Singapore 575722	

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

  
Authorized Signatory

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 1072F

### Vehicle Details

Vehicle No.: SGU1937Y  
Vehicle to be Exported: No  
Intended Deregistration Date: 12 Jun 2019  
Vehicle Make: HONDA  
Vehicle Model: STREAM 1.8 A  
Primary Colour: Blue  
Manufacturing Year: 2007  
Engine No.: R18A1730646  
Chassis No.: RN61027214  
Maximum Power Output: 103.0 kW (138 bhp)  
Open Market Value: \$18,427.00  
Original Registration Date: 04 May 2007  
First Registration Date: 04 May 2007  
Transfer Count: 3  
Actual ARF Paid: \$20,270.00

### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 30 Apr 2022  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$26,004.00  
COE Rebate Amount: \$14,995.00  
Total Rebate Amount: \$14,995.00

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Jun 2019.

OK

Aug dep 9010/yr

MV 22,000/2  
PV 14,995/2  
NV 7,005/2

*[Signature]*  
12/6/19

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main:	12 Jun 2019 <a href="#">Edit Reg</a>		12 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$4,450.00</b> <a href="#">Edit Estimates</a>	<b>S\$4,450.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	FULCO LEASING PTE LTD, Co. Reg. No.: 201021308G		
Main Claimant:	LIM YOKE SIN, ID: S8131072F		
Vehicle Reg. No.:	SGU1937Y	Date of Loss:	06/06/2019 17:00 - :59 [145 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1801766566SG	Policy/Cover Note No.:	0999994292 (Comprehensive)
Vehicle Reg. No. (Insured):	GBG6374X	Policy No. (Claimant):	
		Excess:	
Repairer:	Team Autopro Pte Ltd (sin Ming) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>Ler, Bernard-JQ</b> ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>Lim Teow Guan</b> ] ... [Final Rpt due 21/06/2019]		
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
There are no mail for this case.			
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a>	<a href="#">Search Tasks</a>
		<a href="#">Create New Task</a>	<a href="#">Complete</a>
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>
			<b>Subject</b>
			<b>Handler</b>
			<b>Assigned By</b>
			<b>Completed On</b>
			<b>Created On</b>
			<b>Done?</b>
No results.			

## Claim Documents

\*SGU1937Y (1801766566SG)  
 [GBG6374X]  
 TP  
 LIM YOKE SIN  
 Jun 6 2019 5:00PM  
 [FULCO LEASING PTE LTD]  
 Team Autopro Pte Ltd (sin Ming)

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>   <a href="#">Upload Video</a>   <a href="#">Upload Audio</a>			View	View in Browser
<b>Letters/Correspondences</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
<b>Photos/Images</b>			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
2	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
3	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
4	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
5	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
6	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
7	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
8	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
9	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
10	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
11	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
12	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
13	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
14	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
15	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
16	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
17	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
18	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
19	01/11/19 12:57	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
20	01/11/19 12:57	Chassis Number		Load JPG <input checked="" type="checkbox"/>
21	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
22	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
23	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
24	01/11/19 12:57	General View		Load JPG <input checked="" type="checkbox"/>
25	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
26	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
27	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
28	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
29	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
30	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
31	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
32	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
33	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
34	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
35	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
36	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
37	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
38	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
39	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
40	01/11/19 12:58	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	01/11/19 12:58	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/19 14:55	EMAIL FROM AIG DD 12062019	 Load PDF	
2	12/06/19 14:55	NOTICE & GIA REPORT	 Load PDF	
3	28/06/19 12:15	Letter to OI	 Load PDF	
4	22/07/19 09:03	TP ESTIMATE- MARKED	 Load PDF	
5	19/11/19 09:26	WORKSHOP INVOICE	 Load PDF	
6	19/11/19 09:26	AUTHORISATION TO ACT FORM	 Load PDF	
7	19/11/19 09:26	Release Voucher	 Load PDF	
8	19/11/19 09:26	RENTAL RECEIPT	 Load PDF	
9	19/11/19 09:26	LTA SEARCH	 Load PDF	
10	19/11/19 09:26	GIA SEARCH	 Load PDF	
11	19/11/19 09:26	LOD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/06/19 11:31	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

**THIRD PARTY EXPRESS SETTLEMENT  
(PAYMENT BREAKDOWN)**

<b>Vehicle No:</b>	GBG6374X (Insd veh)	<b>Model:</b>	HONDA STREAM 1.7 (A)
	SGU1937Y (TP veh)		
<b>Date of Accident:</b>	06/06/2019		

Global Sum Settlement	:	[ X ] Yes	[ ] No
Repair Estimate	:	\$	7,636.45
Final Repair Cost	:	\$	5,680.00
Loss of Use	:	\$	_____ days at \$0.00 per day
Rental (if any)	:	\$	10 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
X	:	\$	
Final Settlement Sum (Global Sum)	:	\$	5,680.00

**Is Third Party Workshop GIA Registered?** [ ] YES [ X ] NO (Kindly indicate below)

**A) For Non GIA Registered Workshop:** Agreed Liability \_\_\_\_100\_\_\_\_(%)  
 BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_\_

**B) For GIA Registered Workshop:**  
 BOLA Liability: \_\_\_\_\_(%) Assessed Liability (\*): \_\_\_\_\_(%)  
 \* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_  
 \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Team Autopro Pte Ltd	:	\$ 5,680.00
2)		:	\$
3)		:	\$
4)		:	\$

\_\_\_\_\_  
 JOANNE LEE KHANG MIN  
 LKK Auto Consultants Pte Ltd

19 Nov  
 2019  
 \_\_\_\_\_  
 Date

Please attach all the supporting documents to the form.  
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;  
 Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19010380/BDB3Q2  
**Date:** 19/11/2019

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994292
<b>Claimant</b>		
<b>Vehicle No :</b> SGU1937Y	<b>Insured Vehicle No :</b>	GBG6374X
Date of Loss: 06/06/2019	Nature of Claim: TP	Claim No: 1801766566SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGU1937Y</b>	Engine No:	R18A1730646
Make & Model:	HONDA STREAM, 1.7 (A)	Chassis No:	RN61027214
Reg. Date:	04/05/2007 (Man. Year: 2007)	Odometer:	177084 km
Colour:	Blue		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,676.45	3,793.02	883.43	18.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,810.00	1,150.00	38.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,636.45</b>	<b>5,603.02</b>	<b>2,033.43</b>	<b>26.63</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,450.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,636.45</b>	<b>4,450.00</b>	<b>3,186.45</b>	<b>41.73</b>
+ Car Rental (10.0 x S\$120.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		36.45		
<b>Nett Liability (S\$)</b>		<b>5,686.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,680.00</b>		

#### INSPECTION

Date of Assignment:	12/06/2019	
Date Inspected:	12/06/2019 Inspected At:	Team Autopro Pte Ltd (sin Ming) (HQ) 160 SIN MING DRIVE, #01-14 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	6.0 days	

**Adjuster:** Lim Teow Guan

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT GRILLE	Broken	195.54 FL	*195.54 FL
2	1		*FRONT GRILLE LOGO	Cut	48.50 FL	*35.00 FL
3	1		*FRONT GRILLE CHROME	Cut	250.35 FL	*238.10 FL
4	1		*FRONT BUMPER	Broken	685.70 FL	*685.70 FL
5	2		*FRONT BUMPER SIDE RETAINER	Necessary	137.00 FL	*113.60 FL
6	1		*FRONT BUMPER CENTER GRILLE	Broken	95.20 FL	*95.20 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	318.90 FL	*318.90 FL
8	1		*FRONT FENDER RH	Repair	572.00 FL	*- FL
9	1		*HEADLAMP LH	Broken	689.30 FL	*689.30 FL
10	1		*HEADLAMP RH	Broken	689.30 FL	*689.30 FL
11	1		*HEADLAMP LOWER BRACKET RH	Broken	56.50 FL	*56.50 FL
12	1		*HEADLAMP LOWER BRACKET LH	Broken	56.50 FL	*56.50 FL
13	1		*BONNET	Dented	686.90 FL	*686.90 FL
14	1		*BONNET INSULATOR	Not Necessary	187.64 FL	*- FL
15	1		*BONNET INNER LOCK	Bent	56.33 FL	*56.33 FL
16	1		*BONNET INNER RUBBER	Not Necessary	33.00 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Dented	466.30 FL	*466.30 FL
18	1		*FRONT SUPPORT PANEL TOP GARNISH	Broken	170.60 FL	*170.60 FL
19	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
20	1		*FRONT GRILLE CLIP	Necessary	50.00 FS	*30.00 FS
21	1		*FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
22	1		*BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*60.00 FS
24	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,755.56</b>	<b>4,703.77</b>
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,079.11	910.75
<b>Total Parts (\$\$)</b>	<b>4,676.45</b>	<b>3,793.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R BONNET COMPONENT	New	100.00	50.00
2	R&R WIRE HARNESS AND CHECK FUNCTION	New	80.00	50.00
3	HEADLAMP ADJUSTMENT AND ALIGNMENT	New	80.00	50.00
4	PANEL BEAT	New	1,400.00	800.00
5	RUST PROOFING	New	100.00	60.00
6	SPRAY PAINTING	New	1,200.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,960.00</b>	<b>1,810.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >