

ASS. REC. BY:

REF: CS/SMO19010385/ Rlgd/302

Special Instruction:

Survivor: Kalin**ASSIGNMENT (Office)**From (Person): Gracia Teoof SMODate/Time: 12.6.19 2:36p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBE 8856 UInsured: PBN 41639at Workshop m/s Efficient Motor & EngineeringTel: 82824486of 56 Loyang Way #06-07Policy No: D7 8MTMCO1006046Claim No: CMTD19025041 THE

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19.5.2019

CA / REV / REP. / REV 24 HRS

up

Date/Time: 12.6.19 2:10p.mPerson Contacted: Rizan

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	<u>GBE 8856 U - x</u>
	<u>PBN 41639 - x</u>
<u>12/6/19 @ 11:40am</u>	<u>informed Thelma, we are pending estimate from repairer.</u>
<u>21/6/19 @ 10:57am</u>	<u>revised to Thelma via Messenger.</u>
<u>18/7/19 @</u>	<u>According to Joe (w/ship), they already withdraw the claim</u>
	<u>* Repairer put up estimate as after Kalvin adjusted amount.</u>

08/11/13

Surveyor: Kalvin

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of 56 Long WayInsured: #06-07

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBE 88564 Yr Regn: 12 Apr 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Hiace C.C. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 80199 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KD H2010162776Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD / Rim or _____

Tyre Size: F: 195 / 80 R15

R: _____

BS / DA / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or Firemax

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 19/5/17 D.O.I. 12/6/17Survey held at Efficient Motor & Engineering Works

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>2/6/17</u>	<u>45 \$2600 / 5 hrs. (Red 63477-32, 49%)</u> <u>SMO</u>

RECEIVED 16 JUL 2019

Date/Time, File Pass to?

☐

Prel. Report

11/8/17 to M/S☐

Final Report

Date/Time, File Return to?

2)Days Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

3 + RS \$

Photos

Others

TOTAL

Report Format: MER-TPLump Sum / I.B.I. (\$) 36029011261

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, 12 June, 2019 2:36 PM
To: efficientloyang@gmail.com; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1902504/THE(M) - LKK/ FBN4163P & GBE8856U ACC ON 19/05/2019 at junction of North Buona Vista Rd towards Ayer Rajah Ave

Without Prejudice

Our Reference: CMTD1902504/THE
Your Reference: GBE8856U

Hi Mas,

We acknowledged receipt of your claim documents.

Please be informed that **Ms. Thelma Choo** is the handler of this case who can be contacted at 63224 681.

As agreed, we will appoint **LKK AUTO/ Marcus** to survey the above vehicle.

As spoken, kindly assist to submit the claim via Merimen system.

You may contact the following persons or the handler in charge for transferring of the Merimen folder for your updating/action.

- Grace - 63295 170
- Melvin - 63224 667
- Irene - 63224 618

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for GBE8856U on a without Prejudice and any admission of liability basis.

Please submit your report via Merimen upon completion of survey

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sampo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sampo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: efficient loyang <efficientloyang@gmail.com>

Sent: Wednesday, 12 June, 2019 12:01 PM

To: claimsreport <claimsreport@sampo.com.sg>

Subject: SURVEY INVITATION for accident on 19/05/2019 at junction of North Buona Vista Rd towards Ayer Rajah Ave involving vehicles GBE8856U & FBN4163P

Dear Claims Officer,

We would like to invite your surveyor to our workshop for a pre-repair survey of our client's vehicle GBE8856U that was involved in an accident with your insured FBN4163P.

Please forward us a copy of your insured report.

Note: Vehicle is in our workshop premises

Location: 56 Loyang Way
#06-07 Loyang Enterprise Building, S(508775)

Contact Person: Mr Rizan
H/P: 8282 4486

A copy of the Singapore accident statement/traffic police report is enclosed.
Kindly reply to this email or contact me at 62840827 to confirm.

Thank you.

Best Regards,
Mas Ariyanti
Efficient Motor & Engineering Works Pte Ltd
56 Loyang Way
#06-07 Loyang Enterprise Building, S(508775)
Tel: 6284 0827
Fax: 6341 6758

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Somp Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Thelma Choo

Date: 21 Jun 2019

Preliminary Advice

Insured Vehicle No	: FBN4163P	Accident Date	: 19/05/2019
TP Vehicle No	: GBE8856U	Assignment Date	: 12/06/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 5.00
Date of Inspection	: 12/06/2019		
Inspection At	: EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ) 56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING SINGAPORE 508775		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,072.32
Revised Amount	:S\$	4,518.48
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,518.48

Lump Sum Repair	:S\$	3,600.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 13 June 2019 11:40 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE GBE 8856U (YOUR REF: CMTD1902504)

This mail is associated with :
GBE8856U (CMTD1902504)
[FBN4163P]

TP
PAN PACIFIC VAN & TRUCK LEASING PTE LTD
May 19 2019 11:00PM
[NG THIAM SENG EDDY]
Efficient Motor & Engineering Works Pte Ltd

Dear Thelma,

Please be informed that we have inspected the vehicle GBE 8856U on 12/06/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1635R
Vehicle Details	
Vehicle No.:	GBE8856U
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 3.0 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2568385
Chassis No.:	KDH2010182776
Maximum Power Output:	-
Open Market Value:	\$30,022.00
Original Registration Date:	18 Apr 2016
First Registration Date:	18 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$1,502.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Apr 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$43,370.00
COE Rebate Amount:	\$29,596.00
Total Rebate Amount:	\$29,596.00

The information contained herein is correct as at 21 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/05/2019 12:09
Date Of Accident	19/05/2019 22:30
Exact Location Of Accident	JUNCTION OF NTH BOUNA VISTA RD TWDS AYER RAJAH AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE8856U
Insured/Policyholder	
Name Of Registered Owner	PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Co Reg No	201511635R
Email Address	EFFICIENTLOYANG@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-62840827

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHIN OI LING
NRIC No	S7184090E
Date Of Birth	05/05/1971
Occupation	OUTDOOR
Date Of Driving Pass	07/12/1996
Driving Experience	22 YEARS AND 5 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97855169
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 376C HOUGANG ST 32 #12-32
Postcode	533376
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO MOTORCYCLIST
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8729999 - FAX NO: 67748639
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBN4163P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

- Nature Of Damage
- No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident [all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"], the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


[Handwritten Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12.29pm 21/5/19



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT.

DECLARATION

I/We declare that the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

CHARM Switch/Panel with V3

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12:29pm 21/5/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190520/2013

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

1 of 3

Report No. T/20190520/2013

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/05/2019 01:59		Vide Report No.: D/20190519/0183		Station Diary No.: 30	
Name of Informant: CHIN OI LING					
Address: APT BLK 376C HOUGANG STREET 32 #12-32 SINGAPORE 533378					
ID Type / ID No.: NRIC NO / S7184090E		Contact No.: Home/Office:		Mobile: 97855169	
Nationality: MALAYSIAN		Email:			
Sex: Female	Age: 48	Date of Birth: 05/05/1971	Type of Informant: Driver		
Race: Chinese		Language:		Institution / School Name:	
Occupation: EVENT COORDINATOR		Driving Licence Information: Class: 3		Date of Expiry:	

Type of Accident:	Injury Conveyed By Ambulance:	Drink Drive: No	Date/Time of Accident: 19/05/2019 22:25	Type of Location: X-Junction
Location: Along Road 1 NORTH BUONA VISTA ROAD AYER RAJAH AVENUE At the cross junction of North Buona Vista and Ayer Rajah Avenue				
Weather: Clear	Road Surface: Dry		Road Speed Limit: 60 Km/h	
Traffic Flow: Two Way	Traffic Control: Traffic Light - Working		Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

FBN4163P	Motorcycle				Seriously Damaged	0
GBE8858U	Van				Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20190520/2013

2 of 3

Report No. T/20190520/2013

Police Station Of Origin:

Clementi N.P.C

20 Clementi Avenue 5 SINGAPORE 129858

Tel No: 1800-8729999

CONTINUATION OF REPORT

Brief Details.

On 19/05/2019 at about 2227hrs, I was driving my rented van bearing registration number, GBE8856U along North Buona Vista Road turning right Ayer Rajah Avenue when a blue-coloured motorcycle bearing registration number FBN4163P suddenly hit on my left rear of the van.

Before I turned to Ayer Rajah Avenue, I made a check on the opposite side of the junction which is along North Buona Vista Road.

I then turned right towards Ayer Rajah Avenue when it was safe to do so. The traffic light was green in my favour.

After hearing the loud bang from the impact, I immediately stopped the van and I rendered assistance by calling the ambulance.

The ambulance arrived and conveyed the rider of the motorcycle to the nearest hospital. The traffic police also arrived at scene shortly.

I do not know the cost of the damage but I will send the van for assessment on 21/05/2019 (Tues).

The van was rented from Pan Pacific Leasing. I have already informed the company of the accident.

The van is rented under my supervisor.

Name : Cheong Brandon Hilary

NRIC : S1517857D

Add : 35A Lorong 11 Geylang

I did not suffer any injury from the accident.

I have handed over one SD card 16GB to one Traffic Police officer by the name of SSgt T120270 Farhan at the scene.



**SINGAPORE
POLICE FORCE**



D/20190520/2007

1 of 2

POLICE REPORT (NP322)

Report No. D/20190520/2007

Police Station Of Origin
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

Date/Time Report Made 20/05/2019 02:12	Vide Report No.	Station Diary No. 34
Name Of Informant CHIN OI LING	Address APT BLK 376C HOUGANG STREET 32 #12-32 SINGAPORE 533376	
ID Type / ID No. NRIC NO / S7184090E	Contact No. Home/Office	Mobile 97855169
Nationality MALAYSIAN	Email Address	
Occupation EVENT COORDINATOR	Sex Female	Age 48
Institution/School Name	Date of Birth 05/05/1971	Race Chinese
Date/Time Of Incident 19/05/2019 22:30	Location Of Incident NORTH BUONA VISTA ROAD SINGAPORE	

Brief details.

On 19/05/2019 at about 2230hrs at the junction of Ayer Rajah Avenue and North Buona Vista , I discovered the loss of my Singapore Driving Licence. I am unable to recall where I misplaced or loss my Singapore driving licence.

I am lodging this report as I planned to make a replacement for the loss of my Singapore driving licence.

Signature Of Officer Recording The Report: D / SI IMRAN BIN MOHAMMAD HAJAR	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 20/05/2019 02:12
Officer In-Charge Of Case: D / Clementi Police Divisional Investigation Branch / Sr Staff Sgt LIM CHEW BOON Contact No.: 67740000	Classification Of Case:

Authentication Stamp

FUPO hotline number: 68429645





**SINGAPORE
POLICE FORCE**



T/20190520/2013

Police Station Of Origin:
Clementi N.P.C
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-8729999

3 of 3

Report No. T/20190520/2013

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

SI IMRAN BIN MOHAMMAD HAJAR

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

20/05/2019 01:59

Officer in Charge Of Case:

TP / GIT /

Sr Staff Sgt NOR FAIZAL BIN YAHYA

Contact No.: 65476202

Classification Of Case:

Authentication Stamp
NP168



SINGAPORE
POLICE FORCE

SIGNATURE



**SINGAPORE
POLICE FORCE**



D/20190520/2007

2 of 2

POLICE REPORT (NP322)

CONTINUATION OF REPORT

Report No. D/20190520/2007

1	Licence	Lost	Qualified Driving Licence		S718409 0E	1	One Singapore Driving Licence belonging to one Chin Oi Ling, S7184090E

Signature Of Officer Recording The Report:

D / SI IMRAN BIN MOHAMMAD HAJAR

Signature Of Interpreter:
Not applicableOfficer In-Charge Of Case:
D / Clementi Police Divisional Investigation Branch /
Sr Staff Sgt LIM CHEW BOON
Contact No.: 67740000

Signature Of Informant:

Date/Time:
20/05/2019 02:12

Classification Of Case:

Authentication Stamp

FUPO hotline number: 68429645



SINGAPORE
POLICE FORCE

SIGNATURE

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD
REPAIR ESTIMATE

VEHICLE NUMBER : GBE8856U
MODEL : HIACE DX3.0 MANUAL
CHASSIS : KDH2010182776

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR PANEL LH (Zone & Order)	1		\$ 3,200.00 2072
REAR PANEL WINDOW PANEL LH	1		\$ 860.30 300
SLIDING DOOR LH COVER	1		\$ 655.00 450
REAR BUMPER	1		\$ 568.90 428.10
REAR WHEEL HUB CAP LH	1		\$ 156.20
Rear Tail lamp (LH)	1		\$ 325.00
SUB TOTAL			\$ 5,440.40
LESS 20% 25%			\$ 1,088.08
DISCOUNTED TOTAL			\$ 4,352.32
LABOUR CHARGE			
PANEL BEATING			\$ 1,200.00 1000
SPRAY PAINTING CHARGE			\$ 700.00 600
WIRING CHARGE			\$ 80.00 20
TUFF KOTE			\$ 100.00 50
REMOVE / REFIX CUSHION & UPHOLSTERY			\$ 150.00 50
TRANSFER OF DOOR			\$ 80.00 X 2
FOUR WHEEL ALIGNMENT			\$ 150.00 X 2
TOTAL LABOUR			\$ 2,460.00
ESTIMATE TOTAL			\$ 6,812.32

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum
Will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

& Check Part Price

4/5 \$3600 / 5hr.

7072.32

Efficient Motor & Engineering Works Pte Ltd (Co.Reg.No:201511708E)

56 Loyang Way #06-07, Loyang Enterprise Building

Singapore 508775

Tel: 63416758 / 62840827 Email: efficientloyang@gmail.com

TP INSURER: Sompoo Insurance Singapore Pte. Ltd. (HQ)
NG THIAM SENG EDDY

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:	D18MTMC01006096	Date of Loss:	19/05/2019
Vehicle Reg. No.:	GBE8856U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHIN OI LING	Driver (Insured):	NG THIAM SENG EDDY
Make/Model:	TOYOTA HIACE, 3.0 D (M)	Vehicle Reg. Date:	18/04/2016
Vehicle Colour:	SILVER		
Engine No:	1KD2568385	Chassis No:	KDH2010182776
Odometer:	80199 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Description of Accident/Loss	REFER TO POLICE REPORT		
Present Location:	EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	2,554.72
Miscellaneous Items	0.00
Labour	1,120.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (S\$)	4,274.72
+ GST 7.00% (S\$)	299.23
Nett Amount (S\$)	4,573.95

This claim is handled by: MAS ARIANTI SALEHAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 21 Jun 2019)

Parts: N/A TOYOTA HIACE 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Efficient Motor & Engineering Works Pte Ltd/GBE8856U/21/06/2019 17:06

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR PANEL LH	25.00	0.00	*2,072.00 FL <i>BUC</i>
2	1		*REAR PANEL WINDOW PANEL LH (INNER & OUTER)	25.00	0.00	*300.00 FL <i>Est</i>
3	1		*SLIDING DOOR LH COVER	25.00	0.00	*450.00 FL <i>BUC</i>
4	1		*REAR BUMPER	25.00	0.00	*428.10 FL <i>Est</i>
5	1		*REAR WHEEL HUB CAP LH	25.00	0.00	*156.20 FL <i>Acc</i>
F=Franchise part, L=ListItemDisc.						
			<i>rear trillamp (LH)</i>	<i>25%</i>		
Sub Total (S\$)						3,406.30
- List Item Discount on L Items (S\$)						851.58
Total Parts (S\$)						2,554.72

Efficient Motor & Engineering Works Pte Ltd/GBE8856U/21/06/2019 17:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY PAINTING CHARGE	New	600.00
<u>Labour Items</u>			
2	PANEL BEATING	New	1,000.00
3	WIRING CHARGE	New	20.00
4	TUFF KOTE	New	50.00
5	REMOVE /REFIX CUSHION & UPHOLSTERY	New	50.00
Gross Labour Cost (S\$)			1,720.00

Efficient Motor & Engineering Works Pte Ltd/GBE8856U/21/06/2019 17:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 May 2019 Sendback Est	21 Jun 2019 17:06 S\$4,274.72	12 Jun 2019 14:38 Edit Adj Rpt	S\$3,600.00 Edit Estimates	S\$3,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: NG THIAM SENG EDDY , ID: S9648667G, Tel: +6596488998, Email: NOEMAIL									
Main Claimant: PAN PACIFIC VAN & TRUCK LEASING PTE LTD , Co. Reg. No.: 201511635R									
Vehicle Reg. No.: GBE8856U		Date of Loss: 19/05/2019 23:00 - :59 [37 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / CMTD1902504		Policy/Cover Note No.: D18MTMC01006096 (TP, Fire & Theft)							
Vehicle Reg. No. (Insured): FBN4163P		Policy No. (Claimant):							
		Excess:							
Repairer: Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building, 508775 Loyang - Tel: 63416758 / 62840827									
Handling Insurer: Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 21/06/2019]									
Driver/Custodian (Insured): NG THIAM SENG EDDY (22 / Male) , NRIC: S9648667G, Tel: +6596488998 Email: NOEMAIL									
Adj Asp. Remarks: WS: Mr Rizan 8282 4486									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> SOMPO_SG (21/06/2019): Estimates Sent Back to Repairer: GBE8856U SOMPO_SG (21/06/2019): Estimates Sent Back to Repairer: GBE8856U 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBE8856U (CMTD1902504)
[FBN4163P]
TP
PAN PACIFIC VAN & TRUCK LEASING PTE LTD
May 19 2019 11:00PM
[NG THIAM SENG EDDY]
Efficient Motor & Engineering Works Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports






















1 per page

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	12/06/19 14:35	Accident Statement <small>From: SC - Reg. No: FBN4163P, Claimant: NG THIAM SENG EDDY</small>	1	Load HTM	
No	Finalized On	Efficient Motor & Engineering Works Pte Ltd (HQ)		Thumbnail	Print
1	21/06/19 17:06	Repairer Estimates	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	21/06/19 10:57	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/06/19 09:33	General View	1	Load JPG	
2	13/06/19 09:33	General View	1	Load JPG	
3	13/06/19 09:33	General View	1	Load JPG	
4	13/06/19 09:33	General View	1	Load JPG	
5	13/06/19 09:33	General View	1	Load JPG	
6	13/06/19 09:33	General View	1	Load JPG	
7	13/06/19 09:33	General View	1	Load JPG	
8	13/06/19 09:33	General View	1	Load JPG	
9	13/06/19 09:33	General View	1	Load JPG	
10	13/06/19 09:33	General View	1	Load JPG	
11	13/06/19 09:33	General View	1	Load JPG	
12	13/06/19 09:33	General View	1	Load JPG	
13	13/06/19 09:33	General View	1	Load JPG	
14	13/06/19 09:33	General View	1	Load JPG	
15	13/06/19 09:33	General View	1	Load JPG	
16	13/06/19 09:33	General View	1	Load JPG	
17	13/06/19 09:33	General View	1	Load JPG	
18	13/06/19 09:33	General View	1	Load JPG	
19	13/06/19 09:33	General View	1	Load JPG	
20	13/06/19 09:33	General View	1	Load JPG	
21	13/06/19 09:33	General View	1	Load JPG	
22	13/06/19 09:33	General View	1	Load JPG	
23	13/06/19 09:33	General View	1	Load JPG	
24	13/06/19 09:33	General View	1	Load JPG	
25	13/06/19 09:33	General View	1	Load JPG	
26	13/06/19 09:33	General View	1	Load JPG	
27	13/06/19 09:33	General View	1	Load JPG	
28	13/06/19 09:33	General View	1	Load JPG	
29	13/06/19 09:33	General View	1	Load JPG	
30	13/06/19 09:33	General View	1	Load JPG	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
31	13/06/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
32	13/06/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
33	13/06/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
34	13/06/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
35	13/06/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/06/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/06/19 09:33	General View	 Load JPG	<input checked="" type="checkbox"/>
38	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/19 10:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	12/06/19 14:22	TP - POLICE REPORT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19010385/K1QD3E2

Date: 18/07/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTMC01006096

Claimant Vehicle No: GBE8856U

Insured Vehicle No: FBN4163P

Date of Loss: 19/05/2019

Nature of Claim: TP

Claim No: CMTD1902504

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE8856U

Make & Model: TOYOTA HIACE, 3.0 D (M)

Engine No: 1KD2568385

Reg. Date: 18/04/2016 (Man. Year: 2015)

Chassis No: KDH2010182776

Colour: Silver

Odometer: 80199 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15

Rear Tyre Size: 195/80 R15

Front Left Side: Firemax 6 mm

Rear Left Side: Firemax 6 mm

Front Right Side: Firemax 6 mm

Rear Right Side: Firemax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,554.72	2,798.47	-243.75	-9.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	1,120.00	0.00	0.00
Paintwork Labour	600.00	600.00	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,274.72	4,518.47	-243.75	-5.70
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	4,274.72	3,600.00	674.72	15.78
+ GST 7.00/7.00% (S\$)	299.23	252.00	47.23	15.78
Nett Amount (S\$)	4,573.95	3,852.00	721.95	15.78

INSPECTION

Date of Assignment: 12/06/2019 Present Location:

Efficient Motor & Engineering Works Pte Ltd (HQ)

Date Inspected: 12/06/2019 Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)

56 Loyang Way #06-07, Loyang Enterprise Building
Singapore 508775

Estimated Period of Repair: 5.0 days

Adjuster: KALVIN ANG WEI KUN**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 18 Jul 2019)
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBE8856U)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILLAMP (LH)	Cracked	-	*325.00 FL
2	1		*REAR PANEL LH	Buckled	2,072.00 FL	*2,072.00 FL
3	1		*REAR PANEL WINDOW PANEL LH (INNER & OUTER)	Bent	300.00 FL	*300.00 FL
4	1		*SLIDING DOOR LH COVER	Buckled	450.00 FL	*450.00 FL
5	1		*REAR BUMPER	Cut	428.10 FL	*428.10 FL
6	1		*REAR WHEEL HUB CAP LH	Missing	156.20 FL	*156.20 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,406.30	3,731.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	851.58	932.83
Total Parts (\$\$)	2,554.72	2,798.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	SPRAY PAINTING CHARGE	New	600.00	600.00
<u>Labour Items</u>				
2	PANEL BEATING	New	1,000.00	1,000.00
3	WIRING CHARGE	New	20.00	20.00
4	TUFF KOTE	New	50.00	50.00
5	REMOVE /REFIX CUSHION & UPHOLSTERY	New	50.00	50.00
Gross Labour Cost (S\$)			1,720.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >