



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19010399/Apa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 16-07-2020



ATTN:YVONNE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 7420D	Veh. Inspected	SKS 8789A
Policy No.	GA237225/1	Coverage (\$)	0.00
Claim No.	S9M01Q6I	Excess (\$)	0.00
Assign From		Assign Date	12/06/2019

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6BM42A8G0302291	Colour	GREY
Odometer	55284	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	KUMHO	6 mm
L/H Front Tyre	205/55 R16	KUMHO	6 mm
R/H Rear Tyre	205/55 R16	KUMHO	6 mm
L/H Rear Tyre	205/55 R16	KUMHO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/06/2019	Inspection Date	12/06/2019
Survey held at	CHEW MOTOR PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-41 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------