



Your Ref: S8M00B02

Date: 11th July 2019

Our Ref: CS3/ASM18005126/Bpa3s2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

Attn: Chen Xin You

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GX 321P
INSURED VEHICLE: SGT 7676R ACCIDENT DATE: 15/03/2018**

We thank you for your instruction on 12/06/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GX 321P from M/s Carlink Consultancy.
- b) Final Repair Bill of GX 321P from M/s EM-1 Auto Trade.
- c) Singapore Accident Statement of Vehicles GX 321P and SGT 7676R.
- d) Damaged vehicle photographs of GX 321P.

Pre-Repair Inspection Date: 22/03/2018 at M/s EM-1 Auto Trade, Blk 8 Sin Ming Industrial Estate Sector C #01-68 Singapore 575643.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GX 321P
Make & Model	: Toyota Dyna 150 D
Year of Registration	: 2004
Chassis Number	: JTFUF34Y303002008
Engine Capacity	: 2986 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.