

Our Ref : T 0619/ SHA7271M /KS(st)

Your Ref :

Date : 20-Jun-19

CDGE Taxi Claims Dept

59 Loyang Drive 4th Flr

Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops**Braddell**205 Braddell Road
Singapore 579701**Loyang**59 Loyang Drive
Singapore 508969**Sin Ming**383 Sin Ming Drive
Singapore 575717**Pandan**45 Pandan Road
Singapore 609286**Ubi**320 Ubi Road 3
Singapore 408649**Senoko**24 Senoko Loop
Singapore 758156**Sungei Kadut**7 Sungei Kadut Way
Singapore 728791**Yishun**Yishun Industrial Park A
Singapore 768732
Lonpac Insurance Bhd
300 Beach Road
#17-04 / 07, The Concourse
Singapore 199555
Attn : Motor Claim Department**WITHOUT PREJUDICE**

Dear Sir

ACCIDENT INVOLVING OUR TAXI SHA7271M YOUR INSURED SJP6913Z
AND OTHER _____ ON 09.06.19

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SHA7271M** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : **SJP6913Z** we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 2,193.50
2	3 days Loss of Rental @ \$ 165.46 per day	\$ 496.38
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ 150.00
Sub Total :		\$ 2,847.37

HIRER'S CLAIM

7	3 days Loss of Income @ \$ 80.00 per days	\$ 240.00
Total Claims:		\$ 3,087.37

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 6 pcs.
- b) LTA search slip/s of : SJN5240Z
- c) GIA / Police report/s of : SHA7271M
- d) Letter of authority from owner / hirer / operator
- () PIR () Towing/Medical bill/receipts () Certificate of Insurance (X) Tow receipt
- (X) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) F (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Kazali Hj Selahudin

CDGE Taxi Claims Department

Tel : 6214 8736 Fax: 6214 1843 Email: kazali@cdge.com.sg

This is a computer generated letter. No signature is required.

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING
ALONG****MERCEDES E220 SHA7271M , SJP6913Z
YISHUN AVE 2****ON 09-Jun-19 19:10**

I / We

CHIANG YORK HING KA... (Hirer) NRIC No.: **S1728322G**

and/or

(Relief) NRIC No.:

Taxi Number

SHA7271M

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date

10-Jun-2019

Name of Hirer

CHIANG YORK HING KAREN

Hirer NRIC

S1728322G

Signature :



Address

**992A BUANGKOK LINK #14-173
531992**

Contact No.

98325616

GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 24 Senoko Loop Singapore 758156
383 Sin Ming Drive Singapore 575717 7 Sungei Kadut Way Singapore 728791
45 Pandan Road Singapore 609286 501 Yishun Industrial Park A Singapore 768732
320 Ubi Road 3 Singapore 408649

COMPANY REG. NO.: 199506048W

Page: 1

8010042

LONPAC INSURANCE BERHAD
THE CONCOURSE

300 BEACH ROAD #17-04/07
SINGAPORE 199555

CONTACT NO: 62507388

VEHICLE NO
SHA7271M

NO/DATE
91450120 18.06.2019

MAKE
MERCEDES BENZ

JOB NO.
305302318

MODEL
E220CDI (E5)

ODOMETER READING

DATE OF REG
30.09.2013

CHASSIS CODE
WDD2120022A759873

JOB TYPE

Description : 3P 09.06.2019

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt	2,050.00
Add GST @ 7.000 %	143.50
Total Invoice amount	2,193.50

Issued by : CHEWBEELENG 18.06.2019 14:44:04
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT19060203



Date: 18 June 2019

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 09/06/2019 @ 19:10 hrs
ALONG YISHUN AVE 2
INVOLVING SJP6913Z

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA7271M** (the "Taxi"). The Taxi was hired to **CHIANG YORK HING KAREN IC NO S1728322G** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$165.46** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurance Details

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
SJP6913Z	09 Jun 2019 / 19:10:00	Successful	L06	LONPAC INSURANCE BHD

Previous OK

WORK ORDER


No. P 14044

Svc Date	9/6/2014	Time Received	2215
Member's Name	CDGE	Time Arrived	2310
M'ship / NRIC No.	mdm cheng Yek Heng	Time Completed	2350
Member's Contact No.	9833 5616	From	RTA Bukit Merah
Car Regr. No.	3HA 7271M	To	Leong
Car Make / Model	Merc / White	Tow Truck No.	4P672C
Remarks (if any)	Accident	Amount	\$150-

ADDITIONAL CHARGES

- | | |
|--|--|
| <input checked="" type="checkbox"/> Dolly Wheels /Flat bed | <input type="checkbox"/> Patch Tyre |
| <input type="checkbox"/> Basement /Multi-storey | <input type="checkbox"/> Change Spare Tyre |
| <input type="checkbox"/> Crane up /Bogged | <input type="checkbox"/> Change Battery |
| <input type="checkbox"/> Causeway /2nd Link | Size : _____ |
| <input type="checkbox"/> Jump Start | |
| <input type="checkbox"/> Collection of key | |
| <input type="checkbox"/> ERP /Carpark | |

BODY & PAINT CONDITION RECORD



*please remove any valuables or personal belongings in the car

Tow Driver's Name & Signature

Member's Signature

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

