

ASS. REC. BY:

REF: CS/INC19010421 GV d322

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Annie Koh

of INC

Date/Time: 12/6/19 09:50am

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJS7699U

Insured:

SJW 4931Y

at Workshop m/s

Auburn Auto

Tel:

96191525 / 9787 5558

of

176 Sin Ming Drive #04-18

Sam

Policy No:

Claim No:

MT/1048602-001

Insured:

Broker:

Make of Veh:

(Client's Record)

D.O.A.

8/6/19
13/6/19 @ after 10am

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:24am @ 12/6/19

Person Contacted:

GRIC

Vehicle IN ☒ OUT

Date/Time	Action/Instruction
	SJS7699U - x
	SJW 4931Y - x
24/9/19	LS \$1550 confirmed by email (Red 5525, 24/9)

and!

REF: INC

ASSIGNMENT

From: _____ Date: 13/6/19

Estimated Cost: _____

OD (TP / WS / TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: SJS7699U

at Workshop n/s Auburn Auto

of 176 Sn Ming Drive # 04-18

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: ERIC @ 96191525

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJS 7699U (1 Regn: -)

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Jetta 1390

Colour: Black A/C: Insured / Std / NI / NA

Sp Reading: 22668 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVVWZZZ1K894021227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD M/Rim or

Tyre Size: F: 225/40ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: _____ D.O.I: 13-06-19

Survey held at: w/s 3:30pm

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/6 Estimate Give later.

RECEIVED 4 OCT 2019

Signature
26/9/2019

Date/Time, File Pass (s)

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return (s)

3 4/10 - typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Workshop (\$)

Report Format: TP

Lump Sum / UIC / 1550/2

Survey Fee:

290

Transportation

S + P.S. \$

Phone

Other

TOTAL

290

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Wednesday, 12 June 2019 11:05 AM
To: admin-d@lkkauto.com; 'assignments@lkkauto.com'
Subject: FW: TP CASES FARMED OUT TO LKK ON 12/06/2019

Hi .Nivitha

Resend with more details.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income
more different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 12 June 2019 10:45 AM
To: Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>; Daniel Koh <daniel.koh@income.com.sg>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; Susan Ting <susan.ting@income.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 12/06/2019

Dear Annie,

Thank you for the assignment.

Please be informed that SJS 7699U (AUBURN AUTO) and SLV 3345C (THIAM HENG HUAT),

Vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annie Koh [<mailto:annie.koh@income.com.sg>]

Sent: Wednesday, 12 June 2019 9:50 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Daniel Koh <daniel.koh@income.com.sg>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; Susan Ting <susan.ting@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 12/06/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1048602-001	SJS7699U	AUBURN AUTO PTE LTD	176 SING MING DRIVE #04-18 SIN MING AUTOCARE	Eric Chan / 96191525	SIW4931Y	8/6/2019	

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
Senior Admin Assistant, Motor Insurance
T +65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/06/2019 17:46
Date Of Accident	08/06/2019 04:20
Exact Location Of Accident	NEAR KPE EXIT TO TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS7699U
Insured/Policyholder	
Name Of Registered Owner	COVE RENTALS PTE LTD
Co Reg No	201626878M
Email Address	COVERENTS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-87978998
Alternative Phone No	OFFICE-90998998

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107662372
Cover Note Number	

Driver

Name of Driver	CHU HENG SOON
NRIC No	S7103973J
Date Of Birth	13/02/1971
Occupation	OUTDOOR
Date Of Driving Pass	17/03/1989
Driving Experience	30 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97693511
Fax Number	
Contact Number	
EMail Address	COVERENTS@GMAIL.COM

Address	BLK 450G TAMPINES STREET 42 #08-370
Postcode	527450
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PASSENGER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 62181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT AND POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJW4931Y
Vehicle Make/Model/Colour	HONDA FIT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TOH SEOW TEE
NRIC/Passport Number	S7226458D
Contact Number	98524209

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHU HENG SOON

Approximate Age 48

Injuries Sustain STIFFNESS IN NECK LEADING TO PAINS IN NECK, SHOULDER AND LOWER BACK

Injured person in which vehicle? SJS7699U

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? NO

Address BLK 450G TAMPINES STREET 42 #08-370

Postcode 527450

IMPORTANT NOTICE

SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my insurer and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claim;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or;
 - (v) complying with applicable law in connection with processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; and
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:

NG WING KIN JAMES

admin.vac@vicom.com.sg

11 JUN 2019

KFE EXITING TO TPE (SENGKANG)



KFE EXITING TO CHANGI AIRPORT

A - SJT 7699J

B - SJW 4931Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 08-06-2019 AT ABOUT 0420 HRS, I CHU HENG SOON
 NRIC No: SJ103993J WAS DRIVING PRIVATE-HIRE RENTED CAR PLATE No: SJT 7699J
 WITH A PASSENGER ALONG KFE HEADING TOWARDS TPE (SENGKANG). DRIVING
 WITHIN MY LANE, A CAR PLATE No: SJW 4931Y WHICH WAS DRIVING ON
 THE NEXT LANE TOWARDS CHANGI AIRPORT MADE A SUDDEN SWERVE
 TO MY LANE UPON REACHING THE WHITE ^{FLY} DIVIDER. IT OBVIOUSLY
 WANTED TO SWITCH LANE AT THE LAST MINUTE WITHOUT PROPER
 LOOKOUT AND SIGNAL, COLLIDED INTO THE RIGHT SIDE OF MY CAR.
 THE IMPACT OF THE ACCIDENT BADLY DAMAGED MY CAR AND
 I WAS BADLY SHAKEN. I HAD STIFFNESS IN MY NECK WHICH
 LED TO PAINS IN MY NECK, SHOULDER AND LOWER BACK OF MY
 BODY. I CONSULTED A MEDICAL DOCTOR AT HWONG & LIANG
 AND WAS GIVEN 3 DAYS MEDICAL LEAVE.

MY IN-CAR CAMERA RECORDED THE FOOTAGE OF THE
 OTHER CAR WHICH SWERVED INTO MY LANE AND CAUSED THE
 ACCIDENT.

STATEMENT

I hereby declare that the above statements are true in every respect.



CHU HENG SOON

Driver's Signature

If driver is not the policyholder

Date & Time

10 JUN 2019



Report On: Driver's Personnel & Signature

Name

NIC/FIN No.

NG WING KIN JAMES

admin.vac@vicom.com.sg

6/10/2019

Mail - Vicom VAC Admin - Outlook

M1

4:07 PM

84%

< Cove-Acc(Chu-SJS7699U-VW Je... All Media
9/6/19, 4:00 AM

SINGAPORE POLICE FORCE

Police Station Of Origin:
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
669784
Tel No: 1800-4849999

Report No: T2019009/2027

1 of 3

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/06/2019 03:58

Vide Report No: /

Station Diary No: 31

Informant's Particulars:

Name of Informant: CHU HENG SOON

Address: APT BLK 450G TAMPINES STREET 42 #08-370 SINGAPORE 527450

ID Type / ID No: NRIC NO / S7103975J

Contact No.: Home/Office: Mobile: 97693511

Nationality: SINGAPORE CITIZEN

Email:

Sex: Male Age: 48 Date of Birth: 13/02/1971

Type of Informant: Driver

Race: Chinese

Language: English

Institution / School Name:

Occupation: GRAB DRIVER

Driving Licence Information: Class: Date of Expiry:

General Information of the Accident:

Type of Accident: Injury Others

Drink Drive: No

Date/Time of Accident: 08/06/2019 04:20

Type of Location: Straight Road

Location: Along Road 1
KALLANG PAYA LEBAR EXPRESSWAY

Near KPE exit to TPE

Weather: Clear

Road Surface: Dry

Road Speed Limit:

Traffic Flow: Clockwise

Traffic Control:

Traffic Volume: Light

Mode of Collision: Side Impact - Same Direction

Anyone conveyed by ambulance: No

Details of Vehicles Involved:

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
SJS7699U	Car				Seriously Damaged	1
VW4531Y	Car				Seriously Damaged	1



SINGAPORE
POLICE FORCE

1/20190609/2027

2 of 3

Police Station Of Origin
Ang Mo Kio North N.P.C
51 Ang Mo Kio Avenue 9 SINGAPORE
569784
Tel No: 1600-4849599

Report No: 1/20190609/2027

CONTINUATION OF REPORT

Driver			
Name	CHU HENG SOON	ID No.	S7103973J
Related Vehicle	NIL	Contact No.	97693511
Hospital/Clinic	HWANG & LIANG FAMILY CLINIC & SURGERY	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	08/06/2019	Date Discharge	NIL
No of Days granted Medical Leave	03	Degree of Injury	NIL

Brief Details.

On 08/06/2019 at about 0420hrs, I was driving Private-Hire Rented Car bearing (SJ57699U) with a passenger along KPE heading towards TPE (Sengkang). Driving within my extreme left lane, a car bearing (SJW4931Y) which was driving on the next lane towards Changi Airport made a sudden swerve to my lane upon reaching the white floor divider. It obviously wanted to switch lane at the last minute without proper lookout and signal collided into the right side of my car. The impact of the accident badly damaged my car and I was badly shaken. I had stiffness in my neck which lead to pain in my neck, shoulder and lower back of my body. I had consulted a medical doctor at Hwang & Liang and was given 3 days of medical leave from 08/06/2019 to 10/06/2019. I wish to state that my In-Car camera recorded the footage of the other car which swerve into my lane and caused the accident.

6/10/2019

Mail - Vicom VAC Admin - Outlook

M1

4:07 PM

84%

< Cove-Acc(Chu-SJS7699U-VW Je...
9/6/19, 4:01 AM

All Media

Police Station Of Origin: Ang Mo Kio North N.P.C. 51 Ang Mo Kio Avenue 9 SINGAPORE 569784 Tel No: 1800-4349999		3 of 3 Report No: T20190606/2027	
CONTINUATION OF REPORT			
Sketch Plan Informant is not able to provide sketch plan			
IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the <u>report number</u> as reference.			
Signature Of Officer Recording The Report: SGT KEVIN CHUA MIN YAN		Signature Of Informant:	
Signature Of Interpreter: Not applicable		Date/Time: 09/06/2019 03:58	
Officer In Charge Of Case: TP/AEIT SIANG YI TING, STEPHANIE Contact No: 6547841		Classification Of Case:	
Authentication Stamp			

<https://outlook.office.com/mail/inbox/ld/AAMkAGMwMjx3NTILTU4ZjllNDk5MS1YjllTE5MmZkZjQxNW12NwBGAAAAAAdVlc2lXaQpSV0OyK...> 1/2

3 ANG MO KIO STREET #2 #04-15 S569139

VEHICLE RENTAL AGREEMENT

THIS VEHICLE RENTAL AGREEMENT (AGREEMENT) EFFECTIVE AS OF 23/04/2019 (dd/mm/yyyy), IS MADE AND ENTERED INTO BETWEEN COVE RENTALS PTE LTD (hereinafter "The Company") (SINGAPORE COMPANY REGISTRATION NO. 201408878M), A COMPANY ORGANISED AND EXISTING IN SINGAPORE, WITH OFFICES LOCATED AT LINK@AMK, 3 ANG MO KIO STREET #2 #04-15, S569139

AND

CHU HENG SEON (ZHU XINGSHUN)
(Name of main hire / hereinafter "Hire")

S71009731
(Singapore NRIC No. / Driving Licence No.)

BLK 450G THALAYNES STREET 42 #08-370 S509150
(Residential/Mailing Address)

9769 3511 (Contact No.)

9766 3731 (Emergency contact No.) Wife Kevin (Relationship)

AND

(Name of Co-hire (hereinafter "Hire"))

(Singapore NRIC No. / Driving Licence No.)

(Residential/Mailing Address)

(Contact No.)

(Emergency contact No.) (Relationship)

Authorized Vehicle Details

Make/Model: VOLKSWAGEN JETTA 1.4 TSI

Vehicle No: MIS7699U

Rental Period: 23/04/2019 to 25/04/2019
(dd/mm/yyyy) (dd/mm/yyyy)



Whereas, The Company and Hire desire to enter into a relationship in which the Company has agreed to provide car rental service to the Hire on the terms and conditions set out in this Agreement (from page 1-3 and the Damage Check Sheet), while Hire is of the opinion that the Company has the proper and necessary qualification, experience and ability to provide car rental services to Hire. The Hire also has a copy of this Rental Agreement. The Company may change these terms and conditions at any time by revising them. You agree to be bound by any such revisions.

Page 1 of 3

Accident Photo

M1

3:52 PM

72%



Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo

M1

3:52 PM

72%



Cove-Acc(Chu-SJS7699U-VW... Select

9 Photos





Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo

M1

3:53 PM


72%



Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo

M1


4:04 PM

82%



Cove-Acc(Chu-SJS7699U-VW... Select

9 Photos



Accident Photo

M1

4:04 PM


82%



Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo

M1

4:04 PM


82%



Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo

M1

4:04 PM

82%



Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo

M1

4:04 PM

82%



Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo

M1

4:04 PM

82%




Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



Accident Photo





Cove-Acc(Chu-SJS7699U-VW...

Select

9 Photos



176 Sin Ming Drive
#04-10 Sin Ming Autocare
Singapore 575721
UEN 200805305G
Contact 96191525

ASSESSMENT FOR REPAIRS :
VEHICLE NUMBER : SJ57699U
VEHICLE MODEL : VOLKS WAGEN

Quantity	Description		Estimated costs
1 pc	Side fender (front right) / Due		975.00
1 pc	Driver's Door (right) X Repair.		1,300.00
1 pc	Right rims / Got		850.00
1 pc	Right tyre x NN		600.00
			\$3,725.00
			10%:
Labour charges			
	Repair and fix /replace accident damaged parts		1,600.00
	To check front right wheel alignment		250.00
	To spray paint on all accident area		1,200.00
	TOTAL		\$3,050.00
	TOTAL PARTS & LABOUR CONCLUDED		\$6,775.00

12.06.2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Other

1549-1945
20%: 1200-1550
4 Days.

Veron Chen (LKKAUTO)

From: Auburn Auto <auburnauto.survey@gmail.com>
Sent: Tuesday, 24 September 2019 3:21 PM
To: Veron Chen (LKKAUTO)
Cc: laurachan271@gmail.com; syjoshuachan@gmail.com
Subject: Re: Final repaired/resprayed photos of SJS7699U-Volkswagen Jetta

Dear Veron,
We hereby accept lump sum \$1,550-00(net) with 4 working days repair with regard the above.
Thank you.

Eric Chan
Auburn Auto Pte Ltd

On 12 Sep 2019, at 11:51 AM, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Eric,

WITHOUT PREJUDICE

Offer Lump Sum \$1550/- @ 4 working days.

Please check and confirm.

Kindly forward a copy of GIA report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 29 July 2019 10:21 AM
To: Auburn Auto <auburnauto.survey@gmail.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: RE: Final repaired/resprayed photos of SJS7699U-Volkswagen Jetta

Dear Eric,

WITHOUT PREJUDICE

Offer Lump Sum \$1200/- @ 4 working days.

Please check and confirm.

Kindly forward us a copy of GIA report.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Auburn Auto <auburnauto.survey@gmail.com>

Sent: Tuesday, 25 June 2019 6:25 PM

To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Cc: laurachan271@gmail.com; syjoshuachan@gmail.com

Subject: Final repaired/resprayed photos of SJS7699U-Volkswagen Jetta

Dear Guo Qiang,

As requested, forward herewith final repaired/resprayed photos of Volkswagen Jetta SJS7699U for your records.

Thank you for your time in survey.

Best regards,

Eric Chan

Auburn Auto Pte Ltd

<image001.jpg>

<image002.jpg>

<image003.jpg>

<image004.jpg>

<image005.jpg>

<image006.jpg>

<image007.jpg>

<image008.jpg>

<image009.jpg>

<image010.jpg>

<image011.jpg>

<MARKING.pdf>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Ref: CS/INC19010427/Gvd3e2

Date: 09-10-2019



ATTN : SERENE LIM

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 4931Y	Veh. Inspected	SJS 7699U
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1048602-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	12/06/2019

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN JETTA 1.4	c.c	1390
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WWWZZZ1KZ9U021227	Colour	BLACK
Odometer	222668 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40Z R18	MICHELIN	6 mm
L/H Front Tyre	225/40Z R18	MICHELIN	6 mm
R/H Rear Tyre	225/40Z R18	MICHELIN	6 mm
L/H Rear Tyre	225/40Z R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/06/2019	Inspect Date / Time	13/06/2019 (03:30 PM)
Survey held at	AUBURN AUTO PTE LTD 176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 7699U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SIDE FENDER (FRONT RIGHT)	BUCKLED	975.00	650.00
1	DRIVER'S DOOR (RIGHT)	TO REPAIR SEE LABOUR	1,300.00	-
1	RIGHT TYRE	NOT NECESSARY	600.00	-
	LESS 10% DISCOUNT		-	-65.00
			2,875.00	585.00
	SPECIAL NETT ITEMS			
1	RIGHT RIMS (SN)	CUT	850.00	500.00
			850.00	500.00
	LABOUR			
	REPAIR AND FIX / REPLACE ACCIDENT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF DRIVER'S DOOR (RIGHT).		1,600.00	400.00
	TO CHECK FRONT RIGHT WHEEL ALIGNMENT		250.00	60.00
	TO SPRAY PAINT ON ALL ACCIDENT AREA.		1,200.00	400.00
			3,050.00	860.00
	GRAND TOTAL		6,775.00	1,945.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,550.00

Report Ref No. CS/INC19010427/Gvd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.