Surveyor : _ From (Person	Xenry Annie Koh	ASSIGNMENT (Office)	Da	te/Time: 12/6/19/09.500
Estimated Co	ost	Bill to:		to Third.
To inspect V	/STTP RES / OD RES / EVA / /chicle No:	OBF 43544	Insured:	SLH 9576L
at Workshop of	BIK I Sin Ming Ind.	ock Auto	Tel:	96571534
Policy No:_	, J			047266-002
Sum Insured		Excess:		017000
Make of Veh (Client's Recor	No.		D.0	D.A. 2/6/19
CA / REV Date/Time:	/ REP. / REV 24 HRS	n Contacted: The	meng Vehi	LO.D. Endorsement:
Date/Time	Action/Instruction Volume			
	GBF 4354 X -X			
	SLH 95761-			
	SLH 95761-			

enneth	2 10	ASSIGNMENT
From;	Date:	
Estimated Cost:	Dotte.	Veh No: GBF 435 8 Yr Regn: 10 /
OD PP WS ITP RES 10	D RES / EVA / INV / MV	miojoie / Bus / Van / Zorry / Taxi / Prime Mover /
To Inspect Vehicle No:	T. C.	Truck / Trailer or
at Workshop m/s	11	Make: Toy Dyn 8 c.c 288
of	My Ha	Colour Silve A/C: Insured / Std / NI / N
Insured:		Sp.Reading 253110 T/Radio: Insured / Std / N1 / N
Policy No.		Eng/No:
Claims No.		C/No: KDY 231 . 80255
Sum Insured:	Even	Gen. Cond. Good'/ Fair / Poor / Burnt
(Client's Record)	Excess:	Steering: Inopder? Jammed / Leaked / Burnt or
Make of Veh:		Brake: Inorder / Jammed / Leaked / Burnt or
ACCESS OF THE PARTY OF THE PART		Modi: Mil / S/Rim / STD A/Rim or
(Policy Condition)		Tyre Size: F: Yoku 185R 15 X8
Remark: The veh had comme	anced its	R: (150 tu 155 R17 VIII
repair at the time of		O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
lal. or Market Value:		TOYO/YOKO or
DAC Accident Rport:		Front D Rear
IA / PR Seen:	Consistent? : Yes or No	R/Bal. C mm R/Bal. / /
- 0/	Consistent?: Yes or No	L/Bal. Pmm L/Bal / /
um Sum; 2,	days Res.; Yes or No	D.O.A. 2/6/19 D.O.I. 12/6/16
10	% 3 Val.: Yes or No	Survey held at
A / REV / REP. / 24 H	IRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
te: Person C	Vehicle: IN /	mea ols
ate / Time Action / Instru	The same of the sa	The U/C / Chassis frame / Body Structure affected due to collision.
/ Fix pas		- Condon
2016 61 From 8	3150h eneil \$ 2	confirmed. (Red & 3282.60, 51%)
		Timber. CHEN & 7182.60 , 51%)
	RECEL	VED 1 7 JUL 2019
irra, File Pass (07	rell. Report	Days Of Repair: 4
10 h 1 at 11	nal Report	Resulting No. 177
FI WINGS : FI		Survey Fee: 250
FI WINGS : FI		
FI WINGS : FI	Add Fe	Transportation
ino, File Return to?	Add Fe	99: Site Insp (\$)_S - RS_SI
FI WINGS : FI	Add Fe	Transportation

Nivitha (LKK Auto)

From:

Sent:

<u>ت</u>

Subject:

FW: TP CASES FARMED OUT TO LKK ON 12/06/2019 admin-d@lkkauto.com; 'assignments@lkkauto.com' Daniel Koh <daniel.koh@income.com.sg> Wednesday, 12 June 2019 11:05 AM

Hi .Nivitha

Resend with more details.

Senior Admin Assistant www.income.com.sg Motor Insurance T+65 6430 7901 Daniel Koh









Find out more at income.com.sg/careers

Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. At Income, we are 'In with You' on Performance, Growth,

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Wednesday, 12 June 2019 10:45 AM

fo: Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>; Daniel Koh <daniel.koh@income.com.sg>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; Susan Ting <susan.ting@income.com.sg>; SUR <sur@lkkauto.com> Subject: RE: TP CASES FARMED OUT TO LKK ON 12/06/2019

Dear Annie,

Thank you for the assignment.

Please be informed that SJS 7699U (AUBURN AUTO) and SLV 3345C (THIAM HENG HUAT),

Vehicle is not in the workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: <u>assignments@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annie Koh [mailto:annie.koh@income.com.sg]

Sent: Wednesday, 12 June 2019 9:50 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Daniel Koh <daniel.koh@income.com.sg> Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>; Susan Ting <susan.ting@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 12/06/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

- 8
AUTO PTE
OTJ U6697SLS

		V8 motor werkz pte Itd				
		29/3/2019	2/6/2019	25/5/2019	8/6/2019	8/6/2019
		GBH5962A	SLH9576L	SBR9000Y	GBE1694R	SCX7343C
		Qiang / 91442977	Thomas / 96571534	Mdm Lim / 64536256	Fong / 97335832	Steven / 82636295
SINGAPORE S75721	9 SIN MING ROAD #01- 44 SIN MING INDUSTRIAL	EST SECTOR C SINGAPORE 575630	BLK 1 SIN MING INDUSTRIAL ESTATE C #01-129 SINGAPORE 575636	160 SIN MING DRIVE, 05- 08 SIN MING	10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-20 SINGAPORE 575645	176 SIN MING DRIVE #05- 14 SIN MING
		HOME	KENG HOCK AUTO	KUM CHEW MOTOR WORKSHOP	TEAM AUTOPRO PTE LTD	THIAM HENG HUAT PTE LTD
		GU9224T	GBF4354Y	SLV208K	QT55828	SLV3345C
		MT/1045213- 001	MT/1047266- 002	MT/1046041- 002	MT/1048351- 001	MT/1048228- 002
		Alice	Jared	Jared	Eric	Eric Tang
		7	m	4	25	9

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T+65 6430 7899

www.income.com.sg









Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.

www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

aforesaid.	
A THE RESERVE THE PARTY OF THE	ACCIDENT STATEMENT
Date Of Report	03/06/2019 18:21
Date Of Accident	02/06/2019 15:15
Exact Location Of Accident	TPE TWDS PIE BEFORE PUNGGOL ROAD EXIT
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	GBF4354Y
Insured/Policyholder	
Name Of Registered Owner	DE YI RENOVATION & TRADING
Co Reg No	52814569W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90261587
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-006859
Cover Note Number	
Driver	
Name of Driver	KATHIRVEL SAKTHIVEL
Passport No/FIN	G7712679T
Date Of Birth	08/05/1983

 Passport No/FIN
 G7712679T

 Date Of Birth
 08/05/1983

 Occupation
 OUTDOOR

 Date Of Driving Pass
 05/04/2010

Driving Experience 9 YEARS AND 1 MONTH

Gender MALE

Mobile Number (LOCAL) +65-85354702

Fax Number

Contact Number

EMail Address NOEMAIL

Address

270 TOH GUAN RD

Postcode

600270

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

3

Passenger 1

NAME:

: UNKNOWN

GENDER:

: MALE

Passenger 2

NAME:

: UNKNOWN

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Refer to sketch plan.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

SLH9576L

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

裝修買 DE YI RENOVATION & TRADING

Policyholder's Signature

Date & Time: - 3 JUN 2019 Driver's Signature

(If driver is not the policyholder)

Date & Time: - 3 JUN 2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN	Punggol Rd		TPE	
	A. C.	Slip Rod.	Veh A - Veh B -	- GBF 43549 · SLH 9576
DESCRIBE CIRCUMSTANC	ES OF THE ACCIDENT			
Vehicle A towards 1 traffic. T Vehicle A	is stopping a Punggol Roa hen suddenly rear.	t the Slip of d. to check vehicle B	bang in	TPE
PECLARATION Whe dede to to the fore	DING Yo Part A	t.		
olicyholder Signature ate & Time - 7 JUN 2019	Driver's Signature (If driver is not the police Date & Time:	yholder) N	eporting Centre Personn lame: RIC/FIN No.:	el's Signature

Notice of Compliance-Choa Chu Kang NPC Pg. 1

CONFIDENTIAL

Annex E

NOTICE OF COMPLIANCE

	his is to confirm th $ \begin{array}{ccc} G7712679T \end{array} $			on-injury traffic accident
which oc				BEFORE PUNGGOL
1	/06/2019 at BF4354Y (MY LO		am/pm involv	ing the following vehicles
2. SI	LH9576L . DRIVER: AIDIL	Ø.	SWANDI NRIC	NO: S9412719Z)
2				4 hours of its occurrence, oad Traffic Act, Cap 276.
	Date: 02/06 S/D Ref: 56	/2019	Time:	ORE 689286
	Original – to be issued Duplicate – to be subm		i	

CONFIDENTIAL

Version as of 15 Jan 2002

Insurance Certificate Pg. 1

EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110 tel 65 6223 9433 | fax 65 6224 3903 | www.eqinsurance.com.ag reg no. 1978-00490-N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES(THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP.189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

COMMERCIAL VEHICLE PRIVATE (SCH I) Comprehensive

Certificate No.: DMCPHQ18-006859

 Index Mark and Registration Number of Vehicles GBF4354Y Form: LCVP1 Excess: Section 1: YEID-AC Additional:

EQ Insurance-MARS Motor

Accident Help Center

6311 3211

S\$500.00 S\$3,000.00

2. Name of Policyholder

DE YI RENOVATION & TRADING

- Effective Date of the Commencement of Insurance for the purpose of the Act 25/10/2018
- 4. Date of Expiry of Insurance 24/10/2019

5. Person or Classes of persons entitled to drive*

Goods carrying - (MZ300) Authorised Driver.

Any of the following :-

1. The Policyholder

2. Any person on the order or with the permission of the Policyholder

Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

6. Limitation as to use*

1)Use in connection with the Insured's business.

2)Use for the carriage of passengers (other than for hire or reward) in connection with the Insured's business.

3)Use for social domestic and pleasure purposes.

THE POLICY DOES NOT COVER

1)Use for hire or reward or for racing pace-making reliability trial or speed testing.

2)Use whilst drawing a greater number of trailers in all than is permitted by Law.

3)Use for the carriage of passengers for hire or reward.

 Liability arising from or in connection with the carriage of hazardous materials, high explosives, inflammable liquid or gases including LPG in

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation)
Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

Hire Purchase: Ethoz Capital Ltd


A000298/Tong Hin Insurance Agency Pte Ltd Date of Issue: 08/10/2018 13:29

Authorised Signatory EQ Insurance Company Limited

Exp No. : DMCPHQ17-006123

A Member of Citystate

Driver NRIC and Driving Licence Pg. 1







YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive 05 Apr 2010 of the driver; and other motor vehicles =< 2500kg

NP 428A

KENG HOCK AUTO

Bik. 1, Sin Ming Industrial Estate C, #01 - 129, Singapore 575636

Rear	gate board	1673.60	Ry	\$ 1250.00
Rear	RIRH Siele	board lock	n	4 90.20
Rear	RIRH Corner		ns	A 75. 10
Rear	exhaust k	orbe		#570.70
Rear	exhaust	Pipe mounting	e Dis	\$ 25.10
Reer	lamp	Pipe Mountine	Bn	\$ 350.40
Rear	plate pai	nel 169.80	Ry	A 250 10
Rear	end pan	el	R	\$ 410.10
Rear		1 reflector	cm	\$ 75.80
Reur	lamp brod		B	# 125.10
			25[
				201
	uber plate		cm	4 30.00
70	EM/h Stick	2er	125i - Ma	A 15.00
13	pax stic	Ker	125m - Ma	# 15. ac
				3
To spa	ny anti rust	on accident	affected pa	mel # 80.00
	wring system.		epoir and	20
	dit the son	the Repairer of the following	hence natify	8 120
- (To resurvey heterotals	uwing:	6001
~ (• To display do	AND RESERVED TO THE PARTY OF TH	
pane	el beating	Parts prigne are comments	Tulling resurvey	# 1100.00
	el beating	Parts prices are supported Inird party survey is on a reliable of the supported by	Without Prejudice" basis	# 1100.00
pane	, ,	Parts prices are sub-control Inird party survey to on a rel No illegal modification is supplementary item (s) must is subject to final approval free.	Without Prejudice" basis	# 1100.00
pane	of - painting Gote luner A	Parts prices are supported Inird party survey is on a No illegal modification is is supported to final approval if Acknowledged by Repairer Signature;	Without Prejudice" basis	# 1100.00 56d

4day, Purney Afre Parmy

643260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19010432/Kqd3e2

ESTIMATED NORMAL PERIOD FOR REPAIR:

- 111		Ш
- 111		Ш
- 111		Ш
		ш

		D UNION HOUSESINGAPORE	Date: 17-07-2019	
ATT	N: JARED LIU		Code: INC	
1.		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	SLH 9576L	Veh. Inspected	GBF 4354Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1047266-002	Excess (\$)	0.00
	Assign From	ANNIE KOH	Assign Date	12/06/2019
		Vehicle Parti	culars & Condition	
	Make & Model	TOYOTA TOYOACE (M)	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDY2318025575	Colour	SILVER
	Odometer	253110 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
	the new to	Condit	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	YOKOHAMA	8 mm
	L/H Front Tyre	195 R15X8	YOKOHAMA	8 mm
	R/H Rear Tyre	155 R12X8 (D)	TIANFU	1/1 mm
	L/H Rear Tyre	155 R12X8 (D)	TIANFU	1/1 mm
		Descripti	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	AR O/S PORTION.	
5.		Genera	I Information	
	Accident Date	02/06/2019	Inspect Date / Time	12/06/2019 (10:59 AM)
	Survey held at	BLK 1 SIN MING IND EST C #0	1-129	
	Repairer	KENG HOCK AUTO		
ā.		R	emarks	
	A)THE INSPECTION B)IN ACCORDANCE	ON WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W	THOUT PREJUDICE" BASIS VE HAVE NOT AUTHORISE	D REPAIRS.
5b.		Estimate	Days of Repair	

4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 4354Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR GATE BOARD	BENT	1,850.00	1,675.00
1	REAR R/RH SIDE BOARD LOCK	TO REPAIR SEE LABOUR	90.20	-
1	REAR R/RH CORNER PILLAR	DENTED	75.10	75.10
1	REAR EXHAUST PIPE	BENT	570.70	570.70
1	REAR EXHAUST PIPE MOUNTING	DISTORTED	25.10	25.10
1	REAR LAMP	BROKEN	350.40	238.60
1	REAR PLATE PANEL	BENT	250.10	169.90
1	REAR END PANEL	BENT	410.10	410.10
1	REAR END PANEL REFLECTOR	CRACKED	75.80	75.80
1	REAR LAMP BRACKETS	BENT	125.10	125.10
	LESS 25% DISCOUNT		:-	-841.35
			3,822.60	2,524.05
	SPECIAL NETT ITEMS			
1	NUMBER PLATE (SN)	CRACKED	30.00	20.00
1	70 KM/H STICKER (SN)	NECESSARY	15.00	12.00
1	13 PAX STICKER (SN)	NECESSARY	15.00	12.00
			60.00	44.00
	LABOUR			
	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PANEL.		80.00	30.00
	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME.		120.00	20.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR R/RH SIDE BOARD LOCK.		1,100.00	600.00
	SPRAY PAINTING.		850.00	560.00
	TAIL GATE INNER ALUMINIUM BOARD REAR FLOOR PANEL ALUMINIUM.		400.00	180.00
			2,550.00	1,390.00
	GRAND TOTAL		6,432.60	3,958.05

RECOMMENDED COST OF LUMP SUM REPAIRS	3,150.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)	

Report Ref No. CS/INC19010432/Kqd3e2





Report Ref No. CS/INC19010432/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:-This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.