

ASS. REC. BY:

Investigator: Wong Ching

REP:

083/ALG19010434/Gcd302

Special Instructions:

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

ALG

Date/Time:

11/6/2019 @ 1:50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 6249T

Insured:

SLQ 3366T

at Workshop m/s

2-one Automotive

Tel:

6634 2112

of

1 Kaki Bkt Ave 6 #01-87

Policy No:

Claim No:

741372791686

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8/6/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

R.O.D. Endorsement:

Date/Time:

11:37am @ 12/6/19

Person Contacted:

Yvonne

Vehicle IN/OUT

Date/Time

Action/Instruction

11/6/19 X1

SIN 6249T-X

SLQ 3366T-X

Dismantle: 13/6/2019

After repair: 25/6/2019

ASSIGNMENT

(-2023)

From: _____ Date: _____
Estimated Cost: _____
OD: ☒ TP WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV
To Inspect Vehicle No: _____
at Workshop m/s: 2-one
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$23k
IDAC Accident Rpt.: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 12 days Res.: Yes or No
Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SIN6249T Yr Regn: 09 Sep 2008
Type: ☒ M.Cab / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
Truck / Trailer or _____
Make: Honda Fit 1.3G C.C. 1339
Colour: yellow A/C: Insured / Std / NI / NA
Sp. Reading: 248818 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: GE 61049431
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 185/60 R15
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Dayton
Front: _____ Rear: _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. _____ D.O.I. 12-06-19
Survey held at: W/S 4:45pm
Des. of Damages: ☒ Frt / ☒ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format : DAR


Lump Sum / I.B.I. (\$) _____

180

11

191

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ3366T AND SJN6249T ON 08/06/2019...

From: Chin, Lee-Ying
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY
Sent: 6/11/2019 1:50:46 PM
Attachments:  [GlobeReport.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: prs.pd@slawch.com (mailto:prs.pd@slawch.com)

Sent: Tuesday, June 11, 2019 11:03 AM

To: Hor, Yinnul

Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairidina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Subramaniam, Divyashni; Tong, Wahxin; prs.pd@slawch.com

Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ3366T AND SJN6249T ON 08/06/2019

Dear Sir/Mdm,

ACCIDENT INVOLVING SJN6249T & SLQ3366T ALONG TPE TOWARDS SLE (TPE 11 KM) ON 8/6/2019 @ 17:17

We refer to your letter dated 11 June 2019 confirming your intention to conduct a pre-repair survey on our client's vehicle SJN6249T.

We have instructions to reject your surveyor and propose to engage a surveyor from the list below:-

1) PAL'S APPRAISER PTE LTD - Dennis Yap Teck Wee (HP: 8181 8802)

Address: 1 Kaki Bukit Ave 6 #01-53 Autobay@kaki Bukit Singapore 427883

2) LCW APPRAISER PTE LTD - Yap Teck Lee (HP: 9099 8802)

Address: 54 Edgdale Plains #03-06 Singapore
828821

3) MC-COY APPRAISER PTE LTD - Yap Teck Chye (HP: 9118 8802)

Address: 1 Kaki Bukit Ave 6 #01-28 Autobay@kaki Bukit Singapore 427883

4) TREASURE APPRAISAL SERVICES - Dixon Yeo (HP: 9833 1618)

Address: 9 Joo Chiat Place Singapore
427743

5) United Appraisal And Management Pte Ltd - Mark (HP: 9146 1186)

Address: Blk 9 Defu Lane 10 #01-500 Singapore
539190

6) PROMINENT APPRASIER SERVICES - Andrew How (HP: 9295 2204)

Address: 1 Simel Street 3 #02-24 Singapore
529890

7) ST APPRAISAL SERVICES - T. T. Rajan (HP: 9858 6761)

Address: Blk 633 Veerasamy Road #05-132 Singapore
200633

8) CONSTANCT APPRAISER SERVICES - Sebastian Lim Yong Tian (HP: 9007 5234)

Address: BLK 2 RIVERVALE LINK #09-02 SINGAPORE 545040

9) C L APPRAISER PTE LTD - ALAN CHEONG K.H. (HP: 9068 8689)

Address: NO. 46 SOO CHOW VIEW SINGAPORE
575438

10) AEON AUTO CONSULTANTS LLP - (HP: 9768 7958)

Address: 50 CHIN SWEE ROAD #09-04 SINGAPORE 169874

Please be informed that said vehicle can be inspected at:

Workshop: Z-One Automotive Pte Ltd

Address: 1 Kaki Bukit Ave 6 #01-85/87 Autobay @ Kaki Bukit Singapore 417883

Contact Person: Yvonne (HP: 97552115 / Tel: 62502115)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will comment to you.

Bitmap

From: Hor, Yinnul
Sent: Tue, 11 Jun 2019 00:58:32 +0000
To: Prs.pd@silawch.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tong, Wahxin
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ3366T AND SJN6249T ON 08/06/2019

Without Prejudice

Your Reference : PD.190462/LP
Our Reference : SLQ3366T

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Ho Xiong	Formteam Adjusters Pte Ltd
Chua Seo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yinnul (Yinnul)
AIG
Claim Adjuster II, Singapore FNOL Claims Operations - Auto
Yinnul.Hor@aig.com | www.aig.sg

From: Li Ping [mailto:Prs.pd@silawch.com]
Sent: Monday, June 10, 2019 5:33 PM
To: AIG SGP, Claims-Survey
Cc: service@z-one.com.sg
Subject: [EXTERNAL] Urgent accident involving SJN6249T & SLQ3366T on 8/6/2019. Our Ref: PD.190462/LP

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Dear Sir/Mdm,

ACCIDENT INVOLVING SJN6249T & SLQ3366T ALONG TPE TOWARDS SLE (TPE 11 KM) ON 8/6/2019 @ 17:17

1. We are instructed to notify you of a road accident on 8 June 2019 at about 17:17 hours along TPE Towards SLE (TPE 11 Km) involving our client's vehicle registration number SJN6249T and vehicle registration number SLQ3366T driven by your insured at the material time. A copy of the Accident Statement is enclosed.

2. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Li Ping

Did: 6909 5194

11 Keng Cheow Street #02-03 Riverside Piazza Singapore 059608



This e-mail is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, arrive late or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message which may arise as a result of Internet transmission.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	6152D
Vehicle No.:	SJN6249T
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	FIT 1.3G A
Primary Colour:	Yellow
Manufacturing Year:	2008
Engine No.:	L13A4056312
Chassis No.:	GE61049431
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$12,193.00
Original Registration Date:	09 Sep 2008
First Registration Date:	09 Sep 2008
Transfer Count:	2
Actual ARF Paid:	\$12,193.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	08 Sep 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,170.00
COE Rebate Amount:	\$13,712.00
Total Rebate Amount:	\$13,712.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Jun 2019

OK

▶ Fit Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Honda Fit 1.3A (COE till 02/2022)	\$16,800	\$6,260 /yr	16-Feb-2007	1,339 cc	-	Ocean Motoring	Available

Well Maintain By Previous Owner. Comes With LTA Approved HKS Exhaust. Bank Or In-House Loan Available. Test Drive Welcome.

Office No. - -

Jason - 90489293 | Chan - 90021531

Honda Fit 1.3A (COE till 07/2022)	\$19,800	\$6,420 /yr	12-Jul-2007	1,339 cc	131,000 km	MCT Trader LLP	Available
-----------------------------------	----------	-------------	-------------	----------	------------	----------------	-----------

1 Owner. Excellent And Original Condition, Well Maintained Interior And Exterior, High Loans Available. Call Now To Arrange For A Viewing Appointment!

Office No. - 64648880

Chris Chua - 87482103 | Kelvin Kang - 90098718

Honda Fit 1.3A (COE till 07/2022)	\$22,500	\$7,290 /yr	13-Jul-2007	1,339 cc	92,000 km	360 VR Cars	Available
-----------------------------------	----------	-------------	-------------	----------	-----------	-------------	-----------

Genuine Low Mileage Done! Car In Very Good Condition, All Wear And Tear Done Up. Aircon Compressor Just Changed, Engine Mounting Etc. With Front And Rear Camera. Trade In And Loan Available! Call Now ...

Office No. - 69310005

Pauline - 96211963 | James Tan - 90700005

Honda Fit 1.3A (COE till 08/2022)	\$17,800	\$5,640 /yr	07-Aug-2007	1,339 cc	-	Boeki Auto Pte Ltd	Available
-----------------------------------	----------	-------------	-------------	----------	---	--------------------	-----------

Trade In Welcome, Bank And In House Loan All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Office No. - 67555005

Boeki - 82180500

Honda Fit 1.3A (COE till 10/2022)	\$23,800	\$7,060 /yr	26-Oct-2007	1,339 cc	119,432 km	Car Search	Available
-----------------------------------	----------	-------------	-------------	----------	------------	------------	-----------

Beautifully Fitted J's Racing Bodykit In Nardo Grey. Low Mileage, Taken Care Extremely Well By Owner. View To Believe! Trade-Ins Available, Viewing By Appointment Only!

Office No. - 62620728

Ken - 93388994 | Jack - 91416611 | Justin - 91827511 | Rachel - 91126538

Honda Fit 1.3A G (COE till 11/2027)	\$39,000	\$4,600 /yr	01-Feb-2008	1,339 cc	200,800 km	Otua Auto Pte Ltd	Available
-------------------------------------	----------	-------------	-------------	----------	------------	-------------------	-----------

Consignment Code: A030. Consignment Unit. Flexible Loan Packages Available To Choose From. No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us. V...

Office No. - -

Francis Chen - 87539539 | Paul - 87671091 | Stedson Koh - 97869900 | Jax - 98272818

Honda Fit 1.3A G Skyroof (COE till 03/2023)	\$22,800	\$6,000 /yr	15-Apr-2008	1,339 cc	180,000 km	Car Fleet Auto Pte Ltd	Available
---	----------	-------------	-------------	----------	------------	------------------------	-----------

Balloon Scheme Available! We Are sgCarMart Premium Dealer 2015 To 2017! Buy With Confidence! No Hidden Costs! In House Loan Or Bank Loan Available! Fast And Easy Loan Approval! High Loan Or Over Trade...

Office No. - 69096423

Mr An - 84269807 | Syukur Nico - 82440004

Honda Fit 1.3A GF Skyroof (COE till 03/2028)	\$43,800	\$4,970 /yr	06-May-2008	1,339 cc	95,000 km	Jie Heng Motoring	Available
--	----------	-------------	-------------	----------	-----------	-------------------	-----------

100% Loan Approval With Low Interest Rate! Interest As Low As 3.18%, Definitely Not The Cheapest But For Sure One Of The Better Unit, Quality Is The Key For COE Cars Not Price! High Paper Value Of \$35...

Office No. - 64693350

Keith Khoo - 97973753 | Roy Chua (Hao) - 90121363 | Simpson Tan - 88000787 | Kenneth Chua - 83387618

Honda Fit 1.3A G (COE till 05/2023)	\$25,800	\$6,550 /yr	20-May-2008	1,339 cc	110,000 km	Auto Midas (S) Pte Ltd	Available
-------------------------------------	----------	-------------	-------------	----------	------------	------------------------	-----------

Very Good Condition, Low Depreciation, Call For Appointment.

Office No. - 66592767

Wayne - 93228783 | Ferris - 88185757 | Shin Koh - 97404407

Honda Fit 1.3A G (COE till 05/2028) **\$41,800** \$4,660 /yr 27-May-2008 1,339 cc 153,407 km Lake View Credit Pte Ltd **Available**

Cheapest Fit 1.3A At Low \$4,500 Depreciation Yet Price Negotiable! Low Mileage Clocked Of 14000km Annually. No More Repairs Needed. 100% Accident Free. Flexible In House Loan With Low Rates. Call Now!

Office No. - 67499895

John Gan - 90478223 | Kelvin - 98789995 | Daniel - 96896097

Honda Fit 1.3A G (COE till 05/2028) **\$48,000** \$5,350 /yr 30-May-2008 1,339 cc 108,000 km Monster Motors Pte Ltd **Available**

Honda's Signature Compact And Nimble VTEC Hatchback In Factory Black Exterior And Red On Black Leather Upholstery. Buy With A Peace Of Mind. Always Parked Under Shelter. Regularly Serviced At Reputabl...

Office No. - -

Valentino - 96534300 | Alex Lim - 92207602

Honda Fit 1.3A G (COE till 06/2023) **\$22,700** \$5,660 /yr 16-Jun-2008 1,339 cc 133,000 km Hua Hong Motoring **Available**

With 4 Yrs Left On The COE Yearly Depreciation Less Than \$6k Fuel Saving Yet Powerful Drive. In House Loan Available, At Low Monthly Installment, Flexible Loan Available. 100% Accident Free. Trade In ...

Office No. - -

Terence - 81608080 | Randy Chan - 96949339

Honda Fit 1.3A G (COE till 04/2023) **\$28,000** \$7,210 /yr 23-Jun-2008 1,339 cc 107,800 km Otua Auto Pte Ltd **Available**

Consignment Code: A101. Loan Packages Available To Choose From. High Trade In Value For Your Car! No Hidden Cost. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact...

Office No. - -

Francis Chen - 87539539 | Paul - 87671091 | Stedson Koh - 97869900 | Jax - 98272818

Honda Fit 1.3A G (COE till 06/2023) **\$25,800** \$6,370 /yr 11-Jul-2008 1,339 cc - **Available**

Well Maintained With Nice Paint And Sweet Bodykit. Recently Fitted New Pioneer Headunit Player. Price Slightly Negotiable. Viewing Location At Sengkang. Car Financing Can Be Arranged. Thanks.

Office No. - -

Jameson Sow - 90079509 | Danny Cheah - 92220179

Honda Fit 1.3A (COE till 06/2023) **\$23,800** \$5,870 /yr 11-Jul-2008 1,339 cc 116,051 km Next Drive **Available**

Low Mileage Clocked 10500km Per Year Only. Monthly At \$300 Plus, Extended Warranty Availabe, Aftersales Services Will Be Provided, Buy With A Peace Of Mind With STA Evaluation.

Office No. - -

Jonathan - 91901666

Honda Fit 1.3A G (New 5-yr COE) **\$27,200** \$5,430 /yr 11-Jul-2008 1,339 cc - Grande Car Gallery Pte Ltd **Available**

Clean Interior And Own By Non Smoker. Fuel Saving Yet Powerful Drive. In House Loan Available, At Low Monthly Installment, Flexible Loan Available. 100% Accident Free. Trade In Are Welcome, View To Be...

Office No. - 64524300

Mark - 93803299

Honda Fit 1.3A G Skyroof (COE till 08/2023) **\$22,500** \$5,400 /yr 11-Aug-2008 1,339 cc 158,000 km D&L Auto Trading **Available**

100% Guaranteed Accident-Free, Well Maintained, Wear And Tear Replaced, 90% Loan At 3.18%, Guaranteed Loan For Bad Credit/Ex Bankruptcy, View After Lunch Till 11PM Daily, Please Call To Arrange Viewin...

Office No. - 62960188

Darren Low - 96236322

Honda Fit 1.3A G (COE till 06/2023) **\$22,800** \$5,630 /yr 14-Aug-2008 1,339 cc - **Available**

Well Maintained With Nice Paint And Sweet Bodykit. Recently Fitted New Pioneer Headunit Player. Price Slightly Negotiable. Viewing Location At Sengkang. Car Financing Can Be Arranged. Thanks.

Office No. - -

Jack - 98218086

Honda Fit 1.3A (COE till 09/2023) **\$24,500** \$5,790 /yr 04-Sep-2008 1,339 cc 138,000 km Carsmart Pte Ltd **Available**

Road Tax Until Sep 2019! Cheapest Deal In Town! Well Maintained With No Repairs Needed! STA/VICOM/AA Evaluation Friendly. Welcome

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULAR		Vehicle No: SJN6249T Replace Veh No:	
Name: (as in IC) LEE LI RONG ANDREW		Mileage Out:	
NRIC/PASSPORT No: S8633370H		Mileage Out:	
Address (Res): BLK 456 Hongang Avenue		Make & Model: HONDA FIT <input checked="" type="radio"/> Auto / Manual	
10 # 13-443 Singapore 530456		Group:	
Name & Address of Employer:		OUT: Date 04/06/19 Time:	
Occupation: Sales Driving Exp: 13 years		HIRE/PERIOD EXPIRY 3 months 04/06/19 - 04/09/19	
Driving Licence No: S8633370H D/L Type: Local / International		NON-WAIVER EXCESS: \$ 3500 local / 47000 overseas	
Issue Date: 16/02/2006 Date of Birth: 17/11/1976		CHARGES	
Tel: (O) _____ (R) _____ HP/PG 94881293		Daily @ \$ _____ Per day 12 weeks \$3600	
Named/ Relief Driver		Weekly @ \$ 300 per week 4 weeks \$1200	
Name: (as in IC) _____		Monthly @ \$ _____ per month 200	
NRIC/PASSPORT No: _____		Hours @ \$ _____ per hour	
Address (Res): _____		Others @ \$ 500 deposit 4500	
In Case of Emergency		CDW @ \$ _____ per day/month	
Name: Edmund		PAI @ \$ _____ per day/month	
Contact: 94790792 Relationship: Father		Delivery Service	
		Windscreen Access \$ 500	
		SUB-TOTAL \$ 4100	

Early Termination of Contract

- The Minimum of one week notice is required by the hirer in any case of early termination.
- Full amount of deposit will be forfeited by the Owner and NOT refundable to the Hirer.
- The Hirer will be liable with a penalty of \$ **\$2050/-** and full amount of deposit will be forfeited if the Hirer does not fulfil or comply with the Terms and Conditions of the agreement.

Deposit

- Deposit of Booking Fee is NOT refundable should there be any cancellations of bookings or reservations.
- The refundable deposit specified by ASIA CARZ LEASING PTE LTD from time to time, is payable by the hirer to ASIA CARZ LEASING PTE LTD on the date of delivery of the rented vehicle.
- If the contract duration is not fulfilled, full amount of deposit will NOT be refunded.
- The deposit may be deducted without prior notices to the hirer due to any amount due or owned by the Hirer to the Owner.

Acknowledgement and Delivery Receipt

- By signing this Vehicle Rental Agreement the Hirer (the lesser/the driver) hereby acknowledges and confirms he/she has:
 - Read and understood the Agreement (which consists of the terms and conditions set out herein attached and agrees to bound by these terms and conditions which may be amended by the Owner from time to time);
 - Examined the vehicle and the vehicle is in good order and in good working conditions, to the Hirer's satisfaction in every respect; and
 - Taken delivery of the vehicle in good order and in good working conditions on the date of this agreement.

All payments to be made payable to: **UOB Current "335-3052-134" (Every Monday Before 10:30pm)**

If Hirer makes payment via i-Banking, the Hirer must state their name and vehicle registration number.

SIGNED BY THE HIRER

Name: **Andrew**
NRIC: **S8633370H**
Date: **04/06/19**

SIGNED FOR AND ON BEHALF OF ASIA CARZ LEASING PTE LTD

Name: **Elyse**
NRIC: **S9745638J**
Date: **04/06/19**



IMPORTANT:

- ONLY PERSONS ABOVE 21 YEARS OF AGE WITH MORE THAN 1 YEAR DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL TRAFFIC AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED TO THE HIRER. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN, AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PA WHERE APPLICABLE.
- IN CASE OF ACCIDENT THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY, ASIA CARZ LEASING PTE LTD.
- HIRER WHO OVERLOOK ON MAINTAINING THE ENGINE OIL & COOLANT THAT CAUSES DAMAGE TO THE ENGINE SHALL BEAR THE REPAIR COST.
- PLEASE TAKE NOTE THAT ALL OUR RENTAL CARS ARE EQUIPPED WITH GPS SYSTEM, AND SO THE COMPANY HAS EVERY RIGHTS TO ON THE GPS TO TRACK LOCATE THE CAR'S LOCATION.

RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO ASIA CARZ LEASING PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER



HOTLINE TEL: (65) 6415-3000
FAX: (65) 6415-3723

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1969

ROAD TRANSPORT ACT, 1967 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

U.S.400

THIRD PARTY CERTIFICATE NO.		COMMERCIAL MOTOR SJN6249T	POLICY EXCESS	
POLICY NO.		999994425	WINDSCREEN EXCESS	NA
1) VEHICLE REGISTRATION NO.			SUM INSURED	NA
2) NAME OF INSURED			INSURING WITH COE/PARF	NA
3) EFFECTIVE DATE OF THE COMMENCEMENT OF INSURANCE FOR THE PURPOSES OF THE ACT			SJN6249T	
4) DATE OF EXPIRY OF INSURANCE			ASIA CARZ LEASING PTE LTD	
5) PERSON OR CLASSES OF PERSONS ENTITLED TO DRIVE*			04 October 2018	
Any person who is driving on the Insured's grow or with their permission.			03 October 2019	
Section II Excess is applicable for driver who is between 21 years to 25 years old with minimum 2 years driving experience in Singapore.				
Section II Excess is applicable for driver who is 21 years old with minimum 1 year driving experience.				
The policy does not cover drivers who are below 21 years old or with less than 1 year driving experience.				
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.				
6) LIMITATION AS TO USE*				
1) Use for social, domestic, pleasure purposes and business purposes of Insured.				
2) Use for social, domestic, pleasure purposes and business purposes of any person whom the vehicle is hired.				
3) Use for the carriage of passengers for hire or reward by any person to whom the vehicle is hired.				
The Policy does not cover: 1) Use for tuition, driving test, racing, pace-making, reliability trial or speed-testing; 2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle; 3) Use for any purpose in connection with the Motor Trade.				
LOSS OF USE		Not included		
HIRE PURCHASE COMPANY		Asia Carz Holding Pte Ltd		

*Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1967 (Malaysia).

Issued in Singapore 10 Dec 2018

AIG Asia Pacific Insurance Pte. Ltd.

304631-000
S.A.S. Insurance Agency
No 30 Kallit Bukit Road 3
#05-06
Singapore 417819


AUTHORISED REPRESENTATIVE

ORIGINAL

SSPOEC

MSME19075829 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 10/06/2019 17:42
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/06/2019 17:42
Date Of Accident	08/06/2019 17:20
Exact Location Of Accident	TPE TWDS SLE (TPE 11KM)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN6249T
Insured/Policyholder	
Name Of Registered Owner	ASIA CARZ LEASING PTE LTD
Co Reg No	201606152D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62624666

Vehicle Particulars

Manufacturer	HONDA
Model	FIT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	999994425
Cover Note Number	

Driver

Name of Driver	LEE LI RONG ANDREW
NRIC No	S8633370H
Date Of Birth	17/11/1986
Occupation	INDOOR
Date Of Driving Pass	16/02/2006
Driving Experience	13 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94881293
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 456 HOUGANG AVE 10 #13-443
 Postcode 530456
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 4
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 2
 NAME: : UNKNOWN
 GENDER: : MALE
 Passenger 3
 NAME: : UNKNOWN
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 08/06/2019 AT ABOUT 5.17PM, I WAS TRAVELLING ALONG TPE TOWARDS SLE (TPE 11KM). I WAS ON THE EXTREME RIGHT LANE. I SAW THAT VEHICLE D BRAKE IN FRONT OF ME SO I MANAGED TO BRAKE AND COME TO A COMPLETE STOP. SUDDENLY, I FELT AN IMPACT ON THE REAR PORTION OF MY VEHICLE. VEHICLE B HAD COLLIDED ONTO THE REAR PORTION OF MY VEHICLE DUE TO THE IMPACT FROM VEHICLE C. THUS, I HIT ONTO THE REAR OF VEHICLE D. I WENT TO SEE DOCTOR ONE DAY AFTER THE ACCIDENT AS I FELT MUSCLE PAIN AFTER THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLQ3366T
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR

Name of Driver	NG KIAN SEAH
NRIC/Passport Number	S7134468A
Contact Number	97881460
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJG3572R
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	SURADI BIN SAMANDI
NRIC/Passport Number	
Contact Number	97393744
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLW8818S
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE D
Vehicle Category	PRIVATE CAR
Name of Driver	NG ZHI JIANG
NRIC/Passport Number	
Contact Number	98338671
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LEE LI RONG ANDREW
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJN6249T
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Handwritten signature/initials.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Handwritten signature: Z ONE

Sketch Plan #2 Pg. 1

SKETCH PLAN

Veh A = SJN6249T

Veh B = SLQ3366T

Veh C = SJG3572R

Veh D = SLW8818S



TPE towards SLE (TPE 11km)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08-06-2019 at about 5:17pm, I was travelling along TPE towards SLE (TPE 11km). I was on the extreme right lane. I saw that vehicle D braked in front of me so I also managed to brake & come to a complete stop. Suddenly, I felt an impact on the rear portion of my vehicle. Vehicle B collided onto the rear portion of my vehicle due to the impact from vehicle C. Thus, I hit onto the rear of vehicle D.

I went to see the doctor, one day after the accident, as I felt muscle pain after the accident.



DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Front Portion

Vehicle No:

SJN 6249T

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper			
1005	992341	Frt Bumper Clips			
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad Tow Cover			
1013	991363	Frt Bumper Grille			
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991923	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

(0)Item (1)Damaged (2)Discontinued (3)Cracked (4)In (5)Scratched (6)Deformed (7)Shifted (8)Buckled (9)Broken (10)Necessary (11)Missing (12)Turn (13)Unconformed (14)Not Working

MOTORCAR (Rear)

(1)Replace (2)Repair (3)Check (4)Not Comment (5)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	Re	/	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	Re	/	
1146	992341	Rear Bumper Clips	Re	/	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	Re	/	2
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	Re	/	
1159	993327	Rear End Panel	Re	/	
1160	993339	Rear End Panel Top Garnish	Re	/	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	Re	/	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	Re	/	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid			
1171	991328	Bootlid Emblem			
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate	Re	/	
1182	991328	Tailgate Emblem	Re	/	
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding	Re	/	
1196	994607	Tailgate Glass Sealant	Re	/	
1197	994629	Tailgate Lock	Re	/	
1198	994651	Tailgate Rubber	Re	/	
1199	994611	Tailgate Hinge	Re	/	
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board	Re	/	

Vehicle No: STN6249T

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	Re	/	
1203	994328	Spare Tyre Panel	Re	/	
1204	995065	Spare Tyre	Re	/	
1205	994326	Spare Tyre Lock Screw/Insulation	Re	/	
1206	993787	Spare Tyre Cover	Re	/	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	Re	/	
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	Re	/	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	Re	/	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber	Re	/	
1243	993453	Rear Fender 1/4 Glass Sealant	Re	/	
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

STN6249T (Rear)

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2019 Edit Reg		11 Jun 2019 00:00 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------












































CLAIM SUBFOLDER DETAILS		[Created by adjuster]
Insured:	NG KIAN SEAH, ID: 57134468A	
Main Claimant:	ASTA CARZ LEASING PTE LTD, Co. Reg. No.: 201606152D	
Vehicle Reg. No.:	SJN6249T	Date of Loss: 08/06/2019 00:00 - :59 [128 Months and 30 Days From LTA Reg Date (Mon Yr)]
Claim Type:	TP / 7413727916SG	Policy/Cover Note No.: (Comprehensive) Coverage: 05/07/2018 - 04/07/2019
Vehicle Reg. No. (Insured):	SLQ3366T	Policy No. (Claimant):
		Excess:
Repairer:	Z-one Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6,, Bld D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:	
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2019]	
Claimant's Solicitor:	SI Law Chamber - Tel: 6909 5194	


































ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
<ul style="list-style-type: none"> AIG_SG (13/06/2019): Request To Upload TP GIA Report 		























ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJN6249T (7413727916SG)
[SLQ3366T]
TP
ASIA CARZ LEASING PTE LTD
Jun 8 2019 12:00AM
[NG KIAN SEAH]
Z-one Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
2	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
3	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
4	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
5	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
6	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
7	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
8	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
9	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
10	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
11	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
12	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
13	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
14	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
15	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
16	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
17	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
18	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
19	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
20	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
21	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
22	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
23	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
24	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
25	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
26	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
27	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
28	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
29	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
30	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
31	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
32	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
33	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
34	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
35	20/06/19 18:46	General View														Load JPG	<input checked="" type="checkbox"/>			
36	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
37	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
38	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
39	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
40	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
41	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
42	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			
43	20/06/19 18:49	Photographs of Damaged Parts														Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
88	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
89	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
90	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
91	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
92	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
93	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
94	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
95	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
96	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
97	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
98	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
99	20/06/19 18:49	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
100	20/06/19 18:49	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
101	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
102	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
103	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
104	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
105	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
106	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
107	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
108	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
109	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
110	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
111	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
112	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
113	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
114	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
115	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
116	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
117	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
118	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
119	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
120	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
121	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
122	20/09/19 11:20	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/06/19 10:34	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010434/GCD3E2

Date: 17/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : SJN6249T

Insured Vehicle No : SLQ3366T

Date of Loss: 08/06/2019

Nature of Claim: TP

Claim No: 7413727916SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJN6249T

Make & Model: HONDA FIT, 1.3 (A)

Engine No: L13A4056312

Reg. Date: 09/09/2008 (Man. Year: 2008)

Chassis No: GE61049431

Colour: Yellow

Odometer: 248818 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15

Rear Tyre Size: 185/60 R15

Front Left Side: Dayton 5 mm

Rear Left Side: Dayton 5 mm

Front Right Side: Dayton 5 mm

Rear Right Side: Dayton 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/06/2019

Date Inspected: 12/06/2019 Inspected At:

Z-one Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6,, Bldg D #01-87,
Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Cut	0.00 F	*- F
2	1		*FRT BUMPER	Deformed	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*FRT BUMPER TOW COVER	Missing	0.00 F	*- F
6	1		*FRT LH BUMPER FOG LAMP COVER	Cracked	0.00 F	*- F
7	1		*FRT GRILLE	Broken	0.00 F	*- F
8	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
9	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
10	1		*REAR BUMPER	Deformed	0.00 F	*- F
11	1		*REAR BUMPER TOW COVER	Deformed	0.00 F	*- F
12	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
13	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
14	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
15	1		*REAR END PANEL	Buckled	0.00 F	*- F
16	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
17	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
18	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
19	1		*TAILGATE	Buckled	0.00 F	*- F
20	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
21	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
22	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
23	1		*TAILGATE LOCK	Jammed	0.00 F	*- F
24	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
25	1		*SPARE TYRE BOARD	Cut	0.00 F	*- F
26	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
27	1		*SPARE TYRE TRAY	Cut	0.00 F	*- F
28	1		*SPARE TYRE INSULATION	Necessary	0.00 F	*- F
29	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
30	1		*REAR LH FENDER	Buckled	0.00 F	*- F
31	1		*REAR LH FENDER INNER TRIM	Cracked	0.00 F	*- F
32	1		*REAR FENDER 1/4 GLASS RUBBER	Necessary	0.00 F	*- F
33	1		*REAR FENDER 1/4 GLASS SEALANT	Necessary	0.00 F	*- F
34	1		*TAILGATE INNER BOARD	Cracked	0.00 F	*- F

F=Franchise part.

Total Parts (S\$) 0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >