

ASS. REC. BY:

REF: CS/MSG19010468/ovd3n2

Special Instruction:

Supervisor: Marcus

ASSIGNMENT (Office)

From (Person): Jowyn Tay Mei Ling of MSIE Date/Time: 13.6.19 10.57 a.m

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJF 9904H Insured: SLJ 811R

at Workshop m/s Zoom Autowire Tel: 94507920

of 15 batu Bukit Road 4

Policy No: 28860035 Claim No: 596101

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{"sup"} H.O.D. Endorsement: _____

Date/Time: 13.6.19 11.39 a.m Person Contacted: Elin Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 9904H - NA / INC 19010277 / h4 D.O.A - 10/06 / 2019
	SLJ 811R - NA / INC 19010277 / h4 D.O.A - 10/06 / 2019
<u>14/6/19</u>	Informed Jowyn pending workshop est by merimen
<u>27/6/19</u>	Email preli revised via merimen

merimen

(08/11/13) wef
ASS. REC. BY: Marcus

REF:

MSIS/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJF9904H
at Workshop m/s: Zoom
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 28
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: 2 Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SJF9904H Yr Regn: 61 28
Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or (A)
Make: blunder stream C.C. 1799
Colour: silver A/C: Insured / Std / NI / NA
Sp. Reading: 128940 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: JHMRN684085 203672
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 205/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front R/Bal. 6 mm Rear R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 10/6/19 D.O.I. 13/6/19
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear n/s.
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
we 17-6-2023 4 yrs. LTA 15088

27/6/19 1/5 @ 4000 confirmed with Elin. (Red 6950.36, 637)

RECEIVED 20 JUN 2019

[Signature]
27/6/2019

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 5
Resurvey No. of Trip: 2

1) _____
2) 27/6 - typist

Add Fee: : Site Insp (\$ _____)) S + RS \$
 : Interview (\$ _____)) Photos
 : Tech. Invs (\$ _____)) Others
 : Weekend (\$ _____))

Report Format : meimen
Lump Sum / I.B.I. (\$ 4000/2)

Survey Fee:	200
Transportation:	11
TOTAL	211

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Jowyn Tay Mei Ling	Date: 27 Jun 2019
Preliminary Advice	

Insured Vehicle No	: SLJ8111R	Accident Date	: 10/06/2019
TP Vehicle No	: SJF9904H	Assignment Date	: 13/06/2019
Make	: HONDA STREAM	Est. Duration of Repair	: 5
Date of Inspection	: 13/6/2019		
Inspection At	: ZOOM AUTOWERKS PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	10,950.36
Revised Amount	:SS	4,000.00 (LUMP SUM)
Check Items (Estimated)	:SS	0.00
Total	:SS	4,000.00
Lump Sum Repair	:SS	

Total Loss Consideration

New for Old Value	:SS	
Pre-Accident Value	:SS	
COE / PARF Rebate	:SS	
Salvage Value	:SS	
Margin for Repair	:SS	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019		13 Jun 2019 10:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS				[Created by insurer]																				
Insured:	TAN WEE AIK, ID: S74805461, Tel: +6597362491, Email: NOEMAIL																							
Main Claimant:	WAH KUM HON, ID: S7518055A																							
Vehicle Reg. No.:	SJF9904H	Date of Loss:	10/06/2019 15:00 - :59 [131 Months and 23 Days From LTA Reg Date (Man Yr)]																					
Claim Type:	TP / 596101	Policy/Cover Note No.:	28860035 (Comprehensive) Coverage: 23/11/2018 - 22/11/2019																					
Vehicle Reg. No. (Insured):	SLJ8111R	Policy No. (Claimant):	Excess:																					
Repairer:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53, 417808 Kaki Bukit - Tel:																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/06/2019]																							
Driver/Custodian (Insured):	TAN WEE AIK (45 / Male) , NRIC: S74805461, Tel: +6597362491 Email: NOEMAIL																							
Adj Asg. Remarks:	on WP. Liab: dispute. TP agree on SJE - assign LKK Auto. Contact: Elin Cai @9450 7920																							
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail																				
There are no mail for this case.																								
<div style="border: 1px solid black; padding: 5px;"> <p>ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

View Sent Message

This mail is associated with :

***SJF9904H (596101)**
[SLJ8111R]

TP
WAH KUM HON
Jun 10 2019 3:00PM
[TAN WEE AIK]
Zoom Autowerks Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 14/06/2019 10:59 AM.
To jowyn_tay@sg.msg-asia.com
Subject TP SURVEY SJF 9904H

Dear Jowyn,

Please be informed that we have inspected the vehicle SJF 9904H on 13/6/2019.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

New Cars

Used Cars

Sell My Car


Directory

Products

Insurance

Articles

F



Stream Price Range Depreciation > 10 year(s) Vehicle Type

Home » Used Cars » Kao Lian Enterprise » Honda Stream 1.8A X (COE till 05/2023)

Honda Stream 1.8A X (COE till 05/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price	\$28,666		
Depreciation ⓘ	\$7,290 /yr	Reg Date	27-Jun-2008 (3yrs 11mths 6days COE left)
Mileage	97,800 km (8.9k /yr)	Manufactured ⓘ	2008
Road Tax ⓘ	\$1,076 /yr	Transmission	Auto
Dereg Value ⓘ	\$15,230 as of today (change)	OMV ⓘ	\$17,437
COE ⓘ	\$19,356	ARF ⓘ	\$15,486
Engine Cap	1,799 cc	Power	103.0 kW (138 bhp)
Curb Weight ⓘ	1,350 kg	No. of Owners ⓘ	1
Type of Vehicle	MPV		

Features

Powerful 1.8L 16V I-VTEC Engine, 5 Speed Auto, Dual Airbags, Immobilizer, Multifunction Steering, Climatic Aircon Control. Retractable Side Mirrors. View specs of the Honda Stream (2007-2014)

Accessories

Factory Fitted MP3/CD Audio With CD Changer. Solar Films. Beautiful Black Colour Interior Leather. Sports Rims, Rear Spoiler.

Description

New Arrival! Beautiful And Sporty White In Black Stream 1.8A X. Reliable And Low Maintenance Cost. Own By Careful Owner. Most Popular Honda MPV For Your Family Usage! 100% Accident Free And No Modifications Done! Road Tax Till Jun2020! Call Us Now. Do Not Miss!

Category

COE Car, Low Mileage Car

Status

Available!

[Compare](#)



[Shortlist](#)

[Com](#)

[Report Error](#)

[M](#)

Seller Information

Company	Kao » dea » 55
Address	73 Mi Searc
Location	Mack
Contact Person(s)	Shu Ben

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8055A
Vehicle Details	
Vehicle No.:	SJF9904H
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A12803676
Chassis No.:	JHMRN68408S203672
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,643.00
Original Registration Date:	18 Jun 2008
First Registration Date:	18 Jun 2008
Transfer Count:	1
Actual ARF Paid:	\$20,643.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,953.00
COE Rebate Amount:	\$15,086.00
Total Rebate Amount:	\$15,086.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/06/2019 16:00
Date Of Accident	10/06/2019 15:30
Exact Location Of Accident	UPPER PAYA LEBAR RD B4 PEREIRA RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJF9904H
Insured/Policyholder	
Name Of Registered Owner	WAH KUM HON
NRIC No	S7518055A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81114101
Alternative Phone No	OFFICE-81114101

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5083940420-01
Cover Note Number	-

Driver

Name of Driver	SHARIF MAHADI HASAN
NRIC No	G8431599R
Date Of Birth	03/06/1988
Occupation	INDOOR
Date Of Driving Pass	10/06/2015
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84434956
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 15 JOO SENG RD #06-81
 Postcode 360015
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLJ8111R
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance Companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



- Vehicle A: SJF 9904H
- Vehicle B: 8LJ 8111R
- Vehicle X: Big Vehicle
- Vehicle Y: SBS Bus

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle X, SJF 9904H, was travelling straight along the stated venue. As there was a big vehicle who signal his intention to turn left, I slowed down and stopped. Meanwhile, the SBS bus beside me stopped as well. Suddenly, vehicle B, 8LJ 8111R, hit onto my stationary vehicle's rear portion. I wish to state that prior to the collision, the bus came out of the busstop, thus I kept to the right of the lane.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time


 Reporting Centre Personnel's Signature
 Name
 NRIC/FIN No.



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

21 June 2019

ACCIDENT DATE : 10 June 2019
 OWNER : WAH KUM HON
 REG NO. : SJF 9904 H
 MAKE/MODEL : HONDA STREAM

Not Allowed
L/H *L/S* *4000*
13/6/19
Wah Kum Hon

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ <i>ru</i> 90.10 ✓
1	Rear tailgate	\$ <i>ru</i> 930.00 ✓
2	Rear tailgate dampers	\$ <i>17</i> 242.80 X
1	Rear tailgate inner board	\$ <i>20/one</i> 189.30 —
1	Rear tailgate lock	\$ <i>shred</i> 183.70 —
1	Rear tailgate outer garnish	\$ <i>17</i> 151.90 X
1	Rear tailgate rubber	\$ <i>17</i> 116.90 X
1	Rear tailgate "HONDA" emblem	\$ <i>17</i> 28.80 X
1	Rear tailgate "STREAM" emblem	\$ <i>ru</i> 29.20 —
2	Rear taillamps	\$ <i>MSONG</i> 908.60 <i>1PC</i>
1	Rear taillamp panel -L/H	\$ <i>2</i> 280.80 X
1	Rear end panel	\$ <i>20/reat</i> 371.30 —
1	Rear end panel inner garnish	\$ <i>twi</i> 112.20 —
1	Rear bumper	\$ <i>7.5</i> 660.90 —
1	Rear bumper lower bracket	\$ <i>sub</i> 42.50 —
1	Rear bumper beam	\$ <i>MS</i> 38.60 X
2	Rear bumper side retainers	\$ <i>MS/SL</i> 97.00 <i>1PC</i>
1	Rear bumper towing cover	\$ <i>70m</i> 25.60 —
1	Rear floor panel	\$ <i>ru</i> 1,277.10 X
1	Rear floor board	\$ <i>17</i> 291.10 X
1	Rear fender -L/H	\$ <i>ru</i> 824.90 X
1	Rear fender inner trim board	\$ <i>20/m</i> 276.20 —
1	Rear fender quarter glass moulding	\$ <i>17</i> 124.70 X
		\$ 7,294.20
	Less 20%	\$ 1,458.84
		\$ 5,835.36

903.10

366.20

296.60

588.40

32.50

3134.60
202
2508.48

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	RM	80.00	40
1	Rear bumper clip (1 set)	\$	RM	45.00	30
1	Rear number plate with holder	\$	17	50.00	X
1	Rear reverse sensor (1 set)	\$	shut	450.00	250
1	Rear fender glass sealant	\$	17	80.00	X
		\$		<u>705.00</u>	

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	30
2	To remove and refit inner garnishes.	\$		150.00	80
3	To remove and refit rear reverse sensor.	\$		150.00	50
4	To transfer rear tailgate mechanism and wiring assembly.	\$		120.00	60
5	To remove and refit rear windscreen glass.	\$		180.00	120
6	To remove and refit quarter glass to assist repair.	\$	17	150.00	X
7	To apply undercoating.	\$		180.00	60
8	Panel beating.	\$		1,800.00	800
9	To re-spray painting on the affected areas.	\$		1,600.00	1000
		\$		<u>4,410.00</u>	

GRAND TOTAL :

\$ 10,950.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(a) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

S.N - 320
labu 2200
4028.48
207
4022.78

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19010468/UVD3N2

Date: 02/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28860035AVW
Claimant Vehicle No :	SJF9904H	Insured Vehicle No :	SLJ8111R
Date of Loss:	10/06/2019	Nature of Claim:	TP
		Claim No:	596101

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF9904H	Engine No:	R18A12803676
Make & Model:	HONDA STREAM, 1.7 (A)	Chassis No:	JHMRN68408S203672
Reg. Date:	18/06/2008 (Man. Year: 2008)	Odometer:	128940 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,540.36	2,828.48	3,711.88	56.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,410.00	2,200.00	2,210.00	50.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,950.36	5,028.48	5,921.88	54.08
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	10,950.36	4,000.00	6,950.36	63.47

INSPECTION

Date of Assignment:	13/06/2019		
Date Inspected:	13/06/2019	Inspected At:	Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53 Singapore 417808
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Jul 2019)
Parts: M1-MPV	HONDA STREAM 1.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF9904H)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR WINDSCREEN MOULDING	Necessary	90.10 FL	*90.10 FL
2	1	*REAR TAILGATE	Dented	930.00 FL	*903.10 FL
3	2	*REAR TAILGATE DAMPERS	Not Necessary	242.80 FL	*- FL
4	1	*REAR TAILGATE INNER BOARD	Deformed/Cracked	189.30 FL	*189.30 FL
5	1	*REAR TAILGATE LOCK	Shorted	183.70 FL	*183.70 FL
6	1	*REAR TAILGATE OUTER GARNISH	Not Necessary	151.90 FL	*- FL
7	1	*REAR TAILGATE RUBBER	Not Necessary	116.90 FL	*- FL
8	1	*REAR TAILGATE HONDA STREAM	Not Necessary	28.80 FL	*- FL
9	1	*REAR TAILGATE STREAM EMBLEM	Necessary	29.20 FL	*29.20 FL
10	1	*REAR TAILLAMPS	N/s Cracked	908.60 FL	*366.20 FL
11	1	*REAR TAILLAMP PANEL-L/H	Repair	280.80 FL	*- FL
12	1	*REAR END PANEL	Dented/Bent	371.30 FL	*296.60 FL
13	1	*REAR END PANEL INNER GARNISH	Twisted	112.20 FL	*112.20 FL
14	1	*REAR BUMPER	Distorted	660.90 FL	*588.40 FL
15	1	*REAR BUMPER LOWER BRACKET	Bent	42.50 FL	*42.50 FL
16	1	*REAR BUMPER BEAM	No such part	38.60 FL	*- FL
17	1	*REAR BUMPER SIDE RETAINERS	N/s Bent	97.00 FL	*32.50 FL
18	1	*REAR BUMPER TOWING COVER	Torn	25.60 FL	*25.60 FL
19	1	*REAR FLOOR PANEL	Repair	1,277.10 FL	*- FL
20	1	*REAR FENDER-L/H	Repair	824.90 FL	*- FL
21	1	*REAR FENDER INNER TRIM BOARD	Deformed/Torn	276.20 FL	*276.20 FL
22	1	*REAR FLOOR BOARD	Not Necessary	291.10 FL	*- FL
23	1	*REAR FENDER QUARTER GLASS MOULDING	Not Necessary	124.70 FL	*- FL
24	1	*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
25	1	*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
26	1	*REAR NUMBER PLATE WITH HOLDER	Not Necessary	50.00 FS	*- FS
27	1	*SET REAR REVERSE SENSOR	Shorted	450.00 FS	*250.00 FS
28	1	*REAR FENDER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,999.20	3,455.60
- List Item Discount on L Items 20.00/20.00% (S\$)	1,458.84	627.12
Total Parts (S\$)	6,540.36	2,828.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	30.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	120.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR	New	150.00	0.00
7	TO APPLY UNDERCOATING	New	180.00	60.00
8	PANEL BEATING	New	1,800.00	800.00
9	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	1,000.00
Gross Labour Cost (\$\$)			4,410.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >