

ASS. REC. BY:

REF:

CS3/SMO19010474/TK d3b2

Special Instruction:

Surname: Tantich

Menmen

ASSIGNMENT (Office)

From (Person): Ruth chna Gek of SMODate/Time: 10/6/19 @ 4pm

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No.: YN 4760 TInsured: YN 5321 Xat Workshop in/s: Carport AutoTel: 6268 5390of Blk 3 - Pioneer Rd North #01-24Policy No: D19MTPCVE001828Claim No: CMTD1902741

Sum Insured: _____

Excess: _____

Make of Veh:

(Client's Record)

D.O.A. 6/6/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 10-29am @Person Contacted: Mr. OngVehicle IN OUT

Date/Time	Action/Instruction
	<u>10/6/19 @ 4pm</u> X
	<u>YN 4760 T - X</u>
	<u>YN 5321 X - CS/19/18/01/3816/Usd 3n2</u>
	<u>Dismantle: 5/7/2019.</u>
	<u>After repair: 8/7/2019</u>

D.O.A.: 26/9/2018

ASS. REC. BY: Taupha

REF SMO

ASSIGNMENT

From: _____ Date: 2.7.2019

Estimated Cost: _____

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YN 4760T

at Workshop n/s Carport Auto Service

of Bk 3 Pioneer Road N/Ah #01-24

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 10.00am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS PRS.

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

Veh No: YN4760T Yr Regn: 2014, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mitsubishi Canter FER21 c.c. 2998

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 105998 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FER21FA00198

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or 195/85R15

Tyre Size: F: _____ R: 4 (17)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front 6 mm Rear 6/6 mm

R/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. _____ D.O.I. 02/2/14 2415pm

Survey held at Carport Auto Svc.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Estimated repair range \$2,800 - \$3,300</u>
	<u>PRS.</u>
	<u>9/7/2019</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : PRS

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 3

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	<u>100</u>
Transportation:	<u>60</u>
3 + RS, SI	<u>60</u>
Photos	
Others	<u>11</u>
TOTAL	<u>231</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		10 Jun 2019 16:01 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TOH FOOD PTE LTD, Co. Reg. No.: 201706221M		
Main Claimant:	SICO ASIA PTE LTD, Co. Reg. No.: 199101761M		
Vehicle Reg. No.:	YN4760T	Date of Loss:	06/06/2019 10:00 - :59
Claim Type:	TP / CMTD1902741	Policy/Cover Note No.:	19MTPCVE001828 (Comprehensive)
Vehicle Reg. No. (Insured):	YN5321X	Policy No. (Claimant):	
		Excess:	
Repairer:	Carport Auto Service (HQ) Block 3, Pioneer Road North, #01-24, 628457 Pioneer - Tel: 62685390		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/06/2019]		
Driver/Custodian (Insured):	XU MING (), NRIC: G6815947X, Tel: +6583300955 Email:		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1761M
Vehicle Details	
Vehicle No.:	YN4760T
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Jul 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER3SDEB
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	4P10B04563
Chassis No.:	FEB21EA00198
Maximum Power Output:	-
Open Market Value:	\$28,948.00
Original Registration Date:	03 Mar 2014
First Registration Date:	03 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$1,448.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	02 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$24,703.00
COE Rebate Amount:	\$11,498.00
Total Rebate Amount:	\$11,498.00

The information contained herein is correct as at 06 Jul 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/06/2019 16:00
Date Of Accident	06/06/2019 10:30
Exact Location Of Accident	LOADING NOVOTEL CLARK QUAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YN4760T
Insured/Policyholder	
Name Of Registered Owner	SICO ASIA PTE LTD
Co Reg No	199101761M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91224029
Alternative Phone No	OFFICE-91224029

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5064090978-05
Cover Note Number	

Driver

Name of Driver	YAP MENG HUAT DAVID
NRIC No	S6932825C
Date Of Birth	19/09/1969
Occupation	OUTDOOR
Date Of Driving Pass	21/12/1988
Driving Experience	30 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91224029
Fax Number	
Contact Number	OFFICE-91224029
E-Mail Address	NOEMAIL

Address	106 SERANGOON NORTH AVE #12-729
Postcode	S650106
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN5321X
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	XU MING
NRIC/Passport Number	G6815947X
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
(e) the Information so collected under (d) above may be shared / disclosed:
(i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
(ii) for complying with requirements under any regulations, laws or court orders.

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

- 6 JUN 2019



Handwritten signature of the driver

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2019		10 Jun 2019 16:01 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TOH FOOD PTE LTD , Co. Reg. No.: 201706221M								
Main Claimant:	SICO ASIA PTE LTD , Co. Reg. No.: 199101761M								
Vehicle Reg. No.:	YN4760T	Date of Loss:	06/06/2019 10:00 - :59 [63 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1902741	Policy/Cover Note No.:	19MTPCVE001828 (Comprehensive)						
Vehicle Reg. No. (Insured):	YN5321X	Policy No. (Claimant):							
		Excess:							
Repairer:	Carport Auto Service (HQ) Block 3, Pioneer Road North, #01-24, 628457 Pioneer - Tel: 62685390								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 19/06/2019]								
Driver/Custodian (Insured):	XU MING (), NRIC: G6815947X, Tel: +6583300955 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YN4760T (CMTD1902741)
 [YN5321X]
 TP
 SICO ASIA PTE LTD
 Jun 6 2019 10:00AM
 [TOH FOOD PTE LTD]
 Carport Auto Service

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>	
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)					Thumbnail	Print		
1	10/06/19 16:00	Accident Statement From: SC - Reg. No: YN5321X, Claimant: TOH FOOD PTE LTD.					 Load HTM			
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print		
1	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
2	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
3	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
4	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
5	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
6	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
7	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
8	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
9	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
10	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
11	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
12	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
13	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
14	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
15	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
16	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
17	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
18	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
19	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
20	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
21	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
22	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
23	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
24	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
25	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
26	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
27	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
28	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
29	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
30	06/07/19 14:58	General View					 Load JPG	<input checked="" type="checkbox"/>		
31	11/07/19 19:51	Photographs of Damaged Parts					 Load JPG	<input checked="" type="checkbox"/>		
32	11/07/19 19:51	Photographs of Damaged Parts					 Load JPG	<input checked="" type="checkbox"/>		
33	11/07/19 19:51	Photographs of Damaged Parts					 Load JPG	<input checked="" type="checkbox"/>		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
35	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
36	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
37	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
38	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
39	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
40	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
41	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
42	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
43	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
44	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
45	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
46	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
47	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
48	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
49	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
50	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
51	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
52	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
53	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
54	11/07/19 19:51	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
55	11/07/19 19:52	Photo After Spray		<input checked="" type="checkbox"/>
56	11/07/19 19:52	Photo After Spray		<input checked="" type="checkbox"/>
57	11/07/19 19:52	Photo After Spray		<input checked="" type="checkbox"/>
58	11/07/19 19:52	Photo After Spray		<input checked="" type="checkbox"/>
59	11/07/19 19:52	Photo After Spray		<input checked="" type="checkbox"/>
60	11/07/19 19:52	Photo After Spray		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	10/06/19 09:17	Third Party E-filed GIA report(M)		<input type="checkbox"/>
2	10/06/19 15:59	Pre-Repair Survey - ASSIGN LKK		<input type="checkbox"/>
3	11/06/19 16:12	Pre-Repair Survey - Carport Auto Service		<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/SMO19010474/T1CD3E2**Date:** 15/07/2019REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: 19MTPCVE001828

Claimant Vehicle No : YN4760T **Insured Vehicle No :** YN5321X**Date of Loss:** 06/06/2019 **Nature of Claim:** TP **Claim No:** CMTD1902741DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YN4760T	Engine No:	4P10B04563
Make & Model:	mitsubishi canter, 3.0 D (M)	Chassis No:	FEB21EA00198
Reg. Date:	03/03/2014 (Man. Year: 2013)	Odometer:	105998 km
Colour:	Silver		
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6/6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 10/06/2019

Date Inspected: 02/07/2019 Inspected At: Carport Auto Service (HQ)
Block 3, Pioneer Road North, #01-24
Singapore 628457

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 -\$3,300.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Jul 2019)

Parts: N/A MITSUBISHI CANTER 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN4760T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >