

INSURANCE

INS. CASE OWNER:

CC 4/AIG19010482, Reb3/9

LKK:

IDAC:

Surveyor:

KSL

DOI:

ASSIGNMENT

11/6/19

Date / Time:

11/6/19

Registered in Merimen:

11/6/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKA 3353B

Name of Insured:

PWA TIANHUA

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

8/6/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

31646106054

Policy No.:

21004870-08

Make / Model:

MBLEDES

Place of Accident:

ANKEE TIANHUA KO

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SUM 83AOL

SKA 3353B

SKN 354AK



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS: 01



INSRS:

WSP:

Tel:

Liability:

RMKS: TP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SKN 354AK - 1
SKN 354AK - 11/6/19 14:00/14:00 - 11/6/19

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI: 11/6/19

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: KSL

Repair Cost:

PP \$53,363.03

(3 days) Reduction:

24 %

Email

Call

FINAL SETTLEMENT

Date/Time: 21-05-19

Confirm with: PWA TIANHUA

Email

Call

Final Liability:

\$100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 0%

Repair Cost:

\$54,335.58

3 YEN CL ON 300

Loss of Rental (LOR):

\$5 -

(days)

Loss of Use (LOU):

\$5 250.00

(SS) x 5 days)

Loss of Income (LOI):

\$5 -

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5 -

Medical

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

Total:

\$54,335.58

Global Sum SS:

FINAL PAYMENT

Date/Time: 21-05-19

Confirm with: PWA TIANHUA

Email

Call

Payee 1:

\$54,335.58

Name 1:

WY TAY MOH PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TT

3) Survey fee: 1200

COPY SENT 11/8/19

ASSIGNMENT

Front

Date: **17/6/19**

Estimated Cost:

OD

TP

WS

TP RES

OD RES

EVA

INV

MV

To inspect Vehicle No:

SKN 3549K

at Workshop m/s

Lim Tan Motor

of

Blk 176 Sin Ming Drive # 03-09

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 1030am

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKN 3549K

Regn:

06 / 14

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

79 M71

C.C:

1598

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

39287

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104509548

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD / Rim or

Tyre Size:

F: **205/55R16**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8 mm

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

8/6/19

D.O.I.

1.7/6/19

Survey held at

✓

Des. of Damages : Frt / **Rear** / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	HP: 93,865.03 (RSD: 91,203.43 24/6/19)

Date/Time, File Pass to?

: Prel. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

: Site Insp

\$

: Interview

\$

: Tech. Insp

\$

: Wheel end

\$

Survey Fee:

Transportation:

\$

PS

\$

Home:

Others:

Report Form 41

Damage Summary / N.E.R. 19

He

Not withstanding
61 Day 87
Returning After Pain
5 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKN 3549 K
MAKE : TOYOTA
MODEL : COROLLA ALTIS 1.6L CVT
YEAR : 2014
CHASSIS NO : MR053REH104509548

SURVEYOR NAME : Kenneth (Lxx)
DATE OF SURVEY : 17.06.2019
TIME OF SURVEY : 10.30am

DATE : 10-Jun-19
DATE OF ACCIDENT : 8-Jun-19
THIRD PARTY REF : SKA 3353 B / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ R 486.50
2 pcs	Rear Bumper Retainer		\$ 88.50		\$ D11 177.00
2 pcs	Rear Bumper Bracket		\$ 56.30		\$ R 112.60
1 pc	Rear End Panel			ms D11	\$ R 789.70
1 pc	Rear End Panel Garnish				\$ 189.20
1 pc	Rear Boot				\$ R 784.60
1 pc	Rear Boot Lock				\$ R 458.70
1 pc	Rear Boot Rubber				\$ Sun 85.64
1 pc	Rear Boot Centre Emblem				\$ R 58.70
1 pc	Rear Boot COROLLA Emblem				\$ R 88.50
1 pc	Rear Boot ALTIS Emblem				\$ R 85.90
2 pcs	Taillamps		\$ 381.90		\$ Sun 763.80
1 pc	Rear Spare Tyre Top Cover				\$ Sun 324.11
					\$ 4,404.95
	Less 25%				\$ 1,101.24
					\$ 3,303.71
1 set	Rear Bumper Sensor	S.Nett			\$ Sham 200.00
1 pc	Rear Number Plate	S.Nett			\$ Sun 40.00
	To putty and spray painting				\$ F201 800.00
	To anti-rust				\$ 601 80.00
	Labour charges				\$ 601 650.00
					1pc Rear bumper reinforcement - 386.60
TG/RA-	Total				\$ 5,073.71

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg Website: www.LTM.sg

Co.Reg No. 199307277D

GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

SUPPLEMENTARY TO REPAIR

VEHICLE NO. : SKN 3549 K
 MAKE : TOYOTA
 MODEL : COROLLA ALTIS 1.6L CVT
 YEAR : 2014
 CHASSIS NO : MR053REH104509548

SURVEYOR NAME :
 DATE OF SURVEY :
 TIME OF SURVEY :

DATE : 18-Jun-19
 DATE OF ACCIDENT : 8-Jun-19
 THIRD PARTY REF : SKA 3353 B / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper Reinforcement Less 25%				\$ ^{B1} 386.60 ✓
					\$ 96.65
					\$ 289.95
	Part @ \$1660.10				
	Supp \$386.60				
	\$3046.70				
	-25% \$761.67				
	\$2285.03				
	S/N \$200.00				
	labour \$1300.00				
	PPR \$3865.03 ✓ ok				
	05 days				
TG/RA-	Total				\$ 289.95

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg Website: www.LTM.sg

Co.Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

Not withstanding
11/12/19
Rising After Pain
5 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKN 3549 K
MAKE : TOYOTA
MODEL : COROLLA ALTIS 1.6L CVT
YEAR : 2014
CHASSIS NO : MR053REH104509548

SURVEYOR NAME : Kenneth (Luo)
DATE OF SURVEY : 17.06.2019
TIME OF SURVEY : 10.30am

DATE : 10-Jun-19
DATE OF ACCIDENT : 8-Jun-19
THIRD PARTY REF : SKA 3353 B / AIG

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ R 486.50
2 pcs	Rear Bumper Retainer		\$ 88.50		\$ D 177.00
2 pcs	Rear Bumper Bracket		\$ 56.30		\$ 112.60
1 pc	Rear End Panel				\$ R 789.70
1 pc	Rear End Panel Garnish				\$ 189.20
1 pc	Rear Boot				\$ R 784.60
1 pc	Rear Boot Lock				\$ 458.70
1 pc	Rear Boot Rubber				\$ 85.64
1 pc	Rear Boot Centre Emblem				\$ M 58.70
1 pc	Rear Boot COROLLA Emblem				\$ M c 88.50
1 pc	Rear Boot ALTIS Emblem				\$ M 85.90
2 pcs	Taillamps		\$ 381.90		\$ 763.80
1 pc	Rear Spare Tyre Top Cover				\$ S 324.11
					\$ 4,404.95
	Less 25%				\$ 1,101.24
					\$ 3,303.71
1 set	Rear Bumper Sensor	S.Nett			\$ Shan 200.00
1 pc	Rear Number Plate	S.Nett			\$ S 40.00
	To putty and spray painting				\$ F201 800.00
	To anti-rust				\$ 601 80.00
	Labour charges				\$ 601 650.00
TG/RA-	Total				\$ 5,073.71

LIM TAN MOTOR CONSULTANTS hereby notify the Reparer of the following:

- To remedy before later work is carried out
- To remedy damaged parts and body integrity
- Parts price and labour cost estimation
- They must carry out a "Visual Pre-Check" before
- Repairs are commenced to be carried out
- To carry out any work must be informed and
- be subject to final approval from Insurance Company.

Acknowledged by Reparer

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co.Reg No. 199307277D

GST Reg No. M2-0019088-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	35348
Vehicle Details	
Vehicle No.:	SKN3549K
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jun 2019
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1ZR419242
Chassis No.:	MR053REH104509548
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,761.00
Original Registration Date:	02 Jun 2014
First Registration Date:	02 Jun 2014
Transfer Count:	0
Actual ARF Paid:	\$13,761.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Jun 2024
PARF Rebate Amount:	\$9,632.00
Intended COE Rebate Details	
COE Expiry Date:	01 Jun 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,689.00
COE Rebate Amount:	\$32,686.00
Total Rebate Amount:	\$42,318.00

The information contained herein is correct as at 10 Jun 2019

OK

- Pre repair inspection request - SKN3549K VS SKA3353B (OI) DOA: 08/06/2019

From: Abu Kassim, Noor Mariesa
To: admin-a@lkkauto.com, assignments@lkkauto.com
Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur, Subramaniam, Divyashni, Tor
Sent: 8/12/2019 12:32:07 PM
Attachments: ESTIMATE.pdf GASIE

Hi,

Please refer to the enclosed request from **Lim Tan Motor Pte Ltd**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
Kindly assist to assign Mr Kenneth Kong as Single Joint Expert as requested.

Thank you
Regards,

Mariesa Abu Kassim (Mariesa)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations - Auto

NoorMariesa.AbuKassim@aig.com | www.aig.com

From: richard@itm.sg
To: Yinrul.Hor@aig.com
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairdina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeetkaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahain.Tong@aig.com, mandy@itm.sg
Subject: [EXTERNAL] RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKA3353B AND SKN3549K ON 08/06/2019
Date: Wed, 12 Jun 2019 03:22:48 +0000
This message is from an external sender; be cautious with links and attachments.

Hi Viviane,

We refer to your email dated 11th June 2019.

We select Mr Kenneth Kong from LKK Auto Consultants Pte Ltd to conduct the survey to our client's vehicle.

Please assist to arrange.

Thank you and regards,

Richard Ang

Claims Executive
Lim Tan Motor Pte Ltd

www.ITM.sg
+65 6452 0893 (Office)
+65 6458 9127 (Facsimile)
+65 8484 5418 (Mobile)

Like us in Facebook!!

www.facebook.com/ITMsg
www.facebook.com/ITM.Performance.Singapore

From: Hor, Yinrul [mailto:Yinrul.Hor@aig.com]
Sent: Tuesday, 11 June 2019 8:52 AM
To: richard@itm.sg
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Tong, Wahxin <Wahain.Tong@aig.com>
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKA3353B AND SKN3549K ON 08/06/2019
Importance: High

This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la

2:12pm @ 12/6/19
person @ Richard
VNI

pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2019-06-17 19:52 CDT to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the individual(s) named. If you have received this email in error or simply do not require the information, please notify the sender immediately by e-mail. Do not copy, distribute or take any action in reliance on the contents of this information.

Secured by Postquam Encryption, Copyright © 2009-2017 Postquam, Inc. All rights reserved.

From: Yinnul.Hor@aig.com
To: richard@itm.sg
Cc: Andy-SY.Fong@aig.com, Lee-Ying.Chin@aig.com, Baljit.Kaur@aig.com, NoorMariesa.AbuKassim@aig.com, Syazairina.Azlan@aig.com, yokeshi.chan@aig.com, ShengYang.Lim@aig.com, Aashweenjeet.Kaur.Mithoosingh@aig.com, Divyashni.Subramaniam@aig.com, Wahain.Tong@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKA3353B AND SKN3549K ON 08/06/2019
Date: Tue, 11 Jun 2019 00:52:28 +0000
Without Prejudice

Your Reference : SKN3549K
Our Reference : SKA3353B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasol	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rui (Viviane)
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations - Auto
Yinnul.Hor@aig.com | www.aig.sg

From: richard@itm.sg [mailto:richard@itm.sg]
Sent: Monday, June 10, 2019 3:58 PM
To: AIG SGP, Claims-Survey
Cc: Mandy
Subject: [EXTERNAL] RE: Survey Request - Our Client : SKN3549K Your Insured : SKA3353B D.O.A : 08/06/2019
Importance: High

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

Good Afternoon Sir / Madam,

We are assisting our mutual client the vehicle owner of **SKN3549K** to submit a claim against your insured, **SKA3353B** which we understand that you are insurer at the material time of the accident.

We now enclosed the following documents for your easy reference :

- Our client's GIA report
- Repair Estimate

Please let us have a list of your external surveyor for us to choose

Thank you and regards,

Richard Ang

Claims Executive
Lim Tan Motor Pte Ltd

www.LTM.sg
+65 6452 0893 (Office)
+65 6458 9127 (Facsimile)
+65 8484 5418 (Mobile)


Like us in Facebook!!

www.facebook.com/LTMsg
www.facebook.com/LTM.Performance.Singapore

Bukit timah road in between Botanical garden mrt & Kheam Hock Road



Robert M. R. R. R.
Baker, Thomas
R. C. R. R. R.



Khan, Mark
 P. 100 + ~~100~~ 100
 3000
 10000

The front
side of

SKN 3049K

clipped in
suddenly, breaking Kwan Tung's bumper had to brake
too, since it was too sudden. Though he
had already clipped in the brake this vehicle
SKA 3353B bumped on to vehicle
SKN 3549K. (as shown in pic 2)

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 1 July 2019 11:55 AM
To: Keith Lian
Subject: Accident Involving SLC 493C & SJV 3495B on 11/06/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: SLC 493C
Our Ref: CC4/AIG19010560/eb3

Dear Sir/Madam,

Accident Involving SLC 493C & SJV 3495B on 11/06/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



01 JUL 2019

Date: _____

Your Ref: CC4/AIG19010482/Keb3

Our ref: LTP062019/050 (SKN 3549 K)

(WITHOUT PREJUDICE)

Attention To : MS ASHER SNG (From LKK Auto Consultants Pte Ltd)

Insurance Company : AIG ASIA PACIFIC INSURANCE PTE LTD

Dear Sir/Mdm,

IN THE MATTER OF ACCIDENT INVOLVING SKN3549K & SKA3353B ON 08.06.2019

We refer to the above matter.

We are instructed and authorised by our client to quantify, to act and negotiate settlement in related to the above road traffic accident that was caused by your insured.

All supporting documents are enclosed herewith:-

- | | |
|--|---|
| ☒ [x] Authorization To Act | ☒ [x] Original Tax Invoice no. INV41089 |
| ☐ [] Original Rental Receipt and Agreement | ☐ [] LTA search receipt |
| ☐ [] Letter Of Discharge | ☐ [] _____ |

Survey was done by Insurance Instruction and was surveyed by Mr Kenneth on 17-Jun-19

As a result of the accident, our client's vehicle was damaged and has been put to loss and Expenses, particulars of which are as follows:-

1] Cost of repair (Inclusive of 7% GST)	\$ 4,135.58
2] Loss of Use (\$50.00 x 5 Days)	\$ 250.00
Total	<u>\$ 4,385.58</u>

Please acknowledge receipt of this letter within 14 days. If you agreeable to the above, please forward your payment. Payment to be issued directly to LIM TAN MOTOR PTE LTD within 4 weeks. Should there be any injury related to this matter, any settlement agreed is WITHOUT PREJUDICE to the related injury claim.

Your faithfully

Mandy Lim

Email: mandy@lrm.sg

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/AIG19010482/Keb3

01 JUL 2019

KWA TIONG GUAN
10 WATTEN PARK
SINGAPORE 287408

Dear Sir/Madam,

ACCIDENT INVOLVING SKA 3353B / SKN 3549K / OTHERS ON 08/06/2019

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be with held for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Yours faithfully,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

To Whom It May Concern

AUTHORIZATION TO ACT

I/We, TAN KAY SWEE ('the third party Claimant') of 2 SURREY ROAD #10-00 SINGAPORE 307742 (Address) owner of SKN3549K (vehicle number) hereby authorize LIM TAN MOTOR PTE LTD ('the workshop') to act for me with respect to my/our claim for repair costs and/or rental and/or Loss of use ('claim') for my/our vehicle number SKN3549K that was damaged pursuant to the accident which occurred on 08-Jun-19 (date) along BUKIT TIMAH ROAD TOWARDS UPPER BUJIT TIMAH ROAD (locate on) involving vehicle number SKA3353B (the accident').

I/We further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

Dated this 10th (day) of June (month) 2019 (year)



Signed By ' the third party claimant '



Signed By ' the workshop '

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **LIM TAN MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$4,135.58** (Repair Cost), **S\$250.00** (Loss of Use/Rental), **S\$ -** (Disbursement) for vehicle no. **SKN 3549K** that was damaged pursuant to the accident which occurred on **08/06/2019** (date) along **BUKIT TIMAH ROAD TOWARDS UPPER BUKIT TIMAH ROAD** (location) involving vehicle no/s **SKA 3353B**.

This is pursuant to the inspection conducted on **17/06/2019** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **TAN KAY SWEE** ("the third party claimant") of vehicle no. **SKN 3549K** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SKN 3549K** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27th (day) of August (month) 20 19 (year)



KSC

Signed by appointed surveyor



Signed by "the workshop" (with chop)



LIM TAN MOTOR PTE LTD
林陳摩哆私人有限公司

Company's Registration No.: 199302277D
GST Registration No.: M2-0119086-0

Branch
(Warranty and Performance) Blk 9 Sector C #01-38/40/42
Sin Ming Industrial Estate, Singapore 575644
Tel: +65 6452 2135 Fax: +65 6452 2159

Blk 17 Sector A #01-65
Sin Ming Industrial Estate, Singapore 575675

Main Office / Workshop
Blk 176 Sin Ming Drive #03-09/10/06
Sin Ming Autocare Singapore 575721

Tel: +65 6452 0893 (24Hrs)
Fax: +65 6458 9127
Email: sales@LTM.sg

WWW.LTM.SG

TAN KAY SWEE
2 SURREY ROAD
#10-00
SINGAPORE 307742

TAX INVOICE

NO : INV41089
DATE : 27-06-2019
TERMS : COD
PAGE : 1

ATTN : MOTOR CLAIMS DEPT
TEL :
FAX :
A/C NO. : 30T1/115

MILEAGE :
W.O NO. : SO41867
CAR NO. : SKN3549K
MAKE : TOYOTA
MODEL : COROLLA- ALTIS 1.6

DESCRIPTION	QTY	U.PRICE	DIS	AMOUNT
1 TOTAL REPAIR COSTS AS RECOMMENDED BY SURVEYOR	1 UNIT			3,865.03

SINGAPORE DOLLARS : FOUR THOUSAND ONE HUNDRED THIRTY FIVE AND FIFTY EIGHT CENTS
ONLY

REMARKS: D.O.A : 08.06.2019
LKK REF : CC4/AIG19010482/Keb3

TOTAL QTY: 1.00

SUBTOTAL	3,865.03
DISCOUNT	0.00
TOTAL	3,865.03
GST 7 %	270.55
NET	4,135.58
Deposit	0.00
Balance	4,135.58



AUTHORISED SIGNATURE(S)

CUSTOMER NAME / SIGNATURE / DATE

Customer Acknowledgement

I/We confirm that I/We incurred the repair costs herein and will observe my/our Agreement with the repairer. I/We declare the repair for the above vehicle have been completed to my/our satisfaction

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jun 2019 Edit Reg		12 Jun 2019 00:00 Edit Adj Rpt	S\$3,865.02 Edit Estimates	S\$3,865.02 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KWA TIONG GUAN , ID: S03981412								
Main Claimant:	TAN KAY SWEE , ID: S1163534B								
Vehicle Reg. No.:	SKN3549K	Date of Loss:	08/06/2019 16:00 - :59 [60 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3164610600SG	Policy/Cover Note No.:	2100248026 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKA3353B	Policy No. (Claimant):	S119V05061/VPE/R00						
		Excess:							
Repairer:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care, 575721 Sin Ming - Tel: 6452 0893								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (20/06/2019): Re: Request for OI GIA report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKN3549K (3164610600SG)
[SKA3353B]
TP
TAN KAY SWEE
Jun 8 2019 4:00PM
[KWA TIONG GUAN]
Lim Tan Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit		
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	27/08/19 15:42		General View												1			Load JPG		
2	27/08/19 15:42		General View												1			Load JPG		
3	27/08/19 15:42		General View												1			Load JPG		
4	27/08/19 15:42		General View												1			Load JPG		
5	27/08/19 15:42		General View												1			Load JPG		
6	27/08/19 15:42		General View												1			Load JPG		
7	27/08/19 15:42		General View												1			Load JPG		
8	27/08/19 15:42		General View												1			Load JPG		
9	27/08/19 15:42		General View												1			Load JPG		
10	27/08/19 15:42		General View												1			Load JPG		
11	27/08/19 15:42		General View												1			Load JPG		
12	27/08/19 15:42		General View												1			Load JPG		
13	27/08/19 15:42		General View												1			Load JPG		
14	27/08/19 15:42		General View												1			Load JPG		
15	27/08/19 15:42		General View												1			Load JPG		
16	27/08/19 15:42		General View												1			Load JPG		
17	27/08/19 15:42		General View												1			Load JPG		
18	27/08/19 15:42		General View												1			Load JPG		
19	27/08/19 15:42		Chassis Number												1			Load JPG		
20	27/08/19 15:42		Odometer Reading												1			Load JPG		
21	27/08/19 15:42		General View												1			Load JPG		
22	27/08/19 15:43		Reinspection Photo												1			Load JPG		
23	27/08/19 15:43		Reinspection Photo												1			Load JPG		
24	27/08/19 15:43		Reinspection Photo												1			Load JPG		
25	27/08/19 15:43		Reinspection Photo												1			Load JPG		
26	27/08/19 15:43		Reinspection Photo												1			Load JPG		
27	27/08/19 15:43		Reinspection Photo												1			Load JPG		
28	27/08/19 15:43		Reinspection Photo												1			Load JPG		
29	27/08/19 15:43		Reinspection Photo												1			Load JPG		
30	27/08/19 15:43		Reinspection Photo												1			Load JPG		
31	27/08/19 15:43		Reinspection Photo												1			Load JPG		
32	27/08/19 15:43		Reinspection Photo												1			Load JPG		
33	27/08/19 15:43		Reinspection Photo												1			Load JPG		

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/19 15:00	EMAIL FROM AIG DD 12062019	Load PDF	
2	13/06/19 15:00	TP ESTIMATE	Load PDF	
3	13/06/19 15:00	TP GIA REPORT.	Load PDF	
4	18/06/19 18:07	TP ESTIMATE- MARKED	Load PDF	
5	01/07/19 11:10	LETTER TO OI	Load PDF	
6	05/09/19 10:07	WORKSHOP INVOICE	Load PDF	
7	05/09/19 10:07	AUTHORISATION TO ACT FORM	Load PDF	
8	05/09/19 10:07	Release Voucher	Load PDF	
9	05/09/19 10:07	LOD	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	20/06/19 11:50	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKA3353B (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SKN3549K (TP veh)		1.6 CVT (A)
Date of Accident:	08/06/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	: \$	5,739.12	
Final Repair Cost	: \$	4,135.58	
Loss of Use	: \$	250.00	5.00 days at \$50.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	0.00	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	4,385.58	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Lim Tan Motor Pte Ltd	: \$	4,385.58
2)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

05 Sep
2019

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19010482/KEB3Q2

Date: 05/09/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100248026
Claimant Vehicle No : SKN3549K **Insured Vehicle No :** SKA3353B
 Date of Loss: 08/06/2019 Nature of Claim: TP Claim No: 3164610600SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKN3549K**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CVT (A) Engine No: 1ZR419242
 Reg. Date: 02/06/2014 (Man. Year: 2014) Chassis No: MR053REH104509548
 Colour: Metallic Silver Odometer: 39297 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm
 Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,833.66	2,485.02	1,348.64	35.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,530.00	1,380.00	150.00	9.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,363.66	3,865.02	1,498.64	27.94
+ GST 7.00/7.00% (S\$)	375.46	270.55	104.91	27.94
Nett Amount (S\$)	5,739.12	4,135.57	1,603.55	27.94
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
Nett Liability (S\$)		4,385.57		

INSPECTION

Date of Assignment: 12/06/2019
 Date Inspected: 17/06/2019 Inspected At: Lim Tan Motor Pte Ltd (HQ)
 Blk 176 Sin Ming Drive #03-09/10, Sin
 Ming Auto Care
 Singapore 575721
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	486.50 FL	*486.50 FL
2	2		*REAR BUMPER RETAINER	Distorted	177.00 FL	*177.00 FL
3	2		*REAR BUMPER BRACKET	Repair	112.60 FL	*- FL
4	1		*REAR END PANEL	Bent	789.70 FL	*789.70 FL
5	1		*REAR END PANEL GARNISH	Mtg Distorted	189.20 FL	*189.20 FL
6	1		*REAR BOOT	Bent	784.60 FL	*784.60 FL
7	1		*REAR BOOT LOCK	Repair	458.70 FL	*- FL
8	1		*REAR BOOT RUBBER	Serviceable	85.64 FL	*- FL
9	1		*REAR BOOT CENTRE EMBLEM	Necessary	58.70 FL	*58.70 FL
10	1		*REAR BOOT COROLLA EMBLEM	Necessary	88.50 FL	*88.50 FL
11	1		*REAR BOOT ALTIS EMBLEM	Necessary	85.90 FL	*85.90 FL
12	2		*TAILLAMPS	Serviceable	763.80 FL	*- FL
13	1		*REAR SPARE TYRE TOP COVER	Serviceable	324.11 FL	*- FL
14	1		*SET REAR BUMPER SENSOR	Shorted	200.00 FS	*200.00 FS
15	1		*REAR NUMBER PLATE	Serviceable	40.00 FS	*- FS
16	1		*REAR BUMPER REINFORCEMENT	Bent	386.60 FL	*386.60 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,031.55	3,246.70
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,197.89	761.68
Total Parts (\$\$)	3,833.66	2,485.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY PAINTING	New	800.00	720.00
2	TO ANTI-RUST	New	80.00	60.00
3	LABOUR CHARGES	New	650.00	600.00
Gross Labour Cost (S\$)			1,530.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >