

08/11/13 wef

ASS. REC. BY: *Marcus*

REF:

CC3/MSG190/0493109d/3n2
MSG

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SLJ2282R*
at Workshop m/s: *Rp.*
of *SLQ 3850 G*
Insured: _____
Policy No. *29114756*
Claims No. *596428*
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *4* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: *SLJ2282R* Yr Regn: *11.16*
Type: *Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Mercedes* C.C. *1496*
Colour: *Red* A/C: Insured / Std / NI / NA
Sp. Reading: *50977* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *JM6BM 42A860 346133*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *Good* / Jammed / Leaked / Burnt or
Brake: *Good* / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *205/60R16*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / *MIC* / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front *6* mm Rear *6* mm
R/Bal. *6* mm L/Bal. *6* mm
D.O.A. *12/6/19* D.O.I. *13/6/19*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

14/6/19 @ 10.57am Email GIA report to MSG.

19/6/19 1/5 @ 3850 confirmed with ACR. (Ref # 4675, 751/)

RECEIVED 8 JUL 2019

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: *4*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

1) *08/7/19* Date/Time, File Return to?

2)

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

_____) \$ + RS. _____
_____) Photos
_____) Others

Report Format: *MER-TP*

Lump Sum / I.B.I. (\$) *3850*

TOTAL

200
11
211

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 14 June 2019 10:57 AM
To: motorsurvey@sg.msig-asia.com
Cc: SUR; Accounts (LKKAUTO); KKLau
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 12/06/2019, SLJ 2292R (TP VEHICLE), SLQ 3950G (OI VEHICLE)
Attachments: SLJ2292 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLJ 2292R at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883.

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8621A
Vehicle Details	
Vehicle No.:	SLJ2292R
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	P520374640
Chassis No.:	JM6BM42A8G0346133
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$16,869.00
Original Registration Date:	30 Nov 2016
First Registration Date:	30 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$11,869.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Nov 2026
PARF Rebate Amount:	\$8,901.00
Intended COE Rebate Details	
COE Expiry Date:	29 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$38,000.00
Total Rebate Amount:	\$46,901.00

The information contained herein is correct as at 14 Jun 2019

OK

MSME19076872 / SME Motor Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 12/06/2019 17:54
SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/06/2019 17:54
Date Of Accident	12/06/2019 10:40
Exact Location Of Accident	OUTSIDE HILLION MALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ2292R
Insured/Policyholder	
Name Of Registered Owner	CHUA HOE GHEE
NRIC No	S8308621A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98222014
Alternative Phone No	OFFICE-98222014

Vehicle Particulars

Manufacturer	MAZDA
Model	3
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01017332
Cover Note Number	

Driver

Name of Driver	CHUA HOE GHEE
NRIC No	S8308621A
Date Of Birth	13/03/1983
Occupation	INDOOR
Date Of Driving Pass	13/10/2015
Driving Experience	3 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98222014
Fax Number	
Contact Number	OFFICE-98222014
Email Address	NOEMAIL

Address BLK 546B SEGAR ROAD #07-59
 Postcode 672546
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : PANG SHI YIN
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS WAITING FOR THE TRAFFIC TO MOVE. SUDDENLY, CAR B HIT ONTO THE REAR PORTION OF MY VEHICLE A.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLQ3950G
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver SALEH BIN MAMAT
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

12/6/19

Signature of Policyholder

Driver's Signature
(If driver is not the policyholder)
Date & Time:


12/6/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CHIN MENA

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was waiting for the traffic to move, suddenly car B hit onto my rear part of my car A

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

12/6/19

Gratwic Sketch Plan Form 03

Driver's Signature

(If driver is not the policyholder)

Date & Time:

12/6/19.

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

FASTECT AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: SLJ 2292R

QTY	PARTICULAR		
1 PCS	BOOTLID	1	\$1,269.00 X
1 PCS	BOOTLID REAR LOGO	11	\$75.00 X
1 PCS	BOOTLID 'SKYACTIVE' EMBLEM	11	\$63.60 X
1 PCS	BOOTLID 'MAZDA' EMBLEM	11	\$64.00 X
1 PCS	BOOTLID '3' EMBLEM	11	\$74.40 X
1 PCS	BOOTLID WEATHERSTRIP	11	\$225.00
1 PCS	BOOTLID INNER LOCK	11	\$271.00 X
2 PCS	BOOTLID REFLECTORS @\$485.00	11	\$970.00 X
2 PCS	BOOTLID HINGES @\$121.00	11	\$242.00 X
2 PCS	TAILLAMPS @\$1050.00 915	n/s cne	\$2,100.00 12C
2 PCS	TAILLAMP GASKETS @\$28.00	11	\$56.00 X
1 PCS	REAR BUMPER	11/02	\$1,074.00
2 PCS	REAR BUMPER REFLECTORS @\$150.00	11	\$300.00 X
2 PCS	REAR BUMPER TOWING COVERS @\$45.00	n/s m/s	\$90.00 12C
2 PCS	REAR BUMPER SIDE RETAINERS @\$66.50	11	\$133.00 X
1 SET	REAR BUMPER CLIPS	11	\$60.00
1 PCS	REAR BUMPER REINFORCEMENT	11	\$741.00
4 PCS	REAR BUMPER ULTRASONIC SENSORS @\$185.00 1 set	11	\$740.00 2005.2
1 PCS	REAR END PANEL 505.10	11	\$625.00
1 PCS	REAR END PANEL TOP GARNISH	11	\$288.00 X
2 PCS	REAR FENDER INNER TRIMS @\$385.00	11	\$770.00 X
1 PCS	REAR EXHAUST	11	\$1,024.00 X
2 PCS	REAR EXHAUST MOUNTING @\$65.00	11	\$130.00 X
1 PCS	REAR END PANEL SELANT	11	\$60.00
			\$11,445.00
LABOUR CHARGES:			
TO CHECK WIRING			\$80.00 30
TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00 50
TO TRANSFER BOOTLID MECHANISM		11	\$120.00 X
TO DISMANTLE & REFIX REAR EXHAUST		11	\$120.00 X
TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY			\$150.00 80
TO MOUNT VEHICLE ON CAR O-LINER		11	\$380.00 X
TO SPRAY RUST PROOFING			\$100.00 30
LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,500.00 800
TO PUTTY & SPRAY PAINTING			\$1,500.00 900
TOTAL			\$15,475.00

1. The Repairer shall be notified by the Insurer of the surveyor's findings.
2. The Insurer shall be notified by the Repairer of the surveyor's findings.
3. To display damaged parts during survey.
4. Parts prices are subject to confirmation.
5. Third party survey is on a "Without Prejudice" basis.
6. No illegal modification(s) is allowed.
7. Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:

7-3421.4
202
2737.12
4827.12

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19010493/UQD3N2

Date: 10/07/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114756
Claimant Vehicle No :	SLJ2292R	Insured Vehicle No :	SLQ3950G
Date of Loss:	12/06/2019	Nature of Claim:	TP
		Claim No:	596428

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2292R	Engine No:	P520374640
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Chassis No:	JM6BM42A8G0346133
Reg. Date:	30/11/2016 (Man. Year: 2016)	Odometer:	50977 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	11,445.00	2,937.12	8,507.88	74.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,890.00	2,140.00	53.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,475.00	4,827.12	10,647.88	68.81
Approved Total (Overridden) (S\$)		3,850.00		
(S\$)	15,475.00	3,850.00	11,625.00	75.12
+ GST 7.00/7.00% (S\$)	1,083.25	269.50	813.75	75.12
Nett Amount (S\$)	16,558.25	4,119.50	12,438.75	75.12

INSPECTION

Date of Assignment: 04/07/2019

Date Inspected: 13/06/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ2292R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Repair	1,269.00 F	*- FL
2	1	*BOOTLID REAR LOGO	Not Necessary	75.00 F	*- FL
3	1	*BOOTLID SKYACTIVE EMBLEM	Not Necessary	63.60 F	*- FL
4	1	*BOOTLID MAZDA EMBLEM	Not Necessary	64.00 F	*- FL
5	1	*BOOTLID 3 EMBLEM	Not Necessary	74.40 F	*- FL
6	1	*BOOTLID WEATHERSTRIP	Twisted	225.00 F	*225.00 FL
7	1	*BOOTLID INNER LOCK	Not Necessary	271.00 F	*- FL
8	2	*BOOTLID REFLECTORS	Not Necessary	970.00 F	*- FL
9	2	*BOOTLID HINGES	Not Necessary	242.00 F	*- FL
10	1	*TAILLAMPS	N/s Cracked	2,100.00 F	*915.00 FL
11	2	*TAILLAMP GASKETS	Not Necessary	56.00 F	*- FL
12	1	*REAR BUMPER	Dented / Deformed	1,074.00 F	*1,074.00 FL
13	2	*REAR BUMPER REFLECTORS	Not Necessary	300.00 F	*- FL
14	1	*REAR BUMPER TOWING COVERS	N/s Missing	90.00 F	*45.00 FL
15	2	*REAR BUMPER SIDE RETAINERS	Not Necessary	133.00 F	*- FL
16	1	*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
17	1	*REAR BUMPER REINFORCEMENT	Bent	741.00 F	*537.30 FL
18	1	*REAR END PANEL	Dented	625.00 F	*505.10 FL
19	1	*REAR END PANEL TOP GARNISH	Not Necessary	288.00 F	*- FL
20	2	*REAR FENDER INNER TRIMS	Not Necessary	770.00 F	*- FL
21	1	*REAR EXHAUST	Not Necessary	1,024.00 F	*- FL
22	2	*REAR EXHAUST MOUNTING	Not Necessary	130.00 F	*- FL
23	1	*REAR END PANEL SEALANT	Necessary	60.00 F	*60.00 FL
24	1	*SET REAR BUMPER ULTRASONIC SENSORS	Shorted	740.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,445.00	3,621.40
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	684.28
Total Parts (\$\$)	11,445.00	2,937.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING.	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR.	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM.	New	120.00	0.00
4	TO DISMANTLE & REFIX REAR EXHAUST.	New	120.00	0.00
5	TO DISMANTLE & REFIX SEAT, CUSHION UPHLOSTERY.	New	150.00	80.00
6	TO MOUNT VEHICLE ON CAR O-LINER.	New	380.00	0.00
7	TO SPRAY RUST PROOFING.	New	100.00	30.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS.	New	1,500.00	800.00
9	TO PUTTY & SPRAY PAINTING.	New	1,500.00	900.00
Gross Labour Cost (\$\$)			4,030.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >