



SMRT Accident Vehicle Repair Estimates

Asher

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 21/06/2019

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB1523L
Case Reference Number	BUS/06/19/1011
Registration Date	29/10/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Wu Kangwei
Type of Accident	Rear To Head
Accident Date and Time	5/6/2019 6:22 PM
Accident Reported Date and Time	5/6/2019 8:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101942
Special Instruction to ARC, if any	SMB1523L-FRONT PORTION GBB208J (TP) INSURED WITH CHINA
Prepared Date and Time	12/6/2019 11:02 AM
Chassis Number	WMAA22ZZ4E7002282
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$262.00	\$170.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$792.00	\$435.00
Lump Sum Total	\$800.00	\$0.00
Number of Repair Days	3.0	1.0
Prepared / Adjusted By	Boon Chew Tay	YOU HAN.
ARC / Surveyor Sign Off Date	12/06/2019 11:06 AM	12/06/2019 11:29 AM
Signature		LKK
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

P/P \$435/- 1 day.



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 21/06/2019

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$530.00	\$265.00
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$262.00	\$170.00
Total Spray Painting & Panel Beating	\$262.00	\$170.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010151	Body	F01001-CE265	BUMPER,FRONT:CENT RE,FOR MAN A22 BUS	1.00	\$1,868.80	100.00	\$0.00	Repair	Repair
Total					\$1,868.80		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									