

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/06/2019 17:56
Date Of Accident	12/06/2019 13:10
Exact Location Of Accident	210 MARSILING CRES (CARPARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM5890D
Insured/Policyholder	
Name Of Registered Owner	KANG HOCK HUAT ROY
NRIC No	S7528801H
Email Address	ROY.KANG@REINHAUSEN.SG
Mobile Phone No	(LOCAL) +65-91265686
Alternative Phone No	OTHERS-91265686

Vehicle Particulars

Manufacturer	BMW
Model	216D GRAN TOURER
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2008074
Cover Note Number	

Driver

Name of Driver	KANG HOCK HUAT ROY
NRIC No	S7528801H
Date Of Birth	19/09/1975
Occupation	INDOOR
Date Of Driving Pass	24/09/2001
Driving Experience	17 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91265686
Fax Number	
Contact Number	OTHERS-91265686
Email Address	ROY.KANG@REINHAUSEN.SG

Address	BLK 19 HOUGANG AVENUE 3 #04-195
Postcode	530019
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOGANG N.P.C
Police Station Address	ROAD: 60 HOUGANG AVE 9 SINGAPORE 538775 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG-BURN CD
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBH1010Z
Vehicle Make/Model/Colour	NISSAN WHITE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	AXA INSURANCE PTE LTD

Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature

Date & Time: 15/6/19 5:12pm

Driver's Signature


(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

When returning to my car after lunch, I realised that the right front bumper was found scratches and paint peel-off. I have retrieved my video from car camera and observed the time of accident happened around 1:06pm by a white Nissan car.

The footage shown the driver was trying to make a right turn into the parking slot and causing this accident happened. He did not ~~test~~ leave any form of contact after this accident and drove off via picking up a passenger.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

12/6/13

5:12pm

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


[Signature]

12/6/2013

@ 1716lw



**SINGAPORE
POLICE FORCE**



T/20190613/2001

1 of 3

Report No. T/20190613/2001

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 13/06/2019 00:19	Vide Report No.:	Station Diary No.: 8
--	------------------	-------------------------

Informant's Particulars

Name of Informant: KANG HOCK HUAT, ROY		Address: APT BLK 19 HOUGANG AVENUE 3 #04-195 SINGAPORE 530019	
ID Type / ID No.: NRIC NO / S7528801H		Contact No.: Home/Office: Mobile: 91265686	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 43	Date of Birth: 19/09/1975	Type of Informant: Vehicle Owner
Race: Chinese		Language:	Institution / School Name:
Occupation: SENIOR SALES MANAGER		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 12/06/2019 13:05	Type of Location: Car Park
Location: Along Road 1 MARSILING CRESCENT				
Open Carpark of Blk 210 Marsiling Crescent (unknown Lot)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision:				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SBH1010Z	Car	NISSAN		White		0
SLM5890D	Car	BMW	216D	White	Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20190613/2001

2 of

Report No. T/20190613/20

Police Station Of Origin:

Hougang N.P.C

Hougang Avenue 9 SINGAPORE 538775

Hotline No: 1800-4890999

CONTINUATION OF REPORT

Vehicle Owner			
Name	KANG HOCK HUAT, ROY		ID No. S7528801H
Related Vehicle	SLM5890D (Car)		Contact No. 91265686
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 12/06/2019 at about 1250hrs, I parked my vehicle - One White BMW 216D (Registration Plate Number: SLM5890D) at the Open Carpark of Blk 210 Marsiling Crescent (unknown lot number). I secured my vehicle and left. Everything was normal.

On the same day at about 1320hrs, I came back to retrieve my vehicle and discovered that there was a paint chip and marks on the front right region of my vehicle. No note was left behind.

I made a check on my in-vehicle CCTV and discovered that on the same day at about 1306hrs, One White Nissan (Registration Plate Number: SBH1010Z) had grazed against the front right region of my vehicle when picking up a passenger. I strongly believe that the incident was what caused the damage.

I wish to state that I am not aware if there is any CCTV at the incident location which secures where my vehicle was parked and whether or not it recorded the whole incident.



**SINGAPORE
POLICE FORCE**



T/20190613/2001

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

3 of 3

Report No. T/20190613/20

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 MOHAMAD ZULHIZWAN AQMA BIN
MOHD ZULKEFLEE

Signature Of Informant:

Date/Time:

13/06/2019 00:19

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

Classification Of Case:

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo

