

CASE OWNER:

RA

CC 4, ASM 190 10531, Kga3

LKK:

IDAC:

1M548

ASSIGNMENT

13/06/19

Surveyor:

Kenneth

DOI:

29/6/19

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

smj 3865 u

Claim No.:

sqmola JV

Name of Insured:

Lee Sock Yang

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A.:

17/06/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJR 5862H



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sin mng

Autocare BPR



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Kenneth

Repair Cost:

SS 500.00

(2)

days)

Reduction:

\$376.70

%

38

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Angela

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

SS 588.50

Loss of Rental (LOR):

SS

50

days)

Loss of Use (LOU):

SS

100.00

(\$ 50

x 2

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

698.50

Global Sum SS:

600.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payment 1:

SS

600.00

Payment 2 (BOLA / M.A.):

SS

-

Payment 3 (BOLA / M.A.):

SS

-

Name:

Sin mng Autocare BPR Pte Ltd

Name:

Name:

Name:

✓ ENA

ASS. REC. BY:

Henneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop nvs *Pin Ming BFG*

of

Insured:

Policy No:

Claims No:

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh:

(Policy Condition) *11am*

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *8550*

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *02* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: *4/29* Person Contacted: _____

Vehicle: IN / OUT

Veh No:

Type: *M. Car* M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: *NII* / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: *Frt* / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Yr Regn: *06, 09*

c.c. *1497*

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

JTD1CB20U2.03544368

195/55R16

N/S	O/S

Rear

R/Bal.

L/Bal.

D.O.I.

(Red = \$336.70 / 38%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

☐ : Prell. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$
☐ : Interview (\$
☐ : Tech Invs (\$
☐ : Weekend (\$

Survey Fee:

Transportation:

S + P.S. \$

Fuel \$

Others

TOTAL

*File pass to
Repair done after UIC spare parts delivered 50%*

UIC Rp 8550



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

AXA INSURANCE (SINGAPORE) PTE LTD
8 SHENTON WAY #27-01 AXA TOWER
SINGAPORE 068811

Estimate : E19/2497

Attention : Motor Claim Department
Contact : 18008804741 Fax No. : 6880 4740

Date : 13/06/2019
Vehicle Num. : SJR5862H
Make/Model : TOYOTA PRIUS-2009
Chassis/Eng# : JTDKB20U203544368/1NZ5419610
Accident Date : 12/06/2019
Claim No. : BFG
Reference : TP CLAIM
Policy No. : 5054535193-06

*Not Notation
11/24 8550*

Resumen Adu Repair 2 days

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1PC	FRONT BUMPER		430.51 ✓
2.	1PC	FRONT BUMPER RETAINER RH		58.42 X
List TotalS\$:				488.93
25.00% Discount S\$:				122.23
				366.70
LABOUR :				
LABOUR FOR SPRAY PAINT FRONT BUMPER				400.00 22d
LABOUR FOR REMOVE & REINSTALL FRONT BUMPER				120.00 ✓
Labour Total S\$:				520.00

E. & O.E.

Total S\$: 886.70

[Signature]
for Sin Ming Autocare BFG Pte Ltd

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts photo are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

13 June, 2019

LEE SOKE YANG
50 LENTOR CRESCENT
SINGAPORE 786717

Dear Sir,

OUR REF : CC4/ASM19010531/ga3 // S9M01QJV
YOUR REF : SMJ 3865U
ACCIDENT INVOLVING SMJ 3865U AND SJR 5862H ON 12/06/2019 ALONG/AT
BISHAN COMMUNITY CLUB CARPARK

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)

Service Request Details

Claim

S9M01QJV

Reference

None 

Loss Date

12 June 2019

Report Date

13 Jun 2019 1:38:48 PM

Request Date

13 June 2019

Due Date

20 June 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: Angela

T: 444p m

V: Out

E: ✓

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration

SJR5862H

(PENDING)

PRIUS-1.5 (A)

Service Address

...

Primary Contact/Insured

LEE SOKE YANG

50 LENTOR CRESCENT, 786717, Singapore

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions

NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Catherine Chong (LKK Auto)

From: Motor Claims <motorclaims@autocare.com.sg>
Sent: Thursday, 13 June, 2019 12:00 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: 'Serene Lim'
Subject: THIRD PARTY CLAIM OF SJR5862H & SMJ3865U ACCIDENT ON 12.06.2019 ALONG BISHAN COMMUNITY CLUB CARPARK
Attachments: SAS.pdf
Categories: Raghav

To: AXA Motor Claims Dept. (Arrangement of Surveyor Unit)

RE: NOTICE TO THIRD PARTY INSURERS TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKINGS DAY PURSUANT TO PARAGRAPH PHOTOCOL FOR NIN-INJURY MOTOR ACCIDENT CLAIMS (NIMA) ACCIDENT INVOLVING SJR5862H & SMJ3865U ALONG BISHAN COMMUNITY CLUB CARPARK ON 12.06.2019

We are repairer for TAN HENG GUI the owner of vehicle no SMJ3865U.

Please be informed that the said vehicle can inspected at the following venue:

Sin Ming Autocare BFG Pte Ltd
176 Sin Ming Drive #02-05 Singapore 575721
Tel: 6455 0600 Fax: 64556192 Email: motorclaims@autocare.com.sg

Contact Person: Angela Tan

Please also provide us a list of 10 surveyors as your nominated SJE (Single Joint Expert)

PLEASE ARRANGE OFFICER-IN-CHARGE TO LET US KNOW ASAP IF WE COULD DO DIRECT SETTLEMENT FOR THIS CASE.

Thank you

With Regards,
Angela Tan
Claims & Admin Executive



Sin Ming Autocare BFG Pte Ltd
176 SIN MING DRIVE, #02-05 SINGAPORE 575721
Email: motorclaims@autocare.com.sg
Tel : 6455 0600 | Fax : 6455 6192



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408953 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 29/11/2019

Survey Details:

Date of loss	12-Jun-19
Date of appointment	13-Jun-19
Date of survey	25-Jun-19
Location of survey	SIN MING AUTOCARE BFG PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SJR5862H
Make and Model	TOYOTA PRIUS AUTO
Date of registration	30-Jun-09
Parf Rebate	
Market Value	\$ 55,000.00
Parf Rebate	\$ 35,255.00
Nett Loss	\$ 19,745.00

Repair details:

Initial Estimate	886.70
------------------	--------

Proposed/Revised repair cost:

Parts	\$ 215.26
Check items (estimate)	\$ -
Labour	\$ 340.00
Total	\$ 555.26
Lump Sum(if applicable)	\$ 550.00

Number of days for repair	2.0
---------------------------	-----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

--

Mandate:

Liability(TP)		100%	
Proposed repair cost	\$	588.50	W/GST
Loss of use	\$	120.00	2days x \$60
Loss of rental	\$	-	
Loss of income	\$	-	
LTA search fees	\$	2.00	
Others	\$	-	
Proposed Total	\$	710.50	

 <MANDATE IA> - S9M01QJV {ACCIDENT INVOLVING
SMJ 3865U (OI) & SJR 5862H (TP) ON 12/06/2019}

Type

 Question

Message

LIABILITY: 100% - OI COMING OUT FROM LOT, TP REVERSING INTO LOT. INFORMED OI ABOUT TP CLAIM AND NCD ISSUE, AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$710.50 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION, THANKS - CCL

[Reply](#)



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

Our Ref: BFG/SJR5862H/AXA/TP/AT

20 November 2019

AXA INSURANCE (SINGAPORE) PTE LTD
8 SHENTON WAY
#27-01
AXA TOWER
SINGAPORE 068811

Attn: Motor Claims Dept

Dear Sirs/ Mdm

**ACC INVLG SJR5862H & SMJ3865U ALONG BISHAN COMMUNITY CLUB
CARPARK ON 12.06.2019**

We are the repairers of vehicle nos. SJR5862H and understand that you were the insurer of vehicle nos. SMJ3865U involved in the aforesaid accident. Our investigations reveal that the accident was caused by the negligence of the vehicle insured by you. As such, we are looking to you for reimbursement calculated as follows;

1) Repair Costs	S\$ 588.50
2) Loss of Use for 2 Days at \$100 per day	S\$ 200.00
3) GIA Receipt	S\$ 2.00
TOTAL:	S\$ 790.50

To substantiate our claim, we enclosed the following;

- a) Final Bill
- b) Letter of Authority
- c) SAS Report
- d) GIA Receipt

We look forward to your favorable reply in due course.

Yours faithfully

Serene Lim
Claims Section
Email: serene@autocare.com.sg

Encl.



Sin Ming Autocare BFG Pte Ltd

176, Sin Ming Drive #02-05
Sin Ming Autocare Complex
Singapore 575721
Tel : (65) 6455 0600
Fax : (65) 6455 6192
Website: www.autocare.com.sg
GST Reg. No: 20-0210033-N

AXA INSURANCE (SINGAPORE) PTE LTD
8 SHENTON WAY #27-01 AXA TOWER
SINGAPORE 068811

Attention : Motor Claim Department

Contact : 18008804741 Fax No. : 6880 4740


Tax Invoice : TP19/577

Date : 20/11/2019
Vehicle Num. : SJR5862H
Make/Model : TOYOTA PRIUS-2009
Chassis/Eng# : JTDKB20U203544368/1NZ5419610
Accident Date : 12/06/2019
Claim No. : LKK: CC4/ASM19010531/ga3
Reference : TP CLAIM
Policy No. : 5054535193-06

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		LIST ITEMS : LUMP SUM REPAIR (Parts & Labour inclusive)		550.00
		List TotalS\$:		550.00

E. & O.E.

Total S\$: 550.00
GST @ 7% S\$: 38.50
Amount Due S\$: 588.50
=====


for Sin Ming Autocare BFG Pte Ltd

 **Re:<MANDATE IA> - S9M01QJV {ACCIDENT INVOLVING
SMJ 3865U (OI) & SJR 5862H (TP) ON 12/06/2019}**

Type

 Question

Message

Hi, pls offer \$600/- (global sum). TY.

[Reply](#)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM19010531/Kga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG			Date : 20-12-2019	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 3865U	Veh. Inspected	SJR 5862H	
Policy No.	P2253077	Coverage (\$)	0.00	
Claim No.	S9M01QJV	Excess (\$)	0.00	
Assign From		Assign Date	13/06/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTDKB20U203544368	Colour	METALLIC BLACK	
Odometer	200980	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	195/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	195/55 R16	YOKOHAMA	4 mm	
L/H Rear Tyre	195/55 R16	YOKOHAMA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/06/2019	Inspection Date	25/06/2019	
Survey held at	SIN MING AUTOCARE BFG PTE LTD 176, SIN MING DRIVE #02-05 SIN MING AUTOCARE COMPLEX SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 5862H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	BENT	430.51	430.51
1	FRONT BUMPER RETAINER RH (CONSISTENT)	SERVICEABLE	58.42	-
	LESS 25% DISCOUNT		-122.23	-
	LESS 50% DISCOUNT		-	-215.26
			366.70	215.25
	LABOUR			
	LABOUR FOR SPRAY PAINT FRONT BUMPER .		400.00	220.00
	LABOUR FOR REMOVE & REINSTALL FRONT BUMPER .		120.00	120.00
			520.00	340.00
	GRAND TOTAL		886.70	555.25
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			550.00

Report Ref No. CC4/ASM19010531/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

SPN01QJV

Reference

CC4/ASM19010531/Kga3a2

Loss Date

12 June 2019

Report Date

13 Jun 2019 1:38:48 PM

Request Date

13 June 2019

Due Date

Vendor Name

LKKAUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SJRS6A2H

Make

TPND TOYOTA

Model

PRUIS-1.5 (A)

Service Address

...

Primary Contact/Insured

LEE SOKE YANG

50 LENTOR CRESCENT, 786717, Singapore

Claim Handler

ANG Richard

richard.angbis@aaa.com.sg

Actions

Next Step

Wait for: Approve Invoice

Add Invoice

Additional Instructions

NOT REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Accident Statement

Reports & Statement

Meritman

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKInvoice1.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKKInspection.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 AUTHORIZATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	20 December 2019
 MANDATE IA DO 29112019.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019
 TAX INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019
 LKK SURVEY PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019
 LOD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019
 PARF COE REBATE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LCA.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019
 GIA SEARCH INVOICE.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	29 November 2019
 SUR56A2H (online-video-cutter.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	22 July 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
 TP - IA.pdf	Forms / Claim Documents	Assessment	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
 LKK SURVEY PHOTO.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
 TP VIDEO.mp4	Evidence	Videos	LKK AUTO CONSULTANTS PTE LTD (TP)	26 June 2019
 P2253077_NB_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	ANG Richard	14 June 2019
 P2253077_CI_00001_1.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of Insurance	ANG Richard	14 June 2019
 Ltr to Insured -non reporting.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	13 June 2019
 TP PRI FROM WORKSHOP WITH GIA REPORT.mpeg	Letters and Correspondence	Workshop	DIHAJAL Raghu	13 June 2019