

ASS. REC. BY:

REF: CS 3/MSG 19010539/R1cd3ed Special Instruction:

Survivor: RusuASSIGNMENT (Office)From (Person): Fazel Fouwen yao of MSIG Date/Time: 13.6.19 16.27p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBG 9820E Insured: SLW 4459xat Workshop m/s Tan Eng Huat Tel: 62808927of BK 6 Defu Lane 10 #01-556Policy No: 80350888 MCX Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 11.6.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 14.6.19 9.46a.m Person Contacted: Kat H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	<u>GBG 9820E - X</u>
	<u>SLW 4459x - X</u>
	<u>After repair: 19/6/2019</u>

TOTAL

120
11
131

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019 15:10		13 Jun 2019 16:27 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS			[Created by insurer]
Insured:	SHELTON (S) PTE LTD, Co. Reg. No.: 199706206C		
Main Claimant:	TAC 3 ELECTRIC & RENOVATION CONTRACTOR, Co. Reg. No.: 52416800L		
Vehicle Reg. No.:	GBG9820E	Date of Loss:	11/06/2019 15:00 - :59 [17 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	80350888MCX (Comprehensive) Coverage: 29/05/2019 - 28/05/2020
Vehicle Reg. No. (Insured):	SLW4459X	Policy No. (Claimant):	
		Excess:	
Repairer:	Tan Eng Huat Motor (HQ) Blk 6 Defu Lane 10, #01-556, 539187 Defu Lane - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/06/2019]		
Driver/Custodian (Insured):	CHONG WEE KANG (/ Male) , NRIC: S72257351 Email:		
Adj Asg. Remarks:	on WP. Liab: 100%. TP disagree on SJE - assign LKK Auto Consultants Pte Ltd. Contact: Kat @ 6280 8927		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6800L
Vehicle Details	
Vehicle No.:	GBG9820E
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	YD25422460A
Chassis No.:	JN1MC2E26Z0008570
Maximum Power Output:	-
Open Market Value:	\$25,062.00
Original Registration Date:	21 Dec 2017
First Registration Date:	21 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$1,254.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$41,071.00
COE Rebate Amount:	\$34,823.00
Total Rebate Amount:	\$34,823.00

The information contained herein is correct as at 27 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	12/06/2019 09:43
Date Of Accident	11/06/2019 15:50
Exact Location Of Accident	THOMSON FLYOVER
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GBG9820E
Insured/Policyholder	
Name Of Registered Owner	TAC 3 ELECTRIC & RENOVATION CONTRACTOR
Co Reg No	52416800L
Email Address	TAC3ELECTRIC@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97663848
Alternative Phone No	OFFICE-97663848
Vehicle Particulars	
Manufacturer	NISSAN
Model	NV350
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5106357158
Cover Note Number	
Driver	
Name of Driver	TAN HUAT HENG
NRIC No	S1491141C
Date Of Birth	15/03/1961
Occupation	OUTDOOR
Date Of Driving Pass	14/12/1979
Driving Experience	39 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97663848
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 236 HOUGANG AVENUE 1 #07-280 S 1953
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLW4459X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHONG WEE KUANG
NRIC/Passport Number	S7225735I
Contact Number	81630002
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

特三电器装修工程公司
TAC 3 ELECTRIC & RENOVATION CONTRACTOR
Blk 6 Defu Lane 10 #01-556
Singapore 539187
PUB LICENCE NO: 3/48337
Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan Pg. 1

A-GBG 9820 E
B- 3LW 4459X

11/6/19
3:50 pm

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was traveling along Thomson Flyover.
The traffic was heavy; Suddenly I feel an impact and a loud bang from behind. I came down to check and realized that vehicle B had collided on my rear.

Insurance Co.	NTUC Income	
Vehicle No.	GBG9820E	Date of Accident 11/6/2019
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim <input checked="" type="checkbox"/> Other Workshop TBA		

DECLARATION

I/We declare the foregoing particulars are true in every respect.

特三电器装修工程公司
TAC 3 ELECTRIC & RENOVATION CONTRACTOR
8116 Delo Lane To #01-556
Singapore 639157
Date of Incident NO: 3/48337

Driver's Signature
(If driver is not the policyholder)
Date & Time:

12 Jun 2019
@ 9.45 hr

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Jun 2019 15:10		13 Jun 2019 16:27 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SHELTON (S) PTE LTD , Co. Reg. No.: 199706206C								
Main Claimant:	TAC 3 ELECTRIC & RENOVATION CONTRACTOR , Co. Reg. No.: 52416800L								
Vehicle Reg. No.:	GBG9820E	Date of Loss:	11/06/2019 15:00 - :59 [17 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 596413	Policy/Cover Note No.:	A8035088MCX (Comprehensive) Coverage: 29/05/2019 - 28/05/2020						
Vehicle Reg. No. (Insured):	SLW4459X	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Tan Eng Huat Motor (HQ) Blk 6 Defu Lane 10, #01-556, 539187 Defu Lane - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 14/06/2019]								
Driver/Custodian (Insured):	CHONG WEE KANG (/ Male) , NRIC: S7225735I Email:								
Adj Asg. Remarks:	on WP. Liab: 100%. TP disagree on SJE - assign LKK Auto Consultants Pte Ltd. Contact: Kat @ 6280 8927								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBG9820E (596413)

[SLW4459X]

TP













TAC 3 ELECTRIC & RENOVATION CONTRACTOR

Jun 11 2019 3:00PM

[SHELTON (S) PTE LTD]

Tan Eng Huat Motor

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
2	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
3	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
4	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
5	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
6	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
7	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
8	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
9	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
10	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
11	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
12	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
13	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
14	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
15	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
16	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
17	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
18	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
19	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
20	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
21	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
22	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
23	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
24	24/06/19 18:45	General View	Load JPG	<input checked="" type="checkbox"/>
25	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
26	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
27	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
28	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
29	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
30	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
31	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
32	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
33	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
34	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
35	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
36	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
37	27/06/19 11:01	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
38	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
39	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
40	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
41	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
42	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
43	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
44	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
45	27/06/19 11:01	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	12/06/19 15:11	OI SLW4459X E-FILE REPORT		Load PDF
2	12/06/19 15:11	TP GBG9820E E-FILE REPORT		Load PDF
3	12/06/19 15:11	PRI from Tan Eng Huat Motor		Load PDF
4	13/06/19 10:44	TP disagree on SJE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19010539/R1CD3E2

Date: 01/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A80350888MCX

Claimant Vehicle No: GBG9820E

Insured Vehicle No: SLW4459X

Date of Loss: 11/06/2019

Nature of Claim: TP

Claim No: 596413

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG9820E**

Make & Model: NISSAN NV350, 2.5 D Panel Van (M)

Engine No: YD25422460A

Reg. Date: 21/12/2017 (Man. Year: 2017)

Chassis No: JN1MC2E26Z0008570

Colour: Grey

Odometer: 38150 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C

Rear Tyre Size: 195 R15C

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 13/06/2019

Date Inspected: 14/06/2019

Inspected At:

Tan Eng Huat Motor (HQ)
Blk 6 Defu Lane 10, #01-556
Singapore 539187

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 01 Jul 2019)	
Parts:	N/A	NISSAN NV350 2.5 D Panel Van (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG9820E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >