

ASS. REC. BY:

REF:

CS3 / AIG 19010553 / Gcd 302

Initial Instructions:

Surveyor:

Meimien

ASSIGNMENT (Office)

From (Person):

chin lee ying

of

AIG

Date/Time:

14/6/19 @ 5.59 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 91879

Insured:

SGS 28029

at Workshop m/s

C.H. Motor

Tel:

6748 8888

of

Blk 3019 Ubi Rd 1 # 01-30

Policy No:

Claim No:

8129878565SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

7/6/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:02 am 14/6/19

Person Contacted:

Mr. Joe

Vehicle IN / OUT

Date/Time	Action/Instruction
	13/6/19 [X]
	SJB 91879-CCF / AIG / 300011 / C+2w2
	SGS 28029-X
	Dismantle: 17/6/2019
	After repair: 19/6/2019

JUA: 29/12/2012

ASS. REC. BY:

REF:

A19

ASSIGNMENT

From

Date:

14/6/19

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJB. 9187G

at Workshop n/s

C.H. Motor Vehicle

of Blk 3019A Ubi Rd 1 # 01-30

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 &

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS 'up'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJB9187G

Yr Regn:

Jan / 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Civic 1.8

c.c

1.799

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

144788

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMFD16308S 21417

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55 ZR16

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

14-06-19

Survey held at

w/s

1230pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Wt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~\$500 - \$1000~~

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Week end (\$)

Survey Fee:

180

Transportation:

3 + RS. SI

Phone:

Others:

11

TOTAL

191

Report Format:

DAR.

Lump Sum / LEH:

PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGS2802G AND SJB9187G ON 07/06/...

From: Chin, Lee-Ying
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY
Sent: 6/14/2019 8:59:32 AM
Attachments:  20190611095652.pdf

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947
Lee-Ying.Chin@aig.com | www.aig.sg

From: Elaine Toh [mailto:Elainetoh@visionlawllc.com]

Sent: Monday, June 10, 2019 3:16 PM

To: Hor, Yinrul

Cc: 'Lily.Tan@aig.com'; 'Andy-SY.Fong@aig.com'; 'Baljit.Kaur@aig.com'; 'Lee-Ying.Chin@aig.com'; 'NoorMariesa.AbuKassim@aig.com'; 'Imran.Ishak@aig.com'; 'ShengYang.Lim@aig.com'; 'Darshene.Supramaniam@aig.com'; 'Syazairdina.Azlan@aig.com'; 'yokeshi.chan@aig.com'; Mithoosingh, Aashweenjeetkaur

Subject: [EXTERNAL] PRE REPAIR SURVEY --- YOUR REF: SGS 2802 G --- ACCIDENT INVOLVING SJB 9187 G AND SGS 2802 G ON 7 JUNE 2019 AT OPEN CARPARK OF BLOCK 148 POTONG PASIR AVENUE 1 AT ABOUT 1830 HOURS

Importance: High

This message is from an external sender; be cautious with links and attachments.

Our Ref: SJB 9187 G (et)
WITHOUT PREJUDICE

Dear Sir/Madam,

We are instructed by **TOH CHING SIONG** to notify you of a road traffic accident on 7 June 2019 at about 1830 hours at open carpark of Block 148 Potong Pasir Avenue 1 involving our client's vehicle registration number SJB 9187 G and vehicle registration number SGS 2802 G driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Thank you.

Regards,
Elaine Toh
Vision Law LLC
Tel: 65342811 (Ext. 122)
Fax: 65356802

cc: SJB 9187 G – By fax: 67436878 only

VISION LAW LLC
Advocates & Solicitors
(Incorporated with limited liability)
Unique Entity No. 200721148H
Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413
Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

VISION LAW LLC

Advocates & Solicitors
(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
SELWYN TAN YINGXIAN
CLARISSA CHEONG YUNHUI
EDISON TAM CHYI EU
SONIA LIM WEI LEI

Unique Entity Number: 200721148H

✓HEAD OFFICE

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓: (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SJB 9187 G (et)
Your Ref: SGS 2802 G

11 June 2019

BY EMAIL ONLY

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attention: Motor Claims Department

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SJB 9187 G AND SGS 2802 G ON 7 JUNE 2019 AT OPEN CARPARK OF BLOCK 148 POTONG PASIR AVENUE 1 AT ABOUT 1830 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : **C.H. MOTOR VEHICLE REPAIR TRAINING**
Block 3019A Ubi Road 1
#01-30
Singapore 408713
Contact Person : **Mr. Joe @ 6841-8841 / 6748-8888 (Please call before going)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully


DIANE ANG
(HEAD OFFICE)

cc: SJB 9187 G – By fax: 67436878 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5346J
Vehicle Details	
Vehicle No.:	SJB9187G
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jun 2019
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8LA
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	R18A13018735
Chassis No.:	JHMFD163085211417
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$20,899.00
Original Registration Date:	28 Jan 2008
First Registration Date:	28 Jan 2008
Transfer Count:	0
Actual ARF Paid:	\$22,989.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Nov 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$25,084.00
COE Rebate Amount:	\$17,196.00
Total Rebate Amount:	\$17,196.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Jun 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/06/2019 10:21
Date Of Accident	07/06/2019 18:30
Exact Location Of Accident	BLK 148 POTONG PASIR AVE 1 OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB9187G
Insured/Policyholder	
Name Of Registered Owner	TOH CHING SIONG
NRIC No	S6935346J
Email Address	KEVINTOH95@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96408182
Alternative Phone No	OTHERS-96408182

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.8L A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10130552
Cover Note Number	N.A

Driver

Name of Driver	TOH CHING SIONG
NRIC No	S6935346J
Date Of Birth	14/10/1969
Occupation	INDOOR
Date Of Driving Pass	07/10/1993
Driving Experience	25 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96408182
Fax Number	
Contact Number	OTHERS-96408182
EEmail Address	KEVINTOH95@GMAIL.COM

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was in my vehicle, when this vehicle SGS2802G reversing into the parking lot. While reversing, this vehicle accidentally brushed onto my vehicle front right side portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS2802G
Vehicle Make/Model/Colour	CITROEN GRAND C4 PICASSO 1.6 BLUEHDI EAT6 S/R / WHT
Details Of Properties	NIL
Vehicle Category	PRIVATE CAR
Name of Driver	JIMSON LAI
NRIC/Passport Number	
Contact Number	98202802
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: : PASSENGER 1

GENDER: : FEMALE

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS
REPORTING OFFICER

AIZAM BIN ATAN

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan

A: SJB 9187 G

B: SGS 2802 G

B1K
148

Pasar Pasir Ave 1
Open Carpark

ACCIDENT STATEMENT (2000 characters)

I was in my vehicle,when this vehicle SGS2802G reversing into the parking lot. While reversing ,this vehicle accidentally brushed onto my vehicle front right side portion.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
AIZAM BIN ATAN

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 June 2019 at 10:30 AM

Date/Time:

9 June 2019 at 10:30 AM

SJB 9187 G

Int Bumper / cut

" " clips / etc.

" " Fog lamp RH - CFA

Headlamp RH - CFA


17/6/2019

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jun 2019 Edit Reg		14 Jun 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LAI SWEE PENG, ID: S0212358D								
Main Claimant:	-								
Vehicle Reg. No.:	SJB9187G	Date of Loss:	07/06/2019 00:00 - :59 [136 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8129878565SG	Policy/Cover Note No.:	(Comprehensive)						
Vehicle Reg. No. (Insured):	SGS2802G	Policy No. (Claimant):							
		Excess:							
Repairer:	Ch Motor Vehicle Repair (HQ) BLK 3019A, #01-30 UBI ROAD 1, 408713 Ubi - Tel: 6748 8888								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 25/06/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (17/06/2019): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


***SJB9187G (8129878565SG)
[SGS2802G]**

TP

-

**Jun 7 2019 12:00AM
[LAI SWEE PENG]
Ch Motor Vehicle Repair**

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
2	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
3	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
4	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
5	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
6	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
7	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
8	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
9	17/06/19 10:08	General View		Load JPG	<input checked="" type="checkbox"/>		
10	17/06/19 10:09	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
11	17/06/19 10:09	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
12	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
13	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
14	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
15	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
16	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
17	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
18	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
19	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
20	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
21	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
22	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
23	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
24	26/06/19 11:16	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>		
25	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
26	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
27	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
28	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
29	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
30	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
31	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
32	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
33	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
34	26/06/19 11:16	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/06/19 10:55	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010553/GCD3E2

Date: 01/07/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJB9187G

Insured Vehicle No : SGS2802G

Date of Loss: 07/06/2019

Nature of Claim: TP

Claim No: 8129878565SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB9187G**

Make & Model: HONDA CIVIC, 1.5 (A)

Reg. Date: 28/01/2008 (Man. Year: 2007)

Colour: Grey

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: R18A13018735

Chassis No: JHMFD16308S211417

Odometer: 144788 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55Z R16

Rear Tyre Size: 205/55Z R16

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/06/2019

Date Inspected: 14/06/2019 Inspected At:

 Ch Motor Vehicle Repair (HQ)
 BLK 3019A, #01-30 UBI ROAD 1
 Singapore 408713

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Cut	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRONT BUMPER FOG LAMP RH	Cracked	0.00 F	*- F
4	1		*HEADLAMP RH	Cracked	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >