

12/01/2011

ASS. REC. BY:

REF: CS3/A19/90/0558/Gcd302

Special Instruction:

Surveyor:

Gino Giong

ASSIGNMENT (Office)

From (Person):

Minimen chin lee ying

of

AIG

Date/Time:

14/6/14 @ 8:58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ 6222S

Insured:

SLV 3485G

at Workshop m/s

J.L. Auto

Tel:

9188 5495

of

Blk 3006, Ubi Rd 1 # 01-346

Policy No:

Claim No:

08637807548G

Sum Insured:

Excess:

Make of Veh:

D.O.A.

10/06/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:46am @ 14/6/14

Person Contacted:

Ah Tay

Vehicle IN OUT

Date/Time

Action/Instruction

Estimate (X)

GZ 6222S - NA/INC/90/0202/24

DOA: 10/6/2019

SLV 3485G - NA/INC/90/0202/24

DOA: 10/6/2019

After repair: 19/6/2019

ASS. REC. BY:

REF:

AIG

B 6500D

(-2021)

PRS

## ASSIGNMENT

From:

Date:

14/6/19

Veh No:

686222S

Yr Regn:

12 Jul 2006

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

GZ 6222S

Make:

Nissan Cabstar C.C

3153

at Workshop m/s

J.L. Auto

Colour:

Beige

A/C:

Insured / Std / NI / NA

of

Blk 3006 Ubi Rd 1 # 01-346

Sp.Reading

321703

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

JN1 SF4F238 0861412

Policy No.

C/No:

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: NIP / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F: 195 R15 (CST)

R: 155 R12 (FALKEN)

Remark: The veh had commenced its

repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

5

mm

R/Bal.

5

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

5

mm

L/Bal.

5

mm

Est. Repairs:

4

days

Res.:

Yes or No

D.O.A.

D.O.I.

14-06-19

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

w/s

2pm

CA / REV / REP. / 24 HRS (up)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

~~\$3000 - \$4000~~

Date/Time, File Pass to?



: Preli. Report

Days Of Repair:

4

1)



: Final Report

Resurvey No. of Trip:

1

Date/Time, File Return to?

Survey Fee:

180

2)

Add Fee:



: Site Insp (\$)

Transportation:

S + RS \_\_\_ \$



: Interview (\$)

Photos



: Tech. Insp (\$)

Others



: Weekend (\$)

TOTAL


191

Report Format:

DAR

Lump Sum / N.B. 13

**PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHIC...**

From: Chin, Lee-Ying  
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)  
Cc: Fong, Andy-SY  
Sent: 6/14/2019 8:58:26 AM  
Attachments:  [tmp7B97.tif](#)

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)



883 North Bridge Road  
#11-03 Southbank  
Singapore 198785  
T: 6292 5838  
F: 6292 5938  
(UEN No. 201333127N)  
(GST Reg No. 201333127N)

Our Ref : CY.GZ6222S.19.JLA(HW).wp(Lh)

Your Ref : Your insured vehicle SLV 3485G

11 June 2019

**BIS Motoring Pte Ltd**  
c/o AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
Singapore 079120

By Fax No: 6835 7416

Dear Sirs

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES GZ 6222S & SLV 3485G ON 10.06.2019 @ 15:30HRS ALONG JUNCTION YISHUN CENTRAL & YISHUN AVE 2**


We are instructed by Meng Hui Painting Contractor to notify you of a road traffic accident on 10.06.2019 at 15:30hrs along Junction Yishun Central & Yishun Ave 2 involving our client's customer's vehicle registration number GZ 6222S and vehicle registration number SLV 3485G driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

At the same time, our proposed list of surveyors is appended as below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent
4. Alan Chong

Yours faithfully,



C. Yogarajah LLC  
Enc

Cc: M/s JL Auto Service Pte Ltd  
Block 3006 Ubi Road 1  
#01 - 346  
Mr. Ah Tay (9188 5495)  
Fax no : 6310 7269

**Confidentiality & Privilege:** This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. **Disclaimer:** Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	6500D
Vehicle Details	
Vehicle No.:	GZ6222S
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jun 2019
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR G
Primary Colour:	Beige
Manufacturing Year:	2006
Engine No.:	QD32225744
Chassis No.:	JN1SF4F23Z0861412
Maximum Power Output:	-
Open Market Value:	\$18,482.00
Original Registration Date:	12 Jul 2006
First Registration Date:	12 Jul 2006
Transfer Count:	0
Actual ARF Paid:	\$925.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jul 2021
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,247.00
COE Rebate Amount:	\$9,191.00
<b>Total Rebate Amount:</b>	<b>\$9,191.00</b>
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 17 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/06/2019 17:00
Date Of Accident	10/06/2019 15:30
Exact Location Of Accident	JUNC YISHUN CENTRAL & YISHUN AVE 2
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	GZ6222S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	MENG HUI PAINTING CONTRACTOR
Co Reg No	47376500D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91088102
Alternative Phone No	OFFICE-91088102
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	CABSTAR G
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5044593898-08
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN BOON HUI
NRIC No	S1686452H
Date Of Birth	11/03/1965
Occupation	OUTDOOR
Date Of Driving Pass	06/11/1993
Driving Experience	25 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93803530
Fax Number	
Contact Number	OFFICE-93803530
EEmail Address	NOEMAIL

Address	BLK 201 BEDOK NORTH STREET 1 #11-535
Postcode	460201
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG THE STATED VENUE AS THERE WAS CYCLIST CROSSING ON THE PEDESTRIAN CROSSING. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV3485G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	YAP JUN HONG (YE JUNHONG)
NRIC/Passport Number	S8227101E
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: :

GENDER: :



## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Meng Hui Painting Contractor  
Blk 362C #05-813  
Sembawang Crescent  
Singapore 753362


Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to statement

---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Blk 362C #05-813  
Sembawang Crescent  
Singapore 753362

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:


Vehicle No: 6Z 6225

### Rear Portion

Rear Portion				CON	AC	Qty
NAC	INC	Item				
1137	993626	Rear Number Plate	BT	/		
1138	993627	Rear Number Plate Base				
2044	993628	Rear Number Plate Bracket				
1140	993632	Rear Number Plate Lamp				
1141	992958	Rear Bumper				
1142	993108	Rear Bumper Upper				
1143	993017	Rear Bumper Lower				
1144	993054	Rear Bumper Side				
1147	992976	Rear Bumper Bracket				
1148	993068	Rear Bumper Side Retainer				
1149	993045	Rear Bumper Reinforcement				
2045	993081	Rear Bumper Step Panel				
2046	993079	Rear Bumper Step Garnish				
2047	993186	Rear Crash Bar				
1158	994023	Reverse Sensor	DM	/		
1159	993327	Rear End Panel	Repair	/		
1163	993851	Rear LH Taillamp	CRA	/		
1164	993853	Rear LH Taillamp Garnish				
1165	993859	Rear LH Taillamp Panel				
1166	995116	Rear RH Taillamp				
1167	993853	Rear RH Taillamp Garnish				
1168	993859	Rear RH Taillamp Panel				
1169	993554	Rear Apron Panel				
1289	995156	Rear LH Door				
1350	993201	Rear RH Door				
2048	991328	Rear Door Emblem				
2049	993274	Rear Door Outer Handle				
2050	993228	Rear Door Garnish				
2051	993294	Rear Door Rubber				
1291	995194	Rear LH Door Hinge				
1352	995307	Rear RH Door Hinge				
1301	993261	Rear LH Door Lock				
1362	993261	Rear RH Door Lock				
2052	993232	Rear Door Glass				
2053	993955	Rear Door Glass Sealant				
1248	994729	Third Brake Light				
1181	994543	Tailgate	OD	/		
2054	993700	Rear Rubber Stopper	Cut	/		2
2055	993701	Rear Rubber Stopper Bracket	BT	/		
1182	991328	Tailgate Emblem				
1183	994643	Tailgate Outer Handle				
1185	994545	Tailgate Garnish				
1193	994602	Tailgate Glass				
1194	994606	Tailgate Glass Rubber				
1195	994604	Tailgate Glass Moulding				
1196	994607	Tailgate Glass Sealant				
2056	994597	Tailgate Extension Mirror				
1197	994629	Tailgate Lock	BT	/		
1198	994651	Tailgate Rubber				
1199	994611	Tailgate Hinge				
1200	994594	Tailgate Damper				
1201	994613	Tailgate Inner Board panel	RC	/		2
2057	993992	Rear Wiper Arm				
2058	993995	Rear Wiper Blade				
2059	993997	Rear Wiper Motor				
2060	993484	Rear Floor Panel				
1204	995065	Spare Tyre				
2061	993785	Spare Tyre Bracket				
1212	993364	Rear Exhaust Pipe	Repair	/		
1214	993361	Rear Exhaust Mounting				
1216	995223	Rear LH Chassis Member				
1217	993165	Rear RH Chassis Member				

MAC	INC	Item	CON	AC	Qty
-----	-----	------	-----	----	-----

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			Repair
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker			
		'Nissan' sticker			
		'Nissan Cabstar' sticker			
		'70km/h' sticker			
		'10 pax' sticker			

  
 17/6/2019

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2019 <a href="#">Edit Reg</a>		14 Jun 2019 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [\[Created by adjuster\]](#)

Insured:	<b>BIS MOTORING PTE LTD</b> , Co. Reg. No.: 201735055D		
Main Claimant:	-		
Vehicle Reg. No.:	<b>GZ6222S</b>	Date of Loss:	10/06/2019 00:00 - :59 [154 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 0863780754SG</b>	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	<b>SLV3485G</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>JI Auto Services Pte Ltd (HQ)</b> Blk 3006 UBI ROAD 1 #01-346, 408700 Ubi - Tel:		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 25/06/2019]</b>		
Claimant's Solicitor:	<b>C YOGARAJAH LLC</b> - Tel: 62925838		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (17/06/2019): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GZ6222S (0863780754SG)

[SLV3485G]


































TP


-

Jun 10 2019 12:00AM

[BIS MOTORING PTE LTD]

JI Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser			▼
Photos/Images															3 per page			▼	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print				
1	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
2	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
3	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
4	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
5	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
6	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
7	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
8	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
9	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
10	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
11	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
12	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
13	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
14	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
15	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
16	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
17	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
18	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
19	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
20	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
21	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
22	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
23	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
24	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
25	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
26	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
27	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
28	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
29	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
30	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
31	17/06/19 10:06	General View														Load JPG	<input checked="" type="checkbox"/>				
32	17/06/19 10:07	Odometer Reading														Load JPG	<input checked="" type="checkbox"/>				
33	17/06/19 10:07	Chassis Number														Load JPG	<input checked="" type="checkbox"/>				
34	27/06/19 11:57	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>				
35	27/06/19 11:57	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>				
36	27/06/19 11:57	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>				
37	27/06/19 11:57	Photo After Spray														Load JPG	<input checked="" type="checkbox"/>				

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	17/06/19 10:44	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG19010558/GCD3E2

Date: 01/07/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

**Claimant Vehicle No :** GZ6222S

**Insured Vehicle No :** SLV3485G

Date of Loss: 10/06/2019

Nature of Claim: TP

Claim No: 0863780754SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GZ6222S**

Make &amp; Model: KIA CERATO, 1.6 (A)

Engine No: QD32225744

Reg. Date: 12/07/2006 (Man. Year: 2006)

Chassis No: JN1SF4F23Z0861412

Colour: Beige

Odometer: 321703 km

Engine Capacity: 3153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 155 R12

Front Left Side: CST 5 mm

Rear Left Side: Falken 5 mm

Front Right Side: CST 5 mm

Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 14/06/2019

Date Inspected: 14/06/2019 Inspected At:

 JI Auto Services Pte Ltd (HQ)  
 Blk 3006 UBI ROAD 1 #01-346  
 Singapore 408700

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
2	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
3	1		*REAR END PANEL	Repair	0.00 F	*- F
4	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
5	1		*TAILGATE	Dented	0.00 F	*- F
6	2		*REAR RUBBER STOPPER	Cut	0.00 F	*- F
7	1		*REAR RUBBER STOPPER BRACKET	Bent	0.00 F	*- F
8	1		*TAILGATE LOCK	Bent	0.00 F	*- F
9	2		*TAILGATE INNER PANEL	Necessary	0.00 F	*- F
10	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
11	1		*SIDE GATE LOWER PANEL	Repair	0.00 F	*- F
12	1		*NISSAN STICKER	Necessary	0.00 F	*- F
13	1		*NISSAN CABSTAR STICKER	Necessary	0.00 F	*- F
14	1		*70KM/H STICKER	Necessary	0.00 F	*- F
15	1		*10 PAX STICKER	Necessary	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >