

U.S. MAR 19 010070 / 450302

08/11/13) wef  
ASS. REC. BY: Marcus

REF: MS16/

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLX794EJ  
 at Workshop m/s: Lt.  
 of: \_\_\_\_\_  
 Insured: FBG173E  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_


Veh No: SLX794EJ Yr Regn: 10113  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CA  
 Make: BMW 328i c.c. 1997  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 85044 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WBA3A52060F25458  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: \_\_\_\_\_  
 R: 245/35Zr19  
 BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 1.51 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS LTA73592  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Front 6 mm R/Bal. 6 mm  
 Rear 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 13/6/19 D.O.I. 14/6/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S Body  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	carbon sticker
3/7/19	No second hand parts to owner issue want replaced new door. contact final by # 3123-67 with A.H. (\$ 10,111.13 Red - 76%)

  
 3/7/2019

RECEIVED 4 JUL 2019

Date/Time, File Pass to? 04/07/19  
 1) Typist  : Prel. Report  
 : Final Report  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 4  
 Resurvey No. of Trip: 2

2) \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	200
Transportation:	11
_____ S + RS _____ SI	
Photos	
Others	
TOTAL	211

Report Format : \_\_\_\_\_  
 Lump Sum 11.B. (\$ 3,123.67 P/P)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Monday, 17 June 2019 1:42 PM  
**To:** motorsurvey@sg.msig-asia.com  
**Cc:** SUR; Accounts (LKKAuto); KKLau  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD ,DOA:  
13/06/2019 ,SLX 7945J (TP VEHICLE), FBG 173Z (OI VEHICLE)  
**Attachments:** TP GIA REPORT.pdf; POLICE REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLX 7945J at M/s: FASTECH AUTO PTE LTD,1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 14/06/2019.

Enclosed herewith a copy of TP's GIA report & Police Report Statement. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

- [Self drive to khao kho, khao yai](#)
- [Singapore Private Property prices.still up or down? Pa...](#)
- [Why keep ICs of military personnel?](#)

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

**New 5 Years Renewal COE Toyota Altis 1.6A.**



3.18% P.A \$0 Admin Fees At GV.  
Finance 2 Years Warranty.  
Monthly From \$488.  
[GV Credit Pte Ltd](#) [StarAd](#)

**Auto Inn**  
*An Inspiration For Car Buyers*

[click here to view our PRISTINE USED CARS at GREAT PRICES](#)

Browse by Category

Sort by Date Posted  20 results/page

1 vehicles

bmw 328

Advanced Search  Submit

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

**Search Selection** **bmw 328** Any Any 2013 Any Any Any Available



**BMW 3 Series 328i** **\$75,800** \$15,290 /yr 28-Feb-2013 1,997 cc 72,000 km Luxury Available

1 Expat Owner, 72,000 Km Done Only, Well Maintained By Owner From PML, Excellent Condition, View To Appreciate.

Posted: 07-Jun-2019 Tags: 2013 BMW 328i, 2013 bmw 328i, BMW 338i, bmw 338i, BMW, 328i, Used BMW

[Save this search criteria, to get email alerts whenever a match is found.](#)

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used bmw 328, bmw 328 Singapore, used bmw 328 Singapore, used bmw 328, used vehicles Singapore or even buy used bmw 328 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[Compare](#)

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 4084G

### Vehicle Details

Vehicle No.: SLX7945J  
Vehicle to be Exported: No  
Intended Deregistration Date: 14 Jun 2019  
Vehicle Make: B.M.W.  
Vehicle Model: 328I A  
Primary Colour: White  
Manufacturing Year: 2012  
Engine No.: A1570149N20B20A  
Chassis No.: WBA3A52060F254858  
Maximum Power Output: 180.0 kW (241 bhp)  
Open Market Value: \$42,627.00  
Original Registration Date: 31 Oct 2013  
First Registration Date: 31 Oct 2013  
Transfer Count: 2  
Actual ARF Paid: \$46,678.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 30 Oct 2023  
PARF Rebate Amount: \$32,674.00

### Intended COE Rebate Details

COE Expiry Date: 30 Oct 2023  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$93,889.00  
COE Rebate Amount: \$40,918.00  
**Total Rebate Amount: \$73,592.00**

The information contained herein is correct as at 14 Jun 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/06/2019 14:10
Date Of Accident	13/06/2019 18:00
Exact Location Of Accident	ALONG PIE TWRDS CTE SLIP ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX7945J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ANG WEE MING(HONG WEIMING)
NRIC No	S7934084G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94352865
Alternative Phone No	OTHERS-94352865

### Vehicle Particulars

Manufacturer	BMW
Model	328I A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104138182
Cover Note Number	

### Driver

Name of Driver	ANG WEE MING(HONG WEIMING)
NRIC No	S7934084G
Date Of Birth	26/10/1979
Occupation	INDOOR
Date Of Driving Pass	02/08/1989
Driving Experience	29 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94352865
Fax Number	
Contact Number	OTHERS-94352865
EMail Address	NOEMAIL

Address	BLK 571A #09-902 WOODLANDS AVENUE 1
Postcode	731571
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEE MUN YEE GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20190613/2134;

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBG173Z
Vehicle Make/Model/Colour	HONDA SUPRA GTR 150 MANUAL
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode  
Insurance Company Name MSIG INSURANCE (SINGAPORE) PTE. LTD.  
Nature Of Damage  
No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**B. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

**IDAC KAKI BUKIT(VAC)**  
 23 KAKI BUKIT AVE 4  
 Singapore 415933  
 Reporting Centre   
 Name: Fax: 67492305  
 NRIC/FIN No. Email: vackb@iainet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report / T / 20190613 / 2134

DECLARATION

I/We declare the foregoing particulars are true in every respect.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

**IDAC KAKI BUKIT(VAC)**  
25 KAKI BUKIT AVE 4  
Singapore 415933  
Reporting Centre Person's Signature  
Name: Fax: 67492305  
NRIC/FIN No-Email: vackb@singnet.com.sg





Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	ANG WEE MING	ID No.	S7934084G
Related Vehicle	SLX7945J (Car)	Contact No.	94352865
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 13/06/2019, at around 1800hrs, I was driving along PIE towards CTE when I heard a sound and felt an impact coming from the side of my vehicle (SLX7945J). I made a check saw a motorcycle (FBG173Z) on the right side of my vehicle. the rider fell along with his bike and that was when left side of the motorbike swipe against the right side of my vehicle.

My car suffered from scratches and dents while the bike suffered from damaged gear.

Ambulance was at scene.

Traffic Police was at scene.

Nobody was conveyed to the hospital.



Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

**CONTINUATION OF REPORT**


**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: L / Sgt 2 CHAN JIA HUI, EUNICE <i>h.</i>
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt NOR FAIZAL BIN YAHYA Contact No.: 65476202 SN 130

Signature Of Informant: <i>h.</i>
Date/Time: 13/06/2019 21:23
Classification Of Case:

Authentication Stamp  
  
  
**Singapore Police Force**

Date of Accident : 13/6/19 Accident Time: 6pm (24-HR-Format)  
 Accident Place : Along PIE toward CTE slip road  
 Vehicle No. (Car Plate No.) : SLX7945J Make/Model: \_\_\_\_\_  
 Insurance Company : NTUC Policy No: 5104138182  
 Owner or Company Name /IC No. : Ang Wee Ming /5793408467  
 Owner or Company Contact No. : 94352865 Owner's Hp \_\_\_\_\_ Company Tel \_\_\_\_\_  
 DRIVER'S Name / IC No. : as above  
 DRIVER'S Date Of Birth : 26/10/1979 DRIVER'S License Pass Date 2/8/1989  
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: owner  
 DRIVER'S Address : B1K 571A woodlands Ave 1 #09-902  
 DRIVER'S Contact No./ Alt No. : 1) \_\_\_\_\_ 2) 5731571  
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
 Email Address : \_\_\_\_\_  
 Weather & Road Surface : DRY \ RAINING & WET \ AFTER RAIN & WET  
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
 Number of Passengers (Including Driver): 2 person

Was there any video Captured by car camera: YES \ NO  
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
 Any Injury (If YES, Pls state): yes

**Other Party Driver's Particular (if any)**

Vehicle No: <u>FBG173Z (M510)</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

\* NEW - Passenger's name & gender:  
Lee Mun Yee (F)

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**SKETCH PLAN**

A - SLX7945J  
B - FB61173Z

**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Refer to the police report /T/20190613/2134

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

FASTECH AUTO PTE LTD  
 1 KAKI BUKIT AVE 6 #01-48  
 SINGAPORE 417883 TEL:67467158

SLX 7945J

1PC	FRONT DOOR O/S		R	\$2,445.10	X
1PC	FRONT DOOR INNER RUBBER O/S		11	\$295.30	X
1PC	REAR DOOR O/S	1330.87	11/30/1	\$2,120.50	—
1PC	REAR DOOR INNER RUBBER O/S	147.73	11	\$292.50	—
1PC	REAR DOOR GLASS OUTER MOULDING O/S		11	\$195.00	X
1PC	REAR DOOR GLASS REGULATOR O/S		11	\$388.20	X
1PC	REAR DOOR INNER TRIM BOARD O/S		11	\$812.00	X
1PC	REAR DOOR FRAME MOULDING O/S		11	\$250.00	X
1SET	REAR DOOR CARBON STICKER O/S		11	\$220.00	✓
1PC	REAR BUMPER		R	\$1,431.00	X
1PC	REAR SPORT RIM 19 INCH		11	\$1,800.00	LR 200
1PC	REAR DOOR INNER LOCK O/S		11	\$455.20	X
				\$704.80	

(57)

TO CHECK WIRING	\$80.00	20
TO CONDUCT WHEEL ALIGNMENT	\$150.00	80
TO TRANSFER REAR DOOR MECHANISM	\$150.00	80
TO SPRAY RUST PROOFING	\$50.00	30
LABOUR FOR PANEL BEATING & REPAIRCING PARTS	\$800.00	300
TO PUTTY & SPRAY PAINTING	\$1,300.00	800
<b>TOTAL</b>	<b>\$13,234.80</b>	

LKK Auto Consultants (wince notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party claims shall be on "rejector" basis
- No third party claims shall be allowed
- Supplementary terms must be reviewed and is subject to law approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

not submit  
 14/01/19  
 P/P 312367  
 4dy

P-16986  
 57  
 1613.67

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG19010575/USD3N2

Date: 10/07/2019

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/18-995820-WTT
Claimant Vehicle No :	SLX7945J	Insured Vehicle No :	FBG173Z
Date of Loss:	13/06/2019	Nature of Claim:	TP
		Claim No:	MSC/V/19-000671

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLX7945J	Engine No:	A1570149N20B20A
Make & Model:	BMW 328i, 2.0 (A)	Chassis No:	WBA3A52060F254858
Reg. Date:	31/10/2013 (Man. Year: 2012)	Odometer:	85044 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	245/35ZR19	Rear Tyre Size:	245/35ZR19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

## COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,704.80	1,813.67	8,891.13	83.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	1,310.00	1,220.00	48.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>13,234.80</b>	<b>3,123.67</b>	<b>10,111.13</b>	<b>76.40</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>926.44</b>	<b>218.66</b>	<b>707.78</b>	<b>76.40</b>
<b>Nett Amount (S\$)</b>	<b>14,161.24</b>	<b>3,342.33</b>	<b>10,818.91</b>	<b>76.40</b>

## INSPECTION

Date of Assignment:	17/06/2019		
Date Inspected:	14/06/2019	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 10 Jul 2019)
<b>Parts:</b> 143	BMW 328i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLX7945J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Repair	2,445.10 F	*- FL
2	1		*FRONT DOOR INNER RUBBER O/S	Not Necessary	295.30 F	*- FL
3	1		*REAR DOOR O/S	Dented/Bent	2,120.50 F	*1,330.87 FL
4	1		*REAR DOOR INNER RUBBER O/S	Necessary	292.50 F	*147.73 FL
5	1		*REAR DOOR GLASS OUTER MOULDING O/S	Not Necessary	195.00 F	*- FL
6	1		*REAR DOOR GLASS REGULATOR O/S	Not Necessary	388.20 F	*- FL
7	1		*REAR DOOR INNER TRIM BOARD O/S	Not Necessary	812.00 F	*- FL
8	1		*REAR DOOR FRAME MOULDING O/S	Not Necessary	250.00 F	*- FL
9	1		*SET REAR DOOR CARBON STICKER O/S	Necessary	220.00 F	*220.00 FL
10	1		*REAR BUMPER	Repair	1,431.00 F	*- FL
11	1		*REAR DOOR INNER LOCK O/S	Not Necessary	455.20 F	*- FL
12	1		*REAR SPORT RIM 19 INCH (LOCAL REPAIR)	Cut	1,800.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,704.80</b>	<b>1,898.60</b>
<b>- List Item Discount on L Items 0.00/5.00% (\$\$)</b>	<b>0.00</b>	<b>84.93</b>
<b>Total Parts (\$\$)</b>	<b>10,704.80</b>	<b>1,813.67</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	80.00	20.00
2	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
3	TO TRANSFER REAR DOOR MECHANISM	New	150.00	80.00
4	TO SPRAY RUST PROOFING	New	50.00	30.00
5	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	800.00	300.00
6	TO PUTTY & SPRAY PAINTING	New	1,300.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>2,530.00</b>	<b>1,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >