

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
COMLAW LLC*			Ref : CS/LAW19010611/Utd3e2		
64 CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Date: 11-07-2019 Code: L050			
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SJM 3513E	Veh. Inspected	SJM 3500S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MC/MC 6355/2019	Excess (\$)	0.00	
	Assign From	CHARLENE CHEE	Assign Date	13/06/2019	
2. Vehicle Particulars & Condition					
	Make & Model	DONGFENG EQ6380 (M)	c.c	1310	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	LGK132K7689139812	Colour	MAROON	
	Odometer	140676	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	165/70 R14	FALKEN	5 mm	
	L/H Front Tyre	165/70 R14	FALKEN	5 mm	
	R/H Rear Tyre	165/70 R14	FALKEN	5 mm	
	L/H Rear Tyre	165/70 R14	FALKEN	5 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	5. General Information				
	Accident Date	11/06/2018	Inspection Date	05/07/2019	
	Survey held at	50 BUKIT BATOK ST 23			
	Repairer	FASTECH AUTO PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: